

# Promises Made. Promises Kept.

# Douglas County School District Master Capital Plan



June 18, 2019

Board of Education,

It is our pleasure to present, the 2019-2020 Master Capital Plan (MCP). Many thanks are owed to Douglas County taxpayers for their willingness to approve ballot issue 5B, which will provide the funds to tackle long-deferred critical capital needs of the schools and other facilities that serve our 68,000 students. Presented at a time of significant change for the Douglas County School District, our goal is to convey a clear picture of the needs currently being addressed, as well as to detail those that remain unaddressed.

The incontrovertible effect of 5B will be an improved learning environment for students and work environment for teachers and other staff. Previously identified Tier One needs are being addressed, from fully operational climate control systems and improved security systems, to new carpet and paint. The plan for the F Pod addition to Castle View High School is being developed with substantial community input. Although 5B provides solutions for many identified concerns, it does not provide funds for capital renewal issues arising next year, next month, or even next week, nor does it supply enough capital to upgrade our schools to the latest standards across the board. A sustainable process for meeting continuing capital needs must be developed to avoid another backlog.

In presenting this MCP, the LRPC decided to maintain the listing of Tier One and Tier Two, which are being addressed by 5B funds. For clarity, these are illustrated in shaded colors to allow the Board and the public to see where the funds are being spent and the ongoing process of meeting these needs. The prioritization of spending on Tier Two needs is an ongoing process, with the individual schools deeply involved in that process. As projects are completed each year, they will be removed from the MCP. Security, Information Technology and Transportation projects were removed from this MCP, since these projects are defined and funded by the bond. Without the new construction added since last year and discussed below, this MCP actually decreased by \$216M-\$221M.

As part of the evaluation process for bond funding, the 2018-19 MCP fully integrated the capital needs of our charter schools and established a communication and cooperation paradigm. Superintendent Tucker and his staff are fully committed to addressing the long-term needs, and the capital investment necessary, to meet the needs of all of our students.

An important secondary benefit of passing 5A and 5B, the District has developed new internal and external methods to ensure the funds are well spent and create transparency and an atmosphere of trust between the taxpayers and District administration in the use of taxpayer funds.

The 2018-19 MCP detailed the size and complexity of the Douglas County demographics. Although some areas continue to grow, in other areas the student population is declining, and likely will continue to do so. To address these concerns, the Board approved a school capacity and boundary analysis, which is currently underway. This is a major step to developing the data required for long-term planning.

While this MCP shows that certain areas may likely need new construction, in other areas different solutions, such as boundary adjustments or repurposing of some facilities, might alleviate immediate capacity concerns.

Once again, the MCP identifies new construction needs and costs, and identifies potential alternatives to new construction. The Board is tasked with making complex and nuanced decisions about the best use of tax dollars to meet needs for today and in the future. The District has the opportunity to lead the way to address the educational needs of all students, including vocational and technical education. As examples, the proposed Ridgegate High School can be an opportunity for the District to show leadership and creativity in capital planning, while needs in the growing Sterling Ranch area can be addressed in a number of ways. Other areas of growth will need similar attention and creativity. The entire Douglas County community will have an opportunity to provide input.

This MCP foresees greater needs for facilities to address the increasing percentage of students with special and identified educational needs, as well as educational options for students who do not choose their neighborhood school. While some of these can be met with changes in existing facilities, in other cases new buildings may be necessary to provide a first-class education. The MCP details a number of new facilities in this area.

While significant 5B funds are directed toward school security upgrades, recent events remind us that the safety of our students is an ongoing priority. How capital funds can be part of a plan to address potential threats will require great cooperation between many entities. The LRPC hopes to assist in that process.

Full Day Kindergarten will present opportunities and challenges in capital and facilities planning. Underutilized schools may provide kindergarten space, but in over-utilized schools, creative planning by principals and District staff may be needed.

The LRPC greatly appreciates the collaborative effort with, and the guidance from, staff in developing the MCP. The LRPC thanks the Board of Education for the trust it places in the LRPC to assist in the long-term planning for the District.

On Behalf of the Long Range Planning Committee Brad Geiger, Chair

Brad Geiger, Chair

# **Table of Contents**

DCSD Leaders and Partners	2
Executive Summary	3
Existing Conditions	5
Planning Areas Map	6
Enrollment Trends	8
Methodology	12
2018 Bond Funded Items	17
New Construction	18
School Capacity	26
Neighborhood, Magnet, and Alternative Schools	30
Support Facilities	164
District-wide Needs	192
Charter Schools	203
Summary	240
Appendix 1-History of Capital Improvements	244
Appendix 2-Capital Needs for Select Facilities with Extensive Issues	253
Appendix 3-Development Summary	267
Appendix 4-Capital Needs by Year	274
Appendix 5-Capital Needs Deltas	280
Appendix 6-Capital Needs by Tier	281
Appendix 7-2018 Bond Construction Schedule	282

# Master Capital Plan Overview

The Douglas County School District Master Capital Plan encompasses a five-year period (2019-2024) and represents an important tool in the district's planning decisions. It is used to identify and prioritize school sites for future schools in order to satisfy student enrollment needs. It is also used to prioritize funding for capital reinvestment and new construction. Recognizing that school facilities must adapt to fluid educational requirements and the district exists in a dynamic community, it is imperative that planning for future educational and facility needs of the district is ongoing. This document is updated on an annual basis in coordination with the Long Range Planning Committee.

# DCSD Leadership and Partners

#### Administration

Thomas S. Tucker, Ph.D., Superintendent Richard D. Cosgrove, P.E., Chief Operations Officer Nancy Ingalls, Personalized Learning Officer Mary Kay Klimesh, General Counsel Ted Knight, Assistant Superintendent, School Leadership Stacey Rader, Communications Officer Matt Reynolds, Chief Assessment and Data Officer Gautam Sethi, Chief Technology Officer Scott Smith, Chief Financial Officer Amanda Thompson, Chief Human Resources Officer Marlena Gross-Taylor, Chief Academic Officer

#### **Board of Education**

Christina Ciancio-Schor, Director District D Anthony Graziano, Director District B Krista Holtzmann, Director District G Anne-Marie Lemieux, Director District C Kevin Leung, Director District E David Ray, Director District F Wendy Vogel, Director District A

#### **Long Range Planning Committee**

The Long Range Planning Committee was created in 1983 to work with Douglas County School District. The committee is comprised of two representatives from each high school feeder area, two at-large members, two charter school representatives, and a representative of the development and home building community. The Long Range Planning Committee is one of three committees of the Board of Education. The charge of the Long Range Planning Committee is to continually analyze community population data, evaluate population impacts on district education and support facilities, and collect community feedback. The committee also recommends appropriate actions to the Board of Education regarding school attendance boundaries, facility usage (including facility construction, renovation, or closure) and anticipated capital outlay requirements. Every year the committee presents the updated Master Capital Plan to the Board of Education with recommendations for specific projects that may be needed in the next five years.

#### 2019-20 LRPC Membership

East Planning Area

Lee-Ann Strickoff, Chaparral High School Jaimie Wolf, Chaparral High School Vacant, Legend High School Vacant, Legend High School Vacant, Ponderosa High School Vacant, Ponderosa High School

North Planning Area

Brad Geiger, Highlands Ranch High School John Freeman, Highlands Ranch High School Cathy Lees, Mountain Vista High School Vacant, Mountain Vista High School Vacant, Rock Canyon High School Vacant, Rock Canyon High School Michelle Major, ThunderRidge High School Kristen Hirsch, ThunderRidge High School

West Planning Area

David Strohfus, Castle View High School Bob Binder, Castle View High School Steven Franger, Douglas County High School Vacant, Douglas County High School

Charters

Stephanie Stanley, Charter School Community Rudy Lukez, Charter School Community

At Large Vacant, At Large Vacant, At Large

Non-Voting Members

Andee Ahrens, Secondary Education Representative Aubrie Duncan, Elementary Education Representative

Leela Rajasekar, Director of Construction

Vacant, Development Community Representative

Vacant, Student Body Member

**Guests/Liaisons** 

Krista Holtzmann, Board Director Liaison Richard Cosgrove, Chief Operations Officer,

Derek Stertz, Planning Manager

## **Executive Summary**

n late January 2019, Douglas County School District sold \$250 million in general obligation bonds as approved by voters in the November 2018 election. The proceeds from the bonds provide funds for capital needs such as security upgrades, facility repairs, classroom furnishings, buses and technology. DCSD anticipates using bond proceeds to fund all Tier 1 needs and approximately half of the Tier 2 needs at schools constructed before 2007. In addition, proceeds will enhance safety and security systems and address urgent capital repairs at DCSD Charter Schools. Finally, bond funds will be used to complete an addition to Castle View High School and will be utilized for the construction of an Alternative Education school on the Pine Drive site just North of Parker Town Hall. Over the next 5 years, it is estimated that the total cost of Douglas County School District's capital needs will be \$737-\$840 million. Of that total, approximately \$456 million is for new construction, \$241-\$343 million is for reinvestment in the district's school and support facilities, \$26 million is needed for transportation needs (includes costs for buses and support fleet), \$7-\$8 million is needed to replace some of the district's aging mobiles, \$5 million is needed for safety and security projects, approximately \$0.5-\$0.6 million is needed for playground equipment, and \$1-\$1.2 million is needed as contingency. Needs totaled by type can be seen in figure 1 below. Please note that the costs shown in the figure reflect base construction cost only. Additional costs related to project management and inflation are anticipated and reflected as a range throughout the rest of this document.




Figure 1) Anticipated capital needs over the next five years. Needs summed by capital need type

Estimated Project Management Costs Range: \$20,943,070 - \$88,504,540 Estimated Inflation Range: \$10,828,940-\$46,530,085

Estimated Total Cost: \$736,617,927 - \$839,880,542

Identified capital needs have been classified into a four-tier system with a Tier 1 classification representing the most critical items and a Tier 4 classification representing the least critical items. Douglas County School District's most important reinvestment items (those needs with a Tier 1 classification) are estimated to cost approximately \$132-\$182 million over the next five years. Of this amount, approximately \$116-\$165 million

# **Executive Summary Cont.**

is for facility reinvestment in neighborhood schools and support facilities, approximately \$2.7-\$3.1 million is needed for facility reinvestment in charter schools and approximately \$13.4 million is needed to meet the district's most urgent transportation needs (includes costs for buses and support fleet). Tier 2 needs are estimated to cost approximately \$73-\$102 million, Tier 3 needs are estimated to cost approximately \$56-\$72 million, and Tier 4 needs are estimated to cost approximately \$2.3-\$3.4 million. Costs associated with contingency and needed playground equipment have not been tiered and prioritized. Some capital needs submitted by charter schools are not reinvestment needs but desired modifications and upgrades. These items have been summed separately, outside the tier and priority classification. In total, these untiered needs total approximately \$17-24 million over the next five years. Needs totaled by Tier can be seen in figure 2 below.




Figure 2) Anticipated capital needs over the next five years. Needs summed by Tier

New construction needs over the next five years are estimated at approximately \$456 million. The student population has grown by approximately 10% since the most recent new school construction funded by the district in 2010. Projecting these needs continues to require a dynamic process as demographic changes, new residential construction, and new charter schools affect those needs on a continuing basis. The Long Range Planning Committee (LRPC) expects to continue to evaluate these needs and methods to meet them.



#### **Douglas County Population and Development Summary**

#### **Population**

The Douglas County population estimate for January 1, 2019 is 358,000 persons, a 3.5% increase from the previous year's estimate of 346,000. The Census Bureau and the State of Colorado also produce population estimates using different methodologies. The most current estimate available from the Census Bureau, for July 1, 2017, is 335,299 for Douglas County. The 2020 Census, to be conducted next year, will be a complete count of the U. S. population. The results will be the most accurate population count available, and all previous estimates, if not in line with the Census, will be adjusted up or down.

#### **Permit Trends**

Permits issued for new housing in Douglas County increased 3.8% compared to 2017, with 4,107 housing units permitted in 2018. Apartment units are 29% of the total new units permitted. Nearly 1.3 million square feet of commercial space was permitted in 2018, which includes four hotels and over half a million square feet of warehouse space.

#### Residential Development

In 2018, 4,536 new housing units were completed in Douglas County, which was a 3.5% increase in the total housing stock. The County's total housing stock as of January 1, 2019, is 128,661 units. Single family detached houses account for 75% of that total. The incorporated cities and towns in Douglas County contain 43% of the total housing stock. Ninety-one percent of all housing units are located in the urban-designated areas of the County, which is 18% of the total land area of the County.

#### **Residential Sales**

The median price of all homes sold in Douglas County in the third quarter of 2018 was \$487,500, which is a 6.9% increase compared to the same quarter last year. The number of sales of newly built and existing single-family houses, townhouses, and condominiums in 2018 increased 0.8% compared to 2017. The total number of foreclosure filings initiated in 2018 increased 4.5% from 2017 for a total of 278.


#### **Annual Income**


The 2017 average annual wage for jobs located in Douglas County was \$62,899, which was a 5.1% increase from the previous year. According to the 2017 American Community Survey, the median household income in Douglas County was \$111,482, which ranks 11th in the nation for highest median household income among counties with populations of 65,000 or more. The 2017 American Community Survey also shows that 3.5% of the population had incomes below the poverty level.

#### **Annual Employment**

The number of jobs located in Douglas County increased 3.7% from 2016 to 2017, bringing the average annual total to 121,135 jobs. The largest supersectors in the County in 2017 were professional and business services with 18.4% of jobs, followed by retail trade (14.8%), and leisure and hospitality (13.0%). The two supersectors with the largest absolute increases in jobs were professional and business services which gained 1,185 jobs, and financial activities which gained 948 jobs.

Source: Douglas County Department of Community Development, 2019 Demographic Summary





#### **Douglas County School District Enrollment Trends**

#### Enrollment Trends and Changes in 2018-19

Based on the Colorado Department of Education's official October count (2018), which includes all schools and programs (Neighborhood Schools, Charters, Pre-Schools, Home School, and Alternative Schools), the Douglas County School District saw a decrease of 6 students from the 2017-2018 to the 2018-2019 school year. The total enrollment declined from 67,597 to 67,591. This represents a .01% decrease in enrollment over the year. Over the last 10 years, DCSD enrollment has increased by 8,868 students, or by approximately 13%. While some neighborhood schools experienced an increase in enrollment this year, the majority of this growth can be attributed to DCSD charter schools. See Figure 1.




Figure 1: October Count Total Enrollment (2003-2018)

#### 2019-2020 Enrollment Projections Summary

The Planning and Construction Department projects K-12 using the cohort method, and then adjusts the projections based upon birth rate, historic kindergarten enrollment, open enrollment, and residential development. For capacity planning purposes, pre-school enrollment is added to the enrollment projections at those schools with existing pre-school programs.

Currently, the district's enrollment is declining, however, in comparative terms it is flat. The trend of declining enrollment is most prevalent in the district's neighborhood schools.

Not including pre-school, the Planning and Construction Department is projecting a district-wide decrease of 170 students or an approximate .26% decrease for the coming 2019-20 School Year. District-wide, Elementary School enrollments are expected to decline by 10 students. Declines are also anticipated in Middle school enrollment of 153 students and a decline of 7 High school students. See Figure 2.




Figure 2: 2019 Enrollment Increases and Decreases by School Type, Planning Areas, Charters, Not Pre-K

Not including pre-school, enrollment is projected to decrease by 772 for neighborhood schools, and enrollment is projected to increase by 602 students for charter schools. Charter School enrollment is projected to increase due to growth in enrollment at Ascent Classical Academy, Global Village Academy, Leman Classical Academy, Parker Performing Arts, Renaissance Secondary School, and World Compass Academy.

	2018-19 Enrollment (no- Pre K.)	2019-20 Enroll ment Projection (No Pre- K)	Change in Students from	2018-19 to 2019. 20 Enrollment	2023-24 Enroll ment Projection (No-Pre- K)	Change in Students from 2018-19 to 2020- 24 Enrollment
North Planning A rea						
Highlands Ranch Feeder						
Acres Green	513	497		(16)	508	(5)
Arrow w ood	329	314		(15)	300	(29)
Cougar Run	456	455		(1)	455	(1)
Eagle Ridge	551	537		(14)	581	30
Fox Creek	508	494		(14)	471	(37)
Cresthill MS	826	758		(70)	653	(173)
Highlands Ranch HS	1,676	1,660		(16)	1,405	(271)
Highlands Ranch subtotal	4,859	4,713		(146)	4,373	(486)
M ountain Vista Feeder						
Bear Canyon	493	473		(20)	427	(66)
Copper Mesa	422	413		(9)	329	(93)
Heritage	460	444		(16)	346	(114)
Northridge	659	638		(21)	636	(23)
Sand Creek	391	365		(26)	348	(43)
Summit View	508	478		(30)	455	(53)
Mountain Ridge MS	1,137	1,106		(31)	872	(265)
Mountain Vista HS	2,332	2,342		10	2,187	(145)
Mountain Vista subtotal	6,402	6,259		(143)	5,600	(802)
Rock Canyon Feeder						
Bu ffalo Ridge	405	397		(8)	438	31
Redstone	493	461		(32)	389	(104)
Timber Trail	330	303		(27)	231	(99)
Wildcat Mountain	519	473		(46)	374	(145)
Rocky Heights MS	1,408	1,368		(40)	979	(429)
Rock Canyon HS	2,266	2,262		(4)	1,962	(304)
Rock Canyon subtotal	5,421	5,264		(157)	4,371	(1,050)
ThunderRidge Feeder						
Co yote Creek	401	402		1	372	(29)
Eldorado	404	382		(22)	348	(56)
Roxborough Intermediate (3-8)	416	392		(24)	323	(93)
Rox borough Primary (K-2)	296	290		(6)	279	(17)
Saddle Ranch	443	425		(18)	357	(86)
Stone Mountain	619	613		(6)	589	(30)
Traiblazer	376	371		(5)	339	(37)
Ranch View MS	858	814		(44)	741	(117)
ThunderRidge HS	2,012	1,974		(38)	1,782	(250)
ThunderRi dge subtotal	5,825	5,663		(162)	5,110	(715)

Figure 3: North Planning Area Schools and Feeders Enrollment Changes from 2018-19 to Projected 2019-20

	2018-19 Enrollment (no- Pre K.)	2019-20 Enroll ment Projection (No Pre- K)	Change in Students from 2018-19 to 2019-	20 Enrollment	2023-24 Enroll ment Projection (No-Pre- K.)	Change in Students from 2018-19 to 2020- 24 Enrollment	
East Planning Area							
Chaparral Feeder							
Cherokee Trail	459	457	II.	(2)	441		(18)
Mammoth Heights	603	604		1	679		76
Pine Grove	555	543		(12)	583		28
Pine Lane North (4-6)	321	295		(26)	258		(63)
Pine Lane South (K-3)	369	374		5	396		27
Prairie Crossing	639	663		24	947		308
Sierra MS	857	875		18	834	0	(23)
Chaparral HS	2,241	2,243		2	2,646		405
Chaparral subtotal	6,044	6,054		10	6,784		740
Ponderosa Feeder							
Franktow n	323	333		10	357		34
Legacy Point	295	291		(4)	337		42
Mountain View (K-2)	258	272		14	318		60
Northeast (3-5)	287	276		(11)	318		31
Sagew ood MS	941	900		(41)	738		(203)
Ponderosa HS	1,388	1,408		20	1,375		(13)
Ponderosa subtotal	3,492	3,480		(12)	3,443		(49)
Legend Feeder							
Frontier Valley	479	465		(14)	451		(28)
Gold Rush	635	641	1	6	607	0	(28)
Iron Horse	396	394		(2)	429		33
Pioneer	401	405		4	407		6
Cimarron MS	1,314	1,240		(74)	1,149		(165)
Legend HS	2,209	2,196		(13)	1,842		(367)
Legend subtotal	5,434	5,341		(93)	4,885		(549)

Figure 4: East Planning Area Schools and Feeders Enrollment Changes from 2018-19 to Projected 2019-20




Figure 5: West Planning Area Schools and Feeders Enrollment Changes from 2018-19 to Projected 2019-20



#### Identifying and Prioritizing Facility and Site

Douglas County School District staff updates the Master Capital Plan on an annual basis. The process for identifying and prioritizing Douglas County School District's capital needs includes two distinct steps: facility assessments and prioritizing needs based on the site component tier and priority matrix score. Below is an explanation of how these steps are performed.

#### Facility Assessments

Facility capital needs in the Master Capital Plan (MCP) come from a Capital Improvement Plan (CIP) list, a database for the assessment of assets for district facilities. The majority of the list includes the building/site systems and components in need of repair, replacement or upgrade. The CIP is a 5-year projection tool to help maintain our campuses so they function as intended or better.

A facility assessment (or inventory) is a comprehensive review of a facility's assets. Facility assessments are a standard method for establishing baseline information about the systems and components in a new or existing facility. An assessment is a way of determining the "status" of the facility at a given time - that is, it provides a snapshot of how the various systems and components are operating. A primary objective of a facility assessment is to measure the value of an aging asset relative to the cost of replacing that asset. Thus, facilities assessments are a tool for projecting future capital maintenance costs.

Assessment asset needs can consist of the following:

- •Deferred maintenance Systems and components that are past their end of life and create higher maintenance and future replacement costs
- •Life Cycle Projection Systems and components that are projected to fail within a specific time period based on industry standards
- •Damage/Wear Systems and components that have not met life cycle but have been physically damaged by some means or excessive use causing non-optimal performance
- •Compliance Systems and components that are in need of replacement, upgrades, or were added to meet federal and local codes or requirements. These are usually ADA requirements and building code changes
- •System Improvements Projects that may improve systems to perform more efficiently and save future capital resources.
- •Growth Space and areas that are needed due to increases in student population and iadditional support staff
- •Functionality Systems that are deemed necessary due to policies concerning security enhancements and IT infrastructure

Assessments on newer facilities take place at about the 10-year mark of opening looking forward to a 15-year projected life. Starting in 2015-16, all facilities are being assessed every 5 years. Some assets of a facility may be placed in the CIP based on known life cycle. The majority of systems and components fall within a life cycle range of 15-40 years.

On-site facility assessments are currently performed by the Facility Capital Planner. The Facility Capital Planner collaborates with Principals, Building Engineers, Maintenance Managers and staff in helping supply information to be placed in the CIP. Information may come from the maintenance work order system if the capital cost cannot be justified by the yearly maintenance budget. Architects, Engineers, and Consultants may also be used to determine major deficiencies when warranted.

The yearly maintenance repair budget is separate from the CIP although sometimes items may be performed in conjunction with each other. Typically, capital repair/replacement costs over \$5,000 are listed in the CIP, although the yearly maintenance budget may be used for repair/replacement costs up to around \$30,000. Costs under \$5,000 in the CIP are usually deficiency items that would be combined with others in the same type of project for cost savings.

Currently, the items in the CIP are for capital renewal only. Other major "wants" not for growth or equability of other facilities are placed outside the CIP but continue to be tracked to be considered at a future date if deemed appropriate. Many energy conservation projects for energy and water savings have been taken out of the CIP but are still tracked and may be done if the return on investment (ROI) is warranted in the future.

#### **Prioritizing Needs**

#### Tier Classification

The Planning & Construction team, with input from Security, Transportation, and IT staff, is responsible for classifying needs based on a four tier structure. These tiers are used to rank the significance of the replacement or upgrade of facility assets, systems, components, and services as they affect the occupancy of a facility or level of service requirements.

The tiers used to classify the above are as follows:

Tier	Description
Tier 1	Assets, systems and components that are necessary to occupy a facility and/or may cause large financial costs if a breakdown occurs, along with Federal, State, and Local mandated statutes and code compliance issues. Typical assets in this tier include (but are not limited to) roofing, plumbing infrastructure, HVAC, electrical systems, fire sprinkler repair/replacement, fire alarm, irrigation systems and controllers, major structural movement, site utilities, SPED buses; and state statutes for door hardware fire and security compliance.
Tier 2	Assets, systems and components for suitable occupancy of a facility including security systems and components; and priority bus and support vehicle replacement. Typical assets in this tier include (but are not limited to) building exterior envelope and finishes, interior finishes, flooring, plumbing fixtures, minor mechanical, paving, surfacing, high school athletic fields, cameras, card readers, replacement buses, and snowplow trucks.
Tier 3	Assets, systems and components that are part of a facility infrastructure but do not directly affect the occupancy of the facility including security upgrades and additions; and transportation buses and support vehicles for growth. Typical assets in this tier include (but are not limited to) interior wall structure and finishes, interior doors, ceiling finishes, casework, FF&E (furniture, features, and equipment), cosmetic building structure, multi-purpose fields at elementary and middle schools, additional software programs to enhance security; and additional buses and support vehicles.
Tier 4	Assets, systems and components that are more aesthetic in nature, do not affect building occupancy, and deemed the least important upgrades. Typical assets in this tier include (but are not limited to) landscaping, exterior structures, a variety of site work, and additional security doors.

The Safety and Security Department identifies and prioritizes its capital needs based on a variety of criteria. These criteria range from risk to safety, necessity in order to comply with Federal, State, or Local mandates, frequency of system failure, potential impact to current level of service, life expectancy, the potential to enhance systems, and process improvement strategies.

The Transportation Department identifies and prioritizes fleet related capital needs in two ways. First, assets that present a significant safety concern are identified. This means that the continued operation of the asset places personnel safety, or the safety of others, in jeopardy. Assets identified in this operating condition may have

# Methodology cont.

components or entire structures that will not pass safety inspections. These would be assets that need to be replaced within one year. Second, assets in a mechanical condition requiring ongoing repairs that exceed current value are identified. If these vehicles can no longer be repaired, upgraded, or maintained, they are listed as needing replacement over the next five years.

The IT Department identifies and prioritizes solutions and projects based on the effectiveness and impact to student education delivery. District technology initiatives are proposed by the IT Department based on continual review of school staff and student educational requirements, administrative leadership, and reference to industry best practice solutions. A business case is developed to define scope, deliverables, resources, and cost estimates which are then prioritized by IT leadership. A portfolio review is conducted to ensure new initiatives are unified solutions across the district and maximize delivery of student education in alignment with our strategic goals. With a wealth of technology solutions and opportunities, the IT Department focuses priority on providing the district students, staff, and administration with the most value to provide the greatest education for the students.

#### **Priority Classification**

Every project/need that has been listed in the CIP is ranked based on five different 'levels' of criteria. The criteria 'levels' used to score projects include the following:

Priority Criteria	Definition
Cause	This criteria level is used to evaluate and score projects based on why they are needed. For example, a project could be needed to respond to or prevent a known life safety and health risk, to be code compliant, or because the system or component has failed. It could also be needed to increase functionality and efficiency or to align with district strategic priorities. A project that is required to prevent or respond to a known life safety and health risk would rank higher than a project that is desired or preferred by facility users. Similarly, a project required for code, regulatory or contract compliance would rank higher than a project that would enable the advancement of district-wide goals and strategies
Type of Impact	Potential to interrupt educational programming. Using this criteria level, a failing system or building component that has the potential to result in a full or partial school closure would score higher than a failing system or component that does not directly disrupt classroom instruction.
Risk	Level of risk a system or component failure poses to staff, students, and the district as a whole. Types or risks considered vary widely and include everything from safety and health risk to financial and legal risks. Using this criteria level, a failing system or component that has the potential to compromise student and staff health and safety or close a facility would rank higher than one where the only potential risk is an opportunity loss for improvement.
Urgency	When item it is expected to fail based on life cycle expectancy. A building component that is past its expected life cycle would score higher than a component that has not reached the end of its expected life.
Extent of Impact	The extent to which a potential failure could impact the district. For example, a potential failure that could impact the entire district would score higher than a potential failure that would only impact one classroom.


Final rank scores for each criteria level are multiplied to calculate an overall priority score. Scores range from 1-8000 with a score of 1 being a project of the highest priority and a project with a score of 8000 being of the lowest priority. For simplicity, needs have been classified as high, medium, or low priority using the classification method shown below.

High Priority: 1-200 Priority Score

Medium Priority: 201-1,000 Priority Score Low Priority: 1,001-8,000 Priority Score

#### **How to Assess Capital Priorities**

Every opportunity for capital reinvestment has been classified based on its priority score and its tier. These two classifications have been combined to create the twelve different classes shown in the illustration below. Those opportunities and projects classified as Tier 1-High can be considered the most urgent and those classified as Tier 4-Low can be considered the least urgent. Estimated construction costs have been summarized for each of the classes and are shown on each facility profile page.



#### Estimating Costs for Facility and Site Needs

Along with identifying and prioritizing facility needs, the Planning & Construction team works to provide accurate cost estimates for these needs. These cost estimates are derived by calculating estimates for:

- 1) Component and/or system reinvestment (materials and labor only)
- 2) Potential project management costs and
- 3) Additional costs due to inflation

The method used for calculating these three separate costs is discussed below. Reinvestment costs which are displayed in the 'Estimated Construction Cost-2019' field are contract materials and labor costs only. In general, capital reinvestment work will always require some level of regulatory, professional services, and contracting costs.

#### Calculating Estimated Construction Costs

Estimated costs in the Capital Improvement Plan are developed in a multitude of ways:

- •RS Means Estimating Software RS Means is the industry standard for estimating construction, remodeling, and repair. Costs from RS Means are contractor costs only
- •Similar types or projects Estimates are based on similar projects the district has completed in the past (marked up according to an inflation factor as necessary)
- •Outside resources Architects, Engineers, and Consultants may be used to help derive cost estimates. Estimates vary over time due to many factors. This can include:
  - •Prices for commodities and material can vary within a few months
  - •Labor shortages drive contractor costs higher (Colorado is currently experiencing a labor shortage)
  - •The time of year when the project is bid and project constructed (schools typically have a majority of work done over the summer break)

#### Calculating Estimated Project Management Costs

Along with materials and labor costs, the estimated total project cost also includes costs for design, construction, and professional services. Typically these types of costs that need to be accounted for can include fees associated with one or a combination of any of the following:

- Architectural and design fees
- Trade professional fees
- •Inspections, permitting and or code compliance fees
- •Contingency (costs due to unforeseen circumstances)
- Contractor overhead and profit

These fees can vary depending on regulatory requirements, the size, and the complexity of a project. Dependent on these factors, these costs can range from an additional 10-43% of the estimated construction cost. For example, these additional costs would be around 10% of construction costs if DCSD were to resurface a tennis court. In this instance a consultant would help to determine the product to use, create specifications for the work to be done, and help in bidding and project oversight. To replace a tennis court with post-tension concrete, additional costs would be on the higher end. The district would need to contract with a soils testing agency, a structural engineer, and an observation and testing agency to assure product installation compliance. Contractor fees would be higher due to the specialized nature of the work.

#### **Calculating Estimated Inflation Costs**


Inflation for construction materials and labor is also included in Master Capital Plan cost estimates. An assumed 5% annual increase is used to determine a range of potential additional inflation costs for each project.


#### **How to Assess Project Cost**

Every need has an estimated construction cost, an estimated range for potential project management costs, and an estimated range for inflation. Cost estimates on the low end of the range assume a 10% mark-up for potential regulatory, professional services, and contracting costs. Cost estimates on the high end of the range assume a 43% mark-up. Inflation cost estimates on the low end of the range assume work will occur in year two of the five year outlook. Inflation estimates on the high end of the range assume work will not occur until year five.

Materials and labor

10%-43% Mark-up






Inflation

#### 2018 Bond Funded Items

In late January, DCSD sold approximately \$250 million in general obligation bonds as approved by voters in the November 2018 election. The proceeds from the bonds provide one-time funds for capital needs such as security upgrades, facility repairs, classroom furnishings, buses and technology. All Tier 1 and approximately half of the listed Tier 2 capital renewal items are anticipated to begin construction in the near future. Bond funded projects that are under construction are called out on individual school pages.



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Reg Professional and Contracti	Services,	Potential Inflation Costs				
	Interior Door hardware. Replace current non-restricted key system with restricted. Hardware change.	\$280,670	\$28140-\$1	20740	\$14040-\$60350				
	Air Distribution Systems. HVAC system upgrade.	\$171,210	\$17200-\$7	73700	\$8560-\$36810	1	_	1	
Tier 1	Water Treatment Systems. Upgrade.	\$16,290	\$1720-\$7	7020	\$820-\$3510				
Funded by the	Emergency Light and Power Systems. Generator and Transfer Switch. Replace generator and associated equipment.	\$74,030	\$7480-\$3	1880	\$3710-\$15920				
	Passenger Elevators. Renovate elevator.	\$158,630	\$15880-\$6	58280	\$7940-\$34110				
	Commissioning and Re-Commissioning. Commission if system upgraded.	\$57,220	\$5790-\$2	4690	\$2870-\$12300				
Tier 2 Funded by the 2018 Bond	Flooring Carpet. Replace carpet.	\$346,440	\$34670-\$1	49070	\$17330-\$74490				
	Flooring Kitchen. Replace kitchen flooring. Currently red hubblelite	\$62,400	\$6310-\$2	6910	\$3120-\$13420				
	Flooring Hallways/Classrooms. replace VCT in classroom areas	\$71,280	\$7230-\$1						
	Exterior Wall Construction. Recaulk control joints.	\$4,660	\$550-\$1						
	Exterior Windows. Recaulk windows	\$23,480	\$2430-\$						
	Fabricated Toilet Partitions. Replace with solid plastic in all wings upper and lower	\$25,170	\$2540-\$	The school shown in this example Tier 1 and Tier 2 categorized proje		•			
2-High	Sink Countertops. Replace sink countertops with single surface	\$21,370	\$2140-\$						
	Theater & Stage Equipment, Auditorium Sound Equipment. Strand CD80. Upgrade Strand controller	\$10,580	\$1130-\$ projects are labeled		•				
<u></u>	Fixed Casework. Computer counter tops need to be raised in the library	\$4,230	\$470-\$1	cost bar graph with a muted shade of the					
	Paving & Surfacing, Sidewalks. Needs repaired in areas	\$18,300	\$1910-\$					2	
	Retractable Partition. Repair/refurbish operable partitions at pod areas	\$12,270	\$1240-\$	classification color.					
2-Medium	Wall Foundations. Recaulk foundation where concrete meets	\$9,420	\$990-\$4		T				



#### **New Construction Needs**

#### 1-5 Year Needs

Based on existing school capacities, five-year enrollment projections for the district, and new residential development, the Planning & Construction Department has identified a need for the below listed new construction over the next five years. These priorities may change as findings from boundary and capacity analyses become available.

- One new elementary school in The Meadows development (Castle Rock)
- One new elementary in Northeast Castle Rock (Castle Rock)
- One new elementary school in the Meridian Village or Sierra Ridge developments (East Lone Tree/West Parker Area)
- Space and facilities for eDCSD, DC Support Center, and Bridge programming (locations to be determined)
- An addition to the early childhood center in the West Planning Area (Castle Rock)
- Additional Kindergarten classrooms for full day Kindergarten (locations to be determined)
- One new elementary in Cobblestone Ranch, aka The Villages at Castle Rock development (Castle Rock)
- One new school in the Sterling Ranch development (Northwest Douglas County)
- One new high school in the Ridgegate development (Lone Tree)
- Special education school (location to be determined)
- Nutrition Services warehouse expansion (Castle Rock)
- One new terminal and land for bus and support vehicle fleet maintenance and operations (Parker)
- One new terminal satellite facility and land for bus and support vehicle fleet maintenance and operations (Castle Rock)

#### 6-10 Year Needs

The Planning & Construction Department also monitors capital needs beyond the five-year Master Capital Plan. In the next six to ten years, the following new construction needs are projected in order to accommodate future capacity and operational support needs:

- A new elementary school in The Canyons development (Castle Pines)
- A new elementary school in the Crystal Valley development (Castle Rock)
- A new high school in the Sterling Ranch development (Northwest Douglas County)
- One new terminal and land for bus and support vehicle fleet maintenance and operations (Northwest Douglas County)

#### **Land Needs**

The Planning & Construction Department works with local municipalities and land developers to ensure suitable sites are dedicated to the school district for projected new construction needs. Based on best practices and past facility prototypes, the following acreages have been identified as suitable for the construction of new schools:

Elementary Schools: 12 acres

\*For more information on dedicated school sites see our PK-8 Schools: 15-17 acres

land inventory maps in Appendix 4 Middle Schools: 30 acres

High Schools: 60 acres

#### **New Construction Costs**

The Planning & Construction Department has calculated construction costs using three different scenarios. Cost estimates have been calculated using 1) Current Douglas County School District Standards, 2) Value Engineered Standards, and 3) Residential/Commercial Standards. Cost estimates for new construction are estimated using data from recent bids for public schools in Colorado with similar facility standards. The Planning & Construction Department compared recent contractor bids and projected budgets with public school districts in the Denver area for new high, middle, PK-8 and elementary schools. The cost per square foot of these actual bids and detailed cost estimates from pre-qualified architects and engineers for Transportation and Nutrition Services support facilities are the basis for the new construction cost estimates. The school districts used to benchmark costs have similar facility standards. The cost estimates reflect inflation based on Producer Price Index (PPI) data.

#### Scenario 1: Current DCSD Standards

Douglas County School District currently builds to the highest standards possible. These standards are meant to ensure durable, high quality facilities that will last for the next 50-75 years. The District focuses on providing building components which are long lasting, require minimal maintenance, provide energy efficiency savings, and increase student and staff comfort. DCSD's current standards are meant to increase the quality and life of the building while reducing maintenance and utility costs. Adhering to these standards requires investing larger amounts upfront but provide intermittent cost savings in reduced maintenance over time.

#### 1-5 Year Needs

New Construction Need	Cost
Typical Enrollment/Neighborhood Schools	
All Day Kindergarten	\$24,371,843
Meridian Village/Sierra Ridge Elementary School	\$38,443,892
Meadows Elementary School	\$38,443,892
Northeast Castle Rock Elementary School	\$38,443,892
Cobblestone Ranch Elementary School	\$38,443,892
Sterling Ranch School	\$52,557,750
Ridgegate High School	\$132,968,480
Special Programming	
Castle Rock Early Childhood Center Addition	\$2,627,888
eDCSD Facility	\$5,255,775
DC Support Center	\$5,255,775
Bridge Programming	\$9,460,395
Special Education High School	\$9,985,973
Support Facilities	
Castle Rock Satellite Bus Terminal Land Purchase	\$2,372,332
Castle Rock Satellite Bus Terminal	\$2,576,070
Castle Rock Nutrition Services Warehouse Expansion	\$4,048,110
Parker Bus Terminal Land Purchase	\$5,693,597
Parker Bus Terminal	\$44,749,747
Total (Includes Estimated Inflation)	\$455,699,301

<sup>\*</sup> An additional \$20 M may be needed for road and utility infrastructure to Ridgegate HS site pending the development's buildout

<sup>\*\*</sup>Bridge Programming may require being at various locations

New Construction Need	Cost
Typical Enrollment/Neighborhood Schools	
The Canyons Elementary School	\$41,629,049
Crystal Valley Elementary School	\$41,629,049
Sterling Ranch High School	\$143,985,199
Support Facilities	
Land For Bus Terminal in Northwest	\$6,357,850
Bus Terminal in Northwest	\$54,192,202
Total (Includes Estimated Inflation)	\$287,793,348

#### Scenario 2: Value Engineered Standards

To derive cost estimates for new construction under this scenario the Planning & Construction team researched industry approaches to reducing costs while still maintaining the functionality of facilities for their intended use. This scenario focuses on reducing DCSD's upfront purchase costs while still providing the value needed by our end users. Some examples of the types of reductions that would be made under this scenario are summarized in the following table.

Current DCSD Standards Component	Value Engineered Component	Loss
Automated/Calibrated Lighting and Mechanical Controls	Manual Lighting and Mechanical Controls	Energy efficiency
Carpeting	Hard Surface Flooring	Noise control/comfort
Brick/block walls	Wood siding	Noise control/ease, cost and frequency of maintenance/shortened useful life
Fully adhered, un-ballasted roof (sealed, non- permeable membrane)	Ballasted roof	Ease, cost, and frequency of maintenance/shortened useful life
Drop ceilings	Open ceilings (no drop ceilings)	Noise control/aesthetics
Daylighting (translucent panels, skylights, etc.)	No daylighting	Energy efficiency/comfort
Painted walls	Vinyl wall coverings	Ease, cost, and frequency of maintenance/shortened useful life

<sup>\*\*</sup>Note\*\*This table is meant to provide an example of alternative building components that could be used in a value engineered scenario and is not all inclusive.

#### 1-5 Year Needs

New Construction Need	Cost
Typical Enrollment/Neighborhood Schools	
All Day Kindergarten	\$20,716,067
Meridian Village/Sierra Ridge Elementary School	\$32,677,308
Meadows Elementary School	\$32,677,308
Northeast Castle Rock Elementary School	\$32,677,308
Cobblestone Ranch Elementary School	\$32,677,308
Sterling Ranch School	\$44,674,088
Ridgegate High School	\$113,023,208
Special Programming	
Castle Rock Early Childhood Center Addition	\$2,233,704
eDCSD Facility	\$4,467,409
DC Support Center	\$4,467,409
Bridge Programming	\$8,041,336
Special Education High School	\$8,488,077
Support Facilities	
Castle Rock Satellite Bus Terminal Land Purchase	\$2,372,332
Castle Rock Satellite Bus Terminal	\$2,189,660
Castle Rock Nutrition Services Warehouse Expansion	\$3,440,894
Parker Bus Terminal Land Purchase	\$5,693,597
Parker Bus Terminal	\$38,037,285
Total (Includes Estimated Inflation)	\$388,554,295

New Construction Need	Cost
Typical Enrollment/Neighborhood Schools	
The Canyons Elementary School	\$48,975,351
Crystal Valley Elementary School	\$48,975,351
Sterling Ranch High School	\$169,394,352
Support Facilities	
Land For Bus Terminal in Northwest	\$6,357,850
Bus Terminal in Northwest	\$63,755,532
Total (Includes Estimated Inflation)	\$337,458,435

By pursuing a Value Engineered scenario, DCSD would see initial savings due to decreased purchase costs of building components. However, these reductions ultimately result in increased maintenance costs, increased utility usage costs, and costs associated with more frequent replacement of building components that are beyond their useful life. It should also be pointed out that the initial purchase cost savings seen in this scenario can often be at the expense of comfort and aesthetics.

#### Scenario 3: Least Expensive Facility Standard

This scenario would dramatically decrease the useful life of building components and would result in facilities meant to last approximately 25 years rather than the standard 50-75 years DCSD currently targets. In addition to the tradeoffs made in the Value Engineered scenario, DCSD could achieve significant upfront savings by making the following changes:

- -Constructing slab on grade rather than using a structural foundation (when feasible)
- -Constructing wood frame facilities in lieu of metal framing with masonry walls
- -Eliminating carpet and drop ceilings
- -Eliminating lighting, mechanical, and electrical controls
- -Reducing security systems and technology (not using optimal systems, limited technology)

In this scenario, DCSD would face much greater costs associated with continual maintenance and increased utility costs. In general, finishes are of a lower quality in this scenario.

Cost estimates were not calculated for all listed new construction. This is due to the fact that portions of school facilities cannot be built using these standards. Special learning environments (labs, art rooms, etc.), athletic amenities, and special education spaces have specific facility requirements and needs that cannot be built to alternative standards. Rather, it is more accurate to say that for typical learning spaces only, an additional 60% in initial capital savings could be achieved with the use of these standards.

#### **New Construction Risks and Opportunities**

New construction is only one of the many options available for meeting the district's capacity needs. To address expected growth in the next five years as well as in the next ten years, opportunities for utilizing already existing capacity exist. However, along with these opportunities come risks. The following pages provide information on some of the most feasible opportunities (and the risks they present) for addressing some of the district's anticipated capacity needs.

#### **Special Programming and Support Facilities**

The following table reviews alternatives to constructing new facilities for special programming and support facilities. The need for these facilities is driven by shifting demographics, development, and programming needs. However, unlike neighborhood schools, the need for this space cannot be fully ameliorated by reconfiguring attendance boundaries, grades, or calendars.

Alternative to New Construction	Alternative Risk	Timeframe Needed
Early Childhood Centers (Castle Rock)		
Place PK students in under-utilized elementary school facilities.	Elementary facilities may not be able to accommodate PK students as K-6 student growth occurs within that attendance area. Elementary school facilities may not currently have the special features and amenities needed for early childhood education.	1-5 Years
eDCSD Facility		
Fully utilize existing capacity at other schools.	Potential of increased commute times for students and parents and increased transportation cost for the District. Current neighborhood school facilities may not currently have the special features and amenities needed for eDCSD programming.	1-5 Years
DC Support Center		<u> </u>
Fully utilize existing capacity at other schools.	Potential of increased commute times for students and parents and increased transportation cost for the District. Current neighborhood school facilities may not currently have the special features and amenities needed for DC Support Center programming.	1-5 Years
Bridge Programming		ı
Fully utilize existing capacity at other schools.	Potential of increased commute times for students and parents and increased transportation cost for the District. Current neighborhood school facilities may not currently have the special features and amenities needed for Bridge programming.	1-5 Years
Special Education School		
Fully utilize existing capacity at other schools.	Potential of increased commute times for students and parents and increased transportation cost for the District. Current high school facilities may not currently have the special features and amenities needed for special needs programming.	1-5 Years
Nutrition Service Warehouse Expansion		
Lease a warehouse and freezer space at an off site location	The cost of leasing is very expensive and leased space does not provide joint warehouse and freezer space as needed by Nutrition Services. Off site warehouse and freezer inventory would increase storage costs and decrease management efficiency.	1-5 Years
Parker, Castle Rock, and Northwest Doug	las County Bus Terminals and Land Purchase	
Utilize available parking at existing schools     Plan for satellite transportation parking on dedicated school sites (DCSD owned sites with no schools)	Increased operational costs to shuttle drivers to and from buses. Increased operational costs to shuttle buses to central terminals for cleaning and maintenance. Potential security concerns and vandalism to vehicles if not fenced and lit. Dedicated school sites may need rezoning.	1-5 Years for Parker and Castle Rock Terminals 6-10 Years for Northwest Douglas County Terminal

#### **Neighborhood Schools**

The following table reviews alternatives to constructing new neighborhood schools. The need for new neighborhood schools is driven primarily by shifting demographics and development. This type of enrollment growth can be addressed by reconfiguring attendance boundaries, grades and calendars.

Alternative to New Construction	Alternative Risk	Timeframe Needed		
Meridian Village Elementary School				
Reboundary elementary attendance areas in the Chaparral feeder to utilize existing capacity and balance enrollment      Ridgegate High School	Potential increased commute time for students and parents. Potential congestion, safety, and accessibility issues as updated attendance area boundaries may need to cross major roads and intersections in order to balance enrollment. May go against community desires and preference for current neighborhood school.	1-5 Years		
Klagegate High School				
1) Reboundary high school feeders in the East Planning Area to balance enrollment and utilize existing capacity at Ponderosa High School. 2) Fully utilize existing capacity at Ponderosa High School and Douglas County High School through addition and/or relocation of community desired programming.	1) Reboundary of high school feeders would affect all schools and levels in the East Planning area. Elementary and middle school population would be impacted along with high school population. It also may not be logistically possible to balance enrollment while maintaining existing programming and transportation connectivity.  2) Potential of increased commute times for students and/or no access to busing services (without a boundary change). If not monitored closely, could over-enroll Ponderosa and Douglas County High Schools or under-enroll Chaparral and Legend High Schools.	1-5 Years		
The Meadows Elementary School				
1)Partner with nearby charter schools to weight lottery for students residing in The Meadows development (Castle Rock). 2) Reboundary elementary attendance areas in the Meadows to utilize existing capacity and balance enrollment	1)Students/parents residing in The Meadows do not prefer nearby charter schools and do not enroll. Nearby charter schools reach ideal program capacity with outside enrollment (students residing outside the Castle View feeder) before The Meadows is built out. 2) Potential increased commute time for students and parents. Potential congestion, safety, and accessibility issues as updated attendance area boundaries may need to cross major roads and intersections in order to balance enrollment. May go against community desires and preference for current neighborhood school.	1-5 Years		
Northeast Castle Rock Elementary School				
Reboundary Castle Rock region elementary attendance areas in Douglas County High School feeder to utilize existing capacity and balance enrollment.	Not a long term solution; existing K-6 facilities and available mobile pads in this feeder cannot accommodate complete build out of Castle Oaks, Castleview Estates, and Crystal Valley Ranch. May go against community desires and preference for current neighborhood school.	1-5 Years		
Cobblestone Ranch Elementary School				
Reboundary Cobblestone Ranch development into the Mountain View-Northeast Elementary attendance area. Current residents would have option of selecting Franktown Elementary as neighborhood school. New residents would need to open enroll into schools other than Mountain View Primary or Northeast Intermediate.	Two different neighborhood schools for one development. Could under-enroll Franktown or over-enroll Mountain View- Northeast Elementary schools. May go against community desires and preference for current neighborhood school	1-5 Years		
Sterling Ranch School				
Reboundary elementary and middle school attendance areas in the ThunderRidge High School feeder to utilize existing capacity and balance enrollment.	Potential increased commute time for students and parents. Potential congestion, safety, and accessibility issues as updated attendance area boundaries will need to cross major roads and intersections in order to balance enrollment. Potential congestion, safety, and accessibility issues with K-6 students from Sterling Ranch development crossing US 85 (Santa Fe Drive) to attend neighborhood school. May go against community desires and preference for current neighborhood school.	1-5 Years		

## Neighborhood Schools Cont.

All Day Kindergarten Classrooms			
1) Place all-day Kindergarten students in currently underutilized elementary school facilities. 2) District-wide reboundary effort to accommodate additional enrollment and space needed for all day Kindergarten.	1) K-6 facility space may not exist where Kindergarten enrollment needs arise. 2) May go against community desires and preference for current neighborhood school. Would impact all regions and school levels in the district.	1-5 Years	
Crystal Valley Elementary School			
1) Reboundary elementary attendance areas in the Douglas County High School feeder to utilize existing capacity and balance enrollment	Potential increased commute time for students and parents. Potential congestion, safety, and accessibility issues as updated attendance area boundaries may need to cross major roads and intersections in order to balance enrollment. May go against community desires and preference for current neighborhood school.	6-10 Years	
The Canyons Elementary School			
Reboundary elementary attendance areas in the Rock Canyon High School feeder to utilize existing capacity and balance enrollment.	Increased commute time for North Castle Pines students (i.e., some of the current Timber Trail attendance area would be allocated to Wildcat or Redstone attendance area) and exacerbation of existing connectivity and congestion issues between NW Castle Pines and SE Highlands Ranch. Potential congestion, safety, and accessibility issues with K-6 students from The Canyons development crossing I-25 to attend neighborhood school.	6-10 Years	
Sterling Ranch High School			
Reboundary high school feeders in the North Planning Area to balance enrollment and utilize existing and anticipated capacity at ThunderRidge and Highlands Ranch High Schools.	Reboundary of high school feeders would affect all schools and levels in the North Planning area. Elementary and Middle School population would be impacted along with High School population. It may not be logistically possible to balance enrollment while maintaining existing programming and transportation connectivity. If not monitored closely, could under-enroll or over-enroll North Planning Area high schools.	6-10 Years	



#### Overutilized and Underutilized Neighborhood Schools

#### **Overutilized Schools**

The Planning Department classifies overutilized schools in need of a capacity solution as any school having 50 or less current or projected seats available (including current mobiles on-site and with enrollment projected for next five years). These identified schools are broken into two categories, those needing capacity relief by the 2019-20 school year and those needing capacity relief by year five of the five year outlook.

#### Projected to be Overutilized by 2019-20 School Year

-Rock Canyon High School -Daniel C. Oakes High School -Renaissance Magnet School

#### Projected to be Overutilized by 2023-24 School Year

-Sage Canyon Elementary School -Prairie Crossing Elementary School -Chaparral High School

#### Schools to Closely Monitor for Overutilization

The Planning Department also identifies "schools to closely monitor" on an annual basis. These are schools that currently have and are projected to have enough seats available but are currently utilizing over 95% of their facility capacity and all available mobile capacity. In the case that a sudden or unexpected change causing increased enrollment were to occur these schools would need fast acting solutions (besides mobiles) available to them. Schools that were identified in the 2018-19 school year as schools to closely monitor for potential over-utilization are as follows: Schools to Closely Monitor

-Pine Grove Elementary -Clear Sky Elementary -Rocky Heights Middle School -Northridge Elementary -Prairie Crossing Elementary -Castle View Middle School -Renaissance Magnet School -Sage Canyon Elementary -Legend High School -Daniel C. Oakes High School -South Ridge Elementary

#### **Underutilized Schools**

The Planning Department classifies underutilized schools in need of a capacity solution as any school that is currently utilizing less than 65% of its facility capacity or any schools that are projected to utilize less than 65% of their facility capacity. Those that are projected to utilize less than 65% of their facility capacity by the 2019-20 school year are classified as an immediate need while those that are projected to have this utilization rate within years 3-5 of the 5 year outlook are classified as a long term need. Schools that were identified in the 2018-19 school year as underutilized and in need of capacity relief are as follows:

#### Projected to be Underutilized by 2019-20 School Year

-Arrowwood Elementary -Legacy Point Elementary -Mountain View Elementary -Northeast Elementary -Pine Lane Elementary-North Facility


-Timber Trail Elementary -Cresthill Middle School -Mesa Middle School -Ponderosa High School

### Projected to be Underutilized by 2023-24 School Year

-Arrowwood Elementary -Copper Mesa Elementary -Heritage Elementary -Northeast Elementary -Pine Lane Elementary-North Facility -Roxborough Intermediate -Timber Trail Elementary -Sagewood Middle School -Cresthill Middle School -Ranch View Middle School -Castle Rock Middle School -Highlands Ranch High School -Ponderosa High School


#### **Monitoring and Estimating Capacity Needs**

The Planning Department tracks the facility and mobile capacity available at each neighborhood school in comparison to current and projected enrollment. The chart below is used by staff to evaluate which facilities are being over or under utilized and also which schools may require an additional mobile or some other capacity relief method in future years.




Staff also tracks the total number of seats available at each school including seats provided by mobiles currently on-site.

A chart showing facility and mobile capacity available at each neighborhood school in comparison to current and projected enrollment as been made available on each individual school page in this document. Below is a description of each capacity figure shown in the chart and a brief explanation of how each figure is derived.



#### **Capacity Relief Implementation**

The Planning Department, along with the help of the Long Range Planning Committee, performs an annual review of school enrollment and capacities. School capacity data and capacity relief options are briefed to PK-12 staff and district leadership in order to adjust open enrollment allowances and consider options. The decision to implement a specific capacity relief option would be a process that involves and requires input from district central administration, site-based staff, DCSD students and parents, district citizen advisory committees, and the Board of Education.



New construction and the other opportunities (and associated risks) discussed in this document are only some of the options available to the district to address over-utilized facilities. A variety of alternative methods other than boundary changes and program relocation or replication exist and will need to be carefully reviewed and considered as enrollment growth occurs. Each alternative exhibits benefits as well as shortcomings. Below is a list of the additional capacity relief measures that could be considered and a diagram of how capacity alternatives are evaluated.

#### Capacity Alternatives which Utilize Already Existing Capacity

A			
Attributes:	<u>Deficiencies:</u>		
-Doesn't destabilize special programs	-Actual impact can vary from projected impact; i.e. boundaries are developed to accommodate projected		
-In most situations only applies to new students	enrollment		
-Provides a predictable and constant set of criteria for decisions	-Can take years to fully implement		
	-Can be less effective in a choice district or in neighborhoods with a strong historic allegiance to existing		
	boundaries		
	-Can be disruptive to families and students		
	-Only applicable if boundary change does not under enroll or over enroll nearby schools or significantly change		
	current Middle and High school feeder patterns		
	e the number of students simultaneously utilizing school facilities. Could include converting to year-round, mul		
track for Elementary and Middle and split session for High Schools			
Attributes:	Deficiencies:		
-Makes greater use of existing facilities	-Makes regular maintenance and repair more difficult, i.e. there are fewer extended periods of time when the		
-Keeps current attendance area neighborhood intact	facility is unoccupied		
-Keeps current programming intact	-Could be challenging for parent's schedules		
-Relatively quick to implement	-Could interfere with extracurricular and after-school activities		
-Reduces capital funding requirements (relative to new construction option)	-Additional wear and tear on existing facility		
Treades suprair furnaling requirements (relative to new sorist determ option)	Additional Wear and toda on existing identity		
	rease or reduce the overall enrollment. Common application of this is addition of 6th grade to Middle Schools		
where Elementary Schools are at or over capacity			
Attributes:	<u>Deficiencies:</u>		
-Makes greater use of existing facilities	-Students and families may prefer grade configuration as is		
-Keeps current attendance area neighborhood intact	-School staff and program is impacted		
-Relatively quick to implement	-Could cause hardship or transportation burden on families and staff		
-Reduces capital funding requirements (relative to new construction option)	-Only applicable if reconfiguration does not overcrowd or under enroll nearby schools and/or change current		
	Middle and High school feeder patterns.		
Overflow Busing: Busing students to nearby schools with capacity			
Attribute:	Deficiencies:		
-Makes greater use of existing facilities	-May be inconvenient for staff, parents, and students		
-Relatively guick to implement	-Capacity may not be available elsewhere		
-Reduces capital funding requirements (relative to new construction option)	-Increased transportation costs		
	-Runs counter to concept of neighborhood school		
Program Change: Moving or raplicating stand along programs such as Spo	ecial Education, Preschool, Alternative Secondary, Gifted & Talented, and Discovery to underutilized space		
Program Change. Moving of replicating stand-alone programs such as ope	colar Education, Prescribor, Alternative Secondary, Gilled & Talented, and Discovery to underdiffized space		
Attributes:	<u>Deficiencies:</u>		
-Makes greater use of existing facilities	-School staff and program is impacted		
-Can benefit students living in other attendance areas as well	-Could cause hardship or transportation burden for families and staff		
-Keeps current attendance area neighborhood intact	-Building modifications may have been made specifically for standalone program that are not available in new		
-Relatively quick to implement	facility		
-Reduces capital funding requirements (relative to new construction option)	-Could destabilize effectiveness of program		

#### Capacity Alternatives which Provide Additional Capacity

Attributes:	<u>Deficiencies:</u>		
-Keeps current attendance area neighborhood and programming intact	<ul> <li>-More expensive than program and/or calendar change alternatives</li> <li>-Core spaces remain stressed and overcrowded</li> </ul>		
	-Site may not allow for facility additions		
Mobiles: Installing more modular units			
Attributes:	Deficiencies:		
-Offers flexibility in responding to changes in enrollment	-Often lack architectural quality, special features, and amenities that permanent classrooms have		
-Offers efficient, short term relief	-Core spaces remain stressed and overcrowded		
-Cost less than permanent buildings and additions (to purchase and operate)	-Site may not allow for additional mobiles		
	-Not a long term solution		
Purchase and Tenant Finish: Purchasing already existing space and ten	ant finishing to meet DCSD program needs		
Attributes:	Deficiencies:		
-Costs could be significantly less than new construction	-Subject to market availability and costs		
-Quicker to implement than new construction	<ul> <li>-May be difficult to find sites and facilities that fully meet DCSD criteria and needs (may not be centrall located or core facilities such as a cafeteria, gym, and media center may not be available)</li> <li>-Capital costs associated with property purchase, and modernizing and improving buildings</li> </ul>		

\*\*Note\*\* School capacity alternatives are listed in no particular order



13524 Acres Green Drive Littleton, CO 80124 Highlands Ranch High School Feeder Area, K-6 Funded by 1974 Bond Opened in 1975


Site Acreage:12 Facility Square Feet: 50,480 Mobiles on-site: 3

#### Acres Green Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$1,795,300 Estimated Total Project Costs: \$2,066,200 - \$2,954,820

\$1,000,000



\$1,500,000

Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
Tier 1 Funded by the 2018 Bond	Interior Door Hardware. Replace painted door hinges.	\$14,280	\$1530-\$6230	\$720-\$3070
	Controls. Upgrade control system.	\$317,250	\$31750-\$136450	\$15870-\$68210
	Fire Alarm Systems. Upgrade fire alarm system.	\$105,750	\$10650-\$45550	\$5290-\$22740
	Irrigation Systems. Install seperate meter. Add booster pump.	\$73,710	\$7400-\$31800	\$3690-\$15850
	Emergency Light and Power Systems. Generator and Transfer Switch. Install new generator and associated emergency systems.	\$29,510	\$3000-\$12700	\$1480-\$6350
	Flooring Restroom. Replace tile flooring in restrooms with MMA.	\$68,740	\$6970-\$29570	\$3440-\$14780
	Exterior Wall Construction. Recaulk control joints.	\$4,450	\$460-\$1960	\$230-\$960
	Exterior Windows. Recaulk windows	\$15,760	\$1650-\$6850	\$790-\$3390
ľ	Retractable Partitions. Refurbish or replace 3 classroom partitions	\$42,300	\$4300-\$18200	\$2120-\$9100
	Fabricated Toilet Partitions. Replace in (2) boys restrooms	\$9,520	\$990-\$4190	\$480-\$2050
	Wash Fountains. Replace trough washing stations with sinks (6)	\$16,920	\$1780-\$7280	\$850-\$3640
	Fixed Casework. Replace casework in original building	\$196,380	\$19730-\$84530	\$9820-\$42230
	Paving and Surfacing. Bus Loop. Mill and overlay bus loop	\$24,540	\$2470-\$10570	\$1230-\$5280
 	Paving and Surfacing. Parking Lot. Resurface asphalt parking lot	\$78,680	\$7930-\$33930	\$3940-\$16920
	Paving and Surfacing. Sidewalks. Repair/replace areas of sidewalk	\$8,990	\$920-\$3920	\$450-\$1940
	Paving and Surfacing. Repair/replace asphalt walkways	\$49,180	\$4930-\$21230	\$2460-\$10580
	Playing Fields. Playground. Replace asphalt playground	\$29,510	\$3000-\$12700	\$1480-\$6350
2-Medium	Curbs, Rails and Barriers. Repair/replace areas of curb.	\$5,080	\$530-\$2230	\$260-\$1100
	Wall Foundations. Recaulk foundation where concrete meets	\$7,510	\$800-\$3300	\$380-\$1620
	Interior Doors. Refinish doors, layered paint	\$44,310	\$4500-\$19100	\$2220-\$9530
3-High	Interior Door Frames. Sand down and repaint	\$22,210	\$2300-\$9600	\$1110-\$4780
	Suspended Ceilings. Replace grid ceiling and tile in original building	\$80,480	\$8130-\$34630	\$4030-\$17310
	Playing Fields. Multi-use Field. Renovate multi-use field	\$78,680	\$7930-\$33930	\$3940-\$16920
	Playing Fields. Baseball Field. Renovate upper baseball fields	\$39,450	\$3960-\$17060	\$1980-\$8490
3-Medium	Fire Sprinkler Water Supply. Fire sprinkle building	\$392,650	\$39350-\$168850	\$19640-\$84420
4-High	Seeding and Sodding. Renovate grass area around school.	\$9,950	\$1060-\$4360	\$500-\$2140
4-Medium	Planting. Add landscaping at NW corner of school site	\$29,510	\$3000-\$12700	\$1480-\$6350

Estimated Total Construction Costs (in 2019 Dollars): \$1,795,300 Estimated Project Management Costs Range: \$181,020 - \$773,420 Estimated Inflation Range: \$89,880 - \$386,100


Estimated Total Project Costs: \$2,066,200 - \$2,954,820




10345Arrowwood Drive Highlands Ranch, CO 80130 Highlands Ranch High School Feeder Area, K-6 Funded by 1997 Bond Opened in 2000

Site Acreage:10 Facility Square Feet: 51,668 Mobiles on-site: 1

#### Arrowwood Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$1,942,120 Estimated Total Project Costs: \$2,234,860 - \$3,196,400



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Roof Finishes. Replace .045 mil EPDM ballasted roof with .060 fully adhered.	\$793,130	\$79380-\$341080	\$39660-\$170530
	Door Hardware. Replace door hardware, replace non- restricted key system with restricted.	\$164,970	\$16530-\$71030	\$8250-\$35470
	Chilled Water Systems. Chiller, cooling tower. Replace cooling tower.	\$54,990	\$5510-\$23710	\$2750-\$11830
Tier 1 Funded by the	Fire Alarm Systems. Replace Notifier AFB 200 fire alarm system with Simplex	\$105,750	\$10650-\$45550	\$5290-\$22740
2018 Bond	Emergency Light and Power Systems. Generator and Transfer Switch. Replace generator.	\$17,880	\$1830-\$7730	\$900-\$3850
	Irrigation Systems. Upgrade irrigation system, add booster pump.	\$135,470	\$13640-\$58340	\$6780-\$29130
	Chilled Water Systems. Chiller, cooling tower. Replace cooling tower.	\$63,450	\$6350-\$27350	\$3180-\$13650
	Local Area Networks. ITS/Head End Equipment. Expanded or new MDF closet (minimum 10'X10').	\$70,330	\$7080-\$30280	\$3520-\$15120
	Foundations. Repair footings at playground entrance, cracking and crumbling	\$20,730	\$2080-\$8980	\$1040-\$4460
	Exterior Wall Construction. Repair CMU at cooling tower. Enclosure wall separating from building due to movement.	\$2,120	\$290-\$990	\$110-\$460
	Exterior Wall Construction. CMU and Brick. Re-seal CMU. Repair stress cracks from settling. Re-caulk all joints.	\$16,500	\$1710-\$7110	\$830-\$3550
	Exterior Windows. Re-caulk all windows	\$5,290	\$620-\$2320	\$270-\$1140
2-High	Roof Finishes. Paint metal roof	\$4,760	\$550-\$2150	\$240-\$1030
	Fixed Walls. Repair CMU in Pod 1 on wall near restroom	\$2,120	\$290-\$990	\$110-\$460
	Fabricated Toilet Partitions. Replace 4 boys and 4 girls toilet partitions	\$29,830	\$3080-\$12880	\$1500-\$6420
	Sink Countertops. Replace sink countertops with single surface	\$21,370	\$2140-\$9240	\$1070-\$4600
	Paving and Surfacing. Sidewalks. Repair/replace sections of sidewalk	\$73,710	\$7400-\$31800	\$3690-\$15850
	Flooring Kitchen. Repair cracks in kitchen floor. Potential 2018 (5 year) Bond Project.	\$3,920	\$490-\$1690	\$200-\$850
	Flooring Restroom. Replace original epoxy floor.	\$31,730	\$3180-\$13680	\$1590-\$6830
	Flooring Kitchen. Replace original epoxy floor.	\$63,450	\$6350-\$27350	\$3180-\$13650
2-Medium	Flooring Cafeteria. Replace VCT.	\$15,870	\$1640-\$6840	\$800-\$3410
	Operable Partition. Minor repairs as necessary at gym and classrooms	\$11,640	\$1170-\$5070	\$590-\$2510
	Exhaust Ventilation Systems. Exhaust Fans. Replace exhaust fans	\$22,000	\$2210-\$9510	\$1100-\$4730
3-High	Standard Slab on Grade. Repair cafeteria floor, movement issues	\$18,720	\$1890-\$8090	\$940-\$4030
5	Playing Fields. Multi-use Field. Renovate multi-use field	\$81,330	\$8180-\$34980	\$4070-\$17490
	Vinyl Coverings. Repair vinyl covering in hallways	\$2,650	\$360-\$1160	\$140-\$570
3-Medium	Fences and Gates. Replace dumpster enclosure with new block enclosure, repair site fencing	\$81,330	\$8180-\$34980	\$4070-\$17490
4-High	Other Landscape Features. Renovate/replace areas of landscaping around site	\$27,080	\$2730-\$11730	\$1360-\$5820

Estimated Total Construction Costs (in 2019 Dollars): \$1,942,120 Estimated Project Management Costs Range: \$195,510 - \$836,610 Estimated Inflation Range: \$97,230 - \$417,670

Estimated Total Project Costs: \$2,234,860 - \$3,196,400




9660 Salford Lane Highlands Ranch, CO 80126 Mountain Vista High School Feeder Area, K-6


Funded by 1989 Bond Opened in 1990

Site Acreage:12 Facility Square Feet: 53,237 Mobiles on-site: 1

#### Bear Canyon Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$1,113,300 Estimated Total Project Costs: \$1,281,320 - \$1,832,500



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Direct Expansion Systems. Roof top units. Replace RTU's.	\$317,250	\$31750-\$136450	\$15870-\$68210
	Fire Alarm Systems. Upgrade fire alarm system.	\$105,750	\$10650-\$45550	\$5290-\$22740
Funded by the	Switchgear-Main. Replace main switchgear.	\$31,730	\$3180-\$13680	\$1590-\$6830
2018 Bond	Panels and Transformers. Replace original panels and transformers.	\$21,150	\$2150-\$9150	\$1060-\$4550
	Flooring Kitchen. Replace original kitchen flooring with poured acrylic.	\$58,060	\$5850-\$25050	\$2910-\$12490
	Flooring Cafeteria. Replace VCT.	\$13,120	\$1390-\$5690	\$660-\$2820
2-High	Exterior Windows. Replace exterior windows	\$70,220	\$7090-\$30290	\$3520-\$15100
g	Fabricated Toilet Partitions. Replace toilet partitions in 3 pods	\$23,270	\$2340-\$10040	\$1170-\$5010
	Paving and Surfacing. Sidewalks. Repair/replace areas of sidewalk	\$10,790	\$1120-\$4720	\$540-\$2320
	Flooring Restroom. Replace VCT flooring in staff restrooms.	\$1,800	\$210-\$810	\$90-\$390
	Flooring Carpet. Replace carpet in workrooms in stacked pods.	\$12,800	\$1310-\$5510	\$640-\$2760
	Retractable Partition. Repair operable partitions between classrooms and between gym/cafeteria	\$17,140	\$1770-\$7370	\$860-\$3690
2-Medium	Suspended Ceilings. Replace ceiling grid and tile. Damaged during fire sprinkler install	\$137,480	\$13830-\$59130	\$6880-\$29560
	Water Closets. Replace fixtures in staff restrooms	\$2,650	\$360-\$1160	\$140-\$570
	Sinks. Replace fixtures in staff restrooms	\$1,800	\$210-\$810	\$90-\$390
	Fixed Casework. Replace all original fixed casework in classrooms and offices	\$178,190	\$17920-\$76720	\$8910-\$38320
	Paving & Surfacing, Parking Lot. Repair service drive concrete cracking	\$5,820	\$590-\$2590	\$300-\$1250
3-High	Playing Fields. Multi-use field. Renovate multi-use field	\$91,370	\$9240-\$39340	\$4570-\$19650
4-High	Wall Foundations. Recaulk foundation where concrete meets	\$7,090	\$720-\$3120	\$360-\$1530
	Seeding & Sodding. Resod/reseed grass areas	\$5,820	\$590-\$2590	\$300-\$1250

Estimated Total Construction Costs (in 2019 Dollars): \$1,113,300 Estimated Project Management Costs Range: \$112,270 - \$479,770 Estimated Inflation Range: \$55,750 - \$239,430


Estimated Total Project Costs: \$1,281,320 - \$1,832,500




7075 N. Shoreham Drive Castle Pines, CO 80108 Rock Canyon High School Feeder Area, K-5 Funded by 1993 Bond Opened in 1997

Site Acreage:10 Facility Square Feet: 51,020 Mobiles on-site: 1

## Buffalo Ridge Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$1,846,830 Estimated Total Project Costs: \$2,125,380 - \$3,039,410



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Cold Water Service. Piping and Insulation in poor shape needs replaced.	\$40,820	\$4180-\$17590	\$2050-\$8780
	Hot Water Service. Water heater and storage tank beyond life cycle. Piping and Insulation in poor shape needs replaced.	\$89,150	\$8960-\$38360	\$4460-\$19170
·	Direct Expansion Systems. Roof top units. Replace RTUs.	\$339,460	\$34050-\$146050	\$16980-\$72990
Tier 1 Funded by the	Hot Water Distribution Pumps need upgrade, Insulation needs replaced.	\$18,090	\$1820-\$7820	\$910-\$3890
2018 Bond	Controls. Upgrade control system.	\$317,250	\$31750-\$136450	\$15870-\$68210
	Irrigation Systems. Needs booster pump, possible new controller.	\$62,930	\$6380-\$27080	\$3150-\$13530
	Boiler Room Piping. All in good shape, May have to replace some to upgrade to DDC from pneumatic.	\$32,680	\$3330-\$14130	\$1640-\$7030
	Direct Expansion Systems. Replace swamp cooling MUA unit/s with mechanical cooling.	\$79,320	\$7990-\$34190	\$3970-\$17060
	Flooring Kitchen. Flooring is currently Hubelite material (Red) and needs replaced with MMA poured floor. See floor estimate spreadsheet	\$63,880	\$6430-\$27530	\$3200-\$13740
	Flooring Cafeteria. Replace VCT.	\$15,870	\$1640-\$6840	\$800-\$3410
	Exterior Wall Construction. Recaulk control joints.	\$3,390	\$420-\$1520	\$170-\$730
	Exterior Wall Construction. Needs sealed. Stress cracks same as other schools. Lack of control joints	\$17,560	\$1850-\$7650	\$880-\$3780
	Exterior Paint. Exterior paint	\$8,150	\$860-\$3560	\$410-\$1760
	Exterior Windows. Recaulk windows	\$13,220	\$1390-\$5790	\$670-\$2850
2-High	Storefront windows. Hollow metal. Playground entrance leaks	\$30,670	\$3140-\$13240	\$1540-\$6600
	Retractable Partitions. Repair/replace gym/cafeteria partition. Curtains need replaced due to fire retardant life. Classrooms are not used and are in good shape.	\$16,290	\$1720-\$7020	\$820-\$3510
	Paving and Surfacing. Parking Lot. Resurface asphalt parking lot	\$145,520	\$14590-\$62590	\$7280-\$31290
	Paving & Surfacing. Sidewalks Heaving in many areas, needs replacement	\$24,540	\$2470-\$10570	\$1230-\$5280
	Playing Fields. Playground. Playpad needs resurfacing	\$40,820	\$4180-\$17590	\$2050-\$8780
2-Medium	Fabricated Toilet Partitions. Replce toilet partitions	\$23,270	\$2340-\$10040	\$1170-\$5010
3-High	Insulation Needs removed and replaced.	\$8,150	\$860-\$3560	\$410-\$1760
	Interceptors. Grease interceptor Bypass if allowable	\$8,150	\$860-\$3560	\$410-\$1760
3-Medium	Fire Sprinkler. Cafeteria sprinkled only. New code requires to be fully sprinkled	\$411,900	\$41210-\$177210	\$20600-\$88560
	Retaining Walls. Hillside off playground needs tie wall of some kind	\$32,360	\$3250-\$13950	\$1620-\$6960
4-High	Wall Foundations. Recaulk foundation where concrete meets	\$3,390	\$420-\$1520	\$170-\$730

Estimated Total Construction Costs (in 2019 Dollars): \$1,846,830 Estimated Project Management Costs Range: \$186,090 - \$795,410 Estimated Inflation Range: \$92,460 - \$397,170


Estimated Total Project Costs: \$2,125,380 - \$3,039,410




1103 Canyon Drive Castle Rock, CO 80104 Douglas County High School Feeder Area, K-6 Funded by 1984 Bond Opened in 1984

Site Acreage:15.4 Facility Square Feet: 52,907 Mobiles on-site: 1

## Castle Rock Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$2,653,160 Estimated Total Project Costs: \$3,052,490 - \$4,366,350



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Roof Finishes. Replace .045 EPDM ballasted roof with .060 EPDM fully adhered.	\$740,250	\$74050-\$318350	\$37020-\$159160
	Controls. Upgrade control system.	\$317,250	\$31750-\$136450	\$15870-\$68210
	Switchgear-Main. Replace main switchgear and associated electrical distribution	\$73,710	\$7400-\$31800	\$3690-\$15850
Tier 1 Funded by the	Panels and Transformers. Replace original panels and transformers.	\$445,210	\$44600-\$191500	\$22260-\$95720
2018 Bond	Fire Alarm Systems. Upgrade fire alarm system.	\$105,750	\$10650-\$45550	\$5290-\$22740
	Exhaust Ventilation Systems. Kitchen Hood. Replace MAU.	\$60,810	\$6100-\$26200	\$3040-\$13080
	Exhaust Ventilation Systems. Exhaust Fans. Replace exhaust fans.	\$22,320	\$2290-\$9690	\$1120-\$4800
	Package Units. Replace cabinet heaters at entrys, 7 total.	\$13,440	\$1370-\$5870	\$680-\$2890
	Flooring Cafeteria. Replace VCT.	\$13,120	\$1390-\$5690	\$660-\$2820
2-High	Flooring Kitchen. Replace ceramic tile floor with MMA.	\$63,450	\$6350-\$27350	\$3180-\$13650
2 mgn	Exterior Wall Construction. Recaulk control joints.	\$3,390	\$420-\$1520	\$170-\$730
	Exterior Windows. Recaulk windows	\$4,660	\$550-\$2050	\$240-\$1000
	Flooring Restroom. Replace original ceramic tile with poured acrylic.	\$31,310	\$3200-\$13500	\$1570-\$6730
	Flooring Carpet. Replace carpet in conference rm and 2 rms on upper level.	\$8,990	\$920-\$3920	\$450-\$1940
	Paint Exterior. Paint exterior trim, windows, and doors	\$8,990	\$920-\$3920	\$450-\$1940
	Retractable Partition. Repair operable partitions between classrooms. Partion between gym and cafeteria in worst condition.	\$17,980	\$1830-\$7830	\$900-\$3870
	Sink Countertops. Replace sink countertops in all restrooms with single surface	\$21,370	\$2140-\$9240	\$1070-\$4600
2-Medium	Stair, Tread and Landing Finishes. Replace stair tread	\$4,340	\$470-\$1970	\$220-\$940
2-Medium	Sinks. Replace with sink countertops, single surface	\$13,440	\$1370-\$5870	\$680-\$2890
	Drinking Fountains and Coolers. Replace metal drinking fountains	\$4,130	\$480-\$1780	\$210-\$890
	Boiler Room Piping and Specialties. Add VFDs to motors/pumps	\$51,080	\$5130-\$22030	\$2560-\$10990
	Direct Expansion Systems. Roof top units. Replace RTUs, provide VFDs	\$317,250	\$31750-\$136450	\$15870-\$68210
	Paving and Surfacing. Parking Lot. Parking lot asphalt cracks need filled	\$66,940	\$6760-\$28860	\$3350-\$14400
	Paving and Surfacing. Sidewalks. Repair areas of sidewalk and loading dock	\$17,980	\$1830-\$7830	\$900-\$3870
3-High	Wall Foundations. Recaulk foundation where concrete meets	\$7,090	\$720-\$3120	\$360-\$1530
	Playing Fields. Multi-use Field. Renovate multi-use field	\$78,680	\$7930-\$33930	\$3940-\$16920
	Suspended Ceilings. Replace ceiling grid and tile	\$137,480	\$13830-\$59130	\$6880-\$29560
3-Medium	Movable Furnishing. FFE. Replace wooden basketball backboards in gym, 6 total	\$2,750	\$360-\$1260	\$140-\$600

Estimated Total Construction Costs (in 2019 Dollars): \$2,653,160 Estimated Project Management Costs Range: \$266,560 - \$1,142,660 Estimated Inflation Range: \$132,770 - \$570,530


Estimated Total Project Costs: \$3,052,490 - \$4,366,350



2575 Meadows Boulevard Castle Rock, CO 80126 Castle View High School Feeder Area, 7-8 Funded by 1993 Bond Opened in 1996

Site Acreage:22 Facility Square Feet: 128,680 Mobiles on-site: 0

## Castle Rock Middle School-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority




Estimated Total Construction Costs (in 2019 Dollars): \$1,454,300 Estimated Total Project Costs: \$1,674,220 - \$2,394,010

\$2,000,000

\$1,000,000

\$3,000,000



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Interior Door hardware. Replace current non-restricted key system with restricted. Hardware change.	\$280,670	\$28140-\$120740	\$14040-\$60350
	Air Distribution Systems. HVAC system upgrade.	\$171,210	\$17200-\$73700	\$8560-\$36810
Tier 1	Water Treatment Systems. Upgrade.	\$16,290	\$1720-\$7020	\$820-\$3510
Funded by the 2018 Bond	Emergency Light and Power Systems. Generator and Transfer Switch. Replace generator and associated equipment.	\$74,030	\$7480-\$31880	\$3710-\$15920
	Passenger Elevators. Renovate elevator.	\$158,630	\$15880-\$68280	\$7940-\$34110
	Commissioning and Re-Commissioning. Commission if system upgraded.	\$57,220	\$5790-\$24690	\$2870-\$12300
Tier 2 Funded by the 2018 Bond	Flooring Carpet. Replace carpet.	\$346,440	\$34670-\$149070	\$17330-\$74490
	Flooring Kitchen. Replace kitchen flooring. Currently red hubblelite	\$62,400	\$6310-\$26910	\$3120-\$13420
	Flooring Hallways/Classrooms. replace VCT in classroom areas	\$71,280	\$7230-\$30730	\$3570-\$15330
	Exterior Wall Construction. Recaulk control joints.	\$4,660	\$550-\$2050	\$240-\$1000
	Exterior Windows. Recaulk windows	\$23,480	\$2430-\$10130	\$1180-\$5050
	Fabricated Toilet Partitions. Replace with solid plastic in all wings upper and lower	\$25,170	\$2540-\$10840	\$1260-\$5420
2-High	Sink Countertops. Replace sink countertops with single surface	\$21,370	\$2140-\$9240	\$1070-\$4600
	Theater & Stage Equipment, Auditorium Sound Equipment. Strand CD80. Upgrade Strand controller	\$10,580	\$1130-\$4630	\$530-\$2280
	Fixed Casework. Computer counter tops need to be raised in the library	\$4,230	\$470-\$1870	\$220-\$910
	Paving & Surfacing, Sidewalks. Needs repaired in areas	\$18,300	\$1910-\$7910	\$920-\$3940
	Retractable Partition. Repair/refurbish operable partitions at pod areas	\$12,270	\$1240-\$5340	\$620-\$2640
2-Medium	Wall Foundations. Recaulk foundation where concrete meets	\$9,420	\$990-\$4090	\$480-\$2030
	Regular Stairs. Reseal concrete stairs	\$5,820	\$590-\$2590	\$300-\$1250
	Blinds and Window Treatment. Install blinds on all lower kevel classrooms	\$13,440	\$1370-\$5870	\$680-\$2890
3-High	Blinds and Other Window Treatment. Need-Install blinds on east facing clearstory windows	\$4,550	\$560-\$2060	\$230-\$980
	Suspended Ceilings. Replace kitchen tiles with food grade	\$3,490	\$410-\$1510	\$180-\$750
	Furnishings. Replace chalk boards with white boards. 13 total	\$4,550	\$560-\$2060	\$230-\$980
	Special Facilities. Tech area needs better sink, better exhaust ventilation system, better storage cabinets	\$24,330	\$2480-\$10480	\$1220-\$5230
3-Medium	Retaining Wall. Repair retaining walls at crawlspace entrance	\$5,290	\$620-\$2320	\$270-\$1140
	Playing Fields. Multi-use Field. Replace goal posts on athletic field	\$8,990	\$920-\$3920	\$450-\$1940
	Other Landscape Features. Fix drainage problem on east side of school	\$11,530	\$1180-\$4980	\$580-\$2480
4-Medium	Planting. Replace some trees	\$4,660	\$550-\$2050	\$240-\$1000

Estimated Total Construction Costs (in 2019 Dollars): \$1,454,300 Estimated Project Management Costs Range: \$147,060- \$626,960 Estimated Inflation Range: \$72,860 - \$312,750


Estimated Total Project Costs: \$1,674,220 - \$2,394,010




5254 North Meadows Drive Castle Rock, CO 80109 Castle View High School Feeder Area, 9-12 Funded by 2003 Bond Opened in 2006

Site Acreage: 35.4 Facility Square Feet: 218,106 Mobiles on-site: 6

## Castle View High School-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$3,578,700 Estimated Total Project Costs: \$4,115,820 - \$5,887,400



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
Tier 1	Roof Finishes. Replace .045 EPDM ballasted roof with .060 EPDM fully adhered.	\$2,009,250	\$200950-\$864050	\$100470-\$431990
Funded by the 2018 Bond	Controls. Upgrade control system.	\$1,004,630	\$100480-\$432080	\$50240-\$216000
2016 BOIIU	Fire Alarm Systems. Upgrade fire alarm system.	\$370,130	\$37080-\$159180	\$18510-\$79580
	Exterior Wall Construction. CMU. Re-seal CMU, recaulk control joints	\$60,490	\$6120-\$26020	\$3030-\$13010
	Exterior Windows. Re-caulk windows	\$73,710	\$7400-\$31800	\$3690-\$15850
	Paving and Surfacing. Parking Lot. Resurface/repair parking lot	\$54,990	\$5510-\$23710	\$2750-\$11830
	Paving and Surfacing. Sidewalks. Repair as necessary, decent at time of assessment	\$5,500	\$610-\$2410	\$280-\$1190

Estimated Total Construction Costs (in 2019 Dollars): \$3,578,700 Estimated Project Management Costs Range: \$358,150 - \$1,539,250

Estimated Inflation Range: \$169,205 - \$727,582

Estimated Total Project Costs: \$4,115,820 - \$5,887,400




15665 Brookstone Drive Parker, CO 80134 Chaparral High School Feeder Area, 9-12


Funded by 1993 Bond Opened in 1997

Site Acreage: 50 Facility Square Feet: 240,367 Mobiles on-site: 3

## Chaparral High School-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$4,565,890 Estimated Total Project Costs: \$5,252,420 - \$7,512,860



\$5,000,000

\$4,000,000

Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Roof Finishes. Install new roof on F-pod. Not done with 2013 re-roof.	\$314,820	\$31490-\$135390	\$15750-\$67690
	Direct Expansion Systems. Roof top units. Replace RTUs.	\$1,099,800	\$110000-\$473000	\$54990-\$236460
	Air Distribution Systems. Air handlers, ductwork, VAV's. Update air handlers with HW coils, new motors, and VFDs	\$204,000	\$20410-\$87810	\$10200-\$43860
	Change-over Distribution System. Replace all fan powered boxes to VAV reheat.	\$204,000	\$20410-\$87810	\$10200-\$43860
Tier 1	Glycol Distribution Systems. Poor condition. Upgrade and add HW loop to system.	\$16,290	\$1720-\$7020	\$820-\$3510
Funded by the 2018 Bond	Water Treatment Systems. Poor condition. Upgrade and add HW loop to system.	\$19,780	\$2030-\$8530	\$990-\$4260
	Emergency Light and Power Systems. Generator and Transfer Switch. Replace generator and associated equipment.	\$84,600	\$8500-\$36400	\$4230-\$18190
	Fixed Multiple Seating, Bleachers. Replace main gym bleacher both sides.	\$195,850	\$19660-\$84260	\$9800-\$42110
	Passenger Elevators. Renovate elevator #1.	\$158,630	\$15880-\$68280	\$7940-\$34110
	Energy Supply. Replace main gas line at meter.	\$12,270	\$1240-\$5340	\$620-\$2640
	Commissioning and Re-Commissioning. Rebalance HVAC system.	\$57,220	\$5790-\$24690	\$2870-\$12300
Tier 2 Funded by the 2018 Bond	Flooring Carpet. Replace carpet. X-Carpet in main and pod hallways replaced 2017.	\$329,940	\$33060-\$141960	\$16500-\$70940
	Flooring Kitchen. Replace original hubblelite floor with MMA.	\$74,030	\$7480-\$31880	\$3710-\$15920
	Flooring Cafeteria. Commons floor has settling cracks and was repaired in 2007. Repairs are still in good shape. VCT repairs are needed around stairway and into hall	\$7,090	\$720-\$3120	\$360-\$1530
	Flooring Cafeteria. Replace VCT in commons and hallways.	\$91,060	\$9150-\$39250	\$4560-\$19580
	Exterior Wall Construction. Recaulk control joints. Re-seal CMU	\$56,160	\$5650-\$24150	\$2810-\$12080
	Exterior Windows. Recaulk windows	\$70,220	\$7090-\$30290	\$3520-\$15100
	Exterior Windows. Fix curtain wall window leakage at commons and hallways.	\$147,310	\$14790-\$63390	\$7370-\$31680
	Overhead Doors. Replace (4) four rollup doors at kitchen	\$14,810	\$1500-\$6400	\$740-\$3190
	Other Doors & Entrances. Continuous hinges on storefront doors need replaced	\$9,310	\$1000-\$4100	\$470-\$2010
2-High	Interior Doors. Kitchen entry doors from cafeteria need replaced due to carts hitting them all the time. Replace with metal?	\$5,080	\$530-\$2230	\$260-\$1100
	Fabricated Toilet Partitions. Replace men's & women's PE restrooms. Replace all bathroom partitions in all wings and main area	\$63,450	\$6350-\$27350	\$3180-\$13650
	Sink Countertops. Replace sink counter tops in all restrooms	\$40,510	\$4100-\$17500	\$2030-\$8710
	Showers. Poor condition, showers need replaced	\$17,240	\$1770-\$7470	\$870-\$3710
	Theater & Stage Equipment, Auditorium Sound Equipment. Strand MD 80 Sound Equipment. Replace approximately 100 seats in auditorium due to backs cracking.	\$36,910	\$3700-\$15900	\$1850-\$7940
	Paving & Surfacing, Sidewalks. Repair asphalt sidewalks to athletic fields	\$5,820	\$590-\$2590	\$300-\$1250
	Irrigation Systems. Replace 4 irrigation controllers	\$13,750	\$1460-\$5960	\$690-\$2960
	Paving and Surfacing. Parking Lot. Resurface parking areas, many patches and cracks	\$727,560	\$72840-\$312940	\$36380-\$156430

Estimated Total Construction Costs (in 2019 Dollars): \$4,565,890 Estimated Project Management Costs Range: \$458,080 - \$1,965,180 Estimated Inflation Range: \$228,450 - \$981,790


Estimated Total Project Costs: \$5,252,420 - \$7,512,860



17302 Clarke Farms Dr. Parker, CO 80134 Chaparral High School Feeder Area, K-6 Funded by 1984 Bond Opened in 1989


Site Acreage: 10 Facility Square Feet: 53,237 Mobiles on-site: 4

## Cherokee Trail Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



\$1,500,000

Estimated Total Construction Costs (in 2019 Dollars): \$1,789,710 Estimated Total Project Costs: \$2,059,290 - \$2,945,470



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Glazed Roof Openings.Skylights. Repair/replace main skylight, leaks frequently.	\$12,270	\$1240-\$5340	\$620-\$2640
	Upgrade VAV boxes.	\$456,210	\$45700-\$196200	\$22810-\$98090
	Switchgear-Main. Replace main switchgear.	\$46,750	\$4760-\$20160	\$2340-\$10050
	Panels and Transformers. Replace original panels and transformers.	\$46,750	\$4760-\$20160	\$2340-\$10050
Tier 1 Funded by the	Branch Wiring Devices. Replace sealtite and wiring to equipment on roof.	\$3,180	\$330-\$1430	\$160-\$690
2018 Bond	Lighting Equipment. Replace old exit signs, about half left.	\$6,240	\$670-\$2770	\$320-\$1350
	Fire Alarm Systems. Upgrade fire alarm system.	\$105,750	\$10650-\$45550	\$5290-\$22740
	Direct Expansion Systems. Roof top units. Replace 2 RTU's from 2001.	\$242,600	\$24310-\$104410	\$12130-\$52160
	Switchgear-Main. Replace main switchgear.	\$31,730	\$3180-\$13680	\$1590-\$6830
	Panels and Transformers. Replace original panels and transformers.	\$21,150	\$2150-\$9150	\$1060-\$4550
	Exterior Windows. Replace exterior windows	\$70,220	\$7090-\$30290	\$3520-\$15100
2.15-6	Retractable Partition. Repair and replace vinyl on the portable wall partitions	\$12,270	\$1240-\$5340	\$620-\$2640
2-High	Energy Supply. Replace gas piping on roof	\$1,910	\$200-\$900	\$100-\$410
	Paving & Surfacing, Sidewalks. Repair/replace areas of cracked sidewalk	\$11,530	\$1180-\$4980	\$580-\$2480
	Flooring Kitchen. Replace kitchen flooring.	\$56,160	\$5650-\$24150	\$2810-\$12080
	Flooring Carpet. Replace carpet.	\$317,250	\$31750-\$136450	\$15870-\$68210
	Water Closets. Replace toilets	\$24,330	\$2480-\$10480	\$1220-\$5230
2-Medium	Urinals. Replace urinals	\$17,140	\$1770-\$7370	\$860-\$3690
	Lavatories. Replace lavatories	\$12,270	\$1240-\$5340	\$620-\$2640
	Fixed Casework. Replace all original fixed casework in classrooms and offices	\$178,190	\$17920-\$76720	\$8910-\$38320
3-High	Wall Foundations. Recaulk foundation where concrete meets	\$7,090	\$720-\$3120	\$360-\$1530
	Playing Fields. Multi-use Field. Renovate multi-use field	\$91,370	\$9240-\$39340	\$4570-\$19650
	Seeding & Sodding. Resod/reseed grass areas	\$5,820	\$590-\$2590	\$300-\$1250
4-High	Other Landscape Features. Replace metal edging with concrete mow strip	\$11,530	\$1180-\$4980	\$580-\$2480

Estimated Total Construction Costs (in 2019 Dollars): \$1,789,710 Estimated Project Management Costs Range: \$180,000 - \$770,900 Estimated Inflation Range: \$89,580 - \$384,860


Estimated Total Project Costs: \$2,059,290 - \$2,945,470




9244 South State Highway 83 Franktown, CO 80116 Douglas County High School Feeder Area, K-6 Funded prior to 1952 Opened in 1952

Site Acreage: 4 Facility Square Feet: 4,657 Mobiles on-site: 1

## Cherry Valley Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority




Estimated Total Construction Costs (in 2019 Dollars): \$660,000 Estimated Total Project Costs: \$760,180 - \$1,087,220



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Interior Door hardware. Replace current non-restricted key system with restricted. Hardware change.	\$37,550	\$3760-\$16160	\$1880-\$8080
Funded by the	Emergency Light and Power Systems. Generator and Transfer Switch. Install new generator and associated emergency systems.	\$49,180	\$4930-\$21230	\$2460-\$10580
	Site Heating Distibution. Replace piping at propane tanks.	\$10,580	\$1130-\$4630	\$530-\$2280
	Flooring Restroom. Replace VCT in old school building. Possible abatement.	\$9,950	\$1060-\$4360	\$500-\$2140
	Flooring Restroom. Replace linoleum in staff restroom.	\$1,590	\$220-\$720	\$80-\$350
	Flooring Restroom. Replace ceramic tile with MMA.	\$9,950	\$1060-\$4360	\$500-\$2140
	Flooring Gym, VCT replacement , needs abatement.	\$28,660	\$2950-\$12350	\$1440-\$6170
	Flooring Restroom. Refinish and reseal concrete restroom floors.	\$2,120	\$290-\$990	\$110-\$460
	Flooring Kitchen. Replace kitchen flooring.	\$10,580	\$1130-\$4630	\$530-\$2280
2-High	Flooring Carpet. Replace carpet.	\$4,760	\$550-\$2150	\$240-\$1030
	Flooring Carpet. Replace carpet in all buildings, includes modular classrooms.	\$87,990	\$8820-\$37920	\$4400-\$18920
	Exterior Wall Construction. Re-seal CMU. Repair cracks from settling. Re-caulk all joints.	\$3,600	\$410-\$1610	\$180-\$780
	Exterior Windows. Replace single pane windows in old school house	\$7,940	\$870-\$3470	\$400-\$1710
	Paving and Surfacing. Parking Lot. Install new asphalt parking lot	\$49,180	\$4930-\$21230	\$2460-\$10580
	Solid Exterior Doors. Replace two doors on old schoolhouse	\$1,910	\$200-\$900	\$100-\$410
2-Medium	Roof Eaves and Soffits. Repair soffit on original building	\$2,650	\$360-\$1160	\$140-\$570
	Lavatories. Replace floor urinals with wall mount	\$26,440	\$2670-\$11470	\$1330-\$5690
	Sinks. Replace sinks in restrooms and custodial closet	\$3,710	\$400-\$1600	\$190-\$800
	Suspended Ceilings. Replace ceiling tiles in old school house.	\$2,010	\$300-\$900	\$100-\$440
	Suspended Ceilings. Replace 1x1 glue on tiles in hallways and office	\$9,950	\$1060-\$4360	\$500-\$2140
3-High	Fences and Gates. Replace all fencing at around school perimeter, parking areas	\$5,080	\$530-\$2230	\$260-\$1100
	Playing Fields. Multi-use Field. Install new synthetic turf for multi-use field	\$294,620	\$29480-\$126790	\$14740-\$63350

Estimated Total Construction Costs (in 2019 Dollars): \$660,000 Estimated Project Management Costs Range: \$67,110 - \$285,220

Estimated Inflation Range: \$33,070 - \$142,000 Estimated Total Project Costs: \$760,180 - \$1,087,220




12130 Canterberry Parkway Parker, CO 80134 Legend High School Feeder Area, 6-8 Funded by 2006 Bond Opened in 2010

Site Acreage: 22 Facility Square Feet: 132,414 Mobiles on-site: 4

## Cimarron Middle School-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority





Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs	
	and technology related	No capital projects identified at this time. All security and technology related capital has been summarized in the security and technology pages.			




1470 Clear Sky Way Castle Rock, CO 80109 Castle View High School Feeder Area, K-6 Funded by 2006 Bond Opened in 2008


Site Acreage:10 Facility Square Feet: 73,146 Mobiles on-site: 2

\$1,500,000

## Clear Sky Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$938,580 Estimated Total Project Costs: \$1,080,070 - \$1,544,530



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	Fire Alarm Systems. Upgrade fire alarm system	\$126,900	\$12700-\$54600	\$6350-\$27290
1-Medium	Controls. Upgrade control system	\$370,130	\$37080-\$159180	\$18510-\$79580
2-High	Special Foundations. Repair retaining wall movement where it attaches to building foundation	\$54,990	\$5510-\$23710	\$2750-\$11830
	Exterior Wall Construction. CMU and Brick. Recaulk expansion joints. Reseal CMU	\$15,870	\$1640-\$6840	\$800-\$3410
	Paint Exterior. Paint metal at window shades, metal stantions, all blue metal	\$5,290	\$620-\$2320	\$270-\$1140
	Exterior Windows. Recaulk windows	\$15,870	\$1640-\$6840	\$800-\$3410
2-Medium	Paving and Surfacing. Parking Lot. Repair/resurface parking lot 2022	\$84,600	\$8500-\$36400	\$4230-\$18190
	Playing Fields. Playground. Repair/resurface as necessary	\$31,730	\$3180-\$13680	\$1590-\$6830
	Playing Fields. Multi-use Field. Replace artficial turf, showing wear in 2017. Needs to be raked and cleaned. Coming up at edges, grass growing in turf areas at edges	\$211,500	\$21200-\$91000	\$10580-\$45480
2-Low	Paving and Surfacing. Sidewalks. Repair/replace areas of sidewalk cracks and heaving	\$5,290	\$620-\$2320	\$270-\$1140
3-Medium	Wall Foundations. Repair sprawling at crawlspace ramp area	\$3,180	\$330-\$1430	\$160-\$690
	Vinyl Coverings. Minor repair to seams as necessary	\$2,650	\$360-\$1160	\$140-\$570
3-Low	Seeding and Sodding. Repair areas of grass around school	\$10,580	\$1130-\$4630	\$530-\$2280

Estimated Total Construction Costs (in 2019 Dollars): \$938,580 Estimated Project Management Costs Range: \$94,510 - \$404,110 Estimated Inflation Range: \$46,980 - \$201,840


Estimated Total Project Costs: \$1,080,070 - \$1,544,530




3501 Poston Parkway Highlands Ranch, CO 80126 Mountain Vista High School Feeder Area, K-6 Funded by 2000 Bond Opened in 2006

Site Acreage: 10 Facility Square Feet: 56,868 Mobiles on-site: 2

#### Copper Mesa Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$1,436,680 Estimated Total Project Costs: \$1,652,880 - \$2,364,410



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
Tier 1	Roof Finishes. Replace .045 EPDM ballasted with .060 fully adheared.	\$793,130	\$79380-\$341080	\$39660-\$170530
Funded by the	Boilers. Repair one boiler leaking water.	\$2,540	\$270-\$1170	\$130-\$550
2018 Bond	Fire Alarm Systems. Upgrade fire alarm system.	\$116,330	\$11680-\$50080	\$5820-\$25010
	Controls. Upgrade control system.	\$317,250	\$31750-\$136450	\$15870-\$68210
2-High	Paving and Surfacing. Sidewalks. Repair areas of sidewalk at west entry raised area for drainage issues	\$19,780	\$2030-\$8530	\$990-\$4260
	Flooring Cafeteria. Repair some separation of VCT joints at expansion joint by inside entry.	\$1,380	\$230-\$630	\$70-\$300
	Exterior Wall Construction. CMU. Reseal CMU	\$12,270	\$1240-\$5340	\$620-\$2640
	Exterior Wall Construction. CMU. Recaulk control joints	\$3,810	\$400-\$1700	\$190-\$820
	Exterior WindowsRecaulk windows	\$14,700	\$1510-\$6410	\$740-\$3160
	Retractable Partition. Repair operable partition between stage and gym	\$12,270	\$1240-\$5340	\$620-\$2640
2-Medium	Sink Countertops. Replace sink countertops	\$21,370	\$2140-\$9240	\$1070-\$4600
	Paving and Surfacing. Roadways (Bus Loops). Minor cracking occuring. Repairs will be needed in the future.	\$24,330	\$2480-\$10480	\$1220-\$5230
	Paving and Surfacing. Parking Lot. Minor cracking occuring. Repairs will be needed in the future.	\$48,540	\$4870-\$20970	\$2430-\$10440
	Curbs, Rails and Barriers. Repair areas of damaged curb	\$12,270	\$1240-\$5340	\$620-\$2640
	Playing Fields. Playground. Repair cracks in asphalt. Recheck in future if replacement required	\$12,270	\$1240-\$5340	\$620-\$2640
3-Medium	Insulation. Repair insulation at water heater	\$12,270	\$1240-\$5340	\$620-\$2640
	Planting. Replace plants in N playground area next to wall that are dying	\$6,240	\$670-\$2770	\$320-\$1350
3-Low	Vinyl Coverings. Minor wall vinyl repair. Most walls are vinyl	\$5,930	\$680-\$2580	\$300-\$1280

Estimated Total Construction Costs (in 2019 Dollars): \$1,436,680 Estimated Project Management Costs Range: \$144,290 - \$618,790 Estimated Inflation Range: \$71,910 - \$308,940


Estimated Total Project Costs: \$1,652,880 - \$2,364,410




8780 Venneford Ranch Road Highlands Ranch, CO 80126 Highlands Ranch High School Feeder Area, K-6 Funded by 1993 Bond Opened in 1995

Site Acreage: 8 Facility Square Feet: 51,020 Mobiles on-site: 2

# Cougar Run Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$2,080,030 Estimated Total Project Costs: \$2,393,710 - \$3,423,500



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
Tier 1	Interior Door Hardware. Replace door hardware. Current non- restricted key system.	\$164,970	\$16530-\$71030	\$8250-\$35470
	Hot Water Service. Domestic Water Heater. One in kitchen, replaced in 2006. Pumps in fair condition. Move main water heater to boiler room, prefer on demand pumps 15-20 yr life cycle.	\$16,500	\$1710-\$7110	\$830-\$3550
	Direct Expansion Systems. Roof Top Units. Replacement, code issues with outside air intake.	\$339,460	\$34050-\$146050	\$16980-\$72990
	Air Distribution Systems. Replace VAV boxes, Pneumatic VAV's, cone type, replace with DDC reheat pinch down boxes, duct work and diffusers OK.	\$282,990	\$28320-\$121720	\$14150-\$60850
2018 Bond- Under	Exhaust Ventilation Systems. Exhaust fans. Replace exhaust fans, reaching life cycle.	\$9,420	\$990-\$4090	\$480-\$2030
Construction	Controls. Upgrade control system.	\$317,250	\$31750-\$136450	\$15870-\$68210
	Switchgear-Main , Square D 1200A. Upgrade for surge suppression.	\$82,810	\$8300-\$35700	\$4140-\$17810
	Panels & Transformers. Overall good condition. Need to move Xfmr out of room behind office	\$41,460	\$4150-\$17850	\$2080-\$8920
	Emergency Light and Power Systems. Generator and Transfer Switch. Replace generator and associated equipment.	\$63,450	\$6350-\$27350	\$3180-\$13650
	Irrigation Systems. Upgrade to new controller, existing piping and heads good.	\$19,990	\$2020-\$8620	\$1000-\$4300
	Flooring Hallways/Classrooms. Replace VCT in classrooms.	\$10,470	\$1140-\$4540	\$530-\$2260
	Cafeteria Floor. Repair VCT in cafeteria. Replaced in 2007. VCT. Structural movement causing tile to separate at seams and bubble	\$960	\$150-\$450	\$50-\$210
	Flooring Kitchen. Replace red hubblelite floor with poured acrylic.	\$72,870	\$7340-\$31340	\$3650-\$15670
	Flooring Gym. Replace carpet in gym.	\$18,300	\$1910-\$7910	\$920-\$3940
	Exterior Wall Construction. Recaulk control joints.	\$3,390	\$420-\$1520	\$170-\$730
	Exterior Wall Construction. Recoat of CMU weather proofing. Many cracks in exterior wall due to lack of control joints	\$17,770	\$1840-\$7740	\$890-\$3820
	Exterior Paint. Exterior window, doors & frames need painted.	\$3,920	\$490-\$1690	\$200-\$850
2-High	Exterior Windows. Replace exterior windows	\$46,750	\$4760-\$20160	\$2340-\$10050
	Exterior Windows. Recaulk windows	\$13,220	\$1390-\$5790	\$670-\$2850
	Storefront windows. Hollow metal. Cafeteria - bottom frame rusting. East and west entries have rust developing. Some minor leaking at south entry, affecting drywall inside above doors.	\$31,200	\$3210-\$13510	\$1560-\$6710
	Retractable Partition. Repair/replace Gym/Cafeteria folding wall.	\$12,270	\$1240-\$5340	\$620-\$2640
	Fabricated Toilet partitions. Replace toilet partitions	\$23,270	\$2340-\$10040	\$1170-\$5010
	Sink Countertops. Replace sink countertops with single surface	\$21,370	\$2140-\$9240	\$1070-\$4600
	Floor drains. Replace floor drain in kitchen, poor condition, others fair.	\$960	\$150-\$450	\$50-\$210
	Theater & Stage Equipment. Gym Sound System. Upgrade gym sound system	\$5,820	\$590-\$2590	\$300-\$1250
2-Medium	Flooring Hallways/Classrooms. Replace sheet vinyl flooring in art room.	\$12,270	\$1240-\$5340	\$620-\$2640
3-High	Wall Foundations. Recaulk foundation where concrete meets	\$3,390	\$420-\$1520	\$170-\$730
3-riigii	Column Foundations. Repair structural damage from movement issues	\$13,650	\$1460-\$5960	\$690-\$2940

Estimated Total Construction Costs (in 2019 Dollars): \$2,080,030 Estimated Project Management Costs Range: \$209,540 - \$896,140 Estimated Inflation Range: \$104,140 -\$447,330

Estimated Total Project Costs: \$2,393,710 - \$3,423,500




2861 Baneberry Court Highlands Ranch, CO 80129 ThunderRidge High School Feeder Area, K-6


Funded by 1993 Bond Opened in 1995

Site Acreage: 10 Facility Square Feet: 54,220 Mobiles on-site: 1

## Coyote Creek Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$654,140 Estimated Total Project Costs: \$753,380 - \$1,077,200



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
Tier 1 Funded by the 2018 Bond	Exhaust Ventilation Systems. Exhaust Fans Replace exhaust fans.	\$102,790	\$10320-\$44220	\$5140-\$22100
	Emergency Light and Power Systems. Generator and Transfer Switch. Replace generator.	\$17,880	\$1830-\$7730	\$900-\$3850
	Flooring Kitchen. Replace.	\$74,030	\$7480-\$31880	\$3710-\$15920
	Flooring Carpet. Replace main entry walkoff carpet.	\$1,700	\$210-\$810	\$90-\$370
	Exterior Wall Construction. Recaulk control joints. Re-seal CMU	\$18,720	\$1890-\$8090	\$940-\$4030
2-High	Exterior Windows. Recaulk windows	\$13,220	\$1390-\$5790	\$670-\$2850
	Glazed Doors and Entrances. NE entry leaking at floor, much caulk has been used to alleviate the problem	\$11,000	\$1110-\$4810	\$550-\$2370
	Lavatories. Replace faucets	\$17,240	\$1770-\$7470	\$870-\$3710
	Fixed Casework. Art room counter tops need replaced	\$4,660	\$550-\$2050	\$240-\$1000
	Standard Slab on Grade. Repair crack at cafeteria slab, see flooring.	\$5,500	\$610-\$2410	\$280-\$1190
2-Medium	Flooring Cafeteria. Replace original VCT, repair crack in slab	\$16,500	\$1710-\$7110	\$830-\$3550
2-Medium	Operable Partition. Minor repairs needed on many classrooms, cafeteria/gym	\$11,640	\$1170-\$5070	\$590-\$2510
	Paving and Surfacing. Parking Lot. Repair as necessary, some cracks in 2016	\$54,990	\$5510-\$23710	\$2750-\$11830
	Wall Foundations. Recaulk foundation where concrete meets	\$3,390	\$420-\$1520	\$170-\$730
3-High	Insulation. The piping and insulation is in fair condition throughout the building. There are several areas where insulation needs replacement due to valve leaks.	\$20,630	\$2080-\$8880	\$1040-\$4440
	Playing Fields. Multi-use Field. Soccer and softball field sod has deteriorated due to high use and needs resodded. Area needs renovation	\$91,370	\$9240-\$39340	\$4570-\$19650
3-Medium	Vinyl Coverings. VWC at Art Mr. 502 needs replaced and painted	\$4,660	\$550-\$2050	\$240-\$1000
	Vinyl Coverings. Minor repairs needed, seams splitting	\$5,500	\$610-\$2410	\$280-\$1190
	Suspended Ceilings. Replace ceiling grid, much damage from from fire sprinkler install in 2010	\$164,970	\$16530-\$71030	\$8250-\$35470
4-High	Other Landscape Features. Replace metal edger at shrub beds with concrete mow band.	\$13,750	\$1460-\$5960	\$690-\$2960

Estimated Total Construction Costs (in 2019 Dollars): \$654,140 Estimated Project Management Costs Range: \$66,440 - \$282,340 Estimated Inflation Range: \$32,800 -\$140,720


Estimated Total Project Costs: \$753,380 - \$1,077,200




9195 Cresthill Lane Highlands Ranch, CO 80130 Highlands Ranch High School Feeder Area, 7-8 Funded by 1989 Bond Opened in 1990

Site Acreage:12 Facility Square Feet: 134,400 Mobiles on-site: 0

## Cresthill Middle School-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$582,520 Estimated Total Project Costs: \$670,540 - \$958,760



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
Tier 1	Switchgear-Main. Replace main switchgear.	\$121,410	\$12200-\$52300	\$6070-\$26110
Funded by the 2018 Bond	Switchgear-Main. Replace main switchgear.	\$42,300	\$4300-\$18200	\$2120-\$9100
	Panels and Transformers. Replace original panels and transformers.	\$21,150	\$2150-\$9150	\$1060-\$4550
	Exterior Wall Construction. Recaulk control joints.	\$4,660	\$550-\$2050	\$240-\$1000
2-High	Exterior Windows. Replace exterior windows	\$93,700	\$9410-\$40310	\$4690-\$20150
	Exterior Windows. Recaulk windows	\$37,440	\$3770-\$16170	\$1880-\$8050
2-Medium	Flooring Hallways/Classrooms. Replace VCT in corridors and classrooms.	\$178,190	\$17920-\$76720	\$8910-\$38320
	Flooring Kitchen. Replace kitchen flooring, original poured acrylic.	\$72,870	\$7340-\$31340	\$3650-\$15670
3-High	Wall Foundations. Recaulk foundation where concrete meets	\$3,390	\$420-\$1520	\$170-\$730
3-Low	Vinyl Coverings. Repair vinyl wall coverings as necessary	\$7,410	\$800-\$3200	\$370-\$1600


Estimated Total Construction Costs (in 2019 Dollars): \$582,520 Estimated Project Management Costs Range: \$58,860 - \$250,960 Estimated Inflation Range: \$29,160 - \$125,280

Estimated Total Project Costs: \$670,540 - \$958,760


961 South Plum Creek Boulevard Castle Rock, CO 80104 Douglas County High School Feeder Area, 9-12 Funded by Certificate of Participation **Building Purchased: 2002** 

Site Acreage: 3.3 Facility Square Feet: 21,725 Mobiles on-site: 0

## DC Oakes High School-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$296,650 Estimated Total Project Costs: \$341,500 - \$488,340



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
Tier 1 Funded by the 2018 Bond	Roof Finishes. Replace roof on DMO.	\$79,320	\$7990-\$34190	\$3970-\$17060
	Direct Expansion Systems. Roof top units. Replace RTUs on DMO.	\$84,600	\$8500-\$36400	\$4230-\$18190
	Controls. Upgrade control system in DCO.	\$52,880	\$5330-\$22830	\$2650-\$11370
	Switchgear-Main. Replace main switchgear in DCO.	\$28,130	\$2880-\$12180	\$1410-\$6050
	Panels and Transformers. Replace original panels and transformers in DCO.	\$9,420	\$990-\$4090	\$480-\$2030
	Fire Alarm Systems. Upgrade fire alarm system.	\$42,300	\$4300-\$18200	\$2120-\$9100

Estimated Total Construction Costs (in 2019 Dollars): \$296,650 Estimated Project Management Costs Range: \$29,990 - \$127,890 Estimated Inflation Range: \$14,860 - \$63,800

Estimated Total Project Costs: \$341,500 - \$488,340




Castle Rock, CO 80104 Douglas County High School Feeder Area, 9-12


Funded by 1960 Bond Opened in 1961

Site Acreage: 50 Facility Square Feet: 268,232 (North), 106,616 (South) Mobiles on-site: 0

## Douglas County High School-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$12,280,700 Estimated Total Project Costs: \$14,135,870 - \$20,214,910



Estimated Total Construction Costs (in 2019 Dollars): \$12,280,700 Estimated Project Management Costs Range: \$1,240,200 - \$5,293,100 Estimated Inflation Range: \$614,970 - \$2,641,110

Estimated Total Project Costs: \$14,135,870 - \$20,214,910




7716 Timberline Road Lone Tree, CO 80124 Highlands Ranch High School Feeder Area, K-6


Funded by 1984 Bond Opened in 1989

Site Acreage: 8 Facility Square Feet: 53,237 Mobiles on-site: 3

## Eagle Ridge Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$2,141,330 Estimated Total Project Costs: \$2,463,740 - \$3,523,710



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Direct Expansion Systems. Roof top units. Replace RTU's.	\$317,250	\$31750-\$136450	\$15870-\$68210
	Air Distribution Systems. Upgrade VAVs.	\$456,206	\$45700-\$196200	\$22810-\$98090
Tier 1	Switchgear-Main. Replace main switchgear.	\$46,742	\$4760-\$20160	\$2340-\$10050
Funded by the 2018 Bond	Panels and Transformers. Replace panels and transformers.	\$46,742	\$4760-\$20160	\$2340-\$10050
	Fire Alarm Systems. Upgrade fire alarm system.	\$105,750	\$10650-\$45550	\$5290-\$22740
	Controls. Upgrade control system.	\$317,250	\$31750-\$136450	\$15870-\$68210
Tier 2 Funded by the 2018 Bond	Flooring Carpet. Replace carpet.	\$317,250	\$31750-\$136450	\$15870-\$68210
	Flooring Kitchen. Replace epoxy floor with MMA.	\$63,450	\$6350-\$27350	\$3180-\$13650
2-High	Flooring Cafeteria. Replace VCT.	\$14,086	\$1420-\$6120	\$710-\$3030
	Exterior Windows. Replace exterior windows	\$70,218	\$7090-\$30290	\$3520-\$15100
	Flooring Cafeteria. Replace VCT.	\$18,295	\$1910-\$7910	\$920-\$3940
	Retractable Partition. Refurbish operable partitions as necessary. Gym/cafeteria in poor shape.	\$12,267	\$1240-\$5340	\$620-\$2640
	Water Closets. Replace toilets	\$24,323	\$2480-\$10480	\$1220-\$5230
2-Medium	Urinals. Replace urinals	\$17,132	\$1770-\$7370	\$860-\$3690
2 Medium	Lavatories. Replace lavatories	\$12,267	\$1240-\$5340	\$620-\$2640
	Fixed Casework. Replace all original fixed casework in classrooms and offices	\$178,189	\$17920-\$76720	\$8910-\$38320
	Paving & Surfacing, Parking Lot. Repair service drive concrete cracking	\$5,816	\$590-\$2590	\$300-\$1250
3-High	Wall Foundations. Recaulk foundation where concrete meets	\$3,384	\$420-\$1520	\$170-\$730
	Playing Fields. Multi-use Field. Renovate multi-use field	\$91,368	\$9240-\$39340	\$4570-\$19650
3-Low	Vinyl Coverings. Repair vinyl walls as necessary	\$5,922	\$680-\$2580	\$300-\$1280
	Seeding & Sodding. Resod/reseed grass areas	\$5,816	\$590-\$2590	\$300-\$1250
4-High	Other Landscape Features. Replace metal edging with concrete mow strip	\$11,527	\$1180-\$4980	\$580-\$2480

Estimated Total Construction Costs (in 2019 Dollars): \$2,141,330 Estimated Project Management Costs Range: \$215,240 - \$921,940 Estimated Inflation Range: \$107,170 - \$460,440

Estimated Total Project Costs: \$2,463,740 - \$3,523,710




1305 Timbervale Trail Highlands Ranch, CO 80126 ThunderRidge High School Feeder Area, K-6


Funded by 2000 Bond Opened in 2001

Site Acreage: 10 Original square feet: 51,688 Mobiles on-site: 2

## Eldorado Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$2,288,030 Estimated Total Project Costs: \$2,632,780 - \$3,765,370



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Roofing. Paint metal roof.	\$5,080	\$530-\$2230	\$260-\$1100
	Roof Finishes. Replace .045 EPDM ballasted roof with .060 EPDM fully adhered.	\$793,130	\$79380-\$341080	\$39660-\$170530
	Glazed Roof Openings. Skylights. Re-glaze skylights.	\$29,510	\$3000-\$12700	\$1480-\$6350
	Interior Door hardware. Replace current non-restricted key system with restricted. Hardware change.	\$164,970	\$16530-\$71030	\$8250-\$35470
	Controls. Upgrade control system.	\$317,250	\$31750-\$136450	\$15870-\$68210
Tier 1	Fire Alarm Systems. Upgrade fire alarm system.	\$105,750	\$10650-\$45550	\$5290-\$22740
Funded by the	Emergency Light and Power Systems. Generator and Transfer Switch. Replace generator and associated equipment.	\$63,450	\$6350-\$27350	\$3180-\$13650
	Emergency Light and Power Systems. Generator and Transfer Switch. Replace generator and associated equipment.	\$63,450	\$6350-\$27350	\$3180-\$13650
	Boiler Room Piping and Specialties. Replace boiler pumps and piping around them.	\$26,440	\$2670-\$11470	\$1330-\$5690
	Chilled Water Systems. Chiller, cooling tower. Replace cooling tower.	\$63,450	\$6350-\$27350	\$3180-\$13650
	Flooring Restroom. Replace sheet vinyl flooring with MMA.	\$29,510	\$3000-\$12700	\$1480-\$6350
	Exterior Wall Construction. Recaulk control joints. Re-seal masonry CMU	\$26,230	\$2680-\$11380	\$1320-\$5640
	Exterior Windows. Recaulk windows	\$13,750	\$1460-\$5960	\$690-\$2960
	Solid Exterior Doors. Paint exterior doors	\$530	\$80-\$280	\$30-\$120
2-High	Sink Countertops. Replace sink countertops with single surface	\$21,370	\$2140-\$9240	\$1070-\$4600
2-riigii	Paving & Surfacing. Bus Loop. Resurface asphalt bus loop	\$24,540	\$2470-\$10570	\$1230-\$5280
	Paving and Surfacing. Parking Lot. Resurface asphalt parking lot	\$78,680	\$7930-\$33930	\$3940-\$16920
	Curbs, Rails and Barriers. Repair/replace areas of curb.	\$5,080	\$530-\$2230	\$260-\$1100
	Paving and Surfacing. Sidewalks. Repair/replace sections of sidewalk as necessary	\$9,950	\$1060-\$4360	\$500-\$2140
	Playing Fields. Playground. Replace asphalt playground	\$29,510	\$3000-\$12700	\$1480-\$6350
	Flooring Kitchen. Repair and deep clean kitchen floor	\$15,870	\$1640-\$6840	\$800-\$3410
	Flooring Hallways/Classrooms. Replace VCT in classrooms.	\$7,940	\$870-\$3470	\$400-\$1710
	Flooring Gym. Replace gym carpet.	\$15,870	\$1640-\$6840	\$800-\$3410
2-Medium	Flooring Cafeteria. Replace VCT.	\$15,870	\$1640-\$6840	\$800-\$3410
	Flooring Carpet. Replace carpet.	\$317,250	\$31750-\$136450	\$15870-\$68210
	Window Storefronts. Re-glaze all storefronts as necessary to stop water infiltration	\$7,940	\$870-\$3470	\$400-\$1710
	Fabricated Toilet Partitions. Replace toilet partitions	\$23,480	\$2430-\$10130	\$1180-\$5050
3-High	Wall Foundations. Recaulk foundation where concrete meets	\$3,600	\$410-\$1610	\$180-\$780
3-Medium	Operable Partition. Repair operable partition between gym and cafeteria	\$2,650	\$360-\$1160	\$140-\$570
J Carain	Vinyl Coverings. Repair/replace areas of vinyl	\$5,930	\$680-\$2580	\$300-\$1280

Estimated Total Construction Costs (in 2019 Dollars): \$2,288,030 Estimated Project Management Costs Range: \$230,200 - \$985,300 Estimated Inflation Range: \$114,550 - \$492,040


Estimated Total Project Costs: \$2,632,780 - \$3,765,370




104 Lovington Street Castle Rock, CO 80104 Douglas County High School Feeder Area, K-6 Funded by 2000 Bond Opened in 2003

Site Acreage: 10 Facility Square Feet: 56,566 Mobiles on-site: 3

## Flagstone Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$2,176,060 Estimated Total Project Costs: \$2,503,590 - \$3,580,920



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Roof Finishes. Replace .045 ballasted EPDM with .060 fully adhered.	\$793,130	\$79380-\$341080	\$39660-\$170530
	Controls. Replace Trane controls with Delta.	\$317,250	\$31750-\$136450	\$15870-\$68210
	Clock and Program Systems. Upgrade clock system.	\$21,680	\$2230-\$9430	\$1090-\$4670
	Fire Alarm Systems. Upgrade fire alarm system.	\$116,330	\$11680-\$50080	\$5820-\$25010
Tier 1 Funded by the	Emergency Light and Power Systems. Generator and Transfer Switch. Replace generator and associated equipment.	\$63,450	\$6350-\$27350	\$3180-\$13650
2018 Bond	Hot Water Service. Water Heater. Replace domestic water heater and associated piping	\$89,150	\$8960-\$38360	\$4460-\$19170
	Chilled Water Systems. Upgrade chiller	\$52,880	\$5330-\$22830	\$2650-\$11370
	Chilled Water Systems. Chiller, cooling tower. Replace cooling tower.	\$84,600	\$8500-\$36400	\$4230-\$18190
	Package Units. Replace cabinet heater in fire sprinkler room.	\$1,910	\$200-\$900	\$100-\$410
2-High	Exterior Wall Construction. Recaulk building control joints. Seal CMU	\$26,760	\$2750-\$11550	\$1340-\$5760
	Flooring Restroom. Replace sheet vinyl with poured acrylic.	\$31,310	\$3200-\$13500	\$1570-\$6730
	Flooring Gym. Replace gym carpet.	\$15,710	\$1600-\$6800	\$790-\$3380
	Flooring Carpet. Replace carpet.	\$317,250	\$31750-\$136450	\$15870-\$68210
	Paint Exterior. Paint exterior trim, windows and doors	\$8,990	\$920-\$3920	\$450-\$1940
	Exterior Windows. Recaulk windows	\$14,810	\$1500-\$6400	\$740-\$3190
2-Medium	Solid Exterior Doors. Recaulk door frames	\$1,060	\$150-\$550	\$60-\$230
	Sink Countertops. Replace sink countertops with single surface	\$21,370	\$2140-\$9240	\$1070-\$4600
	Sinks. Replace with sink countertops, single surface	\$13,440	\$1370-\$5870	\$680-\$2890
	Paving & Surfacing. Bus Loop. Resurface asphalt bus loop	\$26,760	\$2750-\$11550	\$1340-\$5760
	Paving and Surfacing. Parking Lot. Resurface asphalt parking lot	\$80,270	\$8040-\$34540	\$4020-\$17260
2 Mardian	Wall Foundations. Recaulk areas where concrete meets foundation walls	\$3,390	\$420-\$1520	\$170-\$730
3-Medium	Vinyl Coverings. Repair areas of vinyl wall covering	\$3,280	\$430-\$1430	\$170-\$710
	Playing Fields. Multi-use Field. Renovate multi-use field	\$71,280	\$7230-\$30730	\$3570-\$15330

Estimated Total Construction Costs (in 2019 Dollars): \$2,176,060 Estimated Project Management Costs Range: \$218,630 - \$936,930 Estimated Inflation Range: \$108,900 - \$467,930


Estimated Total Project Costs: \$2,503,590 - \$3,580,920




6585 Collegiate Drive Highlands Ranch, CO 801306 Highlands Ranch High School Feeder Area, K-6 Funded by 1993 Bond Opened in 1995

Site Acreage: 12 Facility Square Feet: 54,226 Mobiles on-site: 2

## Fox Creek Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$330,840 Estimated Total Project Costs: \$381,360 - \$545,160



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
Tier 1	Roof Finishes. Replace seals at main corridor skylights.	\$6,670	\$740-\$2940	\$340-\$1440
Funded by the 2018 Bond	Emergency Light and Power Systems. Generator and Transfer Switch. Replace generator.	\$17,880	\$1830-\$7730	\$900-\$3850
	Flooring Carpet. New walkoff carpeting at entries.	\$5,500	\$610-\$2410	\$280-\$1190
	Flooring Kitchen. Replace kitchen flooring with MMA.	\$59,540	\$5970-\$25670	\$2980-\$12810
	Flooring Hallways/Classrooms. Replace VCT in classrooms.	\$28,660	\$2950-\$12350	\$1440-\$6170
2-High	Special Foundations. Pre-school slab sinking, repair	\$2,750	\$360-\$1260	\$140-\$600
2-riigii	Exterior Wall Construction. Recaulk control joints. Re-seal CMU	\$18,720	\$1890-\$8090	\$940-\$4030
	Exterior Windows. Recaulk windows	\$13,220	\$1390-\$5790	\$670-\$2850
	Sink Countertops. Replace sink countertops with single surface	\$21,370	\$2140-\$9240	\$1070-\$4600
2-Medium	Flooring Gym. Original, replace carpet.	\$16,500	\$1710-\$7110	\$830-\$3550
2-Medium	Flooring Cafeteria. Original, replace VCT.	\$16,500	\$1710-\$7110	\$830-\$3550
3-High	Wall Foundations. Recaulk foundation where concrete meets	\$3,390	\$420-\$1520	\$170-\$730
3 mg	Playing Fields. Multi-use Field. Renovate multi-use field	\$91,370	\$9240-\$39340	\$4570-\$19650
2 Madium	Vinyl Coverings. Replace vinyl covering main corridors (50%), office 507	\$5,820	\$590-\$2590	\$300-\$1250
3-Medium	Movable Furnishing, FFE. Replace pads at backstops in gym. Replace chalkboards with white boards	\$22,950	\$2360-\$9960	\$1150-\$4940

Estimated Total Construction Costs (in 2019 Dollars): \$330,840 Estimated Project Management Costs Range: \$33,910 - \$143,110 Estimated Inflation Range: \$16,610 - \$71,210

Estimated Total Project Costs: \$381,360 - \$545,160




1384 North State Highway 83 Franktown, CO 80116 Ponderosa High School Feeder Area, K-5 Funded by 1978 Bond Opened in 1980


Site Acreage: 23 Facility Square Feet: 36,147 Mobiles on-site: 1

\$1,500,000

# Franktown Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$2,537,490 Estimated Total Project Costs: \$2,920,020 - \$4,175,820



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Roof Finishes. Silver coat parapet walls.	\$4,870	\$540-\$2140	\$250-\$1050
	Controls. Upgrade control system.	\$264,380	\$26530-\$113730	\$13220-\$56850
	Clock and Program Systems. Upgrade clock system.	\$21,680	\$2230-\$9430	\$1090-\$4670
	Fire Alarm Systems. Upgrade fire alarm system.	\$105,750	\$10650-\$45550	\$5290-\$22740
Tier 1 Funded by the	Irrigation Systems. Upgrade entire system to district standard	\$83,550	\$8360-\$35960	\$4180-\$17970
2018 Bond	Interior Door Hardware. Replace door hardware.	\$164,970	\$16530-\$71030	\$8250-\$35470
	Direct Expansion Systems. Roof top units. Replace RTUs.	\$370,130	\$37080-\$159180	\$18510-\$79580
	Emergency Light and Power Systems. Generator and Transfer Switch. Install new generator and associated emergency systems.	\$46,960	\$4750-\$20250	\$2350-\$10100
	Fabricated Toilet Partitions. Replace toilet partitions when flooring replaced.	\$18,930	\$1980-\$8180	\$950-\$4070
	Flooring Restroom. Replace ceramic tile with MMA.	\$34,480	\$3530-\$14830	\$1730-\$7420
	Flooring Kitchen. Replace kitchen flooring.	\$88,520	\$8890-\$38090	\$4430-\$19030
	Exterior Wall Construction. CMU and Brick. Recaulk control joints, repair grout, repair masonry	\$6,980	\$720-\$3030	\$350-\$1510
	Exterior Windows. Recaulk windows	\$15,760	\$1650-\$6850	\$790-\$3390
2-High	Window Storefronts. Repair/replace, sand/paint entry/classroom storefronts	\$14,920	\$1590-\$6490	\$750-\$3210
	Solid Exterior Doors. Sand/paint exterior doors	\$5,080	\$530-\$2230	\$260-\$1100
	Retractable Partition. Refurbish or replace all classroom partitions, good condition 2012	\$49,180	\$4930-\$21230	\$2460-\$10580
	Wash Fountains. Replace trough washing stations with sinks (6)	\$16,920	\$1780-\$7280	\$850-\$3640
	Fixed Casework. Replace older casework	\$221,020	\$22190-\$95090	\$11060-\$47520
	Paving and Surfacing. Sidewalks. Repair/replace sections of sidewalk as necessary	\$9,950	\$1060-\$4360	\$500-\$2140
2-Medium	Roof Eaves and Soffits. Repair front entry soffit, causing damage to drywall	\$2,120	\$290-\$990	\$110-\$460
	Wall Foundations. Recaulk foundation where concrete meets	\$8,040	\$870-\$3470	\$410-\$1730
3-High	Playing Fields. Multi-use Field. Renovate play field and other site improvements	\$257,720	\$25790-\$110890	\$12890-\$55410
	Playing Fields. Multi-use Field. Install new synthetic turf for multi-use field	\$294,620	\$29480-\$126790	\$14740-\$63350
	Vinyl Coverings. Repair/replace vinyl coverings	\$5,930	\$680-\$2580	\$300-\$1280
3-Medium	Vinyl Coverings. Repair/replace vinyl wall covering as necessary	\$5,290	\$620-\$2320	\$270-\$1140
	Fire Sprinkler Water Supply. Fire sprinkle building	\$392,650	\$39350-\$168850	\$19640-\$84420
3-Low	Seeding and Sodding. Front grass area very bad condition at time of assessment	\$10,580	\$1130-\$4630	\$530-\$2280
3-LOW	Planting. Many dead plants and bushes. Remove/replace	\$10,580	\$1130-\$4630	\$530-\$2280
4-High	Seeding and Sodding. Renovate grass area around school.	\$5,930	\$680-\$2580	\$300-\$1280

Estimated Total Construction Costs (in 2019 Dollars): \$2,537,490 Estimated Project Management Costs Range: \$255,540 - \$1,092,660 Estimated Inflation Range: \$126,990 - \$545,670


Estimated Total Project Costs: \$2,920,020 - \$4,175,820




23919 East Canterberry Trail Parker, CO 80138 Legend High School Feeder Area, K-5 Funded by 2000 Bond Opened in 2003

Site Acreage:10 Facility Square Feet: 55,868 Mobiles on-site: 3

## Frontier Valley Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$2,417,820 Estimated Total Project Costs: \$2,781,840 - \$3,978,850



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Roof Finishes. Replace .045 EPDM ballasted roof with .060 EPDM fully adhered.	\$793,130	\$79380-\$341080	\$39660-\$170530
	Controls. Upgrade control system.	\$317,250	\$31750-\$136450	\$15870-\$68210
	Fire Alarm Systems. Upgrade fire alarm system.	\$105,750	\$10650-\$45550	\$5290-\$22740
Tier 1 Funded by the	Emergency Light and Power Systems. Generator and Transfer Switch. Replace generator and associated equipment.	\$63,450	\$6350-\$27350	\$3180-\$13650
2018 Bond	Roof Finishes. Paint metal roof.	\$4,870	\$540-\$2140	\$250-\$1050
	Glazed Roof Openings. Skylights. Re-glaze skylights.	\$29,510	\$3000-\$12700	\$1480-\$6350
	Insulation. Repair insulation in boiler room.	\$1,060	\$150-\$550	\$60-\$230
	Chilled Water Systems. Chiller, cooling tower. Replace cooling tower.	\$63,450	\$6350-\$27350	\$3180-\$13650
2-High	Exterior Wall Construction. Re-caulk control joints. Seal masonry CMU	\$26,230	\$2680-\$11380	\$1320-\$5640
2-riigii	Window Storefronts. Recaulk windows. Clean framing. Repair frames with moisture penetration	\$5,080	\$530-\$2230	\$260-\$1100
	Flooring Restroom. Replace sheet vinyl flooring with MMA.	\$29,510	\$3000-\$12700	\$1480-\$6350
	Flooring Restroom. Replace sheet vinyl with MMA.	\$31,730	\$3180-\$13680	\$1590-\$6830
	Flooring Gym. Replace gym carpet.	\$15,870	\$1640-\$6840	\$800-\$3410
	Flooring Gym. Replace gym carpet.	\$14,970	\$1540-\$6540	\$750-\$3220
	Flooring Carpet. Replace carpet.	\$317,250	\$31750-\$136450	\$15870-\$68210
	Flooring Carpet. Replace carpet.	\$317,250	\$31750-\$136450	\$15870-\$68210
	Exterior Windows. Recaulk windows	\$13,750	\$1460-\$5960	\$690-\$2960
	Solid Exterior Doors. Paint (4)	\$530	\$80-\$280	\$30-\$120
2-Medium	Sink Countertops. Replace sink countertops with single surface	\$21,370	\$2140-\$9240	\$1070-\$4600
	Paving & Surfacing. Bus Loop. Resurface asphalt bus loop	\$24,540	\$2470-\$10570	\$1230-\$5280
	Paving and Surfacing. Parking Lot. Resurface asphalt parking lot	\$78,680	\$7930-\$33930	\$3940-\$16920
	Curbs, Rails and Barriers. Repair/replace areas of curb.	\$5,080	\$530-\$2230	\$260-\$1100
	Paving and Surfacing. Sidewalks. Repair/replace sections of sidewalk as necessary. Areas may need to be raised	\$9,950	\$1060-\$4360	\$500-\$2140
	Playing Fields. Playground. Replace asphalt playground	\$29,510	\$3000-\$12700	\$1480-\$6350
	Wall Foundations. Re-caulk foundation where concrete meets. Building and surrounding areas showing movement.	\$3,490	\$410-\$1510	\$180-\$750
3-Medium	Upper Floor. Showing cracks through carpet, cafeteria floor moving. 2012	\$9,950	\$1060-\$4360	\$500-\$2140
	Vinyl Coverings. Repair/replace areas of vinyl	\$5,930	\$680-\$2580	\$300-\$1280
	Playing Fields. Multi-use Field. Renovate multi-use playing fie	\$78,680	\$7930-\$33930	\$3940-\$16920

Estimated Total Construction Costs (in 2019 Dollars): \$2,417,820 Estimated Project Management Costs Range: \$242,990 - \$1,041,090 Estimated Inflation Range: \$121,030 - \$519,940


Estimated Total Project Costs: \$2,781,840 - \$3,978,850




12021 South Swift Fox Way Parker, CO 80134 Legend High School Feeder Area, K-5 Funded by 2006 Bond Opened in 2008

Site Acreage:10 Facility Square Feet: 73,146 Mobiles on-site: 0

## Gold Rush Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$703,830 Estimated Total Project Costs: \$810,150 - \$1,158,470



\$1,500,000

Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	Fire Alarm Systems. Upgrade fire alarm system	\$126,900	\$12700-\$54600	\$6350-\$27290
1-Medium	Controls. Upgrade control system	\$370,130	\$37080-\$159180	\$18510-\$79580
	Exterior Wall Construction. CMU and Brick. Repair flashing on east side front entry	\$1,590	\$220-\$720	\$80-\$350
	Exterior Wall Construction. CMU and Brick. Recaulk expansion joints. Reseal CMU	\$15,870	\$1640-\$6840	\$800-\$3410
2-Medium	Paint Exterior. Paint exterior metal, poles, railings, and sunshades	\$5,290	\$620-\$2320	\$270-\$1140
	Exterior Windows. Recaulk windows	\$15,870	\$1640-\$6840	\$800-\$3410
	Paving and Surfacing. Parking Lot. Resurface parking lot	\$84,600	\$8500-\$36400	\$4230-\$18190
	Retaining Walls. Repair railing at retaining wall movement	\$7,940	\$870-\$3470	\$400-\$1710
	Playing Fields. Playground. Resurface asphalt playground	\$52,880	\$5330-\$22830	\$2650-\$11370
2-Low	Paving and Surfacing. Sidewalks. Sidewalk on north side has sunk a couple inches, needs lifted	\$7,940	\$870-\$3470	\$400-\$1710
3-Medium	Wall Foundations. Recaulk foundation where concrete meets	\$3,180	\$330-\$1430	\$160-\$690
	Vinyl Coverings. Repair areas of vinyl wall paper	\$1,060	\$150-\$550	\$60-\$230
3-Low	Seeding and Sodding. Repair areas of grass around school	\$10,580	\$1130-\$4630	\$530-\$2280

Estimated Total Construction Costs (in 2019 Dollars): \$703,830 Estimated Project Management Costs Range: \$71,080 - \$303,280 Estimated Inflation Range: \$35,240 - \$151,360


Estimated Total Project Costs: \$810,150 - \$1,158,470




3350 Summit View Parkway Highlands Ranch, CO 80126 Mountain Vista High School Feeder Area, K-6 Funded by 1997 Bond Opened in 2001

Site Acreage:10 Facility Square Feet: 51,668 Mobiles on-site: 3

### Heritage Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$1,612,980 Estimated Total Project Costs: \$1,856,230 - \$2,654,660



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Roof Finishes. Replace .045 EPDM ballasted roof with .060	\$793,130	\$79380-\$341080	\$39660-\$170530
	EPDM fully adhered.	,	, , , , , , , , , , , , , , , , , , , ,	, , , , , , , , , , , , , , , , , , , ,
	Paint Exterior. Paint metal roof. Glazed Roof Openings. Skylights. Re-glaze skylights.	\$4,870 \$29,510	\$540-\$2140 \$3000-\$12700	\$250-\$1050 \$1480-\$6350
	Interior Door hardware. Replace current non-restricted key	\$29,510	\$3000-\$12700	\$1400-\$0550
	system with restricted. Hardware change.	\$164,970	\$16530-\$71030	\$8250-\$35470
Tier 1	Fire Alarm Systems. Upgrade fire alarm system.	\$105,750	\$10650-\$45550	\$5290-\$22740
Funded by the	Emergency Light and Power Systems. Generator and	•		
2018 Bond	Transfer Switch. Replace generator and associated	\$63,450	\$6350-\$27350	\$3180-\$13650
	equipment.			
	Emergency Light and Power Systems. Generator and Transfer Switch. Replace generator and associated	\$63,450	\$6350-\$27350	\$3180-\$13650
	equipment.	\$03,430	\$0550-\$27550	\$3180-\$13030
	Chilled Water Systems. Chiller, cooling tower. Replace	\$63,450	\$6350-\$27350	\$3180-\$13650
	cooling tower.	\$05,150	\$0550 \$27550	\$3100 \$13030
	Flooring Restroom. Replace sheet vinyl flooring with MMA.	\$29,510	\$3000-\$12700	\$1480-\$6350
	Exterior Wall Construction. Recaulk control joints. Seal masonry CMU	\$26,230	\$2680-\$11380	\$1320-\$5640
	Exterior Windows. Recaulk windows	\$13,750	\$1460-\$5960	\$690-\$2960
	Solid Exterior Doors. Paint (4)	\$530	\$80-\$280	\$30-\$120
2-High	Paving & Surfacing. Bus Loop. Resurface asphalt bus loop	\$24,540	\$2470-\$10570	\$1230-\$5280
	Paving and Surfacing. Parking Lot. Resurface asphalt parking lot	\$78,680	\$7930-\$33930	\$3940-\$16920
	Curbs, Rails and Barriers. Repair/replace areas of curb.	\$5,080	\$530-\$2230	\$260-\$1100
	Paving and Surfacing. Sidewalks. Repair/replace sections of sidewalk as necessary	\$9,950	\$1060-\$4360	\$500-\$2140
	Playing Fields. Playground. Replace asphalt playground	\$29,510	\$3000-\$12700	\$1480-\$6350
2-Medium	Paint Exterior. Paint exterior metal	\$5,290	\$620-\$2320	\$270-\$1140
2.1151-	Wall Foundations. Recaulk foundation where concrete meets	\$3,490	\$410-\$1510	\$180-\$750
3-High	Playing Fields. Multi-use Field. Renovate multi-use playing field	\$78,680	\$7930-\$33930	\$3940-\$16920
3-Medium	Operable Partition. Repair operable partition between gym and cafeteria	\$2,650	\$360-\$1160	\$140-\$570
	Vinyl Coverings. Repair/replace areas of vinyl	\$5,930	\$680-\$2580	\$300-\$1280
3-Low	Seeding and Sodding. Renovate areas of grass around school	\$10,580	\$1130-\$4630	\$530-\$2280

Estimated Total Construction Costs (in 2019 Dollars): \$1,612,980 Estimated Project Management Costs Range: \$162,490 - \$694,790 Estimated Inflation Range: \$80,760 - \$346,890


Estimated Total Project Costs: \$1,856,230 - \$2,654,660




9375 Cresthill Lane Highlands Ranch, CO 80130 Highlands Ranch High School Feeder Area, 9-12 Funded by 1984 Bond Opened in 1985

Site Acreage: 70.82 Facility Square Feet: 243,408 Mobiles on-site: 0

#### Highlands Ranch High School-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$7,565,080 Estimated Total Project Costs: \$8,701,750 - \$12,446,310



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Roof Finishes. Replace .045 EPDM ballasted roof with .060 EPDM fully adhered.	\$2,040,350	\$204060-\$877360	\$102020-\$438680
	Interior Door Hardware. Replace door hardware, install restricted keysystem in 2018.	\$461,920	\$46290-\$198690	\$23100-\$99320
	Direct Expansion Systems. Roof top units. Replace RTUs.	\$1,099,800	\$110000-\$473000	\$54990-\$236460
Tier 1	Switchgear-Main. Replace main switchgear.	\$122,780	\$12330-\$52830	\$6140-\$26400
Funded by the 2018 Bond	Panels and Transformers. Replace older panels and transformers, end of lifecycle.	\$73,710	\$7400-\$31800	\$3690-\$15850
	Clock and Program Systems. Upgrade clock system.	\$29,510	\$3000-\$12700	\$1480-\$6350
	Fixed Multiple Seating. Bleachers. Replace bleachers in main gym.	\$195,640	\$19670-\$84170	\$9790-\$42070
	Irrigation Systems. Replace entire system with new design	\$490,900	\$49110-\$211110	\$24550-\$105550
	Boilers. Replace 2 boilers in E wing.	\$105,750	\$10650-\$45550	\$5290-\$22740
	Flooring Restroom. Replace sheet vinyl with MMA 4 student restrooms, coat tile restrooms with MMA.	\$29,510	\$3000-\$12700	\$1480-\$6350
	Flooring Kitchen. Replace kitchen flooring.	\$68,740	\$6970-\$29570	\$3440-\$14780
	Flooring Gym. Replace auxiliary gym floor.	\$147,310	\$14790-\$63390	\$7370-\$31680
	Flooring Cafeteria. Replace stained VCT sections.	\$5,080	\$530-\$2230	\$260-\$1100
	Exterior Wall Construction. Recaulk control joints.	\$19,990	\$2020-\$8620	\$1000-\$4300
	Exterior Windows. Replace Pella wood windows	\$49,180	\$4930-\$21230	\$2460-\$10580
	Exterior Windows. Recaulk windows	\$58,060	\$5850-\$25050	\$2910-\$12490
2-High	Window Storefronts. Reglaze storefront windows at auditorium entry. Recaulk windows	\$29,510	\$3000-\$12700	\$1480-\$6350
	Solid Exterior Doors. Paint exterior doors	\$5,080	\$530-\$2230	\$260-\$1100
	Fabricated Toilet Partitions. Replace some toilet partitions (50%)	\$56,690	\$5720-\$24420	\$2840-\$12190
	Theater and Stage Equipment. Replace auditorium seating	\$392,650	\$39350-\$168850	\$19640-\$84420
	Fixed Casework. Replace original casework, end of lifecycle	\$490,900	\$49110-\$211110	\$24550-\$105550
	Paving and Surfacing. Sidewalks. Repair/replace walkways to athletic fields	\$9,950	\$1060-\$4360	\$500-\$2140
	Flooring Gym. Sand Aux Gym.	\$15,340	\$1570-\$6670	\$770-\$3300
2-Medium	Flooring Hallways/Classrooms. Replace VCT.	\$1,142,100	\$114300-\$491200	\$57110-\$245560
	Flooring Carpet. Replace carpet.	\$237,940	\$23870-\$102370	\$11900-\$51160
	Wall Foundations. Recaulk foundation where concrete meets	\$9,100	\$1010-\$4010	\$460-\$1960
3-High	Fences and Gates. Replace all fencing around school perimeter, parking areas	\$14,920	\$1590-\$6490	\$750-\$3210
J riigii	Playing Fields. Multi-use Field. Renovate multi-use playing field	\$78,680	\$7930-\$33930	\$3940-\$16920
	Site Lighting Poles. Replace site lighting poles and fixtures (except entry)	\$29,510	\$3000-\$12700	\$1480-\$6350
3-Medium	Vinyl Coverings. Repair/replace sections of vinyl	\$14,920	\$1590-\$6490	\$750-\$3210
4-High	Seeding and Sodding. Renovate areas or sod around school	\$19,780	\$2030-\$8530	\$990-\$4260
4-Medium	Planting. Add/replace trees, bushes, other landscape plantings	\$19,780	\$2030-\$8530	\$990-\$4260

Estimated Total Construction Costs (in 2019 Dollars): \$7,565,080 Estimated Project Management Costs Range: \$758,290 - \$3,254,590 Estimated Inflation Range: \$378,380 - \$1,626,640


Estimated Total Project Costs: \$8,701,750 - \$12,446,310




20151 Tallman Drive Parker, CO 80138 Legend High School Feeder Area, K-5 Funded by 1997 Bond Opened in 1998

Site Acreage:10 Facility Square Feet: 51,676 Mobiles on-site: 1

## Iron Horse Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$1,769,670 Estimated Total Project Costs: \$2,036,810 - \$2,913,000



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Roof Finishes. Replace .045 EPDM ballasted roof with .060 EPDM fully adhered. Bridging occuring on parapret.	\$793,130	\$79380-\$341080	\$39660-\$170530
	Flashings & Trim. Roof flashing Fair condition. Replace with roof	\$4,230	\$470-\$1870	\$220-\$910
	Interior Door Hardware. Replace door hardware. Install restricted key system.	\$173,220	\$17390-\$74590	\$8670-\$37250
	Insulation. Replace insulation in places.	\$8,150	\$860-\$3560	\$410-\$1760
Tier 1	Chilled Water Systems. Chiller, cooling tower. Repair/replace cooling tower.	\$84,600	\$8500-\$36400	\$4230-\$18190
	Hot Water Distribution DHW heater needs replaced	\$18,090	\$1820-\$7820	\$910-\$3890
2018 Bond	Clock & Program Systems. Rauland Master Clock. Replace and move bell schedule.	\$19,780	\$2030-\$8530	\$990-\$4260
	Emergency Light and Power Systems. Generator and Transfer Switch. Replace generator.	\$17,880	\$1830-\$7730	\$900-\$3850
	Irrigation Systems. Upgrade controller.	\$5,820	\$590-\$2590	\$300-\$1250
	Chilled Water Systems. Chiller, cooling tower. Replace chiller.	\$296,100	\$29700-\$127400	\$14810-\$63670
	Local Area Networks. ITS/Head End Equipment. Expanded or new MDF closet (minimum 10'X10').	\$70,330	\$7080-\$30280	\$3520-\$15120
	Flooring. Restroom. Replace with poured acrylic in all restrooms	\$28,980	\$2930-\$12530	\$1450-\$6230
	Exterior Wall Construction. Seal and repair CMU. Stress cracks same as other schools. Lack of control joints	\$17,670	\$1840-\$7640	\$890-\$3800
	Exterior Wall Construction. Recaulk control joints.	\$3,390	\$420-\$1520	\$170-\$730
	Exterior Paint. Fair condition. Needs - Paint metal roof	\$8,150	\$860-\$3560	\$410-\$1760
	Exterior Windows. Recaulk windows	\$13,220	\$1390-\$5790	\$670-\$2850
2-High	Storefront windows. Repair leaks on all entrance storefronts	\$2,120	\$290-\$990	\$110-\$460
g	Fixed Walls. Repair cracks from settling at pod areas	\$5,500	\$610-\$2410	\$280-\$1190
	Retractable Partitions. Repair/replace gym/cafeteria partition. Curtains need replaced due to fire retardant life.	\$16,290	\$1720-\$7020	\$820-\$3510
	Sink Countertops. Replace sink countertops with single surface	\$21,370	\$2140-\$9240	\$1070-\$4600
	Paving & Surfacing. Sidewalks, Repair/replace sections of sidewalk as necessary	\$24,540	\$2470-\$10570	\$1230-\$5280
	Fuel Distribution. Paint gas pipe to prevent corrosion	\$640	\$70-\$370	\$40-\$140
	Flooring Kitchen. Replace kitchen flooring.	\$62,400	\$6310-\$26910	\$3120-\$13420
	Flooring Cafeteria. Replace VCT in cafeteria.	\$16,500	\$1710-\$7110	\$830-\$3550
2-Medium	Solid Exterior Doors. Repair or replace exterior doors	\$2,230	\$280-\$980	\$120-\$480
	Exhaust Ventilation Systems. Exhaust Fans. Replace exhaust fans	\$22,000	\$2210-\$9510	\$1100-\$4730
3-High	Wall Foundations. Recaulk foundation where concrete meets	\$3,390	\$420-\$1520	\$170-\$730
3 Thigh	Wall Foundations. Repair crack in foundation below window at entrance	\$1,700	\$210-\$810	\$90-\$370
	Vinyl Coverings. Repair/replace vinyl as necessary	\$8,780	\$930-\$3830	\$440-\$1890
3-Medium	Suspended Ceilings. Replace all ceiling tiles in the kitchen. (need to be food grade)	\$6,240	\$670-\$2770	\$320-\$1350
	Interceptors. Grease interceptor Good condition. Bypass if possible	\$8,150	\$860-\$3560	\$410-\$1760
4-High	Seeding and Sodding. Repair/replace areas as necessary	\$5,080	\$530-\$2230	\$260-\$1100

Estimated Total Construction Costs (in 2019 Dollars): \$1,769,670 Estimated Project Management Costs Range: \$178,520 - \$762,720 Estimated Inflation Range: \$88,620 - \$380,610

Estimated Total Project Costs: \$2,036,810 - \$2,913,000




1103 West Perry Park Avenue Larkspur, CO 80118 Castle View High School Feeder Area, K-6


Funded by 1970 Bond Opened in 1972

Site Acreage: 10 Facility Square Feet: 30,675 Mobiles on-site: 0

## Larkspur Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$1,548,100 Estimated Total Project Costs: \$1,782,000 - \$2,548,550



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Roof Finishes. Replace area E roof with .060 EPDM fully adhered.	\$30,360	\$3050-\$13150	\$1520-\$6530
	Roof Finishes. Replace section C, small ballasted portion.	\$31,730	\$3180-\$13680	\$1590-\$6830
Tier 1	Interior Door Hardware. Replace door hardware.	\$164,970	\$16530-\$71030	\$8250-\$35470
Funded by the 2018 Bond	Fire Alarm Systems. Upgrade fire alarm system.	\$95,180	\$9530-\$41030	\$4760-\$20470
2010 00110	Irrigation Systems. Replace irrigation system.	\$98,350	\$9860-\$42360	\$4920-\$21150
	Emergency Light and Power Systems. Generator and Transfer Switch. Install new generator and associated emergency systems.	\$73,710	\$7400-\$31800	\$3690-\$15850
	Fabricated Toilet Partitions. Replace when flooring replaced.	\$18,930	\$1980-\$8180	\$950-\$4070
	Flooring Restroom. Replace ceramic tile with MMA.	\$34,480	\$3530-\$14830	\$1730-\$7420
	Exterior Windows. Recaulk windows	\$7,510	\$800-\$3300	\$380-\$1620
2-High	Solid Exterior Doors. Repair, sand and paint exterior doors	\$5,080	\$530-\$2230	\$260-\$1100
2-High	Interior Doors. Replace interior doors	\$98,350	\$9860-\$42360	\$4920-\$21150
	Wash Fountains. Replace trough washing stations with sinks (2)	\$5,720	\$590-\$2490	\$290-\$1230
	Fixed Casework. Replace casework in original building	\$147,310	\$14790-\$63390	\$7370-\$31680
	Paving and Surfacing. Sidewalks. Repair/replace Sections of sidewalk, front entry asphalt.	\$14,920	\$1590-\$6490	\$750-\$3210
	Exterior Wall Construction. Repair areas of metal siding	\$9,950	\$1060-\$4360	\$500-\$2140
	Paint Exterior. Paint exterior	\$7,940	\$870-\$3470	\$400-\$1710
	Sinks. Replace 3 sinks in individual restrooms	\$1,590	\$220-\$720	\$80-\$350
2-Medium	Paving and Surfacing. Parking Lot. Repair areas of asphalt	\$52,880	\$5330-\$22830	\$2650-\$11370
	Playing Fields. Playground. Crack fill asphalt playground as necessary	\$7,940	\$870-\$3470	\$400-\$1710
2-Low	Curbs, Rails and Barriers. Repair curb at entrance/bus loop	\$5,290	\$620-\$2320	\$270-\$1140
	Wall Foundations. Recaulk foundation where concrete meets	\$5,500	\$610-\$2410	\$280-\$1190
	Column Foundations. Repair rusting columns at gym west side	\$7,510	\$800-\$3300	\$380-\$1620
	Perimeter Drainage and Insulation. Improve drainage at parking lot, mobile site, and northwest bus loop	\$41,250	\$4160-\$17760	\$2070-\$8870
3-High	Fixed Walls. Refinish all fixed walls	\$19,780	\$2030-\$8530	\$990-\$4260
	Interior Door Frames. Sand/paint door frames	\$22,210	\$2300-\$9600	\$1110-\$4780
	Suspended Ceilings. Replace grid ceiling and tile in original building	\$82,490	\$8320-\$35520	\$4130-\$17740
	Fences and Gates. Repair/replace fencing where needed, wood and metal	\$7,510	\$800-\$3300	\$380-\$1620
	Playing Fields. Multi-use Field. Renovate multi-use field	\$78,680	\$7930-\$33930	\$3940-\$16920
3-Medium	Vinyl Coverings. Repair or replace vinyl coverings	\$5,930	\$680-\$2580	\$300-\$1280
3-Medium	Fire Sprinkler Water Supply. Fire sprinkle building	\$365,050	\$36560-\$157060	\$18260-\$78490

Estimated Total Construction Costs (in 2019 Dollars): \$1,548,100 Estimated Project Management Costs Range: \$156,380 - \$667,480 Estimated Inflation Range: \$77,520 -\$332,970


Estimated Total Project Costs: \$1,782,000 - \$2,548,550




12736 South Red Rosa Circle Parker, CO 80134 Ponderosa High School Feeder Area, K-5 Funded by 2000 Bond Opened in 2003

Site Acreage:10 Facility Square Feet: 56,868 Mobiles on-site: 1

#### Legacy Point Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$2,074,400 Estimated Total Project Costs: \$2,387,050 - \$3,414,000



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Passenger Elevators. Elevator has had problems since installation. Fix elevator deficiencies.	\$22,320	\$2290-\$9690	\$1120-\$4800
	Controls. Replace Trane controls with Delta.	\$317,250	\$31750-\$136450	\$15870-\$68210
	Fire Alarm Systems. Upgrade fire alarm system.	\$116,330	\$11680-\$50080	\$5820-\$25010
Tier 1 Funded by the 2018 Bond	Emergency Light and Power Systems. Generator and Transfer Switch. Replace generator and associated equipment.	\$63,450	\$6350-\$27350	\$3180-\$13650
	Roof Finishes. Replace .045 ballasted EPDM with .060 fully adhered.	\$793,130	\$79380-\$341080	\$39660-\$170530
	Chilled Water Systems. Chiller, cooling tower. Replace cooling tower.	\$63,450	\$6350-\$27350	\$3180-\$13650
2-High	Exterior Wall Construction. Recaulk building control joints, patch cracks, water seal CMU	\$26,760	\$2750-\$11550	\$1340-\$5760
	Exterior Windows. Fix storefront window leakage	\$9,950	\$1060-\$4360	\$500-\$2140
	Flooring Restroom. Replace sheet vinyl with poured acrylic.	\$31,310	\$3200-\$13500	\$1570-\$6730
	Flooring Gym. Replace gym carpet.	\$16,920	\$1790-\$7290	\$850-\$3640
	Flooring Carpet. Replace carpet.	\$317,250	\$31750-\$136450	\$15870-\$68210
	Flooring Carpet. Replace walk off carpet at entries.	\$22,320	\$2290-\$9690	\$1120-\$4800
	Paint Exterior. Paint exterior trim, windows and doors	\$8,990	\$920-\$3920	\$450-\$1940
	Exterior Windows. Recaulk windows	\$14,810	\$1500-\$6400	\$740-\$3190
	Solid Exterior Doors. Recaulk door frames	\$1,060	\$150-\$550	\$60-\$230
2-Medium	Sink Countertops. Replace sink countertops with single surface	\$21,370	\$2140-\$9240	\$1070-\$4600
	Stair, Tread and Landing Finishes. Replace stair tread, not wearing well with discoloration	\$4,550	\$560-\$2060	\$230-\$980
	Sinks. Replace with sink countertops, single surface	\$13,440	\$1370-\$5870	\$680-\$2890
	Paving & Surfacing. Bus Loop. Resurface asphalt bus loop	\$26,760	\$2750-\$11550	\$1340-\$5760
	Paving and Surfacing. Parking Lot. Resurface asphalt parking lot	\$80,270	\$8040-\$34540	\$4020-\$17260
	Paving and Surfacing. Sidewalks. Repair/replace damage to sidewalks due to ground movement	\$17,980	\$1830-\$7830	\$900-\$3870
	Wall Foundations. Recaulk areas where concrete meets foundation walls	\$3,390	\$420-\$1520	\$170-\$730
3-Medium	Vinyl Covering. Repair areas of vinyl wall covering	\$3,280	\$430-\$1430	\$170-\$710
5-Medium	Blinds and Other Window Treatment. Replace blinds in conference room at front entry	\$4,550	\$560-\$2060	\$230-\$980
	Playing Fields. Multi-use Field. Renovate multi-use field	\$71,280	\$7230-\$30730	\$3570-\$15330
4-Medium	Other Landscape Features. Place bollards in front of conference room at front entry	\$2,230	\$280-\$980	\$120-\$480

Estimated Total Construction Costs (in 2019 Dollars): \$2,074,400 Estimated Project Management Costs Range: \$208,820 - \$893,520 Estimated Inflation Range: \$103,830 - \$446,080


Estimated Total Project Costs: \$2,387,050 - \$3,414,000




22219 Hilltop Road Parker, CO 80134 Legend High School Feeder Area, 9-12 Funded by 2003 Bond Opened in 2008

Site Acreage: 45 Facility Square Feet: 256,865 Mobiles on-site: 5

## Legend High School-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$2,848,410 Estimated Total Project Costs: \$3,276,460 - \$4,686,240



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	Fire Alarm Systems. Upgrade fire alarm system	\$370,130	\$37080-\$159180	\$18510-\$79580
1-Medium	Controls. Upgrade control system	\$1,004,630	\$100480-\$432080	\$50240-\$216000
	Flooring Carpet. Replace walkoff carpet at entries	\$5,290	\$620-\$2320	\$270-\$1140
	Exterior Wall Construction. CMU and Brick. Repair moisture penetration at F pod entrance	\$5,290	\$620-\$2320	\$270-\$1140
	Paint Exterior. Paint metal railings	\$1,590	\$220-\$720	\$80-\$350
2-Medium	Exterior Windows. Recaulk windows	\$68,740	\$6970-\$29570	\$3440-\$14780
	Paving and Surfacing. Parking Lot. Resurface asphalt areas as necessary	\$613,350	\$61350-\$263750	\$30670-\$131870
	Playing Fields. Track. Resurface track	\$317,250	\$31750-\$136450	\$15870-\$68210
	Playing Fields. Football Field. Replace artificial turf	\$423,000	\$42300-\$181900	\$21150-\$90950
2-Low	Paving and Surfacing. Sidewalks. Repair areas of sidewalk as necessarry	\$5,290	\$620-\$2320	\$270-\$1140
3-Medium	Wall Foundations. Mitigate movement at F pod (E wing). Recaulk where concrete meets exterior wall. Severe at F pod (E wing)	\$21,150	\$2150-\$9150	\$1060-\$4550
	Vinyl Coverings. Repair vinyl wall covering as necessary	\$2,120	\$290-\$990	\$110-\$460
3-Low	Seeding and Sodding. Repair areas of grass around school	\$10,580	\$1125-\$4625	\$530-\$2280

Estimated Total Construction Costs (in 2019 Dollars): \$2,848,410 Estimated Project Management Costs Range: \$285,580 - \$1,225,380 Estimated Inflation Range: \$142,470 - \$612,450


Estimated Total Project Costs: \$3,276,460 - \$4,686,240




9375 Heritage Hills Circle Lone Tree, CO 80124 Highlands Ranch High School Feeder Area, K-6 Funded by Certificate of Participation Opened in 2007

Site Acreage: 9.7 Facility Square Feet: 57,509 Mobiles on-site: 0

## Lone Tree Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars):\$1,399,870 Estimated Total Project Costs: \$1,610,650 - \$2,303,510



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	Fire Alarm Systems. Upgrade fire alarm system	\$116,330	\$11680-\$50080	\$5820-\$25010
1-Medium	Roof Finishes. Replace .045 EDPM ballasted roof with .060 EDPM fully adhered	\$793,130	\$79380-\$341080	\$39660-\$170530
	Controls. Upgrade control system	\$317,250	\$31750-\$136450	\$15870-\$68210
	Flooring Cafeteria. Repair VCT at cafeteria entrance	\$2,120	\$290-\$990	\$110-\$460
	Exterior Wall Construction. Recaulk control joints. Seal masonry CMU	\$15,870	\$1640-\$6840	\$800-\$3410
	Exterior Windows. Recaulk windows	\$12,690	\$1310-\$5510	\$640-\$2730
2-Medium	Curtain Walls Recaulk windows. Clean framing	\$12,690	\$1310-\$5510	\$640-\$2730
	Sink Countertops. Replace sink counter tops in all restrooms	\$21,370	\$2140-\$9240	\$1070-\$4600
	Paving and Surfacing. Parking Lot. Resurface/repair parking lot	\$84,600	\$8500-\$36400	\$4230-\$18190
2-Low	Paving & Surfacing, Sidewalks. Repair/replace areas of cracked sidewalk	\$5,290	\$620-\$2320	\$270-\$1140
3-Medium	Wall Foundations. Recaulk foundation where concrete meets	\$3,180	\$330-\$1430	\$160-\$690
	Operable Partition. Repair operable partition between gym and cafeteria	\$2,650	\$360-\$1160	\$140-\$570
	Vinyl Covering. Repair areas of vinyl wall covering	\$2,120	\$290-\$990	\$110-\$460
3-Low	Seeding and Sodding. Renovate grass areas around school.	\$10,580	\$1130-\$4630	\$530-\$2280


Estimated Total Construction Costs (in 2019 Dollars): \$1,399,870 Estimated Project Management Costs Range: \$140,730 - \$602,630 Estimated Inflation Range: \$70,050 - \$301,010

Estimated Total Project Costs: \$1,610,650 - \$2,303,510


9500 Stonegate Parkway Parker, CO 80134 Chaparral High School Feeder Area, K-6 Funded by 2006 Bond Opened in 2007

Site Acreage:10 Facility Square Feet: 73,146 Mobiles on-site: 2

#### Mammoth Heights Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$768,340 Estimated Total Project Costs: \$884,520 - \$1,264,760



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	Fire Alarm Systems. Upgrade fire alarm system	\$126,900	\$12700-\$54600	\$6350-\$27290
1-Medium	Controls. Upgrade control system	\$370,130	\$37080-\$159180	\$18510-\$79580
	Exterior Wall Construction. CMU and Brick. Recaulk expansion joints. Reseal CMU	\$15,870	\$1640-\$6840	\$800-\$3410
	Paint Exterior. Paint metal of sun shades, starting to peel	\$5,290	\$620-\$2320	\$270-\$1140
	Exterior Windows. Recaulk windows	\$15,870	\$1640-\$6840	\$800-\$3410
	Fixed Walls. Check crack in wall at entrance to south classrooms	\$530	\$80-\$280	\$30-\$120
2-Medium	Paving and Surfacing. Parking Lot. Resurface parking lot	\$84,600	\$8500-\$36400	\$4230-\$18190
	Retaining Walls. Repair retaining wall movement at north entry	\$37,020	\$3790-\$15990	\$1860-\$7960
	Retaining Walls. Repair leaning retaining wall on east side of playing field by baseball area	\$37,020	\$3790-\$15990	\$1860-\$7960
	Playing Fields. Playground. Resurface asphat playground	\$52,880	\$5330-\$22830	\$2650-\$11370
2-Low	Paving and Surfacing. Sidewalks. Repair/replace areas of sidewalk as necessary	\$5,290	\$620-\$2320	\$270-\$1140
3-Medium	Wall Foundations. Recaulk foundation where concrete meets.	\$3,180	\$330-\$1430	\$160-\$690
	Vinyl Coverings. Repair areas of vinyl wall paper	\$2,120	\$290-\$990	\$110-\$460
	Boiler Room Piping and Specialties. Boiler pump piping shows signs of leaking, repair	\$1,060	\$150-\$550	\$60-\$230
3-Low	Seeding and Sodding. Repair areas of grass around school	\$10,580	\$1130-\$4630	\$530-\$2280

Estimated Total Construction Costs (in 2019 Dollars): \$768,340 Estimated Project Management Costs Range: \$77,690 - \$331,190 Estimated Inflation Range: \$38,490 - \$165,230


Estimated Total Project Costs: \$884,520 - \$1,264,760




3700 Butterfield Crossing Castle Rock, CO 80109 Castle View High School Feeder Area, K-6 Funded by 1997 Bond Opened in 2000

Site Acreage: 15 Facility Square Feet: 51,668 Mobiles on-site: 1

# Meadow View Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$2,540,010 Estimated Total Project Costs: \$2,922,330 - \$4,179,950



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Roof Finishes. Replace .045 mil EPDM ballasted roof with .060 fully adhered.	\$793,130	\$79380-\$341080	\$39660-\$170530
	Door Hardware. Levers reaching end of life cycle. Replace levers. Replace non-restricted key system with restricted.	\$164,970	\$16530-\$71030	\$8250-\$35470
	Controls. Upgrade control system.	\$317,250	\$31750-\$136450	\$15870-\$68210
Tier 1	Clock and Program Systems. Replace Simplex clock system.	\$17,770	\$1840-\$7740	\$890-\$3820
Funded by the 2018 Bond	Fire Alarm Systems. Upgrade fire alarm system.	\$105,750	\$10650-\$45550	\$5290-\$22740
2016 Bollu	Emergency Light and Power Systems. Generator and Transfer Switch. Replace generator.	\$17,880	\$1830-\$7730	\$900-\$3850
	Irrigation Systems. Upgrade irrigation controller.	\$16,290	\$1720-\$7020	\$820-\$3510
	Chilled Water Systems. Chiller, cooling tower. Replace cooling tower.	\$63,450	\$6350-\$27350	\$3180-\$13650
	Local Area Networks. ITS/Head End Equipment. Expanded or new MDF closet (minimum 10'X10').	\$70,330	\$7080-\$30280	\$3520-\$15120
	Exterior Wall Construction. CMU. Re-seal CMU. Repair stress cracks from settling. Re-caulk all joints.	\$16,500	\$1710-\$7110	\$830-\$3550
	Exterior Windows. Recaulk windows	\$13,220	\$1390-\$5790	\$670-\$2850
	Window Storefronts. Repair water infiltration at storefront entrances	\$11,000	\$1110-\$4810	\$550-\$2370
	Retractable Partition. Replace operable partition at gym	\$16,290	\$1720-\$7020	\$820-\$3510
	Fabricated Toilet Partitions. Replace toilet partitions in 4 boys and 4 girls restrooms	\$23,270	\$2340-\$10040	\$1170-\$5010
2-High	Sink Countertops. Replace sink countertops with single surface	\$21,370	\$2140-\$9240	\$1070-\$4600
	Paving & Surfacing. Bus Loop. Resurface asphalt bus loop	\$86,720	\$8690-\$37390	\$4340-\$18650
	Paving and Surfacing. Parking Lot. Resurface parking lot	\$162,540	\$16270-\$69970	\$8130-\$34950
	Curbs, Rails and Barriers. Replace curb with snow curb	\$81,330	\$8180-\$34980	\$4070-\$17490
	Paving & Surfacing. Sidewalks. Repair/replace sections of sidewalk as necessary	\$54,150	\$5460-\$23360	\$2710-\$11650
	Playing Fields. Playground. Replace playground asphalt playpad	\$97,510	\$9800-\$42000	\$4880-\$20970
2-Medium	Flooring Restroom. Replace original epoxy floor.	\$51,400	\$5210-\$22110	\$2570-\$11050
Z-WEUTUIII	Flooring Kitchen. Replace epoxy floor with MMA.	\$63,450	\$6350-\$27350	\$3180-\$13650
3-High	Exterior Wall Construction. Recaulk control joints.	\$3,390	\$420-\$1520	\$170-\$730
	Playing Fields. Multi-use Field. Renovate multi-use field	\$97,510	\$9800-\$42000	\$4880-\$20970
	Vinyl Coverings. Repair in multiple locations	\$5,500	\$610-\$2410	\$280-\$1190
3-Medium	Fences and Gates. Replace dumpster enclosure with new enclosure, repair site fencing and backstop	\$162,540	\$16270-\$69970	\$8130-\$34950
	Retaining Walls. Minor repairs on retaining wall	\$5,500	\$610-\$2410	\$280-\$1190

Estimated Total Construction Costs (in 2019 Dollars): \$2,540,010 Estimated Project Management Costs Range: \$255,210- \$1,093,710

Estimated Inflation Range: \$127,110 - \$546,230

Estimated Total Project Costs: \$2,922,330 - \$4,179,950



-\$311,970


365 Mitchell Street Castle Rock, CO 80104 Douglas County High School Feeder Area, 7-8

High


Funded by 2003 Bond Opened in 2008

Site Acreage: 22 Facility Square Feet: 132,414 Mobiles on-site: 0

## Mesa Middle School-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$504,250 Estimated Total Project Costs: \$580,550 - \$830,030



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Fire Alarm Systems. Upgrade fire alarm system	\$237,940	\$23870-\$102370	\$11900-\$51160
1-High	Emergency Light and Power Systems. Generator and Transfer Switch. Replace generator and associated equipment. Resupport gas piping	\$74,030	\$7480-\$31880	\$3710-\$15920
	Flooring Carpet. Replace walkoff carpet at entries	\$5,290	\$620-\$2320	\$270-\$1140
	Exterior Wall Construction. CMU and Brick. Recaulk expansion joints. Reseal CMU	\$26,440	\$2670-\$11470	\$1330-\$5690
	Exterior Windows. Recaulk windows	\$24,330	\$2480-\$10480	\$1220-\$5230
2-Medium	Sink Countertops. Replace sink counter tops	\$40,510	\$4100-\$17500	\$2030-\$8710
	Domestic Water Supply Equipment. Check water supply, hot water mixes with cold water	\$530	\$80-\$280	\$30-\$120
	Paving and Surfacing. Parking Lot. Resurface parking area, potholes and cracks down center from entrance	\$84,600	\$8500-\$36400	\$4230-\$18190
2-Low	Paving and Surfacing. Sidewalks. Repair/replace areas of sidewalk cracks and heaving	\$5,290	\$620-\$2320	\$270-\$1140
3-Medium	Miscellaneous Structures. Markee sign, shade structures. Repair CMU at planter boxes	\$5,290	\$620-\$2320	\$270-\$1140

Estimated Total Construction Costs (in 2019 Dollars): \$504,250 Estimated Project Management Costs Range: \$51,040 - \$217,340 Estimated Inflation Range: \$25,260 - \$108,440


Estimated Total Project Costs: \$580,550 - \$830,030




10590 Mountain Vista Ridge Highlands Ranch, CO 80126 Mountain Vista High School Feeder Area, 7-8 Funded by 2000 Bond Opened in 2003

Site Acreage: 31.7 Facility Square Feet: 136,760 Mobiles on-site: 2

#### Mountain Ridge Middle School-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$2,844,660 Estimated Total Project Costs: \$3,272,850 - \$4,681,140



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Fire Alarm Systems. Upgrade fire alarm system.	\$237,940	\$23870-\$102370	\$11900-\$51160
Tier 1 Funded by the	Emergency Light and Power Systems. Generator and Transfer Switch. Replace generator and associated equipment.	\$74,030	\$7480-\$31880	\$3710-\$15920
	Roof Finishes. Replace .060 EPDM ballasted with .060 fully adhered.	\$1,057,500	\$105800-\$454800	\$52880-\$227370
2018 Bond	Chilled Water Systems. Clean cooling tower.	\$2,230	\$280-\$980	\$120-\$480
2010 20114	Chilled Water Systems. Chiller, cooling tower. Replace cooling tower.	\$63,450	\$6350-\$27350	\$3180-\$13650
	Controls. Replace Trane control system.	\$317,250	\$31750-\$136450	\$15870-\$68210
	Fixed Multiple Seating. Bleachers. Repair bleachers in gym.	\$6,770	\$740-\$2940	\$340-\$1460
2-High	Exterior Wall Construction. Recaulk building control joints, repair crack in gym wall	\$5,190	\$520-\$2320	\$260-\$1120
2 mgn	Paving and Surfacing. Parking Lot. Resurface asphalt parking lot	\$78,680	\$7930-\$33930	\$3940-\$16920
	Flooring Gym. Sand and refinish gym floor.	\$8,990	\$920-\$3920	\$450-\$1940
	Flooring Cafeteria. Replace VCT.	\$12,800	\$1310-\$5510	\$640-\$2760
	Flooring Carpet. Replace carpet.	\$687,380	\$68830-\$295630	\$34370-\$147790
	Paint Exterior. Paint exterior trim and doors	\$8,990	\$920-\$3920	\$450-\$1940
	Exterior Windows. Recaulk windows	\$25,170	\$2540-\$10840	\$1260-\$5420
	Solid Exterior Doors. Recaulk door frames	\$1,060	\$150-\$550	\$60-\$230
2-Medium	Retractable Partition. Repair operable partitions in pods. One between SPED rooms in poor shape	\$22,320	\$2290-\$9690	\$1120-\$4800
	Fabricated Toilet Partitions. Replace toilet partitions in all restrooms	\$42,300	\$4300-\$18200	\$2120-\$9100
	Sink Countertops. Replace sink countertops in all restrooms with single surface	\$38,500	\$3910-\$16610	\$1930-\$8280
	Sinks. Replace with sink countertops, single surface	\$26,760	\$2750-\$11550	\$1340-\$5760
	Paving & Surfacing. Sidewalks. Repair/replace sections of sidewalk as necessary	\$4,550	\$560-\$2060	\$230-\$980
3-High	Upper Floor. Repair prestress concrete tees at cafeteria/commons, separating causing cracks in floor and VCT damage	\$14,920	\$1590-\$6490	\$750-\$3210
3-Medium	Wall Foundations. Recaulk areas where concrete meets foundation walls	\$5,080	\$530-\$2230	\$260-\$1100
	Upper floor. Some movement occurring south of commons expansion joint. Carpet splitting, wall joint seperation	\$8,990	\$920-\$3920	\$450-\$1940
	Vinyl Coverings. Repair areas of vinyl wall covering	\$4,550	\$560-\$2060	\$230-\$980
	Playing Fields. Multi-use Field. Renovate multi-use field	\$71,280	\$7230-\$30730	\$3570-\$15330
4-Medium	Other Landscape Features. Renovate areas of landscaping around school. Many patches of bare ground	\$17,980	\$1830-\$7830	\$900-\$3870

Estimated Total Construction Costs (in 2019 Dollars): \$2,844,660 Estimated Project Management Costs Range: \$285,860 - \$1,224,760 Estimated Inflation Range: \$142,330 - \$611,720


Estimated Total Project Costs: \$3,272,850 - \$4,681,140




8502 East Pinery Parkway Parker, CO 80134 Ponderosa High School Feeder Area, K-2 Funded by 1978 Bond Opened in 1980

Site Acreage: 10 Facility Square Feet: 48,638 Mobiles on-site: 0

## Mountain View Primary School-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$2,189,120 Estimated Total Project Costs: \$2,519,160 - \$3,602,460



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Roof Finishes. Silver coat parapet walls.	\$9,520	\$990-\$4190	\$480-\$2050
	Direct Expansion Systems. Replace Rooftop Units.	\$370,130	\$37080-\$159180	\$18510-\$79580
	Controls. Upgrade control system.	\$317,250	\$31750-\$136450	\$15870-\$68210
Tier 1	Fire Alarm Systems. Upgrade fire alarm system.	\$105,750	\$10650-\$45550	\$5290-\$22740
Funded by the 2018 Bond	Irrigation Systems. Upgrade entire system to district standard	\$54,040	\$5470-\$23270	\$2710-\$11620
	Emergency Light and Power Systems. Generator and Transfer Switch. Install new generator and associated emergency systems.	\$73,710	\$7400-\$31800	\$3690-\$15850
	Fabricated Toilet Partitions. Replace when flooring replaced.	\$18,930	\$1980-\$8180	\$950-\$4070
	Flooring Restroom. Replace ceramic tile with MMA.	\$34,480	\$3530-\$14830	\$1730-\$7420
	Flooring Hallways/Classrooms. Refinish stage floor.	\$5,080	\$530-\$2230	\$260-\$1100
	Exterior Windows. Recaulk windows, repair a couple rusting through, kitchen and teachers lounge	\$16,920	\$1780-\$7280	\$850-\$3640
	Window Storefronts. Repair/replace, sand/paint entry/classroom storefronts	\$14,920	\$1590-\$6490	\$750-\$3210
	Solid Exterior Doors. Repair or refinish exterior doors	\$5,080	\$530-\$2230	\$260-\$1100
	Retractable Partitions. Refurbish or replace classroom partitions	\$49,180	\$4930-\$21230	\$2460-\$10580
	Wash Fountains. Replace trough washing stations with sinks (6)	\$16,920	\$1780-\$7280	\$850-\$3640
2-High	Fixed Casework. Replace older casework	\$147,310	\$14790-\$63390	\$7370-\$31680
	Paving & Surfacing. Bus Loop. Resurface asphalt bus loop	\$78,680	\$7930-\$33930	\$3940-\$16920
	Paving and Surfacing. Parking Lot. Resurface asphalt parking lot	\$59,010	\$6000-\$25400	\$2950-\$12690
	Curbs, Rails and Barriers. Repair/replace areas of curb. Install new curb and gutter at parking lot for better drainage. Move trash container area	\$49,180	\$4930-\$21230	\$2460-\$10580
	Paving and Surfacing. Sidewalks. Repair/replace sections of sidewalk. Widen side walk at service entry area. Install drainage chase under sidewalk outside gym entry	\$29,510	\$3000-\$12700	\$1480-\$6350
	Playing Fields. Playground. Resurface asphalt playground	\$19,780	\$2030-\$8530	\$990-\$4260
2-Medium	Exterior Wall Construction. Re-caulk remaining control joints	\$2,650	\$360-\$1160	\$140-\$570
2 Ulah	Wall foundations. Caulk remaining areas where concrete meets the building	\$7,940	\$870-\$3470	\$400-\$1710
3-High	Playing Fields. Multi-use Field. Install new synthetic turf for multi-use field	\$294,620	\$29480-\$126790	\$14740-\$63350
3-Medium	Vinyl Coverings. Repair/replace vinyl wall coverings	\$5,930	\$680-\$2580	\$300-\$1280
	Fire Sprinkler Water Supply. Fire sprinkle building	\$392,650	\$39350-\$168850	\$19640-\$84420
4-High	Seeding and Sodding. Renovate grass area around school.	\$9,950	\$1060-\$4360	\$500-\$2140

Estimated Total Construction Costs (in 2019 Dollars): \$2,189,120 Estimated Project Management Costs Range: \$220,470 - \$942,580

Estimated Inflation Range: \$109,570 - \$470,760


Estimated Total Project Costs: \$2,519,160 - \$3,602,460




10585 Mountain Vista Ridge Highlands Ranch, CO 80126 Mountain Vista High School Feeder Area, 9-12 Funded by 1997 Bond Opened in 2001

Site Acreage: 93.2 Facility Square Feet: 241,604 Mobiles on-site: 2

## Mountain Vista High School-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$6,272,780 Estimated Total Project Costs: \$7,215,260 - \$10,320,470



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Roof Finishes. Replace .045 EPDM ballasted roof with .060			
	EPDM fully adhered. Roof over office and 200 pod leaks	\$2,009,250	\$200950-\$864050	\$100470-\$431990
	often. Does not include F-pod. Paint Exterior. Paint metal roof.	\$9,520	\$990-\$4190	\$480-\$2050
<b>-</b> . ,	Interior Door hardware. Replace current non-restricted key			
Tier 1 Funded by the	system with restricted. Hardware change.	\$461,920	\$46290-\$198690	\$23100-\$99320
2018 Bond	Controls. Upgrade control system.	\$951,750	\$95250-\$409350	\$47590-\$204630
	Emergency Light and Power Systems. Generator and			
	Transfer Switch. Replace generator and associated	\$84,600	\$8500-\$36400	\$4230-\$18190
	equipment.	£1,000,000	¢110000 ¢472000	#F 4000 #22C4C0
	Direct Expansion Systems. Roof top units. Replace RTUs.	\$1,099,800	\$110000-\$473000	\$54990-\$236460
Tier 2 Funded by the 2018 Bond	Flooring Carpet. Replace carpet.	\$423,000	\$42300-\$181900	\$21150-\$90950
	Flooring Restroom. Repair crack upper level main hall women's and men's restroom.	\$5,080	\$530-\$2230	\$260-\$1100
	Flooring Kitchen. Mountain Vista High School the flooring in the kitchen needs redone the cooks have slipped and fell several times this year	\$59,010	\$6000-\$25400	\$2950-\$12690
	Exterior Wall Construction. Repair cracks in CMU east wall on new wing northern area	\$3,070	\$340-\$1340	\$160-\$660
	Exterior Wall Construction. Recaulk control joints. Seal masonry CMU	\$61,230	\$6180-\$26380	\$3070-\$13170
2-High	Exterior Windows. Recaulk windows	\$74,770	\$7540-\$32240	\$3740-\$16080
	Window Curtain Walls. Recaulk/reglaze curtain wall windows	\$39,450	\$3960-\$17060	\$1980-\$8490
	Solid Exterior Doors. Paint exterior doors (8) total	\$850	\$160-\$460	\$50-\$190
	Fabricated Toilet Partitions. Repair toilet partitions as necessary	\$9,520	\$990-\$4190	\$480-\$2050
	Paving and Surfacing. Parking Lot. Resurface asphalt parking lot	\$638,210	\$63900-\$274500	\$31910-\$137220
	Paving & Surfacing. Sidewalks. Repair/replace sections of sidewalk as necessary	\$9,950	\$1060-\$4360	\$500-\$2140
	Flooring Hallways/Classrooms. Replace VCT in pod hallways, classrooms as needed.	\$79,320	\$7990-\$34190	\$3970-\$17060
2-Medium	Paint Exterior. Paint all equipment on roof, severe paint peeling	\$5,290	\$620-\$2320	\$270-\$1140
2 Medium	Site Improvements. Add additional parking and new roadways for traffic flow	\$51,720	\$5190-\$22290	\$2590-\$11120
	Retaining Walls. Repair retaining wall southeast corner of building	\$3,710	\$400-\$1600	\$190-\$800
2.1151-	Wall Foundations. Recaulk foundation where concrete meets	\$35,220	\$3590-\$15190	\$1770-\$7580
3-High	Playing Fields. Multi-use Field. Renovate multi-use playing field	\$117,810	\$11800-\$50700	\$5890-\$25330
	Standard Slab on Grade. Repair crack in slab where it meets upper floor, from auditorium to F pod	\$10,580	\$1130-\$4630	\$530-\$2280
3-Medium	Operable Partition. Repair operable partitions between classrooms as necessary	\$7,940	\$870-\$3470	\$400-\$1710
	Interior Doors. Refinish interior doors in high use areas.	\$5,290	\$620-\$2320	\$270-\$1140
	Vinyl Coverings. Repair/replace areas of vinyl	\$14,920	\$1590-\$6490	\$750-\$3210

Estimated Total Construction Costs (in 2019 Dollars): \$6,272,780 Estimated Project Management Costs Range: \$628,740 - \$2,698,940

Estimated Inflation Range: \$313,740 - \$1,348,750


Estimated Total Project Costs: \$7,215,260 - \$10,320,470




6598 North State Highway 83 Parker, CO 80134 Ponderosa High School Feeder Area, 3-5 Funded by 1960 Bond Opened in 1966

Site Acreage:15 Facility Square Feet: 47,660 Mobiles on-site: 0

## Northeast Intermediate School-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$2,300,090 Estimated Total Project Costs: \$2,646,950- \$3,785,260



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Roof Finishes. New blocks for roof piping, disintegrating.	\$4,870	\$540-\$2140	\$250-\$1050
	Roof Finishes. Replace 60mil ballasted roof over 1991 addition (front entry,gym and band rooms).	\$237,940	\$23870-\$102370	\$11900-\$51160
	Gutters and Downspouts. Fix gutter and downspout drainage issues.	\$9,950	\$1060-\$4360	\$500-\$2140
Tier 1	Interior Door hardware. Replace current non-restricted key system with restricted. Hardware change.	\$173,220	\$17390-\$74590	\$8670-\$37250
Funded by the 2018 Bond	Panels and Transformers. Replace original panels and transformers.	\$49,180	\$4930-\$21230	\$2460-\$10580
	Irrigation Systems. Update entire irrigation system.	\$19,780	\$2030-\$8530	\$990-\$4260
	Roof Finishes. Replace 60mil fully adhered roof over original building and art room.	\$466,360	\$46650-\$200550	\$23320-\$100270
	Emergency Light and Power Systems. Generator and Transfer Switch. Install new generator and associated emergency systems.	\$73,710	\$7400-\$31800	\$3690-\$15850
	Fabricated Toilet Partitions. Replace toilet partitions when flooring replaced.	\$18,930	\$1980-\$8180	\$950-\$4070
	Flooring Restroom. Replace ceramic tile with MMA.	\$34,480	\$3530-\$14830	\$1730-\$7420
	Flooring Kitchen. Replace poured acrylic floor in kitchen.	\$63,880	\$6430-\$27530	\$3200-\$13740
	Flooring Gym. Replace synthetic tartan floor.	\$39,450	\$3960-\$17060	\$1980-\$8490
	Flooring Cafeteria. Replace VCT in cafeteria.	\$9,520	\$990-\$4190	\$480-\$2050
	Flooring Carpet. Replace carpet.	\$216,050	\$21660-\$92960	\$10810-\$46450
	Exterior Wall Construction. Recaulk control joints, repair grout, fix crack on west side	\$34,480	\$3530-\$14830	\$1730-\$7420
	Paint Exterior. Paint CMU chiller enclosure	\$1,060	\$150-\$550	\$60-\$230
2-High	Exterior Windows. Recaulk windows	\$13,960	\$1450-\$6050	\$700-\$3010
2 mgn	Window Storefronts. Repair/replace, sand/paint entry/classroom storefronts	\$19,780	\$2030-\$8530	\$990-\$4260
	Solid Exterior Doors. Sand/paint exterior doors	\$5,080	\$530-\$2230	\$260-\$1100
	Fixed Casework. Replace all old casework	\$147,310	\$14790-\$63390	\$7370-\$31680
	Paving & Surfacing. Bus Loop. Resurface asphalt bus loop	\$78,680	\$7930-\$33930	\$3940-\$16920
	Paving and Surfacing. Parking Lot. Resurface asphalt parking lot	\$59,010	\$6000-\$25400	\$2950-\$12690
	Paving and Surfacing. Sidewalks. Repair/replace sections of sidewalk	\$24,540	\$2470-\$10570	\$1230-\$5280
	Playing Fields. Playground. Resurface playground play pads	\$29,510	\$3000-\$12700	\$1480-\$6350
2-Medium	Roof Construction. Repair laminated support beams beams	\$15,870	\$1640-\$6840	\$800-\$3410
	Site Improvements. Fix site drainage issues around building	\$19,780	\$2030-\$8530	\$990-\$4260
	Wall Foundations. Repair foundation wall on south side	\$19,780	\$2030-\$8530	\$990-\$4260
3-High	Wall Foundations. Recaulk foundation where concrete meets	\$7,620	\$790-\$3290	\$390-\$1640
3-Medium	Vinyl Coverings. Repair/replace vinyl wall coverings	\$5,930	\$680-\$2580	\$300-\$1280
3 Medium	Fire Sprinkler Water Supply. Fire sprinkle building	\$392,650	\$39350-\$168850	\$19640-\$84420
3-Low	Miscellaneous Structures. Markee sign, shade structures. Replace picnic tables front side of building	\$2,650	\$360-\$1160	\$140-\$570
4-High	Seeding and Sodding. Renovate grass areas around school.	\$5,080	\$530-\$2230	\$260-\$1100

Estimated Total Construction Costs (in 2019 Dollars): \$2,300,090 Estimated Project Management Costs Range: \$231,710 - \$990,510 Estimated Inflation Range: \$115,150 - \$494,660

Estimated Total Project Costs: \$2,646,950 - \$3,785,260


6555 Southpark Road Highlands Ranch, CO 80126 Mountain Vista High School Feeder Area, K-6

Funded by Capital Reserve Opened in 1982


Site Acreage:10 Facility Square Feet: 48,055 Mobiles on-site: 4

\$1,500,000

#### Northridge Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$1,377,380 Estimated Total Project Costs: \$1,585,520 - \$2,267,680



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Exhaust Ventilation System. Replace MUA in kitchen.	\$57,220	\$5790-\$24690	\$2870-\$12300
Tion 1	Emergency Light and Power Systems. Generator and Transfer Switch. Replace generator and associated equipment.	\$63,450	\$6350-\$27350	\$3180-\$13650
Tier 1 Funded by the 2018 Bond	Hot Water Service. Water Heater. Replace domestic water heater and associated piping	\$89,150	\$8960-\$38360	\$4460-\$19170
2010 20114	Air Distribution Systems. Air handlers. Ductwork. VAV's. Paint roof AHUs.	\$1,910	\$200-\$900	\$100-\$410
	Panels and Transformers. Replace original panels and transformers.	\$21,150	\$2150-\$9150	\$1060-\$4550
	Flooring Restroom. Replace ceramic tile with MMA.	\$34,480	\$3530-\$14830	\$1730-\$7420
	Flooring Kitchen. Replace ceramic tile floor with MMA.	\$63,450	\$6350-\$27350	\$3180-\$13650
	Paint Exterior. Exterior trim and doors need painted	\$8,040	\$870-\$3470	\$410-\$1730
	Exterior Windows. Replace exterior windows	\$70,220	\$7090-\$30290	\$3520-\$15100
2-High	Exterior Windows. Recaulk windows	\$13,220	\$1390-\$5790	\$670-\$2850
2-High	Paving & Surfacing. Bus Loop. Resurface asphalt bus loop	\$39,450	\$3960-\$17060	\$1980-\$8490
	Paving and Surfacing. Parking Lot. Resurface asphalt parking lot	\$78,680	\$7930-\$33930	\$3940-\$16920
	Playing Fields. Playground. Replace playground play pads	\$29,510	\$3000-\$12700	\$1480-\$6350
	Flooring Hallways/Classrooms. Repair VCT in art room and preschool seperating. Might be shrinking.	\$4,550	\$560-\$2060	\$230-\$980
	Flooring Carpet. Replace carpet.	\$317,250	\$31750-\$136450	\$15870-\$68210
	Exterior Wall Construction. Repair CMU and brick at corners where cracked and broken off	\$8,990	\$920-\$3920	\$450-\$1940
	Retractable Partition. Repair/replace or replace with fixed wall all operable partitions between classrooms	\$26,760	\$2750-\$11550	\$1340-\$5760
2-Medium	Fabricated Toilet Partitions. Replace toilet partitions in all restrooms, original	\$21,150	\$2150-\$9150	\$1060-\$4550
	Sinks. Replace sinks in kindergarten restrooms and restrooms by cafeteria, 4 total	\$17,980	\$1830-\$7830	\$900-\$3870
	Drinking Fountains and Coolers. Replace metal drinking fountains in hallways, 2 total	\$2,750	\$360-\$1260	\$140-\$600
	Fixed Casework. Replace all original fixed casework in classrooms and offices	\$142,560	\$14350-\$61350	\$7130-\$30650
	Paving & Surfacing. Sidewalks. Repair/replace sections of sidewalk as necessary	\$8,990	\$920-\$3920	\$450-\$1940
3-High	Wall Foundations. Recaulk foundation where concrete meets	\$3,390	\$420-\$1520	\$170-\$730
	Playing Fields. Multi-use Field. Renovate multi-use field	\$78,680	\$7930-\$33930	\$3940-\$16920
	Suspended Ceilings. Replace ceiling grid and tile in original building	\$137,480	\$13830-\$59130	\$6880-\$29560
3-Medium	Blinds and Other Window Treatment. Replace blinds at gym windows.	\$8,990	\$920-\$3920	\$450-\$1940
	Site Improvements. Repair drainage issues at front of site	\$9,950	\$1060-\$4360	\$500-\$2140
4-Medium	Seeding and Sodding. Renovate grass areas around school	\$17,980	\$1830-\$7830	\$900-\$3870

Estimated Total Construction Costs (in 2019 Dollars): \$1,377,380 Estimated Project Management Costs Range: \$139,150 - \$594,050 Estimated Inflation Range: \$68,990 - \$296,250

Estimated Total Project Costs: \$1,585,520 - \$2,267,680




10450 Stonegate Parkway Parker, CO 80134 Chaparral High School Feeder Area, K-6 Funded by 1993 Bond Opened in 1995

Site Acreage:10 Facility Square Feet: 55,016 Mobiles on-site: 4


\$1,500,000

## Pine Grove Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$632,660 Estimated Total Project Costs: \$728,470 - \$1,041,850

\$1,000,000



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
Tier 1	Exhaust Ventilation Systems. Exhaust Fans. Replace exhaust fans throughout the building.	\$114,210	\$11490-\$49190	\$5720-\$24560
Funded by the 2018 Bond	Direct Expansion Systems. Replace swamp cooling MUA unit/s with mechanical cooling.	\$79,320	\$7990-\$34190	\$3970-\$17060
	Flooring Kitchen. Replace kitchen flooring with MMA.	\$59,540	\$5970-\$25670	\$2980-\$12810
	Exterior Wall Construction. Recaulk control joints. Re-seal CMU	\$18,720	\$1890-\$8090	\$940-\$4030
	Paint. All exterior hollow metal door and window frames and doors need painted	\$8,040	\$870-\$3470	\$410-\$1730
	Exterior Windows. Recaulk windows	\$13,220	\$1390-\$5790	\$670-\$2850
2-High	Retractable Partition. Repair operable partitions in gym/cafeteria and classrooms as necessary	\$12,270	\$1240-\$5340	\$620-\$2640
	Fabricated Toilet Partitions. Replace Boys/girls and main hallway restrooms, 8 total	\$23,270	\$2340-\$10040	\$1170-\$5010
	Sink Countertops. Replace sink countertops with single surface	\$22,530	\$2280-\$9780	\$1130-\$4850
	Paving and Surfacing. Sidewalks. Slab sinking at kitchen entry	\$3,390	\$420-\$1520	\$170-\$730
	Interior Doors. Refinish interior doors	\$8,250	\$860-\$3560	\$420-\$1780
2-Medium	Paving and Surfacing. Parking Lot. Resurface asphalt parking lot	\$54,990	\$5510-\$23710	\$2750-\$11830
	Wall Foundations. Recaulk foundation where concrete meets	\$3,390	\$420-\$1520	\$170-\$730
3-High	Insulation. Repair/replace insulation in several areas due to valve leaks.	\$45,690	\$4620-\$19720	\$2290-\$9830
	Playing Fields. Multi-use Field. Renovate sod at multi-use field	\$91,370	\$9240-\$39340	\$4570-\$19650
3-Medium	Vinyl Coverings. Repair/replace 50% VWC in Main Corridors, replace art room	\$17,240	\$1770-\$7470	\$870-\$3710
4-High	Other Landscape Features. Metal edger at shrub beds should be replaced with concrete mow band. Hillside between asphalt play area and ballfield is eroding. Regrade to eliminate steep areas	\$57,220	\$5790-\$24690	\$2870-\$12300

Estimated Total Construction Costs (in 2019 Dollars): \$632,660 Estimated Project Management Costs Range: \$64,090 - \$273,090 Estimated Inflation Range: \$31,720 - \$136,100

Estimated Total Project Costs: \$728,470 - \$1,041,850




6475 East Ponderosa Drive Parker, CO 80138 Chaparral High School Feeder Area, K-6


Funded by 1978 Bond Opened in 1980

Site Acreage: 30 (North & South) Facility Square Feet: 39,687 (North), 51,938 (South) Mobiles on-site: 5

## Pine Lane Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$6,521,840 Estimated Total Project Costs: \$7,503,780 - \$10,732,680



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Co
	Controls. Upgrade control system.	\$317,250	\$31750-\$136450	\$15870-\$68210
	Direct Expansion Systems. Roof top units. Replace RTUs.	\$523,470	\$52440-\$225140	\$26180-\$112550
	Fire Alarm Systems. Upgrade fire alarm system.	\$95,180	\$9530-\$41030	\$4760-\$20470
	Gutters and Downspouts. Rework gutters and downspouts when new soffit installed.	\$14,920	\$1590-\$6490	\$750-\$3210
	Interior Door hardware. Replace current non-restricted key system with restricted. Hardware change.	\$164,970	\$16530-\$71030	\$8250-\$35470
	Irrigation Systems. Upgrade entire system to district standard	\$122,780	\$12330-\$52830	\$6140-\$26400
	Roof Construction. Replace rotted beam on the porch / partition on East side bus loop. possible hazard.	\$3,070	\$340-\$1340	\$160-\$660
	Controls. Upgrade control system.	\$317,250	\$31750-\$136450	\$15870-\$68210
Tier 1	Fire Alarm Systems. Upgrade fire alarm system.	\$105,750	\$10650-\$45550	\$5290-\$22740
Funded by the 2018 Bond	Interior Door Hardware. Replace door hardware.	\$164,970	\$16530-\$71030	\$8250-\$35470
2018 Bond	Irrigation Systems. Upgrade entire system to district standard	\$122,780	\$12330-\$52830	\$6140-\$26400
	Roof Finishes. Silver coat parapet walls, seal brick on parapet.	\$9,520	\$990-\$4190	\$480-\$2050
	Emergency Light and Power Systems. Generator and Transfer Switch. Install new generator and associated emergency systems.	\$73,710	\$7400-\$31800	\$3690-\$15850
	Roof Construction. Install new roofing system.	\$634,500	\$63500-\$272900	\$31730-\$136420
	Roof Finishes. Replace metal roof, new support system required.	\$1,057,500	\$105800-\$454800	\$52880-\$227370
	Emergency Light and Power Systems. Generator and Transfer Switch. Install new generator and associated emergency systems.	\$73,710	\$7400-\$31800	\$3690-\$15850
	Roof Finishes. Paint metal roof.	\$4,760	\$550-\$2150	\$240-\$1030
	Flooring Cafeteria. Replace VCT.	\$31,730	\$3180-\$13680	\$1590-\$6830
	Flooring Kitchen. Replace VCT with MMA. Abatement.	\$88,520	\$8890-\$38090	\$4430-\$19030
	Fabricated Toilet Partitions. Replace when flooring replaced.	\$18,930	\$1980-\$8180	\$950-\$4070
	Flooring Restroom. Replace ceramic tile in restrooms with MMA.	\$34,480	\$3530-\$14830	\$1730-\$7420
	Fabricated Toilet Partitions. Replace when flooring replaced.	\$18,930	\$1980-\$8180	\$950-\$4070
	Exterior Windows. Recaulk windows	\$7,510	\$800-\$3300	\$380-\$1620
	Fixed Casework. Replace casework in original building	\$147,310	\$14790-\$63390	\$7370-\$31680
	Glazed Doors and Entrances. Repair/replace entry storefronts	\$29,510	\$3000-\$12700	\$1480-\$6350
2-High	Paving & Surfacing. Bus Loop. Resurface asphalt bus loop	\$78,680	\$7930-\$33930	\$3940-\$16920
	Paving and Surfacing. Parking Lot. Resurface asphalt parking lot	\$78,680	\$7930-\$33930	\$3940-\$16920
	Paving and Surfacing. Sidewalks. Repair/replace sections of sidewalk, front entry	\$24,540	\$2470-\$10570	\$1230-\$5280
	Playing Fields. Playground. Replace asphalt playground	\$29,510	\$3000-\$12700	\$1480-\$6350
	Retractable Partitions. Replace gym/cafeteria partition. Refurbish or replace all classroom partitions	\$73,710	\$7400-\$31800	\$3690-\$15850
	Exterior Wall Construction. Recaulk control joints, repair grout	\$6,980	\$720-\$3030	\$350-\$1510
	Exterior Windows. Recaulk windows	\$15,760	\$1650-\$6850	\$790-\$3390
	Fixed Casework. Replace casework room 109	\$9,950	\$1060-\$4360	\$500-\$2140

Estimated Total Construction Costs (in 2019 Dollars): \$6,521,840 Estimated Project Management Costs Range: \$655,580 - \$2,808,390 Estimated Inflation Range: \$326,360 - \$1,402,450


Estimated Total Project Costs: \$7,503,780 - \$10,732,680




10881 Riva Ridge Street Parker, CO 80134 Legend High School Feeder Area, K-5 Funded by 1993 Bond Opened in 1997

Site Acreage:10 Facility Square Feet: 51,020 Mobiles on-site: 3

# Pioneer Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$1,644,420 Estimated Total Project Costs: \$1,892,450 - \$2,706,680



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Interior Door Hardware. Replace door hardware, install restricted key system.	\$164,970	\$16530-\$71030	\$8250-\$35470
	Direct Expansion Systems. Roof top units. Replace RTUs.	\$339,460	\$34050-\$146050	\$16980-\$72990
	Exhaust Ventilation Systems. Exhaust fans. Fair condition. MUA needs replaced and upgraded to DX beyond life cycle	\$60,810	\$6100-\$26200	\$3040-\$13080
Tier 1 Funded by the	Hot Water Distribution. Water Heater New Lochinvar wtr htr. Replace storage tank needs, corroded and beyond life cycle	\$7,510	\$800-\$3300	\$380-\$1620
2018 Bond	Controls. Upgrade to full DDC.	\$317,250	\$31750-\$136450	\$15870-\$68210
	Emergency Light and Power Systems. Generator and Transfer Switch. Replace generator and associated equipment.	\$63,450	\$6350-\$27350	\$3180-\$13650
	Irrigation Systems. New controller, existing piping and heads good.	\$5,820	\$590-\$2590	\$300-\$1250
	Direct Expansion Systems. Replace swamp cooling MUA unit/s with mechanical cooling.	\$79,320	\$7990-\$34190	\$3970-\$17060
	Flooring Kitchen. Replace flooring, currently Hubelite material (Red), replace with poured acrylic.	\$59,540	\$5970-\$25670	\$2980-\$12810
	Flooring Gym. Replace original carpeting.	\$18,300	\$1910-\$7910	\$920-\$3940
	Flooring Cafeteria. Replace VCT.	\$15,870	\$1640-\$6840	\$800-\$3410
	Exterior CMU and Brick. Reseal CMU. Stress cracks same as other schools. Seams are deteriorated and need re-caulking	\$17,560	\$1850-\$7650	\$880-\$3780
	Paint Exterior. Paint exterior	\$8,150	\$860-\$3560	\$410-\$1760
2-High	Exterior Windows. Recaulk windows	\$13,220	\$1390-\$5790	\$670-\$2850
	Retractable Partitions. Refurbish operable partitions. Gym/cafeteria needs replaced. Classrooms are in good shape.	\$16,290	\$1720-\$7020	\$820-\$3510
	Sink Countertops. Replace sink countertops with single surface	\$21,370	\$2140-\$9240	\$1070-\$4600
	Paving & Surfacing, Sidewalks. Repair/Replace areas of sidewalk	\$8,150	\$860-\$3560	\$410-\$1760
	Playing Fields. Playground. Replace playground play pads	\$44,310	\$4500-\$19100	\$2220-\$9530
2-Medium	Flooring Hallways/Classrooms. Replace VCT in art room.	\$7,940	\$870-\$3470	\$400-\$1710
3-High	Wall Foundations. Recaulk foundation where concrete meets	\$3,390	\$420-\$1520	\$170-\$730
3 1 11911	Movable Furnishing. FFE. Replace chalk boards with white boards	\$12,270	\$1240-\$5340	\$620-\$2640
	Vinyl Coverings-Repair vinyl wall finishes. Vinyl has a lot of tears, patches, water damage and seams coming apart in hallways and pods. Bathroom halls have colored vinyl that need replaced. All entrances need replaced.	\$4,230	\$470-\$1870	\$220-\$910
3-Medium	Suspended Ceilings. Replace all ceiling tiles in the kitchen. (need to be food grade)	\$6,560	\$750-\$2850	\$330-\$1410
	Grease Interceptor. Remove if possible	\$8,150	\$860-\$3560	\$410-\$1760
	Fire Sprinkler. Sprinkled only in cafeteria Current code requires fully sprinkled building	\$315,990	\$31620-\$135920	\$15800-\$67940
	Playing Fields. Replacement at hill area	\$24,540	\$2470-\$10570	\$1230-\$5280

Estimated Total Construction Costs (in 2019 Dollars): \$1,644,420 Estimated Project Management Costs Range: \$165,700 - \$708,600 Estimated Inflation Range: \$82,330 - \$353,660


Estimated Total Project Costs: \$1,892,450 - \$2,706,680




7007 East Bayou Gulch Road Parker, CO 80134 Ponderosa High School Feeder Area, 9-12 Funded by 1978 Bond Opened in 1982

Site Acreage: 65 Facility Square Feet: 248,300 Mobiles on-site: 0

## Ponderosa High School-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$9,547,650 Estimated Total Project Costs: \$10,983,280 - \$15,708,720



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Roof Finishes. Replace .045 ballasted EPDM areas A,K with .060 fully adhered.	\$317,250	\$31750-\$136450	\$15870-\$68210
	Boilers. Replace 2 boilers not replaced in 2016.	\$105,750	\$10650-\$45550	\$5290-\$22740
	Auxiliary Equipment. Poor to fair condition. Upgrade.	\$16,290	\$1720-\$7020	\$820-\$3510
	Direct Expansion Systems. Replace MAU #1 that serves band area with a roof top unit	\$79,320	\$7990-\$34190	\$3970-\$17060
	Exhaust Ventilation Systems. Exhaust Fans. Science, shops, industrial arts all need upgraded	\$40,820	\$4180-\$17590	\$2050-\$8780
	Hot Water Distribution. Complete upgrade, Poor condition.	\$57,220	\$5790-\$24690	\$2870-\$12300
	Glycol Distribution Systems. Poor condition. Upgrade system.	\$24,540	\$2470-\$10570	\$1230-\$5280
	Water Treatment Systems. Poor condition. All needs to be upgraded	\$16,290	\$1720-\$7020	\$820-\$3510
	Terminal Self-Contained Units. Some old units need replaced. Need evaluation or complete system redesign	\$81,640	\$8270-\$35170	\$4090-\$17560
	Package Units. Some old units need replaced. Need evaluation or complete system redesign	\$61,230	\$6180-\$26380	\$3070-\$13170
Tier 1 Funded by the	Controls. Upgrade to full DDC. Currently some pnuematic with DDC.	\$1,269,000	\$126900-\$545700	\$63450-\$272840
2010 Band	Fire Alarm Systems. Upgrade fire alarm system.	\$370,130	\$37080-\$159180	\$18510-\$79580
	Fixed Multiple Seating, Bleachers. Auxiliary gym - Replace. Main gym - Replace portable wood bleachers in upper section. Main floor bleachers are plastic and are in good condition	\$57,220	\$5790-\$24690	\$2870-\$12300
	Irrigation Systems. Replace irrigation controllers.	\$13,750	\$1460-\$5960	\$690-\$2960
	Roof Finishes. Replace .060 EPDM ballasted with .060 fully adhered.	\$1,374,750	\$137550-\$591150	\$68740-\$295580
	Passenger Elevators. Renovate elevator #1 & #2.	\$317,250	\$31750-\$136450	\$15870-\$68210
	Boiler Room Piping. Pumps need upgrading with VFD'S.	\$242,600	\$24310-\$104410	\$12130-\$52160
	Boiler Room Piping and Specialties. Poor to fair condition. Upgrade for controls if new boilers installed	\$40,820	\$4180-\$17590	\$2050-\$8780
	Chilled Water Systems. Chiller, cooling tower. Replace cooling tower.	\$63,450	\$6350-\$27350	\$3180-\$13650
	Air Distribution Systems. Air handlers, ductwork, VAV's. System needs to be re-evaluated for proper distribution	\$81,640	\$8270-\$35170	\$4090-\$17560
	Change-over Distribution System. Poor condition. All needs to be upgraded	\$32,680	\$3330-\$14130	\$1640-\$7030
	Commissioning and Re-Commissioning. System needs retest and rebalance on both air and water systems.	\$32,680	\$3330-\$14130	\$1640-\$7030
Tier 2 Funded by the 2018 Bond	Flooring Carpet. Replace carpet 80% of building. Possible abatement needed for glue.	\$1,948,770	\$194940-\$838040	\$97440-\$418990
	Flooring Hallway/Classrooms. Replace VCT that has not been replaced. Possible abatement.	\$222,710	\$22300-\$95800	\$11140-\$47890
	Flooring Restroom. Replace all Terrazzo tile. Locker room concrete floors need re-sealed. Tile in showers need deep cleaned and re-sealed.	\$3,490	\$410-\$1510	\$180-\$750
2-High	Exterior Windows. Replace all Pella wood windows. Replace/repair all other windows as necessary	\$374,150	\$37460-\$160960	\$18710-\$80450
g.i	Exterior Windows. Recaulk windows	\$46,750	\$4760-\$20160	\$2340-\$10050
	Solid Exterior Doors. Replace exterior doors	\$122,460	\$12350-\$52750	\$6130-\$26330
	Roof Hatches. Replace main roof hatch	\$2,540	\$270-\$1170	\$130-\$550
	Fabricated Toilet Partitions. Replace with solid plastic partitions in the following bathrooms, 142/144 and c164/c166 and the same for upstairs, 8 bathrooms total.	\$56,480	\$5730-\$24330	\$2830-\$12150

Estimated Total Construction Costs (in 2019 Dollars): \$9,547,650 Estimated Project Management Costs Range: \$957,990 - \$4,108,120


Estimated Inflation Range: \$477,640 - \$2,052,950

Estimated Total Project Costs: \$10,983,280 - \$15,708,720


11605 S. Bradbury Ranch Drive Parker, CO 80134 Chaparral High School Feeder Area, K-6 Funded by 1997 Bond Opened in 2001

Site Acreage: 8.6 Facility Square Feet: 51,668 Mobiles on-site: 4

# Prairie Crossing Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$2,072,900 Estimated Total Project Costs: \$2,385,150 - \$3,411,470



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Roof Finishes. Replace .045 EPDM ballasted roof with .060 EPDM fully adhered.	\$793,130	\$79380-\$341080	\$39660-\$170530
	Paint Exterior. Paint metal roof.	\$4,870	\$540-\$2140	\$250-\$1050
	Glazed Roof Openings. Skylights. Re-glaze skylights.	\$29,510	\$3000-\$12700	\$1480-\$6350
	Interior Door Hardware. Replace door hardware, install restricted key system.	\$164,970	\$16530-\$71030	\$8250-\$35470
	Controls. Upgrade control system.	\$317,250	\$31750-\$136450	\$15870-\$68210
Tier 1	Fire Alarm Systems. Upgrade fire alarm system.	\$105,750	\$10650-\$45550	\$5290-\$22740
Funded by the 2018 Bond	Emergency Light and Power Systems. Generator and Transfer Switch. Replace generator and associated equipment.	\$63,450	\$6350-\$27350	\$3180-\$13650
	Emergency Light and Power Systems. Generator and Transfer Switch. Replace generator and associated equipment.	\$63,450	\$6350-\$27350	\$3180-\$13650
	Chilled Water Systems. Chiller, cooling tower. Replace cooling tower.	\$63,450	\$6350-\$27350	\$3180-\$13650
	Exhaust Ventilation Systems. Exhaust Fans. Replace exhaust fans.	\$37,020	\$3790-\$15990	\$1860-\$7960
	Flooring. Repair flooring in kitchen area	\$3,490	\$410-\$1510	\$180-\$750
	Flooring Restroom. Replace sheet vinyl flooring with MMA.	\$29,510	\$3000-\$12700	\$1480-\$6350
	Exterior Wall Construction. Recaulk control joints. Seal masonry CMU	\$26,230	\$2680-\$11380	\$1320-\$5640
	Exterior Windows. Recaulk windows	\$13,750	\$1460-\$5960	\$690-\$2960
	Exterior Windows. Fix storefront window leakage	\$49,180	\$4930-\$21230	\$2460-\$10580
2-High	Solid Exterior Doors. Paint (4)	\$530	\$80-\$280	\$30-\$120
,	Paving & Surfacing. Bus Loop. Resurface asphalt bus loop	\$24,540	\$2470-\$10570	\$1230-\$5280
	Paving and Surfacing. Parking Lot. Resurface asphalt parking lot	\$78,680	\$7930-\$33930	\$3940-\$16920
	Curbs, Rails and Barriers. Repair/replace areas of curb.	\$5,080	\$530-\$2230	\$260-\$1100
	Paving & Surfacing. Sidewalks. Repair/replace sections of sidewalk as necessary	\$9,950	\$1060-\$4360	\$500-\$2140
	Playing Fields. Playground. Replace asphalt playground	\$29,510	\$3000-\$12700	\$1480-\$6350
2-Medium	Flooring Kitchen. Replace MMA flooring.	\$63,450	\$6350-\$27350	\$3180-\$13650
2 11:	Wall Foundations. Recaulk foundation where concrete meets	\$3,600	\$410-\$1610	\$180-\$780
3-High	Playing Fields. Multi-use Field. Renovate multi-use playing field	\$78,680	\$7930-\$33930	\$3940-\$16920
3-Medium	Operable Partition. Repair operable partitions as necessary	\$7,940	\$870-\$3470	\$400-\$1710
	Vinyl Coverings. Repair/replace areas of vinyl	\$5,930	\$680-\$2580	\$300-\$1280

Estimated Total Construction Costs (in 2019 Dollars): \$2,072,900 Estimated Project Management Costs Range: \$208,480 - \$892,780 Estimated Inflation Range: \$103,770 - \$445,790

Estimated Total Project Costs: \$2,385,150 - \$3,411,470




1731 Wildcat Reserve Parkway Highlands Ranch, CO 80129 ThunderRidge High School Feeder Area, 7-8


Funded by 1996 Bond Opened in 1997

Site Acreage: 20 Facility Square Feet: 127,951 Mobiles on-site: 0

# Ranch View Middle School-Identified Facility Projects Estimated Construction Costs (in 2018 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2018 Dollars): \$3,495,970 Estimated Total Project Costs: \$4,022,350 - \$5,753,030



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Roof Finishes. Replace roof with .060 fully adhered EPDM. Current .060 fully ballasted.	\$1,163,250	\$116350-\$500250	\$58170-\$250100
	Interior Door Hardware. Replace door hardware, install restricted key system.	\$302,450	\$30260-\$130060	\$15130-\$65030
	Hot Water Service. Water Heater. Replace domestic hot water system, heaters, pumps, and storage.	\$82,490	\$8320-\$35520	\$4130-\$17740
	Controls. Upgrade control system.	\$634,500	\$63500-\$272900	\$31730-\$136420
Tier 1 Funded by the	Clock and Program Systems. Replace current Simplex clock system.	\$22,850	\$2360-\$9860	\$1150-\$4920
2018 Bond	Emergency Light and Power Systems. Generator and Transfer Switch. Replace generator and associated equipment.	\$74,030	\$7480-\$31880	\$3710-\$15920
	Fixed Multiple Seating. Bleachers. Repair/replacement of bleachers. Structural problems.	\$44,000	\$4410-\$19010	\$2200-\$9460
	Irrigation Systems. Replace station controllers and update entire irrigation system.	\$162,540	\$16270-\$69970	\$8130-\$34950
	Local Area Networks. ITS/Head End Equipment. Expanded or new MDF closet (minimum 10'X10').	\$49,180	\$4930-\$21230	\$2460-\$10580
	Flooring Hallways/Classrooms. VCT repair in room 234.	\$1,170	\$140-\$540	\$60-\$250
	Flooring Cafeteria. Replace VCT.	\$5,500	\$610-\$2410	\$280-\$1190
	Flooring Kitchen. Replace epoxy floor with MMA.	\$74,030	\$7480-\$31880	\$3710-\$15920
	Exterior Wall Construction. Brick. Recaulk control joints and areas where there are cracks	\$5,290	\$620-\$2320	\$270-\$1140
	Exterior Windows. Recaulk windows	\$23,480	\$2430-\$10130	\$1180-\$5050
	Energy Supply. Paint gas piping, starting to corrode	\$640	\$70-\$370	\$40-\$140
2-High	Paving & Surfacing. Bus Loop. Resurface asphalt bus loop	\$54,150	\$5460-\$23360	\$2710-\$11650
	Paving and Surfacing. Parking Lot. Resurface asphalt parking lot	\$86,720	\$8690-\$37390	\$4340-\$18650
	Curbs, Rails and Gutters. Repair curb and gutter	\$27,080	\$2730-\$11730	\$1360-\$5820
	Paving and Surfacing. Sidewalks. Repair stairs on NE side of building	\$2,230	\$280-\$980	\$2460-\$10580 \$60-\$250 \$280-\$1190 \$3710-\$15920 \$270-\$1140 \$1180-\$5050 \$40-\$140 \$2710-\$11650 \$4340-\$18650 \$1360-\$5820 \$120-\$480 \$140-\$600 \$2110-\$9080 \$17330-\$74490 \$420-\$1780 \$2030-\$8710
	Fences and Gates. Repair/replace fencing at dumpster area	\$2,750	\$360-\$1260	\$140-\$600
	Flooring Restroom. Replace original sheet vinyl flooring with poured acrylic in all restrooms.	\$42,200	\$4310-\$18210	\$2110-\$9080
	Flooring Carpet. Replace carpet.	\$346,440	\$34670-\$149070	\$17330-\$74490
	Solid Exterior Doors. Repair and paint exterior doors	\$8,250	\$860-\$3560	\$420-\$1780
	Fabricated Toilet Partitions. Replace toilet partitions in all restrooms	\$40,510	\$4100-\$17500	\$2030-\$8710
2-Medium	Sink Countertops. Replace sink counter tops in all restrooms	\$40,510	\$4100-\$17500	\$2030-\$8710
	Regular Stairs. Refinish stairs at stage	\$2,230	\$280-\$980	\$120-\$480
	Exhaust Ventilation Systems. Exhaust Fans. Replace exhaust fans	\$60,490	\$6120-\$26020	\$3030-\$13010
	Playing Fields. Playground. Repair concrete at basketball court	\$8,150	\$860-\$3560	\$410-\$1760
	Wall Foundations. Recaulk foundation where concrete meets	\$4,450	\$460-\$1960	\$230-\$960
	Superstructure. Repair cracks in commons floor and areas of block due to settling	\$14,600	\$1510-\$6310	\$730-\$3140
3-High	Upper Floor. There is a crack under the carpet in the commons area. Mortar has fallen away and light can be seen through. Repair prestress flooring at commons	\$11,530	\$1180-\$4980	\$2030-\$8710 \$120-\$480 \$3030-\$13010 \$410-\$1760 \$230-\$960 \$730-\$3140 \$580-\$2480 \$710-\$3050
	Playing Fields. Multi-use field. Reseed and top dress both fields	\$14,180	\$1430-\$6130	\$710-\$3050

Estimated Total Construction Costs (in 2018 Dollars): \$3,495,970 Estimated Project Management Costs Range: \$351,390 - \$1,505,290

Estimated Inflation Range: \$174,990 - \$751,770


Estimated Total Project Costs: \$4,022,350 - \$5,753,030




9970 Glenstone Circle Highlands Ranch, CO 80130 Rock Canyon High School Feeder Area, K-5 Funded by 2000 Bond Opened in 2005

Site Acreage:11.8 Facility Square Feet: 56,868 Mobiles on-site: 3

# Redstone Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$1,291,720 Estimated Total Project Costs: \$1,486,260- \$2,126,280



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
Tier 1	Roof Finishes. Replace .045 EPDM ballasted with .060 EPDM fully adhered.	\$559,630	\$55980-\$240680	\$27990-\$120320
	Fire Alarm Systems. Upgrade fire alarm system.	\$116,330	\$11680-\$50080	\$5820-\$25010
2018 Bond	Controls. Upgrade control system.	\$317,250	\$31750-\$136450	\$15870-\$68210
	Flooring Cafeteria. Repair gap in VCT near entry area.	\$1,380	\$230-\$630	\$70-\$300
	Flooring Carpet. Replace walk off carpet squares at entries.	\$9,210	\$1000-\$4000	\$460-\$1980
	Exterior Wall Construction. CMU. Recaulk control joints	\$3,810	\$400-\$1700	\$190-\$820
	Exterior Wall Construction. CMU. CMU needs sealed. Repair cracks at joints left of main entrance and other areas	\$14,700	\$1510-\$6410	\$740-\$3160
2-Medium	Exterior WindowsRecaulk windows	\$14,700	\$1510-\$6410	\$740-\$3160
	Retractable Partition. Refurbish operable partition at gym	\$3,180	\$330-\$1430	\$160-\$690
	Sink Countertops. Replace sink countertops with single surface	\$21,370	\$2140-\$9240	\$1070-\$4600
	Paving & Surfacing. Bus Loop. Resurface asphalt bus loop	\$48,540	\$4870-\$20970	\$2430-\$10440
	Paving and Surfacing. Parking Lot. Repair asphalt as needed	\$48,540	\$4870-\$20970	\$2430-\$10440
3-High	Structural Slab on Grade. Repair crack in floor at staff restroom main floor pod	\$1,910	\$200-\$900	\$100-\$410
	Suspended Ceilings. Replace tile in kitchen. The tiles are stained and dirty	\$3,180	\$330-\$1430	\$160-\$690
	Paving and Surfacing. Sidewalks. Repair/replace sidewalk at drive through lane south end handicap curb	\$3,180	\$330-\$1430	\$160-\$690
3-Medium	Retaining Walls. Repair retaining wall north side	\$1,910	\$200-\$900	\$100-\$410
	Playing Fields. Multi-use Field. Reonvate areas of worn grass	\$97,080	\$9730-\$41830	\$4860-\$20880
	Planting. Replace dead plants on east side at stacked pods	\$6,240	\$670-\$2770	\$320-\$1350
3-Low	Paint Interior. Repair damage to column in cafeteria	\$1,380	\$230-\$630	\$70-\$300
3-LOW	Vinyl Coverings. Repair vinyl on walls as necessary	\$5,930	\$680-\$2580	\$300-\$1280
4-Medium	Seeding and Sodding. Renovate areas of worn grass	\$12,270	\$1240-\$5340	\$620-\$2640

Estimated Total Construction Costs (in 2019 Dollars): \$1,291,720 Estimated Project Management Costs Range: \$129,880 - \$556,780 Estimated Inflation Range: \$64,660 - \$277,780


Estimated Total Project Costs: \$1,486,260 - \$2,126,280




3960 Trail Boss Lane Castle Rock, CO 80104 Douglas County High School Feeder Area, K-6 Funded by 2000 Bond Opened in 2006

Site Acreage: 16 Facility Square Feet: 35,863 Mobiles on-site: 2

## Renaissance Expeditionary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$147,460 Estimated Total Project Costs: \$170,110 - \$243,240



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
Tier 1 Funded by the 2018 Bond	Fire Alarm Systems. Upgrade fire alarm system.	\$95,180	\$9530-\$41030	\$4760-\$20470
2-High	Energy Supply. Paint gas piping on roof, starting to corrode	\$640	\$70-\$370	\$40-\$140
	Flooring Hallways/Classrooms. Replace entry walkoff carpet.	\$3,390	\$420-\$1520	\$170-\$730
	Exterior Wall Construction. Precast Concrete. Repair cracks in walls	\$2,750	\$360-\$1260	\$140-\$600
	Paint Exterior. Paint exterior. All of the building is paint.	\$8,250	\$860-\$3560	\$420-\$1780
2-Medium	Solid Exterior Doors. Paint exterior doors	\$2,230	\$280-\$980	\$120-\$480
2 Medium	Sink Countertops. Resurface restoom countertops, 2 total. Main hall adult restrooms not showing as much wear.	\$6,880	\$730-\$3030	\$350-\$1480
	Paving and Surfacing. Parking Lot. Parking lot has been recently oiled and cracks filled. Cracks starting to open up again.	\$22,000	\$2210-\$9510	\$1100-\$4730
	Wall Foundations. Recaulk foundation walls	\$3,390	\$420-\$1520	\$170-\$730
3-Medium	Roof Finishes. Good condition. Repair ponding at roof access section, along wall on fully adhered section	\$2,750	\$360-\$1260	\$140-\$600

Estimated Total Construction Costs (in 2019 Dollars): \$147,460 Estimated Project Management Costs Range: \$15,240 - \$64,040 Estimated Inflation Range: \$7,410 - \$31,740


Estimated Total Project Costs: \$170,110 - \$243,240




5810 McArthur Ranch Road Highlands Ranch, CO 80124 Rock Canyon High School Feeder Area, 9-12 Funded by 1997 Bond Opened in 2003

Site Acreage: 80 Facility Square Feet: 248,055 Mobiles on-site: 0

# Rock Canyon High School-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$4,508,390 Estimated Total Project Costs: \$5,185,260 - \$7,416,830



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
Tier 1	Roof Finishes. Replace .045 ballasted EPDM with .060 fully adhered, does not include F pod.	\$2,326,500	\$232700-\$1000400	\$116330-\$500200
Funded by the	Fire Alarm Systems. Upgrade fire alarm systems.	\$370,130	\$37080-\$159180	\$18510-\$79580
2018 Bond	Controls. Upgrade control system.	\$1,004,630	\$100480-\$432080	\$50240-\$216000
	Flooring Cafeteria. VCT cracking and peeling next to windows in commons. Repair as necessary.	\$3,810	\$400-\$1700	\$190-\$820
	Flooring Gym. Sand Gym.	\$14,600	\$1510-\$6310	\$730-\$3140
	Exterior Wall Construction. CMU. Reseal CMU	\$36,490	\$3720-\$15720	\$1830-\$7850
	Exterior WindowsRecaulk windows	\$71,490	\$7220-\$30820	\$3580-\$15370
2-Medium	Site Improvements. Add additional expanded roadways and exit for traffic flow	\$25,600	\$2610-\$11010	\$1280-\$5510
	Paving and Surfacing. Parking Lot. Repair/resurface parking lots. Many cracks and potholes starting to form (2015)	\$606,380	\$60730-\$260830	\$30320-\$130370
	Paving and Surfacing. Sidewalks. Repair minor cracking and movement areas	\$12,270	\$1240-\$5340	\$620-\$2640
3-Medium	Wall Foundations. Recaulk areas where concrete meets foundation. Area outside North F pod has sunk a couple inches	\$36,490	\$3720-\$15720	\$1830-\$7850

Estimated Total Construction Costs (in 2019 Dollars): \$4,508,390 Estimated Project Management Costs Range: \$451,410 - \$1,939,110 Estimated Inflation Range: \$225,460 - \$969,330


Estimated Total Project Costs: \$5,185,260 - \$7,416,830




400 North Heritage Road Castle Rock, CO 80104 Douglas County High School Feeder Area, K-6 Funded by 1984 Bond Opened in 1988

Site Acreage: 7.5 Facility Square Feet: 53,237 Mobiles on-site: 3

## Rock Ridge Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$2,239,180 Estimated Total Project Costs: \$2,575,850 - \$3,684,480



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Roof Finishes. Replace.045 ballasted (2005) with .060 fully adhered.	\$713,820	\$71390-\$306990	\$35700-\$153470
	Direct Expansion Systems. Roof top units. Replace RTUs.	\$317,250	\$31750-\$136450	\$15870-\$68210
	Switchgear-Main. Replace main switchgear.	\$46,750	\$4760-\$20160	\$2340-\$10050
Tier 1 Funded by the	Panels and Transformers. Replace original panels and transformers.	\$46,750	\$4760-\$20160	\$2340-\$10050
2018 Bond	Clock and Program Systems. Upgrade clock system.	\$21,680	\$2230-\$9430	\$1090-\$4670
	Fire Alarm Systems. Upgrade fire alarm system.	\$105,750	\$10650-\$45550	\$5290-\$22740
	Emergency Light and Power Systems. Generator and Transfer Switch. Replace generator and associated equipment.	\$63,450	\$6350-\$27350	\$3180-\$13650
	Controls. Upgrade control system.	\$317,250	\$31750-\$136450	\$15870-\$68210
	Flooring Cafeteria. Replace VCT.	\$14,090	\$1420-\$6120	\$710-\$3030
2-High	Flooring Restroom. Replace original sheet vinyl flooring in staff restrooms.	\$1,910	\$200-\$900	\$100-\$410
	Flooring Kitchen. Replace kitchen flooring.	\$53,620	\$5390-\$23090	\$2690-\$11530
	Flooring Gym. Replace gym carpet.	\$16,660	\$1750-\$7250	\$840-\$3590
	Flooring Carpet. Replace carpet.	\$317,250	\$31750-\$136450	\$15870-\$68210
2-Medium	Sink Countertops. Replace sink countertops with single surface	\$21,370	\$2140-\$9240	\$1070-\$4600
	Fixed Casework. Replace all original fixed casework in classrooms and offices	\$178,190	\$17920-\$76720	\$8910-\$38320
3-High	Vinyl Coverings. Vinyl has a lot of tears, patches, water damage and seams coming apart in hallways and pods. Bathroom halls have colored vinyl that need replaced. All entrances need replaced.	\$3,390	\$420-\$1520	\$170-\$730


Estimated Total Construction Costs (in 2019 Dollars): \$2,239,180 Estimated Project Management Costs Range: \$224,630 - \$963,830 Estimated Inflation Range: \$112,040 - \$481,470

Estimated Total Project Costs: \$2,575,850 - \$3,684,480


11033 Monarch Boulevard Highlands Ranch, CO 80124 Rock Canyon High School Feeder Area, 6-8 Funded by 1997 Bond Opened in 2003

Site Acreage: 23.3 Facility Square Feet: 136,760 Mobiles on-site: 5

## Rocky Heights Middle School-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$4,400,370 Estimated Total Project Costs: \$5,061,970 - \$7,240,350



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
Tier 1 Funded by the	Fire Alarm Systems. Upgrade fire alarm system.	\$237,940	\$23870-\$102370	\$11900-\$51160
	Emergency Light and Power Systems. Generator and Transfer Switch. Replace generator and associated equipment.	\$74,030	\$7480-\$31880	\$3710-\$15920
	Roof Finishes. Replace .060 EPDM ballasted with .060 fully adhered.	\$1,057,500	\$105800-\$454800	\$52880-\$227370
2018 Bond	Chilled Water Systems. Chiller, cooling tower. Replace cooling tower.	\$63,450	\$6350-\$27350	\$3180-\$13650
	Controls. Replace Trane control system.	\$1,004,630	\$100480-\$432080	\$50240-\$216000
	Fixed Multiple Seating. Bleachers. Repair bleachers in gym.	\$6,770	\$740-\$2940	\$340-\$1460
2-High	Exterior Wall Construction. Recaulk building control joints	\$5,190	\$520-\$2320	\$260-\$1120
	Flooring Restroom. Replace sheet vinyl with poured acrylic.	\$53,620	\$5390-\$23090	\$2690-\$11530
	Flooring Cafeteria. Replace VCT.	\$12,800	\$1310-\$5510	\$640-\$2760
	Flooring Gym. Sand Gym.	\$14,600	\$1510-\$6310	\$730-\$3140
	Flooring Carpet. Carpet showing wear in high traffic areas. Look at replacement before lifecycle.	\$280,670	\$28140-\$120740	\$14040-\$60350
	Flooring Carpet. Replace carpet.	\$687,380	\$68830-\$295630	\$34370-\$147790
	Flooring Carpet. Replace carpet.	\$523,470	\$52440-\$225140	\$26180-\$112550
	Paint Exterior. Paint exterior trim and doors	\$8,990	\$920-\$3920	\$450-\$1940
	Exterior Windows. Recaulk windows	\$25,170	\$2540-\$10840	\$1260-\$5420
2-Medium	Solid Exterior Doors. Recaulk door frames	\$1,060	\$150-\$550	\$60-\$230
	Retractable Partition. Repair operable partitions in pods	\$17,980	\$1830-\$7830	\$900-\$3870
	Fabricated Toilet Partitions. Replace toilet partitions in all restrooms	\$40,510	\$4100-\$17500	\$2030-\$8710
	Sink Countertops. Replace sink countertops in all restrooms with single surface	\$38,500	\$3910-\$16610	\$1930-\$8280
	Sinks. Replace with sink countertops, single surface	\$26,760	\$2750-\$11550	\$1340-\$5760
	Paving and Surfacing. Parking Lot. Resurface asphalt parking lot	\$106,920	\$10790-\$45990	\$5350-\$22990
	Paving & Surfacing. Sidewalks. Repair/replace sections of sidewalk as necessary	\$4,550	\$560-\$2060	\$230-\$980
	Wall Foundations. Recaulk areas where concrete meets foundation walls	\$5,080	\$530-\$2230	\$260-\$1100
3-Medium	Upper floor. Some movement occurring south of commons expansion joint. Carpet splitting, wall joint seperation	\$8,990	\$920-\$3920	\$450-\$1940
	Vinyl Coverings. Repair areas of vinyl wall covering	\$4,550	\$560-\$2060	\$230-\$980
	Playing Fields. Multi-use Field. Renovate multi-use field	\$71,280	\$7230-\$30730	\$3570-\$15330
4-Medium	Other Landscape Features. Renovate areas of landscaping around school. Many patches of bare ground	\$17,980	\$1830-\$7830	\$900-\$3870

Estimated Total Construction Costs (in 2019 Dollars): \$4,400,370 Estimated Project Management Costs Range: \$441,480 - \$1,893,780 Estimated Inflation Range: \$220,120 - \$946,200


Estimated Total Project Costs: \$5,061,970 - \$7,240,350




7370 Village Circle East Littleton, CO 80125 ThunderRidge High School Feeder Area, 3-6 Funded by 2006 Bond Opened in 2008

Site Acreage:14 Facility Square Feet: 68,751 Mobiles on-site: 0

## Roxborough Intermediate School-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$978,670 Estimated Total Project Costs: \$1,126,090 - \$1,610,440



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	Chilled Water Systems. Chiller, cooling tower. Repair one ice storage unit that appears to be leaking water.	\$2,650	\$360-\$1160	\$140-\$570
	Fire Alarm Systems. Upgrade fire alarm system	\$126,900	\$12700-\$54600	\$6350-\$27290
1-Medium	Boiler Room Piping and Specialties. Repair piping at pumps in boiler room that are leaking	\$1,060	\$150-\$550	\$60-\$230
	Controls. Upgrade control system	\$370,130	\$37080-\$159180	\$18510-\$79580
2-High	Special Foundations. Repair retaining wall movement where it attaches to building foundation	\$54,990	\$5510-\$23710	\$2750-\$11830
	Exterior Wall Construction. CMU and Brick. Recaulk expansion joints. Reseal CMU	\$15,870	\$1640-\$6840	\$800-\$3410
2-Medium	Paint Exterior. Paint exterior metal, poles, railings, and sunshades	\$5,290	\$620-\$2320	\$270-\$1140
	Exterior Windows. Recaulk windows	\$15,870	\$1640-\$6840	\$800-\$3410
2-Low	Paving and Surfacing. Sidewalks. Repair areas of sidewalk as necessary	\$15,870	\$1640-\$6840	\$800-\$3410
3-High	Playing Fields. Multi-use Field. Install synthetic turf field in lieu of grass field.		\$35630-\$153230	\$17820-\$76600
3-Medium	Wall Foundations. Recaulk foundation where concrete meets		\$330-\$1430	\$160-\$690
3-Low	Seeding and Sodding. Repair areas of grass around school	\$10,580	\$1130-\$4630	\$530-\$2280

Estimated Total Construction Costs (in 2019 Dollars): \$978,670 Estimated Project Management Costs Range: \$98,430 - \$421,330 Estimated Inflation Range: \$48,990 - \$210,440

Estimated Total Project Costs: \$1,126,090 - \$1,610,440




8000 Village Circle West Littleton, CO 80125 ThunderRidge High School Feeder Area, K-2 Funded by 1989 Bond Opened in 1991

Site Acreage: 12.4 Facility Square Feet: 53,491 Mobiles on-site: 0


\$1,500,000

# Roxborough Primary School-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$642,920 Estimated Total Project Costs: \$740,680 - \$1,058,780

\$1,000,000



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
Tier 1 Funded by the 2018 Bond	Switchgear-Main. Replace main switchgear.	\$42,300	\$4300-\$18200	\$2120-\$9100
	Panels and Transformers. Replace original panels and transformers.	\$21,150	\$2150-\$9150	\$1060-\$4550
	Flooring Gym. Replace tartan floor.	\$30,460	\$3150-\$13150	\$1530-\$6550
	Exterior Wall Construction. Recaulk control joints.	\$3,390	\$420-\$1520	\$170-\$730
	Exterior Wall Construction. CMU and Brick. Recoat CMU weatherproofing. Repair cracks in block	\$17,560	\$1850-\$7650	\$880-\$3780
	Exterior Windows. Replace hollow metal exterior windows	\$91,370	\$9240-\$39340	\$4570-\$19650
	Exterior Windows. Replace exterior windows	\$70,220	\$7090-\$30290	\$3520-\$15100
	Exterior Windows. Recaulk windows	\$18,720	\$1890-\$8090	\$940-\$4030
2-High	Other Doors & Entrances. Replace hollow metal doors at entry	\$9,310	\$1000-\$4100	\$470-\$2010
	Lavatories. Replace faucets at all lavatories.	\$11,530	\$1180-\$4980	\$580-\$2480
	Paving & Surfacing. Bus Loop. Resurface asphalt bus loop	\$59,010	\$6000-\$25400	\$2950-\$12690
	Paving and Surfacing. Parking Lot. Resurface asphalt parking lot	\$78,680	\$7930-\$33930	\$3940-\$16920
	Paving & Surfacing, Sidewalks. Repair/Replace areas of sidewalk	\$39,980	\$4030-\$17230	\$2000-\$8600
	Playing Fields. Playground. Repair/reseal asphalt	\$17,240	\$1770-\$7470	\$870-\$3710
2-Medium	Flooring Kitchen. Replace kitchen flooring with poured acrylic.	\$72,870	\$7340-\$31340	\$3650-\$15670
	Flooring Restroom. Replace restroom flooring with MMA.	\$21,150	\$2150-\$9150	\$1060-\$4550
3-High	Wall Foundations. Recaulk foundation where concrete meets	\$3,390	\$420-\$1520	\$170-\$730
3-Medium	Interior Doors. Refinish wood doors	\$18,300	\$1910-\$7910	\$920-\$3940
3-Mealum	Vinyl Coverings. Repair sections of vinyl wall covering	\$6,980	\$720-\$3030	\$350-\$1510
4-Medium	Other Landscape Features. Repair drainage issues	\$9,310	\$1000-\$4100	\$470-\$2010

Estimated Total Construction Costs (in 2019 Dollars): \$642,920 Estimated Project Management Costs Range: \$65,540 - \$277,550 Estimated Inflation Range: \$32,220 - \$138,310

Estimated Total Project Costs: \$740,680 - \$1,058,780




805 West English Sparrow Trail Highlands Ranch, CO 80129 ThunderRidge High School Feeder Area, K-6


Funded by 1997 Bond Opened in 2001

Site Acreage:10 Facility Square Feet: 51,688 Mobiles on-site: 2

#### Saddle Ranch Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$1,981,460 Estimated Total Project Costs: \$2,280,220 - \$3,261,380



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Roof Finishes. Replace .045 EPDM ballasted roof with .060 EPDM fully adhered.	\$793,130	\$79380-\$341080	\$39660-\$170530
	Chilled Water Systems. Chiller, cooling tower. Replace chiller, has excessive starts, may need replaced before lifecycle.	\$296,100	\$29700-\$127400	\$14810-\$63670
	Fire Alarm Systems. Upgrade fire alarm system.	\$105,750	\$10650-\$45550	\$5290-\$22740
Tier 1 Funded by the	Emergency Light and Power Systems. Generator and Transfer Switch. Replace generator and associated equipment.	\$63,450	\$6350-\$27350	\$3180-\$13650
2018 Bond	Irrigation Systems. Replace irrigation controllers and sprinkler heads.	\$27,080	\$2730-\$11730	\$1360-\$5820
	Door Hardware. Replace door hardware, install restricted key system.	\$164,970	\$16530-\$71030	\$8250-\$35470
	Chilled Water Systems. Chiller, cooling tower. Replace cooling tower.	\$84,600	\$8500-\$36400	\$4230-\$18190
	Local Area Networks. ITS/Head End Equipment. Expanded or new MDF closet (minimum 10'X10').	\$49,180	\$4930-\$21230	\$2460-\$10580
	Flooring Kitchen. Replace epoxy floor with MMA.	\$63,450	\$6350-\$27350	\$3180-\$13650
	Exterior Wall Construction. CMU. Re-seal CMU. Repair stress cracks from settling. Re-caulk all joints.	\$16,500	\$1710-\$7110	\$830-\$3550
	Exterior Windows. Recaulk windows	\$13,220	\$1390-\$5790	\$670-\$2850
	Exterior Windows. Fix storefront window and hallway skylight leakage.	\$19,780	\$2030-\$8530	\$990-\$4260
2-High	Roof Hatches. Replace, latch bad, weather striping is deteriorating	\$10,370	\$1040-\$4540	\$520-\$2230
2 mg	Fabricated Toilet Partitions. Replace Boys/girls and main hallway restrooms, 8 total	\$23,270	\$2340-\$10040	\$1170-\$5010
	Sink Countertops. Replace sink countertops with single surface	\$21,370	\$2140-\$9240	\$1070-\$4600
	Public Address and Music Systems. Gym sound system. Replace current Advance system	\$10,370	\$1040-\$4540	\$520-\$2230
	Paving & Surfacing. Sidewalks. Repair/replace sections of sidewalk as necessary	\$7,300	\$810-\$3210	\$370-\$1570
	Operable Partition. Minor repairs needed at cafeteria/gym. Classrooms in good condition	\$11,640	\$1170-\$5070	\$590-\$2510
2-Medium	Fixed Casework. Art room countertop needs resurfaced, relace FRP behind sinks	\$3,920	\$490-\$1690	\$200-\$850
	Wall Foundations. Recaulk foundation where concrete meets	\$3,390	\$420-\$1520	\$170-\$730
3-High	Playing fields. Multi-use field. Renovate multi-use field. Reseeding and resodding	\$121,830	\$12280-\$52480	\$6100-\$26200
	Vinyl Coverings. Minor repairs	\$5,500	\$610-\$2410	\$280-\$1190
	Fences and Gates. Replace gates and dumpster enclosure	\$6,670	\$740-\$2940	\$340-\$1440
3-Medium	Fences and Gates. Install new fence at playground next to basketball court.	\$3,390	\$420-\$1520	\$170-\$730
3-Meululii	Retaining Walls. Install retaining walls where needed.	\$6,670	\$740-\$2940	\$340-\$1440
	Miscellaneous Structures. Replace top on shade structure.	\$5,500	\$610-\$2410	\$280-\$1190
	Planting. Replace and add plant material around building.	\$4,980	\$530-\$2230	\$250-\$1070
4-High	Seeding and sodding. Seed, sod, and top dress areas around school		\$610-\$2410	\$280-\$1190
4-Medium	Other Landscape Features. Repair area between parking lot and main drive. Rock gets pushed into both areas	\$32,580	\$3330-\$14030	\$1630-\$7010

Estimated Total Construction Costs (in 2019 Dollars): \$1,981,460 Estimated Project Management Costs Range: \$199,570 - \$853,770 Estimated Inflation Range: \$99,190 - \$426,150


Estimated Total Project Costs: \$2,280,220 - \$3,261,380


2420 Autumn Sage Street Castle Rock, CO 80104 Mountain Vista High School Feeder Area, K-6

Funded by 2006 Bond Opened in 2010

Site Acreage:10 Facility Square Feet: 73,146 Mobiles on-site: 0

#### Sage Canyon Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority






Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	No capital projects ide and technology related in the security			




4725 Fox Sparrow Drive Parker, CO 80134 Ponderosa High School Feeder Area, 6-8 Funded by 1995 Bond Opened in 1997

Site Acreage: 23.3 Facility Square Feet: 127,951 Mobiles on-site: 0

# Sagewood Middle School-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$4,049,530 Estimated Total Project Costs: \$4,658,690 - \$6,663,240



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Roof Finishes. Replace roof with .060 fully adhered EPDM. Current .060 fully ballasted. Bridging occuring at parapet.	\$1,163,250	\$116350-\$500250	\$58170-\$250100
	Roof Insulation and Fill. Replace 25% of insulation when roof replaced.	\$41,250	\$4160-\$17760	\$2070-\$8870
	Flashings and Trim. Replace flashing when new roof installed.	\$20,730	\$2080-\$8980	\$1040-\$4460
	Glazed Roof Openings. Skylights. Replace 4 skylights.	\$20,730	\$2080-\$8980	\$1040-\$4460
Tier 1	Interior Door Hardware. Replace door hardware, install restricted key system.	\$302,450	\$30260-\$130060	\$15130-\$65030
Funded by the	Chilled Water Systems. Chiller, cooling tower. Repair/replace cooling tower.	\$84,600	\$8500-\$36400	\$4230-\$18190
2018 Bond	Controls. Upgrade control system.	\$634,500	\$63500-\$272900	\$31730-\$136420
	Emergency Light and Power Systems. Generator and Transfer Switch. Replace generator and associated equipment.	\$74,030	\$7480-\$31880	\$3710-\$15920
	Fixed Multiple Seating. Bleachers. Repair/replace gym bleachers.	\$44,000	\$4410-\$19010	\$2200-\$9460
	Irrigation Systems. Upgrade irrigation system, add booster pump.	\$135,470	\$13640-\$58340	\$6780-\$29130
	Local Area Networks. ITS/Head End Equipment. Expanded or new MDF closet (minimum 10'X10').	\$49,180	\$4930-\$21230	\$2460-\$10580
	Flooring Cafeteria. Repair/replace VCT in commoms. Expansion joint strip that is lifting up in places.	\$32,790	\$3320-\$14120	\$1640-\$7050
	Flooring Hallways/classrooms Replace health room flooring.	\$3,070	\$340-\$1340	\$160-\$660
	Flooring Hallways/Classrooms. Repair VCT in copy center.	\$1,170	\$140-\$540	\$60-\$250
	Exterior Wall Construction. CMU and Brick. Repair cracks and caulk all joints on exterior brick walls	\$5,290	\$620-\$2320	\$270-\$1140
	Exterior Windows. Recaulk windows	\$23,480	\$2430-\$10130	\$1180-\$5050
2-High	Fabricated Toilet Partitions. Replace toilet partitions in 6 boys and 6 girls restrooms	\$42,300	\$4300-\$18200	\$2120-\$9100
	Sink Countertops. Replace sink countertops with single surface	\$21,370	\$2140-\$9240	\$1070-\$4600
	Paving & Surfacing. Bus Loop. Resurface asphalt bus loop	\$81,330	\$8180-\$34980	\$4070-\$17490
	Paving and Surfacing. Parking Lot. Resurface asphalt parking lot	\$135,470	\$13640-\$58340	\$6780-\$29130
	Curbs, Rails and Barriers. Repair curbs at parking lot area	\$108,400	\$10910-\$46710	\$5420-\$23310
	Paving and Surfacing. Sidewalks. Repair sidewalks and concrete playpad	\$32,580	\$3330-\$14030	\$1630-\$7010
2-Medium	Flooring Carpet. Replace carpet.	\$346,440	\$34670-\$149070	\$17330-\$74490
2 11.0010111	Fixed Walls. Repair cracks in CMU wall behind stage	\$1,170	\$140-\$540	\$60-\$250
3-High	Playing Fields. Multi-use Field. Top dress and reseed multipurpose field.	\$16,290	\$1720-\$7020	\$820-\$3510
	Fences and Gates. Install fencing around ball fields. Install fencing around dumpster. Repair fencing at softball field	\$324,870	\$32540-\$139740	\$16250-\$69850
3-Medium	Retaining Walls. Repair/add retaining walls	\$135,470	\$13640-\$58340	\$6780-\$29130
	Playing Fields. Softball Field. Renovate softball infield	\$21,680	\$2230-\$9430	\$1090-\$4670
	Playing Fields. Football Field. Replace football and soccer goal posts	\$5,290	\$620-\$2320	\$270-\$1140
4-High	Seeding and Sodding. Seed, sod, and top dress areas around school	\$32,580	\$3330-\$14030	\$1630-\$7010
	Planting. Plant trees around ballfields	\$54,150	\$5460-\$23360	\$2710-\$11650
4-Medium	Other Landscape Features. Install landscaping around ballfields	\$54,150	\$5460-\$23360	\$2710-\$11650

Estimated Total Construction Costs (in 2019 Dollars): \$4,049,530 Estimated Project Management Costs Range: \$406,550 - \$1,742,950 Estimated Inflation Range: \$202,610 - \$870,760


Estimated Total Project Costs: \$4,658,690 - \$6,663,240




8898 South Maplewood Drive Highlands Ranch, CO 80126 Mountain Vista High School Feeder Area, K-6 Funded by 1984 Bond Opened in 1986

Site Acreage: 11.1 Facility Square Feet: 53,237 Mobiles on-site: 4

# Sand Creek Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$2,652,850 Estimated Total Project Costs: \$3,052,190 - \$4,365,770



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Roof Finishes. Replace .045 ballasted EPDM with .060 fully adhered.	\$793,130	\$79380-\$341080	\$39660-\$170530
	Direct Expansion Systems. Roof top units. Replace rooftop units. Current ones need painted.	\$317,250	\$31750-\$136450	\$15870-\$68210
	Controls. Upgrade control system.	\$317,250	\$31750-\$136450	\$15870-\$68210
	Switchgear-Main. Replace main switchgear.	\$46,750	\$4760-\$20160	\$2340-\$10050
Tier 1 Funded by the	Panels and Transformers. Replace original panels and transformers.	\$46,750	\$4760-\$20160	\$2340-\$10050
2018 Bond	Fire Alarm Systems. Upgrade fire alarm system.	\$105,750	\$10650-\$45550	\$5290-\$22740
	Emergency Light and Power Systems. Generator and Transfer Switch. Replace generator and associated equipment.	\$63,450	\$6350-\$27350	\$3180-\$13650
	Hot Water Service. Water Heater. Replace domestic water heater and associated piping	\$89,150	\$8960-\$38360	\$4460-\$19170
	Lighting Equipment. Replace two fixtures in health room.	\$430	\$80-\$280	\$30-\$100
	Flooring Kitchen. Replace epoxy floor with MMA.	\$63,450	\$6350-\$27350	\$3180-\$13650
	Exterior Wall Construction. Recaulk control joints.	\$3,390	\$420-\$1520	\$170-\$730
2-High	Exterior Windows. Replace exterior windows	\$70,220	\$7090-\$30290	\$3520-\$15100
3	Exterior Windows. Recaulk windows	\$18,720	\$1890-\$8090	\$940-\$4030
	Fabricated Toilet Partitions. Replace toilet partitions in 3 pods	\$23,270	\$2340-\$10040	\$1170-\$5010
	Flooring Hallways/Classrooms. Replace VCT in classrooms and healthroom.	\$4,550	\$560-\$2060	\$230-\$980
	Flooring Carpet. Replace carpet.	\$317,250	\$31750-\$136450	\$15870-\$68210
	Retractable Partition. Repair operable partitions between classrooms. Partion between gym and cafeteria in worst condition.	\$17,980	\$1830-\$7830	\$900-\$3870
2-Medium	Sinks. Replace with sink countertops, single surface	\$13,440	\$1370-\$5870	\$680-\$2890
	Fixed Casework. Replace all original fixed casework in classrooms and offices	\$142,560	\$14350-\$61350	\$7130-\$30650
	Paving & Surfacing. Bus Loop. Resurface asphalt bus loop	\$26,760	\$2750-\$11550	\$1340-\$5760
	Paving and Surfacing. Parking Lot. Resurface asphalt parking lot	\$80,270	\$8040-\$34540	\$4020-\$17260
2-Low	Exterior Wall Construction. Repair brick where cracking at front retaining wall, clean water stained areas	\$3,280	\$430-\$1430	\$170-\$710
3-High	Wall Foundations. Recaulk foundation where concrete meets	\$3,390	\$420-\$1520	\$170-\$730
	Interior Doors. Refinish interior doors	\$44,630	\$4480-\$19280	\$2240-\$9600
3-Medium	Blinds and Other Window Treatment. Replace blinds in school	\$17,980	\$1830-\$7830	\$900-\$3870
3-Mediuili	Movable Furnishing. FFE. Replace wooden basketball backboards in gym, 4 total	\$1,910	\$200-\$900	\$100-\$410
	Movable Furnishing. FFE. Replace health room beds	\$1,910	\$200-\$900	\$100-\$410
4-Medium	Seeding and Sodding. Renovate grass areas around school	\$17,980	\$1830-\$7830	\$900-\$3870

Estimated Total Construction Costs (in 2019 Dollars): \$2,652,850 Estimated Project Management Costs Range: \$266,570 - \$1,142,470 Estimated Inflation Range: \$132,770 - \$570,450


Estimated Total Project Costs: \$3,052,190 - \$4,365,770




5449 North Huxtable Street Sedalia, CO 80135 Castle View High School Feeder Area, K-6 Funded prior to 1952 Opened in 1952

Site Acreage:5 Facility Square Feet: 35,177 Mobiles on-site: 0

#### Sedalia Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$1,874,740 Estimated Total Project Costs: \$2,157,500 - \$3,085,600



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Roof Finishes. Replace existing built up roof, sections A,C,E.	\$105,750	\$10650-\$45550	\$5290-\$22740
	Roof Finishes. Replace fully adhered roof over gym, music, and front office, sections F,G,H,J (1999).	\$158,630	\$15880-\$68280	\$7940-\$34110
	Roof Finishes. Replace ballasted roof, section B (1992) with fully adhered.	\$105,750	\$10650-\$45550	\$5290-\$22740
	Roof Eaves & Soffits. Soffits need repaired along the older classrooms wing.	\$12,380	\$1330-\$5330	\$620-\$2660
	Interior Door hardware. Replace current non-restricted key system with restricted. Hardware change.	\$109,980	\$11020-\$47320	\$5500-\$23650
	Direct Expansion Systems. Roof top units. Replace RTUs as necessary.	\$158,630	\$15880-\$68280	\$7940-\$34110
Tier 1	Controls. Upgrade required if current system changes.	\$211,500	\$21200-\$91000	\$10580-\$45480
	Panels and Transformers. Replace old branch wiring panels in building.	\$5,500	\$610-\$2410	\$280-\$1190
	Air Distribution Systems. Air handlers, ductwork, VAV's. Current VVT system in good shape. Should upgrade to VAV reheat system	\$367,170	\$36740-\$157940	\$18360-\$78940
	Terminal Self-Contained Units. Replace unit heaters at entries.	\$16,500	\$1710-\$7110	\$830-\$3550
	Commissioning and Re-Commissioning. Commission if upgrades to current system made	\$57,220	\$5790-\$24690	\$2870-\$12300
	Emergency Light and Power Systems. Generator and Transfer Switch. Install new generator and associated emergency systems.	\$73,710	\$7400-\$31800	\$3690-\$15850
	Playing Fields. Playground. Needs. Replace pea gravel play area Install new basketball hoops	\$29,510	\$3000-\$12700	\$1480-\$6350
	Flooring Restroom. Replace all ceramic tile bathroom floors and walls.	\$29,510	\$3000-\$12700	\$1480-\$6350
	Flooring Kitchen. Replace kitchen floor.	\$56,160	\$5650-\$24150	\$2810-\$12080
	Flooring Carpet. Replace walk off carpet at all entrances.	\$5,500	\$610-\$2410	\$280-\$1190
	Exterior Wall Construction. Recaulk control joints.	\$3,390	\$420-\$1520	\$170-\$730
	Exterior Wall Construction. Brick and stucco. Good condition. Areas where the new meets the old need sealed. Repair cracks and deterioration in stucco on newer classrooms addition.	\$16,290	\$1720-\$7020	\$820-\$3510
2-High	Exterior Windows. Replace plexiglass in double doors to playground SW with insulated safety glass. Entire east facing windows are in bad shape from condensation. They are single pane, replace with Low E insulated units. Will require frame modif	\$40,820	\$4180-\$17590	\$2050-\$8780
	Exterior Windows. Recaulk windows	\$14,070	\$1440-\$6140	\$710-\$3030
	Sink Countertops. Replace counter tops only in rooms 107, 208, 207,209, 210	\$11,850	\$1260-\$5160	\$600-\$2550
	Paving & Surfacing, Parking Lot. \$60,000 in asphalt work, \$10,000 on site drainage east side of school	\$68,430	\$6880-\$29480	\$3430-\$14710
	Paving & Surfacing, Sidewalks. Need-Repair areas of sidewalk, stairs at west entry	\$5,820	\$590-\$2590	\$300-\$1250
2-Medium	Flooring Hallways/Classrooms. Replace red ceramic tile in hallway, showing wear and cracks.	\$11,000	\$1110-\$4810	\$550-\$2370
3-High	Wall Foundations. Recaulk foundation where concrete meets	\$2,330	\$280-\$1080	\$120-\$500
3-Medium	Vinyl Coverings. Rooms/hallways that have vinyl have been painted. Would recommend removal or replacement.	\$18,300	\$1910-\$7910	\$920-\$3940
	Ceiling Finishes. Replace ceiling grid and tile	\$164,970	\$16530-\$71030	\$8250-\$35470
	Site Lighting Poles. Replace two light poles	\$2,540	\$270-\$1170	\$130-\$550
4-High	Other Landscape Features. Site drainage on east side of school needs addressed	\$11,530	\$1180-\$4980	\$580-\$2480

Estimated Total Construction Costs (in 2019 Dollars): \$1,874,740 Estimated Project Management Costs Range: \$188,890 - \$807,700

Estimated Inflation Range: \$93,870 - \$403,160


Estimated Total Project Costs: \$2,157,500 - \$3,085,600




6651 Pine Lane Avenue Parker, CO 80134 Chaparral High School Feeder Area, 7-8 Funded by 1974 Bond Opened in 1975

Site Acreage:50 Facility Square Feet: 115,538 Mobiles on-site: 1

# Sierra Middle School-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$4,955,930 Estimated Total Project Costs: \$5,701,700 - \$8,154,940



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Gutters and Downspouts. Repair and paint downspouts.	\$5,080	\$530-\$2230	\$260-\$1100
	Interior Door hardware. Replace current non-restricted key system with restricted. Hardware change.	\$302,450	\$30260-\$130060	\$15130-\$65030
	Direct Expansion Systems. Roof top units. Replace RTUs.	\$793,130	\$79380-\$341080	\$39660-\$170530
Tier 1	Controls. Upgrade control system.	\$740,250	\$74050-\$318350	\$37020-\$159160
2018 Bond- Under Construction	Emergency Light and Power Systems. Generator and Transfer Switch. Replace generator and associated equipment.	\$74,030	\$7480-\$31880	\$3710-\$15920
Construction	Irrigation Systems. Upgrade entire system to district standard	\$245,560	\$24650-\$105650	\$12280-\$52800
	Roof Finishes. Replace fully adhered .060 roof sections A,F,J,K,L.	\$475,880	\$47630-\$204730	\$23800-\$102320
	Site Heating Distibution. Replace gas meter and associated piping.	\$21,150	\$2150-\$9150	\$1060-\$4550
	Flooring Restroom. Replace ceramic tile with poured acrylic. 2 main hallway, 2 locker room, 2 PE teacher office restroom Replace sheet viynl in library restroom.	\$49,180	\$4930-\$21230	\$2460-\$10580
	Flooring Hallways/Classrooms. Replace VCT throughout school where needed.	\$196,380	\$19730-\$84530	\$9820-\$42230
	Flooring Cafeteria. Replace VCT in cafeteria.	\$29,510	\$3000-\$12700	\$1480-\$6350
	Flooring Carpet. Replace carpeting in classrooms.	\$140,440	\$14070-\$60470	\$7030-\$30200
	Exterior Wall Construction. Repair/seal cracks in brick	\$9,950	\$1060-\$4360	\$500-\$2140
	Paint Exterior. Green metal and trim need painted.	\$19,780	\$2030-\$8530	\$990-\$4260
	Exterior Windows. Recaulk windows	\$14,920	\$1590-\$6490	\$750-\$3210
	Fixed Walls. Repair drywall at stage area	\$1,060	\$150-\$550	\$60-\$230
2.00.1	Retractable Partitions. Refurbish classroom retractable partitions	\$24,540	\$2470-\$10570	\$1230-\$5280
2-High	Fabricated Toilet Partitions. Replace toilet partitions in girls locker room	\$4,870	\$540-\$2140	\$250-\$1050
	Sink Countertops. Replace sink countertops as necessary	\$28,350	\$2860-\$12260	\$1420-\$6100
	Fixed Casework. Replace original casework in building	\$392,650	\$39350-\$168850	\$19640-\$84420
	Paving & Surfacing. Bus Loop. Resurface asphalt bus loop	\$78,680	\$7930-\$33930	\$3940-\$16920
	Paving and Surfacing. Parking Lot. Resurface asphalt parking lot	\$78,680	\$7930-\$33930	\$3940-\$16920
	Paving & Surfacing. Sidewalks. Repair/replace sections of sidewalk as necessary, Stairs need attention, new tread edge	\$9,950	\$1060-\$4360	\$500-\$2140
	Playing Fields. Playground. Replace playground play pads	\$44,310	\$4500-\$19100	\$2220-\$9530
2-Medium	Site Lighting Poles. Paint light poles	\$2,120	\$290-\$990	\$110-\$460
	Wall Foundations. Repair concrete foundation walls below brick	\$19,780	\$2030-\$8530	\$990-\$4260
3-High	Wall Foundations. Recaulk foundation where concrete meets		\$420-\$1520	\$170-\$730
	Interior Doors. Replace/repair/refinish interior doors	\$73,710	\$7400-\$31800	\$3690-\$15850
	Playing Fields. Multi-use Field. Renovate multi-use playing fields	\$196,380	\$19730-\$84530	\$9820-\$42230

Estimated Total Construction Costs (in 2019 Dollars): \$4,955,930 Estimated Project Management Costs Range: \$497,810 - \$2,133,310 Estimated Inflation Range: \$247,960 - \$1,065,700


Estimated Total Project Costs: \$5,701,700 - \$8,154,940




4665 Tanglevine Drive Castle Rock, CO 80109 Castle View High School Feeder Area, K-6 Funded by 2000 Bond Opened in 2004

Site Acreage:11 Facility Square Feet: 56,868 Mobiles on-site: 3

# Soaring Hawk Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$1,349,400 Estimated Total Project Costs: \$1,552,270 - \$2,220,210



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
Tier 1	Roof Finishes. Replace .045 ballasted EPDM with .060 fully adhered.	\$793,130	\$79380-\$341080	\$39660-\$170530
Funded by the	Fire Alarm Systems. Upgrade fire alarm system.	\$116,330	\$11680-\$50080	\$5820-\$25010
2018 Bond	Controls. Upgrade control system.	\$317,250	\$31750-\$136450	\$15870-\$68210
2-High	Flooring Cafeteria. VCT buckling, repairs needed.	\$1,380	\$230-\$630	\$70-\$300
	Exterior Wall Construction. CMU. Recaulk control joints	\$3,810	\$400-\$1700	\$190-\$820
	Exterior Wall Construction. CMU. CMU needs sealed.	\$12,270	\$1240-\$5340	\$620-\$2640
2-Medium	Exterior WindowsRecaulk windows	\$14,700	\$1510-\$6410	\$740-\$3160
	Paving and Surfacing. Parking Lot. Resurface asphalt parking lot	\$84,600	\$8500-\$36400	\$4230-\$18190
3-Medium	Vinyl Coverings. Repair vinyl wall covering. Poor installation due to lack of glue, peeling all over building.	\$5,930	\$680-\$2580	\$300-\$1280

Estimated Total Construction Costs (in 2019 Dollars): \$1,349,400 Estimated Project Management Costs Range: \$135,370 - \$580,670 Estimated Inflation Range: \$67,500 - \$290,140


Estimated Total Project Costs: \$1,552,270 - \$2,220,210




1100 South Street Castle Rock, CO 80104 Douglas County High School Feeder Area, K-6 Funded by 1970 Bond Opened in 1972

Site Acreage: 8.9 Facility Square Feet: 52,287 Mobiles on-site: 4

#### South Ridge Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$3,764,450 Estimated Total Project Costs: \$4,331,880 - \$6,195,330



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Roof Finishes. Replace metal standing seam areas C,D,E,F.	\$380,700	\$38100-\$163800	\$19040-\$81860
	Roof Finishes. Replace areas A.B,M.	\$105,750	\$10650-\$45550	\$5290-\$22740
	Roof Finishes. Replace .045 ballasted EPDM area N with .060 fully adhered.	\$52,880	\$5330-\$22830	\$2650-\$11370
	Gutters and Downspouts. Rework gutters and downspouts when new soffit installed. Improve drainage.	\$14,920	\$1590-\$6490	\$750-\$3210
Tier 1	Interior Door hardware. Replace current non-restricted key system with restricted. Hardware change.	\$164,970	\$16530-\$71030	\$8250-\$35470
Funded by the 2018 Bond	Direct Expansion Systems. Roof top units. Replace RTUs.	\$339,460	\$34050-\$146050	\$16980-\$72990
	Controls. Upgrade control system.	\$290,820	\$29090-\$125090	\$14550-\$62530
	Panels and Transformers. Replace original SW gear now subfed. Replace original panels and transformers.	\$98,350	\$9860-\$42360	\$4920-\$21150
	Fire Alarm Systems. Upgrade fire alarm system.	\$105,750	\$10650-\$45550	\$5290-\$22740
	Emergency Light and Power Systems. Generator and Transfer Switch. Replace generator and associated equipment.	\$63,450	\$6350-\$27350	\$3180-\$13650
	Irrigation Systems. Replace entire irrigation system. Install seperate meter.	\$98,350	\$9860-\$42360	\$4920-\$21150
	Fabricated Toilet Partitions. Replace when flooring replaced.	\$18,930	\$1980-\$8180	\$950-\$4070
	Flooring Restroom. Replace ceramic tile with MMA.	\$34,480	\$3530-\$14830	\$1730-\$7420
	Exterior Wall Construction. Recaulk control joints	\$5,400	\$610-\$2410	\$270-\$1160
	Exterior Windows. Recaulk windows Window Storefronts. Repair/replace entry storefronts	\$7,510 \$7,510	\$800-\$3300 \$800-\$3300	\$380-\$1620 \$380-\$1620
	sand/paint. Solid Exterior Doors. Sand and paint	\$5,080	\$530-\$2230	\$260-\$1100
	Retractable Partitions. Refurbish or replace all classroom		\$330-\$2230	\$200-\$1100
2-High	partitions in east wing	\$29,510	\$3000-\$12700	\$1480-\$6350
	Interior Doors. Replace interior doors	\$98,350	\$9860-\$42360	\$4920-\$21150
	Fixed Casework. Replace casework in original building	\$98,350	\$9860-\$42360	\$4920-\$21150
	Special Facilities. Replace sound panels in music room	\$10,580	\$1130-\$4630	\$530-\$2280
	Paving & Surfacing. Bus Loop. Resurface asphalt bus loop  Paving and Surfacing. Parking Lot. Resurface asphalt parking	\$78,680	\$7930-\$33930	\$3940-\$16920
	lot	\$98,350	\$9860-\$42360	\$4920-\$21150
	Paving and Surfacing. Sidewalks. Repair/replace areas of sidewalk, front entry	\$19,780	\$2030-\$8530	\$990-\$4260
	Playing Fields. Playground. Replace asphalt playground	\$29,510	\$3000-\$12700	\$1480-\$6350
2-Medium	Roof Eaves and Soffits. Replace soffit around building with new metal soffit	\$21,150	\$2150-\$9150	\$1060-\$4550
	Pipe and Fittings. Replace gas piping on roof for RTUs	\$2,650	\$360-\$1160	\$140-\$570
2-Low	Paving and Surfacing. Sidewalks. Repair/replace areas of sidewalk, replace back stairway to mobiles	\$7,940	\$870-\$3470	\$400-\$1710
	Column Foundations. Repair rusting columns at gym south side	\$9,950	\$1060-\$4360	\$500-\$2140
	Fixed Walls. Refinish all fixed walls	\$19,780	\$2030-\$8530	\$990-\$4260
3-High	Interior Door Frames. Sand/paint door frames	\$22,210	\$2300-\$9600	\$1110-\$4780
3	Interior Finishes. Replace sound panels in music room and gym	\$26,760	\$2750-\$11550	\$1340-\$5760
	Suspended Ceilings. Replace grid ceiling and tile	\$132,190	\$13320-\$56920	\$6610-\$28420
	Movable Furnishing. FFE. Replace hallway tack boards	\$19,780	\$2030-\$8530	\$990-\$4260

Estimated Total Construction Costs (in 2019 Dollars): \$3,764,450 Estimated Project Management Costs Range: \$379,020 - \$1,621,330 Estimated Inflation Range: \$188,410- \$809,550


Estimated Total Project Costs: \$4,331,880 - \$6,195,330




10625 Weathersfield Way Highlands Ranch, CO 80130 ThunderRidge High School Feeder Area, K-6 Funded by 2006 Bond Opened in 2007

Site Acreage:10 Facility Square Feet: 73,146 Mobiles on-site: 0

#### Stone Mountain Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$732,580 Estimated Total Project Costs: \$843,180 - \$1,205,740



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	Fire Alarm Systems. Upgrade fire alarm system	\$126,900	\$12700-\$54600	\$6350-\$27290
	Controls. Upgrade control system	\$370,130	\$37080-\$159180	\$18510-\$79580
1-Medium	Lighting Equipment. Repair lighting on stairs to crawlspace, not working	\$220	\$90-\$190	\$20-\$50
	Exterior Wall Construction. CMU and Brick. Recaulk expansion joints. Reseal CMU	\$15,870	\$1640-\$6840	\$800-\$3410
2-Medium	Paint Exterior. Paint exterior metal, poles, railings, and sunshades	\$5,290	\$620-\$2320	\$270-\$1140
	Exterior Windows. Recaulk windows	\$15,870	\$1640-\$6840	\$800-\$3410
2-Low	Paving and Surfacing. Sidewalks. Repair areas of sidewalk as necessary	\$5,290	\$620-\$2320	\$270-\$1140
3-Medium	Wall Foundations. Recaulk foundation where concrete meets	\$3,180	\$330-\$1430	\$160-\$690
3-Medium	Playing Fields. Replace synthetic play field. 1/2 costs shared with Highlands Ranch Metro District	\$178,190	\$17920-\$76720	\$8910-\$38320
3-Low	Gutters and Downspouts. Mitigate erosion from roof scuppers on norht side of building	\$1,060	\$150-\$550	\$60-\$230
J LOW	Seeding and Sodding. Repair areas of grass around school	\$10,580	\$1130-\$4630	\$530-\$2280

Estimated Total Construction Costs (in 2019 Dollars): \$732,580 Estimated Project Management Costs Range: \$73,920- \$315,620 Estimated Inflation Range: \$36,680 - \$157,540


Estimated Total Project Costs: \$843,180 - \$1,205,740




10200 South Piedmont Way Highlands Ranch, CO 80126 Mountain Vista High School Feeder Area, K-6 Funded by Certificate of Participation Opened in 1992

Site Acreage:10 Facility Square Feet: 56,475 Mobiles on-site: 3

#### Summit View Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$737,610 Estimated Total Project Costs: \$849,330 - \$1,214,620



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Branch Wiring Devices. Replace sealtite conduit and wiring	\$3,180	\$330-\$1430	\$160-\$690
	to all equipment on roof.	£11C 220	£11000 £50000	¢5020 ¢25010
Tier 1 Funded by the	Fire Alarm Systems. Upgrade fire alarm system.  Special Electrical Systems. Low voltage wiring in boiler room should be redone. Dropped ceiling not reinstalled, plenum cable does not meet code, should be in conduit	\$116,330 \$12,270	\$11680-\$50080 \$1240-\$5340	\$5820-\$25010 \$620-\$2640
2018 Bond	Emergency Light and Power Systems. Generator and Transfer Switch. Replace generator and associated equipment.	\$63,450	\$6350-\$27350	\$3180-\$13650
	Switchgear-Main. Replace main switchgear.	\$31,730	\$3180-\$13680	\$1590-\$6830
	Panels and Transformers. Replace original panels and transformers.	\$21,150	\$2150-\$9150	\$1060-\$4550
	Flooring Kitchen. Replace kitchen flooring.	\$56,160	\$5650-\$24150	\$2810-\$12080
	Flooring Cafeteria. Replace VCT.	\$15,870	\$1640-\$6840	\$800-\$3410
	Exterior Wall Construction. Recaulk control joints.	\$3,390	\$420-\$1520	\$170-\$730
	Exterior Windows. Replace exterior windows	\$70,220	\$7090-\$30290	\$3520-\$15100
	Exterior Windows. Recaulk windows	\$18,720	\$1890-\$8090	\$940-\$4030
2-High	Fabricated Toilet Partitions. Replace toilet partitions in 3 pods	\$23,270	\$2340-\$10040	\$1170-\$5010
2 mgn	Sink Countertops. Replace sink counter tops in 3 pods	\$21,370	\$2140-\$9240	\$1070-\$4600
	Energy Supply. Reattach supports for gas line on roof. Rusted piping should be replaced	\$1,910	\$200-\$900	\$100-\$410
	Paving & Surfacing, Sidewalks. Repair/Replace areas of sidewalk	\$11,530	\$1180-\$4980	\$580-\$2480
	Playing Fields. Playground. Repair asphalt cracks at playground	\$22,950	\$2360-\$9960	\$1150-\$4940
	Flooring Restroom. Replace VCT flooring in staff restrooms.	\$1,800	\$210-\$810	\$90-\$390
	Flooring Carpet. Replace carpet in workrooms in stacked pods.	\$12,800	\$1310-\$5510	\$640-\$2760
2-Medium	Retractable Partition. Repair operable partitions between classrooms and between gym/cafeteria	\$17,140	\$1770-\$7370	\$860-\$3690
2-Medium	Suspended Ceilings. Replace ceiling grid and tile. Damaged during fire sprinkler install	\$158,630	\$15880-\$68280	\$7940-\$34110
	Water Closets. Replace fixtures in staff restrooms	\$2,650	\$360-\$1160	\$140-\$570
	Sinks. Replace fixtures in staff restrooms	\$1,800	\$210-\$810	\$90-\$390
	Paving & Surfacing, Parking Lot. Minor asphalt crack repair, repair concrete service drive	\$28,660	\$2950-\$12350	\$1440-\$6170
3-High	Wall Foundations. Recaulk foundation where concrete meets	\$3,280	\$430-\$1430	\$170-\$710
	Seeding & Sodding. Resod/reseed grass areas	\$5,820	\$590-\$2590	\$300-\$1250
4-High	Other Landscape Features. Replace metal edging with concrete mow strip	\$11,530	\$1180-\$4980	\$580-\$2480

Estimated Total Construction Costs (in 2019 Dollars): \$737,610 Estimated Project Management Costs Range: \$74,730 - \$318,330

Estimated Inflation Range: \$36,990 - \$158,680


Estimated Total Project Costs: \$849,330 - \$1,214,620




1991 Wildcat Reserve Parkway Highlands Ranch, CO 801296 ThunderRidge High School Feeder Area, 9-12 Funded by 1993 Bond Opened in 1996

Site Acreage: 50 Facility Square Feet: 240,640 Mobiles on-site: 1

#### ThunderRidge High School-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$5,776,950 Estimated Total Project Costs: \$6,645,480 - \$9,505,400



Estimated Total Construction Costs (in 2019 Dollars): \$5,776,950 Estimated Project Management Costs Range: \$579,540 - \$2,486,250 Estimated Inflation Range: \$288,990 - \$1,242,200


Estimated Total Project Costs: \$6,645,480 - \$9,505,400




690 West Castle Pines Parkway Castle Pines, CO 80108 Rock Canyon High School Feeder Area, K-5 Funded by 2000 Bond Opened in 2003

Site Acreage: 6.98 Facility Square Feet: 56,868 Mobiles on-site: 1

#### Timber Trail Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$1,984,250 Estimated Total Project Costs: \$2,282,980 - \$3,265,370



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Roof Finishes. Replace .045 ballasted EPDM with .060 fully adhered.	\$793,130	\$79380-\$341080	\$39660-\$170530
Tier 1	Controls. Upgrade control system.	\$317,250	\$31750-\$136450	\$15870-\$68210
Funded by the	Fire Alarm Systems. Upgrade fire alarm system.	\$116,330	\$11680-\$50080	\$5820-\$25010
2018 Bond	Emergency Light and Power Systems. Generator and Transfer Switch. Replace generator and associated equipment.	\$63,450	\$6350-\$27350	\$3180-\$13650
	Exterior Wall Construction. Recaulk building control joints, patch cracks, water seal CMU	\$26,760	\$2750-\$11550	\$1340-\$5760
2-High	Window Curtain Walls. Water infiltration has happened in the past. Some caulking done but window wall frames should be rebuilt.	\$44,630	\$4480-\$19280	\$2240-\$9600
	Flooring Gym. Replace gym carpet.	\$15,950	\$1660-\$6860	\$800-\$3430
	Flooring Carpet. Replace walk off carpet at entries.	\$22,320	\$2290-\$9690	\$1120-\$4800
	Flooring Carpet. Replace carpet.	\$317,250	\$31750-\$136450	\$15870-\$68210
	Paint Exterior. Paint exterior trim, windows and doors	\$8,990	\$920-\$3920	\$450-\$1940
	Exterior Windows. Recaulk windows	\$14,810	\$1500-\$6400	\$740-\$3190
2-Medium	Solid Exterior Doors. Recaulk door frames	\$1,060	\$150-\$550	\$60-\$230
2-Medium	Sink Countertops. Replace sink countertops with single surface	\$21,370	\$2140-\$9240	\$1070-\$4600
	Sinks. Replace with sink countertops, single surface	\$13,440	\$1370-\$5870	\$680-\$2890
	Paving & Surfacing. Bus Loop. Resurface asphalt bus loop	\$26,760	\$2750-\$11550	\$1340-\$5760
	Paving and Surfacing. Parking Lot. Resurface asphalt parking lot	\$80,270	\$8040-\$34540	\$4020-\$17260
	Paving and Surfacing. Sidewalks. Repair/replace damage to sidewalks due to ground movement	\$17,980	\$1830-\$7830	\$900-\$3870
	Wall Foundations. Some building movement, not severe but causing cracks on inside flooring and walls	\$4,550	\$560-\$2060	\$230-\$980
3-Medium	Wall Foundations. Recaulk areas where concrete meets foundation walls	\$3,390	\$420-\$1520	\$170-\$730
	Vinyl Coverings. Repair areas of vinyl wall covering	\$3,280	\$430-\$1430	\$170-\$710
	Playing Fields. Multi-use Field. Renovate multi-use field	\$71,280	\$7230-\$30730	\$3570-\$15330

Estimated Total Construction Costs (in 2019 Dollars): \$1,984,250 Estimated Project Management Costs Range: \$199,430 - \$854,430 Estimated Inflation Range: \$99,300 - \$426,690


Estimated Total Project Costs: \$2,282,980 - \$3,265,370




9760 South Hackberry Highlands Ranch, CO 80129 ThunderRidge High School Feeder Area, K-6 Funded by DC Developers Trust Fund Opened in 1997

Site Acreage:10 Facility Square Feet: 51,020 Mobiles on-site: 1

#### Trailblazer Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$1,674,930 Estimated Total Project Costs: \$1,927,550 - \$2,756,520



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Domestic Water Supply Equipment. Upgrade backflow.	\$8,150	\$860-\$3560	\$410-\$1760
	Direct Expansion Systems. Roof top units. Replace RTUs.	\$339,460	\$34050-\$146050	\$16980-\$72990
Tier 1	Exhaust Ventilation Systems. Kitchen hood exhaust and MUA replacement/upgrade.	\$60,810	\$6100-\$26200	\$3040-\$13080
Funded by the	community of the commun	\$317,250	\$31750-\$136450	\$15870-\$68210
2018 Bond	Emergency Light and Power Systems. Generator and Transfer Switch. Replace generator and associated equipment.	\$63,450	\$6350-\$27350	\$3180-\$13650
	Irrigation Systems. Update the clock, need to pull pump out of pit	\$62,930	\$6380-\$27080	\$3150-\$13530
	Kitchen Flooring. Replace kitchen flooring with poured acrylic. Currently Hubelite material (Red).	\$59,540	\$5970-\$25670	\$2980-\$12810
	Flooring Gym. Replace gym carpet.	\$18,300	\$1910-\$7910	\$920-\$3940
	Flooring Cafeteria. Replace VCT.	\$13,710	\$1400-\$5900	\$690-\$2950
	Exterior Wall Construction. CMU and Brick. Reseal CMU.Stress cracks same as other schools. Control joints need re-caulking	\$17,560	\$1850-\$7650	\$880-\$3780
	Exterior WindowsRecaulk windows	\$14,700	\$1510-\$6410	\$740-\$3160
2-High	Storefront windows. Hollow metal. Recaulk all windows	\$8,150	\$860-\$3560	\$410-\$1760
9	Retractable Partitions. Refurbish gym/cafeteria partition. Curtains need replaced due to fire retardant life. Classrooms are not used and are in good shape.	\$16,290	\$1720-\$7020	\$820-\$3510
	Fabricated Toilet partitions. Replace toilet partitions	\$23,270	\$2340-\$10040	\$1170-\$5010
	Paving & Surfacing. Bus Loop. Resurface asphalt bus loop	\$81,640	\$8270-\$35170	\$4090-\$17560
	Paving & Surfacing. Sidewalks. Repair/replace sections of sidewalk as necessary	\$24,540	\$2470-\$10570	\$1230-\$5280
	Playing Fields. Playground. One playpad needs to be replaced R&R, the other needs and overlay	\$57,220	\$5790-\$24690	\$2870-\$12300
3-High	Wall Foundations. Good condition. Gym has cracks SE corner, corner of building appears to be settling.	\$12,380	\$1330-\$5330	\$620-\$2660
	Vinyl Coverings. Wall Finishes. Repair walls vinyl. Many tears, patches, water damage and seams coming apart in hallways and pods. Bathroom halls have colored vinyl that need replaced.	\$8,150	\$860-\$3560	\$410-\$1760
	Suspended Ceilings. Replace all ceiling tiles in the kitchen. (need to be food grade)	\$6,560	\$750-\$2850	\$330-\$1410
3-Medium	Grease interceptor. Bypass grease interceptor if possible	\$8,150	\$860-\$3560	\$410-\$1760
	Fire Sprinkler. Install sprinkler system. Only in Cafeteria. Current code requires fully sprinkled building if remodeled	\$411,900	\$41210-\$177210	\$20600-\$88560
	Playing Fields. Fields, Have drainage issue on north end of playground next to privacy fence	\$40,820	\$4180-\$17590	\$2050-\$8780

Estimated Total Construction Costs (in 2019 Dollars): \$1,674,930 Estimated Project Management Costs Range: \$168,770 - \$721,380 Estimated Inflation Range: \$83,850 - \$360,210


Estimated Total Project Costs: \$1,927,550 - \$2,756,520




6585 Lionshead Parkway Littleton, CO 80124 Rock Canyon High School Feeder Area, K-5 Funded by 1997 Bond Opened in 1998

Site Acreage:10 Facility Square Feet: 51,676 Mobiles on-site: 2

# Wildcat Mountain Elementary-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$1,121,690 Estimated Total Project Costs: \$1,291,180 - \$1,846,460



Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Interior Door hardware. Replace current non-restricted key	\$164,970	\$16530-\$71030	\$8250-\$35470
	system with restricted. Hardware change. Chilled Water Systems. Chiller, cooling tower. Rebuild/replace cooling tower.	\$84,600	\$8500-\$36400	\$4230-\$18190
Tier 1	Air Distribution Systems Air handlers, ductwork, VAV's. AHU #4 needs some ductwork changed, moisture damage.	\$5,080	\$530-\$2230	\$260-\$1100
Funded by the 2018 Bond	Emergency Light and Power Systems. Generator and Transfer Switch. Replace generator and associated equipment.	\$63,450	\$6350-\$27350	\$3180-\$13650
	Chilled Water Systems. Chiller, cooling tower. Replace chiller	\$290,820	\$29090-\$125090	\$14550-\$62530
	Local Area Networks. ITS/Head End Equipment. Expanded or new MDF closet (minimum 10'X10').	\$49,180	\$4930-\$21230	\$2460-\$10580
	Flooring Hallways/Classrooms. Replace VCT in classrooms due to building movement.	\$9,840	\$1070-\$4270	\$500-\$2120
	Flooring Kitchen. Replace kitchen flooring.	\$62,400	\$6310-\$26910	\$3120-\$13420
	Flooring Cafeteria. Replace VCT.	\$15,870	\$1640-\$6840	\$800-\$3410
	Exterior Wall Construction. Seal and repair CMU. Stress cracks same as other schools. Lack of control joints	\$17,670	\$1840-\$7640	\$890-\$3800
	Exterior Wall Construction. Recaulk control joints.	\$3,390	\$420-\$1520	\$170-\$730
2-High	Exterior Windows . Major gaps need sealed and maintained yearly due to building movement.	\$3,920	\$490-\$1690	\$200-\$850
	Exterior Windows. Recaulk windows	\$13,220	\$1390-\$5790	\$670-\$2850
	Storefront windows. All entrances need filler plates fabricated and installed. The building movement has created large gaps which has been filled with caulking and is only temporary due to shrinkage creating air gaps	\$30,670	\$3140-\$13240	\$1540-\$6600
	Paving & Surfacing. Sidewalks. Repair/replace sections of sidewalk as necessary	\$24,540	\$2470-\$10570	\$1230-\$5280
	Glazed Roof Openings.Skylights. Repair leakage at skylights	\$5,500	\$610-\$2410	\$280-\$1190
	Operable Partition. Minor repairs needed	\$11,640	\$1170-\$5070	\$590-\$2510
2-Medium	Fabricated Toilet partitions. Replace toilet partitions	\$23,270	\$2340-\$10040	\$1170-\$5010
	Paving & Surfacing. Parking Lot Fair. Resurface and crack fill asphalt as necessary. Overlay parking lot at east end by drain	\$48,970	\$4940-\$21140	\$2450-\$10530
3-High	Wall Foundations. Recaulk foundation where concrete meets	\$3,280	\$430-\$1430	\$170-\$710
	Vinyl Coverings. Repair/ replace vinyl due to building movement and water damage at storefronts	\$16,290	\$1720-\$7020	\$820-\$3510
3-Medium	Ceiling Finishes. Repair ceiling grid due to building movement	\$164,970	\$16530-\$71030	\$8250-\$35470
	Grease interceptor. Bypass if applicable	\$8,150	\$860-\$3560	\$410-\$1760


Estimated Total Construction Costs (in 2019 Dollars): \$1,121,690 Estimated Project Management Costs Range: \$113,300 - \$483,500 Estimated Inflation Range: \$56,190 - \$241,270

Estimated Total Project Costs: \$1,291,180 - \$1,846,460



312 Cantril Street Castle Rock, CO 80104 Administration/District Offices and Preschool Facility Constructed in 1897

#### Cantril Building-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$1,830,480 Estimated Total Project Costs: \$2,109,160 - \$3,015,100

Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Roof Finishes. Replace shingled roof.	\$152,280	\$15320-\$65520	\$7620-\$32740
	Controls. Better control of existing steam distribution system.	\$23,480	\$2430-\$10130	\$1180-\$5050
	Panels and Transformers. Replace panel on second level, small office.	\$2,970	\$340-\$1340	\$150-\$640
	Panels and Transformers. Replace panel in furnace closet PS.	\$2,540	\$270-\$1170	\$130-\$550
	Branch Wiring Devices. Upgrade branch wiring and devices to current code.	\$23,480	\$2430-\$10130	\$1180-\$5050
	Branch Wiring Devices. Upgrade electrical wiring to current code PS.	\$4,660	\$550-\$2050	\$240-\$1000
	Sanitary Sewer Systems. Repair/replace sanitary sewer system piping.	\$23,480	\$2430-\$10130	\$1180-\$5050
	Roof Finishes. Replace EPDM gym roof.	\$25,380	\$2620-\$10920	\$1270-\$5460
	Roof Finishes. Replace EPDM roof on pre-school addition.	\$38,070	\$3830-\$16430	\$1910-\$8190
	Roof Eaves and Soffits. Restoration of eaves and soffits.	\$23,480	\$2430-\$10130	\$1180-\$5050
Tier 1 Funded by the	Gutters and Downspouts. Replace all gutters and downspouts. Reconfigure down spouts and drains at SE entry.	\$7,620	\$790-\$3290	\$390-\$1640
2018 Bond	Steam Distribution Systems. Steam piping is old and needs to be checked thoroughly for replacement. Many fittings and valves rusting and in need of replacement. Many of the radiators need renovated or replaced.	\$52,880	\$5330-\$22830	\$2650-\$11370
	Hot Water Distribution. Add hot water distribution to fan coil units in each room. Add heat exchanger for boiler.	\$67,050	\$6760-\$28860	\$3360-\$14420
	Chilled Water Distribution. Add chilled water distribution and fan coil units in each room.	\$334,390	\$33520-\$143820	\$16720-\$71900
	Package Units. Install new window AC units.	\$4,660	\$550-\$2050	\$240-\$1000
	Controls. Add new DDC controls if new HVAC system installed.	\$256,130	\$25680-\$110180	\$12810-\$55070
	Lighting Equipment. Replace incandescent lighting fixtures throughout as necessary.	\$2,970	\$340-\$1340	\$150-\$640
	Lighting Equipment. Replace old incandescent fixtures in hallways PS.	\$2,540	\$270-\$1170	\$130-\$550
	Clock and Program Systems. Install new clock system.	\$4,660	\$550-\$2050	\$240-\$1000
	Emergency Light and Power Systems. Add LED emergency/exit lighting.	\$4,660	\$550-\$2050	\$240-\$1000
	Emergency Light and Power Systems. Add LED emergency/exit lighting PS.	\$2,970	\$340-\$1340	\$150-\$640
	Flooring Restroom. Replace restoom flooring. Currently all 3 restrooms have VCT.	\$7,300	\$810-\$3210	\$370-\$1570
	Flooring Gym. Replace carpet in gym.	\$13,750	\$1460-\$5960	\$690-\$2960
2-High	Glazed Doors and Entrances. Restoration of two front entrances	\$2,970	\$340-\$1340	\$150-\$640
2-High	Fabricated Toilet Partitions. Restore or replace (historic) partitions on lower level	\$6,980	\$720-\$3030	\$350-\$1510
	Sinks. Replace older sinks in restrooms	\$2,750	\$360-\$1260	\$140-\$600
	Waste Piping. Check waste piping at restroom areas. The piping is old and many are exposed.	\$530	\$80-\$280	\$30-\$120
	Flooring Hallways/Classrooms. Sand and refinish all wood flooring.	\$23,480	\$2430-\$10130	\$1180-\$5050
	Flooring Restroom. Replace VCT in all restrooms, includes abatement PS.	\$1,910	\$200-\$900	\$100-\$410
2-Medium	Flooring Hallways/Classrooms. Replace VCT in preschool classroms and offices, includes abatement PS.	\$9,420	\$990-\$4090	\$480-\$2030
	Flooring Carpet. Replace carpet on stairs and room 102. Replace carpet squares upper level, landing and two offices, or remove and refinish wood floor. Carpet newer in 204, 205. Newest in 107.	\$14,070	\$1440-\$6140	\$710-\$3030


Estimated Total Construction Costs (in 2019 Dollars): \$1,830,480 Estimated Project Management Costs Range: \$186,790 - \$790,900 Estimated Inflation Range: \$91,890 - \$393,720

Estimated Total Project Costs: \$2,109,160 - \$3,015,100

# **Douglas County Schools Stadium**

2842 Front Street Castle Rock, CO 80104 DCSD Stadium

# Douglas County Schools Stadium-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$1,298,770 Estimated Total Project Costs: \$1,494,160 - \$2,137,060

Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
Tier 1	Roof Finishes. Replace roof.	\$63,450	\$6350-\$27350	\$3180-\$13650
Funded by the 2018 Bond	Fire Alarm Systems. Upgrade fire alarm system.	\$21,150	\$2150-\$9150	\$1060-\$4550
2.15-6	Paving and Surfacing. Sidewalks. Replace/repair areas of sidewalk around concession and bleachers	\$108,400	\$10910-\$46710	\$5420-\$23310
2-High	Miscellaneous Structures. Replace bleachers including concrete supporting system	\$245,560	\$24650-\$105650	\$12280-\$52800
2.11.1	Storage Shelving and Lockers. Band lockers need replaced	\$9,420	\$990-\$4090	\$480-\$2030
3-High	Fences and Gates. Repair/replace sections of fence around site	\$81,330	\$8180-\$34980	\$4070-\$17490
3-Medium	Ceiling Finishes. Caulk areas where ceiling meets CMU in stadium restrooms	\$2,230	\$280-\$980	\$120-\$480
з-меашт	Retaining Walls. Install new retaining walls for drainage issues	\$189,510	\$19000-\$81500	\$9480-\$40750
3-Low	Playing Fields. Other. Install concrete mow strip and crusher fines around new track	\$36,380	\$3730-\$15730	\$1820-\$7830
4-High	Other Landscape Features. Renovate areas inside and outside of immediate stadium area with new landscaping	\$541,340	\$54170-\$232870	\$27070-\$116390


Estimated Total Construction Costs (in 2019 Dollars): \$1,298,770 Estimated Project Management Costs Range: \$130,410 - \$559,010 Estimated Inflation Range: \$64,980 - \$279,280

Estimated Total Project Costs: \$1,494,160- \$2,137,060



3950 Trail Boss Lane Castle Rock, CO 80104 Early Childhood Center

# Early Childhood Center-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$84,600 Estimated Total Project Costs: \$97,330 - \$139,190

Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
2-Medium	Paving and Surfacing. Parking Lot. Resurface asphalt parking lot	\$84,600	\$8500-\$36400	\$4230-\$18190

Estimated Total Construction Costs (in 2019 Dollars): \$84,600 Estimated Project Management Costs Range: \$8,500 - \$36,400 Estimated Inflation Range: \$4,230 - \$18,190


Estimated Total Project Costs: \$97,330 - \$139,190



11901 Newlin Gulch Blvd. Parker, CO 80134 DCSD Stadium

Funded by 2006 Bond Opened in 2009

# **EchoPark Stadium-Identified Facility Projects** Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$21,150 Estimated Total Project Costs: \$24,360 - \$34,850

Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Miscellaneous Structures. Repair gap between concrete bleacher structure and retaining walls main side	\$21,150	\$2150-\$9150	\$1060-\$4550

Estimated Total Construction Costs (in 2019 Dollars): \$21,150 Estimated Project Management Costs Range: \$2,150 - \$9,150

Estimated Inflation Range: \$1,060 - \$4,550

Estimated Total Project Costs: \$24,360 - \$34,850



9195 East Mineral Avenue Centennial, CO 80112 DCSD Fleet and Bus Service Center

# Joint Service Center-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$362,510 Estimated Total Project Costs: \$417,880 - \$597,160


Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Roof Finishes. Install new roof over admin and garage areas.x-Roof over garage area replaced 2014, admin area parapet walls only.	\$116,650	\$11760-\$50160	\$5840-\$25080
Tier 1	Fire Alarm Systems. Upgrade fire alarm system. 1/2 share.	\$47,590	\$4820-\$20520	\$2380-\$10240
Funded by the 2018 Bond	Exhaust Ventilation Systems. Exhaust fans in garage are very loud and need some type of sound insulation.	\$2,540	\$270-\$1170	\$130-\$550
	Terminal Self-Contained Units. Replace MAU for garage with DX heating and cooling unit.	\$60,810	\$6100-\$26200	\$3040-\$13080
	Site Electrical Distribution. Repair concrete bollards protecing bus heater outlets.	\$2,540	\$270-\$1170	\$130-\$550
	Flooring Restroom. Replace sheet vinyl in restrooms.	\$7,620	\$790-\$3290	\$390-\$1640
	Flooring Hallways/Classrooms. Replace VCT in lounge.	\$3,920	\$490-\$1690	\$200-\$850
	Exterior Wall Construction. Re-seal CMU and recaulk control joints	\$4,660	\$550-\$2050	\$240-\$1000
	Overhead Doors. Repair garage doors, repair controls	\$4,660	\$550-\$2050	\$240-\$1000
	Sink Countertops. Replace sink countertops in admin restrooms	\$2,440	\$270-\$1070	\$130-\$530
	Wash Fountains. Replace wash fountain at garage area	\$2,970	\$340-\$1340	\$150-\$640
2-Medium	Hazardous Waste Remediation. Water drains into used oil holding area. Mitigate water flow into pit	\$2,970	\$340-\$1340	\$150-\$640
	Paving and Surfacing. Parking Lot. Repair areas of concrete parking area. Recaulk all joints	\$46,750	\$4760-\$20160	\$2340-\$10050
	Paving and Surfacing. Parking Lot. Improve drainage in front of admin entrance	\$23,480	\$2430-\$10130	\$1180-\$5050
	Curbs, Rails and Barriers. Repair/replace areas of curb and gutter	\$9,420	\$990-\$4090	\$480-\$2030
	Paving & Surfacing. Sidewalks. Repair/replace sections of sidewalk as necessary	\$9,420	\$990-\$4090	\$480-\$2030
3-High	Standard Slab on Grade. F-wing, drama room and science room had the floor lifted in 2007. Floor has dropped by the column by 500L entrance.	\$14,070	\$1440-\$6140	\$710-\$3030

Estimated Total Construction Costs (in 2019 Dollars): \$362,510 Estimated Project Management Costs Range: \$37,160 - \$156,660 Estimated Inflation Range: \$18,210 - \$77,990

Estimated Total Project Costs: \$417,880 -\$597,160

3002 North State Highway 83 Franktown, CO 80116 DCSD Operations & Maintenance Facility

# Operations & Maintenance East Facility-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$409,150 Estimated Total Project Costs: \$471,670 - \$674,340

Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Energy Supply. Replace outside gas piping to inside of building	\$1,590	\$220-\$720	\$80-\$350
	Switchgear-Main. Replace main switchgear.	\$37,440	\$3770-\$16170	\$1880-\$8050
	Panels and Transformers. Replace panels and transformer.	\$14,070	\$1440-\$6140	\$710-\$3030
Tier 1 Funded by the	Branch Wiring Devices. Replace romex wiring with conduit system.	\$14,070	\$1440-\$6140	\$710-\$3030
2018 Bond	Roof Finishes. New roof on north wood structure if kept for storage.	\$15,760	\$1650-\$6850	\$790-\$3390
	Interior Door Hardware. Replace hardware where necessary.	\$26,760	\$2750-\$11550	\$1340-\$5760
	Auxiliary Equipment. Replace furnace units.	\$12,690	\$1310-\$5510	\$640-\$2730
	Package Units. Replace AC units.	\$23,480	\$2430-\$10130	\$1180-\$5050
	Exterior Wall Construction. Re-point areas of brick, repair cracks	\$4,660	\$550-\$2050	\$240-\$1000
	Exterior Windows. Caulk windows	\$2,970	\$340-\$1340	\$150-\$640
	Lavatories. Replace faucets	\$2,970	\$340-\$1340	\$150-\$640
	Sinks. Replace sinks in restrooms and in shop area	\$2,540	\$270-\$1170	\$130-\$550
	Wash Fountains. Replace wash fountain in shop area	\$12,690	\$1310-\$5510	\$640-\$2730
2-Medium	Drinking Fountains and Coolers. Replace electric drinking fountains (2)	\$7,620	\$790-\$3290	\$390-\$1640
	Paving and Surfacing. Roadways. Replace sections of concrete roadway around building	\$28,130	\$2880-\$12180	\$1410-\$6050
	Paving and Surfacing. Parking Lot. Replace sections of concrete parking areas	\$18,720	\$1890-\$8090	\$940-\$4030
	Paving & Surfacing. Sidewalks. Repair/replace sections of sidewalk as necessary	\$9,420	\$990-\$4090	\$480-\$2030
2-Low	Curbs, Rails and Barriers. Install curbs to improve drainage	\$9,420	\$990-\$4090	\$480-\$2030
	Wall Foundations. Re-caulk where sidewalks meet foundation walls	\$2,970	\$340-\$1340	\$150-\$640
	Paint Interior. Paint interior office areas	\$9,420	\$990-\$4090	\$480-\$2030
3-Medium	Fire Sprinkler Water Supply. Install sprinkler system	\$140,440	\$14070-\$60470	\$7030-\$30200
	Retaining Walls. Repair brick retaining walls at both dock areas, timber retaining walls at north dock and along fenceline in back	\$11,320	\$1190-\$4890	\$570-\$2440

Estimated Total Construction Costs (in 2019 Dollars): \$409,150 Estimated Project Management Costs Range: \$41,950 - \$177,150 Estimated Inflation Range: \$20,570- \$88,040

Estimated Total Project Costs: \$471,670 - \$674,340

2806 Highway 85, Building A Castle Rock, CO 80109 DCSD Operations & Maintenance Facility

# Operations & Maintenance West Facility-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$57,290 Estimated Total Project Costs: \$66,170 - \$94,800

Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
Tier 1	Fire Alarm Systems. Upgrade fire alarm system.	\$21,150	\$2150-\$9150	\$1060-\$4550
Funded by the 2018 Bond	Roof Eaves and Soffits. Fix drainage issues at front and rear entries.	\$2,540	\$270-\$1170	\$130-\$550
	Flooring Carpet. Replace carpet.	\$19,190	\$2020-\$8320	\$960-\$4130
	Paint Exterior. Paint exterior	\$7,620	\$790-\$3290	\$390-\$1640
2-Medium	Exterior Windows. Replace windows	\$1,910	\$200-\$900	\$100-\$410
z-meatum	Exterior Windows. Replace basement windows	\$1,910	\$200-\$900	\$100-\$410
	Solid Exterior Doors. Replace north and south entry doors	\$1,910	\$200-\$900	\$100-\$410
	Solid Exterior Doors. Replace exterior door at NE office	\$1,060	\$150-\$550	\$60-\$230

Estimated Total Construction Costs (in 2019 Dollars): \$57,290 Estimated Project Management Costs Range: \$5,980 -\$25,180 Estimated Inflation Range: \$2,900 - \$12,330


Estimated Total Project Costs: \$66,170 - \$94,800



3270 Redstone Park Circle Littleton, CO 80129 DCSD Stadium

Funded by 1997 Bond Opened in 2000

#### Shea Stadium-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$1,128,870 Estimated Total Project Costs: \$1,299,000 - \$1,858,160

Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Hot Water Service. Water Heater. Replace vent pipe on north unit.	\$3,810	\$400-\$1700	\$190-\$820
Tier 1	Air Distribution Systems. Air handlers. ductwork. VAV's. Replace vent piping due to condensation.	\$3,810	\$400-\$1700	\$190-\$820
Funded by the 2018 Bond	Fire Alarm Systems. Upgrade fire alarm system.	\$12,690	\$1310-\$5510	\$640-\$2730
2018 Bollu	Emergency Light and Power Systems. Generator and Transfer Switch. Replace generator and associated equipment.	\$63,450	\$6350-\$27350	\$3180-\$13650
	Exterior Wall Construction. CMU and Brick. Reseal and repair block walls, severe cracks due to movement multiple locations	\$10,370	\$1040-\$4540	\$520-\$2230
	Paint Exterior. Paint red steel and handrails	\$31,100	\$3110-\$13410	\$1560-\$6690
	Paint Exterior. Paint all red iron and trim	\$19,780	\$2030-\$8530	\$990-\$4260
	Exterior Windows. Replace press box windows	\$20,730	\$2080-\$8980	\$1040-\$4460
2-High	Fixed Casework. Replace press box countertops	\$6,350	\$660-\$2760	\$320-\$1370
2 mgn	Paving and Surfacing. Parking Lot. Resurface asphalt parking lot	\$216,480	\$21730-\$93130	\$10830-\$46550
	Curbs, Rails and Barriers. Repair curbs at parking lot	\$21,680	\$2230-\$9430	\$1090-\$4670
	Paving & Surfacing. Sidewalks. Repair/replace sections of sidewalk as necessary	\$32,580	\$3330-\$14030	\$1630-\$7010
	Miscellaneous Structures. Bleachers. Replace bleachers with stronger seating	\$324,870	\$32540-\$139740	\$16250-\$69850
2-Medium	Paint Exterior. Paint bleacher flooring, paint all metal.	\$8,250	\$860-\$3560	\$420-\$1780
3-High	Special Foundations. Large gap needs filled completely around the new classroom addition between the foundation and sidewalk	\$84,710	\$8500-\$36500	\$4240-\$18220
	Upper Floor. Repairs needed on bleacher section, water leaks creating damage underneath	\$10,370	\$1040-\$4540	\$520-\$2230
	Suspended Ceilings. Replace ceiling tiles in storage areas due to water leaks	\$640	\$70-\$370	\$40-\$140
	Paint Interior. Paint storage room due to water damage	\$2,650	\$360-\$1160	\$140-\$570
3-Medium	Fences and Gates. Repair/replace fencing around site and bleacher areas	\$216,480	\$21730-\$93130	\$10830-\$46550
	Retaining Walls. Repair work on retaining walls	\$38,070	\$3830-\$16430	\$1910-\$8190


Estimated Total Construction Costs (in 2019 Dollars): \$1,128,870 Estimated Project Management Costs Range: \$113,600 - \$486,500 Estimated Inflation Range: \$56,530 - \$242,790

Estimated Total Project Costs: \$1,299,000 - \$1,858,160



11722 Dransfeldt Road, Building B Parker, CO 80134 **DCSD Support Services** 

#### Student Support Center-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$67,320 Estimated Total Project Costs: \$78,160 - \$111,530


Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Roof Finishes. Replace roof. Asphalt shingle.	\$10,580	\$1130-\$4630	\$530-\$2280
Tier 1 Funded by the	Hot Water Distribution. Replace water baseboard heaters	\$2,970	\$340-\$1340	\$150-\$640
2018 Bond	Air Distribution Systems. Improve ventilation in conference room.	\$4,660	\$550-\$2050	\$240-\$1000
	Flooring Restroom. Replace VCT in 2 bathrooms.	\$1,060	\$150-\$550	\$60-\$230
	Carpeting. Replace carpet.	\$4,660	\$550-\$2050	\$240-\$1000
	Paint Exterior. Paint exterior	\$2,540	\$270-\$1170	\$130-\$550
2-Medium	Windows. Replace windows (10)	\$7,620	\$790-\$3290	\$390-\$1640
	Interior Construction. Enlarge restroom on main floor	\$4,660	\$550-\$2050	\$240-\$1000
	Sinks. Replace sinks	\$1,060	\$150-\$550	\$60-\$230
	Paving & Surfacing. Resurface parking area	\$4,660	\$550-\$2050	\$240-\$1000
	Miscellaneous Structures. Replace wooden decks front and rear. Rear deck non-code compliant	\$18,720	\$1890-\$8090	\$940-\$4030
2-Low	Water Closets. Replace toilets (2)	\$1,590	\$220-\$720	\$80-\$350
3-Medium	Paint Interior. Paint interior. Repair drywall as necessary	\$2,540	\$270-\$1170	\$130-\$550

Estimated Total Construction Costs (in 2019 Dollars): \$67,320 Estimated Project Management Costs Range: \$7,410 - \$29,710 Estimated Inflation Range: \$3,430 - \$14,500

Estimated Total Project Costs: \$78,160 - \$111,530

2808 Highway 85, Building B Castle Rock, CO 80109 **DCSD Transportation Terminal** 

#### West Transportation Terminal-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$804,950 Estimated Total Project Costs: \$926,720 - \$1,325,270

Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Panels and Transformers. Replace panels inside and at bus parking.	\$9,420	\$990-\$4090	\$480-\$2030
Tier 1	Fire Alarm Systems. Upgrade fire alarm system.	\$26,440	\$2670-\$11470	\$1330-\$5690
Funded by the	Interior Door Hardware. Replace door hardware.	\$22,000	\$2210-\$9510	\$1100-\$4730
2018 Bond	Branch Wiring Devices. Replace outlets and wiring for bus outlets.	\$9,420	\$990-\$4090	\$480-\$2030
	Glazed Roof Openings. Add sola tubes for daylighting.	\$28,130	\$2880-\$12180	\$1410-\$6050
2-High	Paving and Surfacing. Parking Lot. Resurface asphalt parking lot	\$392,650	\$39350-\$168850	\$19640-\$84420
	Flooring Restroom. Replace ceramic tile with seamless acrylic.	\$4,660	\$550-\$2050	\$240-\$1000
	Overhead Doors. Replace garage doors, add windows for daylighting	\$46,750	\$4760-\$20160	\$2340-\$10050
	Interior Doors. Replace interior doors in admin area	\$9,420	\$990-\$4090	\$480-\$2030
	Fabricated Toilet Partitions. Replace toilet partitions in both restrooms	\$2,440	\$270-\$1070	\$130-\$530
2-Medium	Sink Countertops. Replace countertop in men's restroom	\$1,490	\$220-\$720	\$80-\$320
	Stair, Tread and Landing Finishes. Replace railing of storage area above electrical room. Not code compliant	\$1,910	\$200-\$900	\$100-\$410
	Lavatories. Replace faucets in mens restroom	\$1,060	\$150-\$550	\$60-\$230
	Sinks. Replace sinks in mens restroom	\$1,060	\$150-\$550	\$60-\$230
	Paving and Surfacing. Parking Lot. Pave areas of asphalt for excess parking	\$187,180	\$18730-\$80530	\$9360-\$40250
3-High	Structural Slab on Grade. Apply coating to garage floor	\$28,130	\$2880-\$12180	\$1410-\$6050
3-Medium	Interior Door Frames. Replace door jambs in admin area	\$4,660	\$550-\$2050	\$240-\$1000
3-Mediuili	Site Lighting Poles. Add site lighting to parking area	\$28,130	\$2880-\$12180	\$1410-\$6050


Estimated Total Construction Costs (in 2019 Dollars): \$804,950 Estimated Project Management Costs Range: \$81,420 - \$347,220 Estimated Inflation Range: \$40,350 - \$173,100

Estimated Total Project Costs: \$926,720 - \$1,325,270



8236 Carter Court Littleton, CO 80125 **DCSD Transportation Terminal** 

#### North Transportation Terminal-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$2,148,940 Estimated Total Project Costs: \$2,474,170 - \$3,537,710


Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Roof Finishes. Replace area D.	\$50,760	\$5140-\$21840	\$2540-\$10920
	Boilers. Remove boiler and hot water heating system (HVAC option 2).	\$4,660	\$550-\$2050	\$240-\$1000
	Boilers. Install new boiler if current heating system is used (HVAC option 1).	\$28,130	\$2880-\$12180	\$1410-\$6050
	Direct Expansion Systems. Replace RTU's with gas fired for heating. Add gas lines for all units, Add split system for MDF closet (HVAC option 2).	\$327,410	\$32800-\$140800	\$16370-\$70400
	Direct Expansion Systems. Replace RTU's 5 total. Add split system for MDF closet (HVAC option 1).	\$257,190	\$25820-\$110620	\$12860-\$55300
	Hot Water Distribution. Replace radiators. Replace fin tube heaters in lounge and in restroom off gym (option 1)	\$4,660	\$550-\$2050	\$240-\$1000
	Controls. Upgrade DDC system.	\$158,630	\$15880-\$68280	\$7940-\$34110
	Panels and Transformers. Replace two panels in main electrical room and one in SW addition.	\$11,320	\$1190-\$4890	\$570-\$2440
Tier 1	Fire Alarm Systems. Replace fire alarm system.	\$26,440	\$2670-\$11470	\$1330-\$5690
Funded by the	Fuel Distribution. Replace natural gas service.	\$18,720	\$1890-\$8090	\$940-\$4030
2018 Bond	Roof Eaves and Soffits. Replace facia board where necessary.	\$4,660	\$550-\$2050	\$240-\$1000
	Hot Water Service. Water Heater. In lieu of boiler replacement and HVAC RTU replacement upgrade, install water heaters for domestic service (HVAC option 2).	\$14,070	\$1440-\$6140	\$710-\$3030
	Roof Drains. Check roof drains for proper functionality.	\$1,060	\$150-\$550	\$60-\$230
	Boiler Room Piping and Specialties. Replace piping at boiler room (HVAC option 1).	\$14,070	\$1440-\$6140	\$710-\$3030
	Exhaust Ventilation Systems. Replace exhaust fans as necessary.	\$4,660	\$550-\$2050	\$240-\$1000
	Lighting Equipment. Replace plastic lense diffusers on 2x4 fixtures. Replace wrap around difussers on a few fixtures.	\$4,660	\$550-\$2050	\$240-\$1000
	Site Electrical Distribution. Install electrical power for bus heaters. Repair current service at east parking lot.	\$18,720	\$1890-\$8090	\$940-\$4030
	Retention Ponds. Rework water entry to south pond, clean pond.	\$4,660	\$550-\$2050	\$240-\$1000
2-High	Flooring Carpet. Replace carpet.	\$120,500	\$12110-\$51910	\$6030-\$25910
	Flooring Gym. Replace VCT in gym (abatement)(option1).	\$46,750	\$4760-\$20160	\$2340-\$10050
	Flooring Gym. Install carpet over gym tile, no abatement (option 2).	\$14,070	\$1440-\$6140	\$710-\$3030
	Exterior Wall Construction. Repair/repoint CMU and brick as necessary	\$9,420	\$990-\$4090	\$480-\$2030
	Paint Exterior. Paint exterior of garage	\$9,420	\$990-\$4090	\$480-\$2030
	Paint Exterior. Paint exterior	\$9,420	\$990-\$4090	\$480-\$2030
	Exterior Windows. Replace exterior windows	\$46,750	\$4760-\$20160	\$2340-\$10050
2-Medium	Solid Exterior Doors. Replace exterior doors and jambs	\$19,780	\$2030-\$8530	\$990-\$4260
2 Wediani	Interior Doors. Replace interior doors	\$20,730	\$2080-\$8980	\$1040-\$4460
	Pipe and Fittings. Piping and fittings need to be checked for replacement	\$1,060	\$150-\$550	\$60-\$230
	Fixed Casework. Replace/refinish casework as necessary	\$28,130	\$2880-\$12180	\$1410-\$6050
	Paving and Surfacing. Parking Lot. Resurface parking lot, front of building and south bus parking area	\$280,670	\$28140-\$120740	\$14040-\$60350
	Paving and Surfacing. Parking Lot. Install asphalt for bus parking east area and employee parking south of building	\$327,410	\$32800-\$140800	\$16370-\$70400

Estimated Total Construction Costs (in 2019 Dollars): \$2,148,940 Estimated Project Management Costs Range: \$217,520 - \$926,620 Estimated Inflation Range: \$107,710 - \$462,150

Estimated Total Project Costs: \$2,474,170 - \$3,537,710

2812 Highway 85, Building E Castle Rock, CO 80109 Administration/District Offices Facility

### Warehouse Service Center-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2018 Dollars): \$372,720 Estimated Total Project Costs: \$429,220 - \$613,890

Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Roof Finishes. Replace .045 ballasted EPDM with .060 fully adhered on Bld. B.	\$101,520	\$10180-\$43680	\$5080-\$21830
	Controls. Replace current control system with Delta.	\$158,630	\$15880-\$68280	\$7940-\$34110
Tier 1	Roof Finishes. Apply roof coating to metal roof of warehouse.	\$17,980	\$1830-\$7830	\$900-\$3870
Funded by the 2018 Bond	Terminal Self-Contained Units. Replace Whirlpool unit for warehouse offices.	\$18,720	\$1890-\$8090	\$940-\$4030
	Terminal Self-Contained Units. Replace split system for print room.	\$32,790	\$3320-\$14120	\$1640-\$7050
	Terminal Self-Contained Units. Replace outdoor AC unit closest to rear entry door.	\$4,660	\$550-\$2050	\$240-\$1000
	Flooring Restroom. Replace VCT in restrooms by copier.	\$1,060	\$150-\$550	\$60-\$230
	Flooring Kitchen. Replace VCT in breakroom.	\$2,540	\$270-\$1170	\$130-\$550
2-Medium	Flooring Hallways/Classrooms. Replace VCT in hallway by breakroom.	\$640	\$70-\$370	\$40-\$140
2-Medium	Flooring Carpet. Replace carpet in conference/training room in warehouse.	\$10,580	\$1130-\$4630	\$530-\$2280
	Exterior Wall Construction. Reseal CMU on Bld E	\$4,660	\$550-\$2050	\$240-\$1000
	Paint Exterior. Paint exterior	\$11,320	\$1190-\$4890	\$570-\$2440
3-Medium	Paint Interior. Paint interior of Bld E and warehouse office areas	\$7,620	\$790-\$3290	\$390-\$1640

Estimated Total Construction Costs (in 2019 Dollars): \$372,720 Estimated Project Management Costs Range: \$37,800 - \$161,000

Estimated Inflation Range: \$18,700 - \$80,170

Estimated Total Project Costs: \$429,220 - \$613,890



701 Prairie Hawk Drive Castle Rock, CO 80109 Administration/District Offices Facility

#### West Support Center-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$426,110 Estimated Total Project Costs: \$490,500 - \$701,290

Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Glazed Roof Openings. Replace fiberglass translucent panels.	\$16,920	\$1780-\$7280	\$850-\$3640
Tier 1 Funded by the	Roof Finishes. Apply roof coating to metal roof to extend life.	\$52,880	\$5330-\$22830	\$2650-\$11370
2018 Bond	Flashings & Trim. Replace roof cap.	\$2,970	\$340-\$1340	\$150-\$640
	Piping. Improve storm water drainage by adding more underground piping.	\$93,700	\$9410-\$40310	\$4690-\$20150
2-High	Paving and Surfacing. Parking Lot. Resurface asphalt parking lot	\$245,560	\$24650-\$105650	\$12280-\$52800
2-Medium	Exterior Wall Construction. Improve insulation on warehouse walls	\$9,420	\$990-\$4090	\$480-\$2030
	Overhead Doors. Replace or insulate original garage doors east side warehouse	\$4,660	\$550-\$2050	\$240-\$1000


Estimated Total Construction Costs (in 2019 Dollars): \$426,110 Estimated Project Management Costs Range: \$43,050 - \$183,550 Estimated Inflation Range: \$21,340 - \$91,630

Estimated Total Project Costs: \$490,500 - \$701,290



620 Wilcox Street Castle Rock, CO 80104 Administration/District Offices Facility

#### Wilcox Building-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$1,424,260 Estimated Total Project Costs: \$1,639,330 - \$2,345,070


Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Roof Finishes. Replace sningles on original building areas A,B,C.D.	\$132,190	\$13320-\$56920	\$6610-\$28420
	Flooring Carpet. Replace entry carpets.	\$11,430	\$1180-\$4980	\$580-\$2460
	Passenger Elevators. Overhaul elevators.	\$317,250	\$31750-\$136450	\$15870-\$68210
	Direct Expansion Systems. Roof top units. Replace RTUs.	\$105,750	\$10650-\$45550	\$5290-\$22740
	Hot Water Distribution. Ceiling unit heater at front entrance needs reset into drywall.	\$430	\$80-\$280	\$30-\$100
	Switchgear-Main. Replace main switchgear.	\$28,130	\$2880-\$12180	\$1410-\$6050
Tier 1 Funded by the	Panels and Transformers. Replace panels and transformers.	\$28,130	\$2880-\$12180	\$1410-\$6050
2018 Bond	Fire Alarm Systems. Upgrade fire alarm system.	\$95,180	\$9530-\$41030	\$4760-\$20470
2010 50114	Emergency Light and Power Systems. Generator and Transfer Switch. Replace generator and associated equipment.	\$63,450	\$6350-\$27350	\$3180-\$13650
	Roof Finishes. Re-coat roof at main section.	\$53,940	\$5470-\$23270	\$2700-\$11600
	Flashings and Trim. Paint roof flashings.	\$2,540	\$270-\$1170	\$130-\$550
	Gutters and Downspouts. Paint gutters and downspouts.	\$2,540	\$270-\$1170	\$130-\$550
	Interior Door hardware. Replace current non-restricted key system with restricted	\$35,640	\$3670-\$15370	\$1790-\$7670
	Intercommunication & Paging System. Install new intercom system for building.	\$46,750	\$4760-\$20160	\$2340-\$10050
2-High	Paving and Surfacing. Parking Lot. Resurface asphalt parking lot	\$78,680	\$7930-\$33930	\$3940-\$16920
	Flooring Kitchen. Replace sheet vinyl 3rd fl break rm	\$1,910	\$200-\$900	\$100-\$410
	Flooring Carpet. Replace carpet.	\$140,440	\$14070-\$60470	\$7030-\$30200
2-Medium	Exterior Windows. Re-finish anodized aluminum frames. Replace 2 windows in Suite 311 and 1 in Board room	\$7,090	\$720-\$3120	\$360-\$1530
	Curbs, Rails and Barriers. Repair/replace sections of curb, repair and paint railing at back entry	\$9,420	\$990-\$4090	\$480-\$2030
	Paving & Surfacing. Sidewalks. Repair/replace sections of sidewalk as necessary	\$4,660	\$550-\$2050	\$240-\$1000
2-Low	Ceiling Finishes. Restain wood ceiling 2nd fl north (old gym)	\$9,420	\$990-\$4090	\$480-\$2030
	Wall Foundations. Recoat foundation walls on east side	\$2,540	\$270-\$1170	\$130-\$550
	Suspended Ceilings. Fix sagging ceiling grid lower level at mech rm entrance hallway.	\$1,060	\$150-\$550	\$60-\$230
3-Medium	Fire Sprinkler Water Supply. Install sprinkler system for entire building	\$187,180	\$18730-\$80530	\$9360-\$40250
	Blinds and Other Window Treatment. Re-attach blinds to wall in Board Rm	\$640	\$70-\$370	\$40-\$140
21	Paint Interior. Paint interior, metal beams and ductwork 2nd fl north	\$46,750	\$4760-\$20160	\$2340-\$10050
3-Low	Miscellaneous Structures. Clean brick and stone entry barriers	\$1,060	\$150-\$550	\$60-\$230
4 Modium	Seeding and Sodding. Repair areas of lawn	\$9,420	\$990-\$4090	\$480-\$2030
4-Medium	Site Lighting Poles. Paint lighting poles	\$640	\$70-\$370	\$40-\$140

Estimated Total Construction Costs (in 2019 Dollars): \$1,424,260 Estimated Project Management Costs Range: \$143,700- \$614,500 Estimated Inflation Range: \$71,370 - \$306,310

Estimated Total Project Costs: \$1,639,330 - \$2,345,070



#### Athletics-Identified Items Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority




Estimated Total Construction Costs (in 2019 Dollars): \$3,773,480 Estimated Total Project Costs: \$4,340,110 - \$6,208,070

Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Castle View High School track. Resurface track	\$528,750	\$52950-\$227450	\$26440-\$113690
	DCHS Stadium football field. Replace synthetic turf.	\$528,750	\$52950-\$227450	\$26440-\$113690
	Echo Park Stadium football field. Replace synthetic turf.	\$528,750	\$52950-\$227450	\$26440-\$113690
2-Medium	Echo Park Stadium track.Resurface track	\$528,750	\$52950-\$227450	\$26440-\$113690
	Legend High School football field. Replace synthetic turf.	\$528,750	\$52950-\$227450	\$26440-\$113690
	Legend High School track. Resurface track	\$528,750	\$52950-\$227450	\$26440-\$113690
2-Low	DCHS Stadium track. Resurface track	\$528,750	\$52950-\$227450	\$26440-\$113690

Estimated Total Construction Costs (in 2019 Dollars): \$3,773,480 Estimated Project Management Costs Range: \$377,930 - \$1,623,230 Estimated Inflation Range: \$188,700 - \$811,360

Estimated Total Project Costs: \$4,340,110 - \$6,208,070

#### Furniture, Fixtures, and Equipment-Identified Items Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$11,815,000 Estimated Total Project Costs: \$13,587,250 - \$18,254,255


Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Acres Green Elementary . Replace classroom furniture	\$200,000	\$20000-\$86000	\$10000-\$43000
	Arrowwood Elementary . Replace classroom furniture	\$200,000	\$20000-\$86000	\$10000-\$43000
	Bear Canyon Elementary . Replace classroom furniture	\$200,000	\$20000-\$86000	\$10000-\$43000
	Buffalo Ridge Elementary . Replace classroom furniture	\$200,000	\$20000-\$86000	\$10000-\$43000
	Castle Rock Elementary . Replace classroom furniture	\$200,000	\$20000-\$86000	\$10000-\$43000
	Castle Rock Middle School . Replace classroom furniture	\$300,000	\$30000-\$129000	\$15000-\$64500
	Chaparral High School . Replace classroom furniture	\$400,000	\$40000-\$172000	\$20000-\$86000
	Cherokee Trail Elementary . Replace classroom furniture	\$200,000	\$20000-\$86000	\$10000-\$43000
	Cherry Valley Elementary . Replace classroom furniture	\$30,000	\$3000-\$12900	\$1500-\$6450
	Cougar Run Elementary . Replace classroom furniture	\$200,000	\$20000-\$86000	\$10000-\$43000
	Coyote Creek Elementary . Replace classroom furniture	\$200,000	\$20000-\$86000	\$10000-\$43000
	Cresthill Middle School . Replace classroom furniture	\$300,000	\$30000-\$129000	\$15000-\$64500
	Douglas County High School . Replace classroom furniture	\$400,000	\$40000-\$172000	\$20000-\$86000
	Douglas County HS South Bldg . Replace classroom furniture	\$200,000	\$20000-\$86000	\$10000-\$43000
	Eagle Ridge Elementary . Replace classroom furniture	\$200,000	\$20000-\$86000	\$10000-\$43000
	Eldorado Elementary . Replace classroom furniture	\$200,000	\$20000-\$86000	\$10000-\$43000
	Flagstone Elementary . Replace furniture with 21st century learning furniture	\$200,000	\$20000-\$86000	\$10000-\$43000
	Fox Creek Elementary . Replace classroom furniture	\$200,000	\$20000-\$86000	\$10000-\$43000
	Franktown Elementary . Replace classroom furniture	\$200,000	\$20000-\$86000	\$10000-\$43000
	Frontier Valley Elementary . Replace classroom furniture	\$200,000	\$20000-\$86000	\$10000-\$43000
	Heritage Elementary . Replace classroom furniture	\$200,000	\$20000-\$86000	\$10000-\$43000
	Highlands Ranch High School . Replace classroom furniture	\$400,000	\$40000-\$172000	\$20000-\$86000
	Iron Horse Elementary . Replace classroom furniture	\$200,000	\$20000-\$86000	\$10000-\$43000
2 Madiana	Legacy Point Elementary . Replace furniture with 21st century learning furniture	\$200,000	\$20000-\$86000	\$10000-\$43000
3-Medium	Mountain Ridge Middle School . Replace furniture with 21st century learning fuurniture	\$300,000	\$30000-\$129000	\$15000-\$64500
	Mountain Vista High School . Replace classroom furniture	\$400,000	\$40000-\$172000	\$20000-\$86000
	Northeast Elementary . Replace classroom furniture	\$200,000	\$20000-\$86000	\$10000-\$43000
	Northridge Elementary . Replace classroom furniture	\$70,000	\$7000-\$30100	\$3500-\$15050
	Pine Grove Elementary . Replace classroom furniture	\$200,000	\$20000-\$86000	\$10000-\$43000
	Pine Lane North . Replace classroom furniture	\$200,000	\$20000-\$86000	\$10000-\$43000
	Pine Lane South . Replace classroom furniture	\$200,000	\$20000-\$86000	\$10000-\$43000
	Pioneer Elementary . Replace classroom furniture	\$200,000	\$20000-\$86000	\$10000-\$43000
	Ponderosa High School . Replace classroom furniture	\$400,000	\$40000-\$172000	\$20000-\$86000
	Prairie Crossing Elementary . Replace classroom furniture	\$200,000	\$20000-\$86000	\$10000-\$43000
	Ranch View Middle School . Replace classroom furniture	\$400,000	\$40000-\$172000	\$20000-\$86000
	Rock Ridge Elementary . Replace classroom furniture	\$200,000	\$20000-\$86000	\$10000-\$43000
	Rocky Heights Middle School . Replace furniture with 21st century learning furniture	\$300,000	\$30000-\$129000	\$15000-\$64500
	Roxborough Primary . Replace classroom furniture	\$200,000	\$20000-\$86000	\$10000-\$43000
	Saddle Ranch Elementary . Replace classroom furniture	\$200,000	\$20000-\$86000	\$10000-\$43000
	Sagewood Middle School . Replace classroom furniture	\$300,000	\$30000-\$129000	\$15000-\$64500
	Sand Creek Elementary . Replace classroom furniture	\$200,000	\$20000-\$86000	\$10000-\$43000
	Sedalia Elementary . Replace classroom furniture	\$90,000	\$9000-\$38700	\$4500-\$19350
	Sierra Middle School . Replace classroom furniture	\$300,000	\$30000-\$129000	\$15000-\$64500
	South Ridge Elementary . Replace classroom furniture	\$200,000	\$20000-\$86000	\$10000-\$43000
	ThunderRidge High School . Replace classroom furniture	\$400,000	\$40000-\$172000	\$20000-\$86000
	Timber Trail Elementary . Replace furniture with 21st century learning furniture	\$200,000	\$20000-\$86000	\$10000-\$43000
	Trailblazer Elementary . Replace classroom furniture	\$200,000	\$20000-\$86000	\$10000-\$43000
	Wildcat Mountain Elementary . Replace classroom furniture	\$200,000	\$20000-\$86000	\$10000-\$43000

Estimated Total Construction Costs (in 2019 Dollars): \$11,815,000 Estimated Project Management Costs Range: \$1,181,500 - \$3,899,000 Estimated Inflation Range: \$590,750 - \$2,540,225

Estimated Total Project Costs: \$13,587,250 - \$18,254,255



#### District-wide Facilities-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$14,815,820 Estimated Total Project Costs: \$15,195,820 - \$16,449,820

\*Note\* Estimated total costs include ADA contingency, Special Education contingency, and playground equipment. These needs are not prioritized and are not displayed in the graph above.

Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	36 Support Vehicles 150,000+ miles and over 15 years old.	\$1,332,580	N/A	N/A
	57 Support Vehicles under 150,000 miles and over 15 years old.	\$2,211,740	N/A	N/A
Tier 1 Funded by the	7 Support Vehicles 150,000+ miles and under 15 years old.	\$416,500	N/A	N/A
2018 Bond	Heavy Duty Use Vehicles. May not meet age and miles criteria but on replacement list, i.e., plow trucks, etc.	\$375,000	N/A	N/A
	39 Support Vehicles over 10 years old.	\$1,365,000	N/A	N/A
	29 Support Vehicles that will be over 10 years old in the next 5 years (no mileage accounted for).	\$1,015,000	N/A	N/A
	Bear Canyon Elementary - Mobile 18	\$200,000	N/A	\$10000-\$43000
	Castle View High School - Mobile 20	\$200,000	N/A	\$10000-\$43000
	Cherokee Trail Elementary - Mobile 11	\$200,000	N/A	\$10000-\$43000
	Eagle Ridge Elementary - Mobile 32	\$200,000	N/A	\$10000-\$43000
	Frontier Valley Elementary - Mobile 27	\$200,000	N/A	\$10000-\$43000
	Heritage Elementary - Mobile 17	\$200,000	N/A	\$10000-\$43000
	Legend High School - Mobile 19	\$200,000	N/A	\$10000-\$43000
	Northridge Elementary - Mobile 3	\$200,000	N/A	\$10000-\$43000
	Pine Lane North - Mobile 7	\$200,000	N/A	\$10000-\$43000
	Pine Lane South - Mobile 4	\$200,000	N/A	\$10000-\$43000
3-High	Pine Lane South - Mobile 5	\$200,000	N/A	\$10000-\$43000
5-riigii	Pioneer Elementary - Mobile 1	\$200,000	N/A	\$10000-\$43000
	Pioneer Elementary - Mobile 12	\$200,000	N/A	\$10000-\$43000
	Rock Ridge Elementary - Mobile 16	\$200,000	N/A	\$10000-\$43000
	Rocky Heights Middle School - Mobile 13	\$200,000	N/A	\$10000-\$43000
	Rocky Heights Middle School - Mobile 23	\$200,000	N/A	\$10000-\$43000
	Sand Creek Elementary - Mobile 15	\$200,000	N/A	\$10000-\$43000
	Sierra Middle School -Mobile 26	\$200,000	N/A	\$10000-\$43000
	Soaring Hawk Elementary - Mobile 14	\$200,000	N/A	\$10000-\$43000
	South Ridge Elementary - Mobile 24	\$200,000	N/A	\$10000-\$43000
	South Ridge Elementary - Mobile 28	\$200,000	N/A	\$10000-\$43000
	Wildcat Mtn Elementary - Mobile 22	\$200,000	N/A	\$10000-\$43000
	Castle View High School - Mobile 36	\$200,000	N/A	\$10000-\$43000
	Frontier Valley Elementary - Mobile 47	\$200,000	N/A	\$10000-\$43000
	Legacy Point Elementary - Mobile 42	\$200,000	N/A	\$10000-\$43000
	Pine Grove Elementary - Mobile 39	\$200,000	N/A	\$10000-\$43000
	Pine Grove Elementary - Mobile 43	\$200,000	N/A	\$10000-\$43000
3-Medium	Prarie Crossing Elementary - Mobile 38	\$200,000	N/A	\$10000-\$43000
	Rocky Heights Middle School - Mobile 44	\$200,000	N/A	\$10000-\$43000
	Saddle Ranch Elementary - Mobile 35	\$200,000	N/A	\$10000-\$43000
	Saddle Ranch Elementary - Mobile 35	\$200,000	N/A	\$10000-\$43000
	Sand Creek Elementary - Mobile 30	\$200,000	N/A	\$10000-\$43000
	Summit View Elementary - Mobile 31	\$200,000	N/A	\$10000-\$43000
	Contingency for ADA Compliance Projects	\$500,000	N/A	\$25000-\$107500
N/A-N/A	Contingency for Special Education Needs Related Projects	\$500,000	N/A	\$25000-\$107500
	Playground Equipment	\$500,000	N/A	\$25000-\$107500

Estimated Total Construction Costs (in 2019 Dollars): \$14,815,820

Estimated Project Management Cost Range: N/A Estimated Inflation Range: \$380,000 - \$1,634,000

Estimated Total Project Costs: \$15,195,820 - \$16,449,820



The Safety and Security Department identifies and prioritizes their capital needs based on a variety of criteria. These criteria range from risk to safety, necessity in order to comply with Federal, State, or Local mandates, frequency of system failure, potential impact to current level of service, life expectancy, the potential to enhance systems, and process improvement strategies.

Security Reinvestment Needs vs. Security Enhancements:

School Radio Core Infrastructure: Increase coverage and reliability of communication at each District school and provide emergency communication paths and identification to District Security.


School Radios: Replacement of radios District-wide to operate on new core infrastructure.

In-House Alarm Monitoring: Core infrastructure needed to move alarm monitoring in-house, includes servers, line cards, software, network and redundancy.

DTRS Radio Equipment for School Radios: Additional local radios and gateway for interoperability between DTRS system and School Radio system for Dispatch and First Responders.

Server Rotation: Replace 7 servers that will no longer be supported or overcapacity in the next 5 years at nonschool facilities.

\*The 2018 Bond will provide funds to address all security capital reinvestment needs noted in the Master Capital Plan. The Bond will also provide funds to upgrade building cameras along with other physical security enhancements to harden our schools. Beyond the next five years listed in this plan, the Safety and Security Department has identified \$14.7M-\$21.2M in projects to further enhance physical security at schools and other district assets and to replace security infrastructure due to life expectancy. To include charter schools, an increase in costs of 15%-25% would be needed.



Tier & Priority Class	Project Description	Estimated Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	In-House Alarm Monitoring	\$150,000	\$0	\$0
3-High	School Radio Core Infrastructure	\$1,452,872	\$0	\$0
	School Radios	\$3,256,343	\$0	\$0
	DTRS Radio Equipment for School Radios	\$65,000	\$0	\$0
3-Medium	Server Rotation	\$56,000	\$0	\$0

Estimated Total Project Costs: \$4,980,215

### Information Technology

The DCSD Information Technology Department supports all of the district technology applications and infrastructure distributed throughout our schools and office buildings. Ubiquitous availability of high speed internet is not a nice to have any more. There is a large impact to the smooth operations of schools and offices if internet connectivity is severed. To that end, the District's IT team continuously performs system updates to ensure connectivity of phone, internet, and other critical systems is maintained at the highest levels of operation. Critical Information Technology projects are being addressed with the funding made available from the 2018 Bond funds. Master Capital Plan requirements will continue to be assessed during the 2020-21 planning cycle.

Currently, DCSD owns and is responsible for:

- -75+ core district application services
- -730+/- servers to run and operate the district infrastructure
- -6,000 phones
- -3,800 wireless access points across all building/schools
- -2,000+/- network switches
- -55,000+ devices connected wirelessly (Laptops, Tablets, Notebooks, Smartphones, etc.)
- -300+ Terabytes of storage
- -130,000+ active directory accounts (staff, students, parents etc.)

The Information Technology Division's currently identified solutions and projects are prioritized on the effectiveness and impact to student education delivery. District technology initiatives are proposed by the IT division based on continual review of school staff and student educational requirements, administrative leadership, and reference to industry best practice solutions. A business case is developed to define scope, deliverables, resources, and cost estimates which then is prioritized by IT leadership. A portfolio review is conducted to ensure new initiatives are unified solutions across the district and maximize delivery of student education in alignment with our strategic goals. With a wealth of technology solutions and opportunities, the IT division focuses priority on providing the district students, staff, and administration with the most value to provide the greatest education for the students.


## **Transportation**

The Douglas County School District's Transportation Fleet Department provides transportation for approximately 10,600 general education students, 1,000 special education students and over 7,000 field trip athletic or activity trips. The district has 3 bus terminals (Parker, Highlands Ranch, and Castle Rock), employs approximately 400 staff, and owns 354 buses. The Transportation Fleet Maintenance Department employs 5 ASE Master Mechanics and 15 mechanics that are Certified CDE Inspectors.

Currently, the district owns 236 general education buses, with an average age of 15 years and an average of 239,150 miles; 94 special education buses with an average age of 8 years and 256,970 average miles; and 24 field trip buses with an average age of 11 years and 201,400 miles. As an example the average age of a bus across similar Colorado districts is 10.5 years. Buses are removed from the fleet when they are become cost prohibitive to repair. To align with growth or replacement needs new buses are purchased from the general fund transportation budget.

Only fleet related capital items are identified and discussed on this page. Capital needs at the three bus terminals are considered facility needs and are assessed, inventoried, and prioritized as part of the facility assessment and Capital Improvement Plan process discussed in the Methodology section. The need for new terminals is assessed and priced as part of the District's review of new construction needs.

#### Transportation-Identified Items Estimated Capital Costs (in 2019 Dollars) by Year Needed



Estimated Total Project Costs: \$19,369,894

Tier	Project Description				
Tier 1 Funded by the 2018 Bond	Buses: To bring the fleets age to 15 years, replacement of 112 total buses 16 to 33 years. 98 GenEd, 9 SPED, 5 OTR buses ranging in age from 1985-2002. Cost to purchase new buses 98 GenEd \$100,000-\$150,000 each depending on fuel type, 9 SPED at \$110,000 each, 5 Over the Road buses at \$139,000. Bond money has allowed the District to purchase 31 of the GenEd buses, 10 large SPED buses, 1 Over the Road bus, 10 small SPED buses, and 1 wrecker. Total Bond \$5.6 for Tier 1 needs.				
	Zonar Connect: Addition of Zonar Connect. Electronic route books that provide student count assistance, turn-by-turn route information, video and GPS. This would replace route books that drivers currently hold while driving in order to see the printed route instructions. Pilot program for 28 buses at \$700 each				
Tion 2	Buses: Cost for 49 new GenEd buses \$85-\$90K each depending on fuel type (\$85K Deisel/\$87K Gasoline/\$90K Propane each). 5 SPED buses at 83,000 each and 3 OTR at \$143,000 each				
Tier 2	<u>Wrecker</u> : Replacement cost for 1973 International Wrecker with 415,700 miles. <u>Service Truck:</u> Add additional service truck to support outlying areas of Franktown and Ponderosa to suport buses for repairs and maintenance.				
Tier 3	<u>Buses:</u> Cost for 49 general ed. Cost to purchase new GenEd buses \$85-\$90K each depending on fuel type (\$85K Deisel/\$87K Gasoline/\$90K Propane each). 4 SPED buses at \$83,000 each and 2 OTR at \$143,000 each				
	Zonar Connect: Addition of Zonar Connect. Electronic route books that provide student count assistance, turn-by-turn route information, video and GPS. This would replace route books that drivers currently hold while driving in order to see the printed route instructions. Remaining buses 298 buses at \$700 each.				

Tier & Priority Class	Project Description	Total Cost
Tier 1	Vehicle Replacement	\$5,793,461
Funded by the 2018 Bond	Radios/Cameras/Zonar (buses, handheld, console)	\$920,000
2-High	Vehicle Replacement	\$6,268,681
2-Medium	2-Medium Service Truck	
3-High	3-High Vehicle Replacement	
3-Medium	Zonar Connect	\$208,600

Estimated Total Capital Costs (in 2019 Dollars): \$19,369,894 Estimated Project Management Cost Range: \$0 Estimated Inflation Range: \$0

Estimated Total Project Costs: \$19,369,894

# Charter Schools

Public Charter Schools were authorized by the Colorado Charter School Act in 1993, and DCSD chartered the first charter school in the state shortly thereafter, Academy Charter School. The Charter School Act authorizes teachers, parents and/or community members to contract with the local board of education to establish a publicly funded school. Charter schools operate under a "charter contract" between the charter school and the local board of education which defines the charter school's goals, standards, education design, governance, and operations. All charter schools must meet accreditation standards as set by their authorizing school district and comply with federal and state statutes related to non-discrimination, school accountability, assessments, finance and financial transparency, and performance.

All charter schools authorized by the Douglas County School District Board of Education have legal arrangements to lease, acquire, utilize, and maintain their own facilities, including grounds and buildings. Each charter facility is an individual operating entity utilizing different ownership structures and business models. Each charter school, while always a public school, is individually managed by an independent board of directors. Ultimately, charter schools are accountable to provide educational spaces that are safe to all students and staff through its charter with the Board of Education. Charters must also properly maintain each facility to support their defined programs and objectives. Currently, this maintenance, and any facility modifications or additions, is carried out by each individual charter school.

Each charter school must fund its educational programs (including salaries for teachers, support staff, and administrators) and pay for all infrastructure needs. These may include facility purchases, technology, supplies, routine and emergency maintenance items, facility modifications or new construction. These costs are paid by the charter school from the per pupil revenue and mill levy override dollars received from the authorizing school district. Like all other public school facilities, charters must also always meet all federal, state and local code requirements for health and safety.

DCSD charter schools occupy a variety of different types of buildings of different ages and histories, from converted warehouses to new commercial construction not dissimilar from standard neighborhood schools. When financed, each facility carries its own terms using interest rates often greater than rates for public debt offered to school districts like DCSD. Charter schools generally target spending 12% to 18% of their total annual budget on their facility debt service or lease payments. As public schools subject to TABOR, charters do not solicit voter funding through bonds, so capital expenses must be funded through their annual budgets and contingency reserves. Each charter school is 100% liable for these costs, which are not covered by the District.

While DCSD is not directly responsible for charter school capital needs, this inventory of charter school facilities is required to fully appreciate the cost needs and public ownership value of buildings and other capital required for public K-12 education throughout the District.


For this MCP, all DCSD charter schools were asked to submit their capital needs data. Charter schools have submitted needs other than capital renewal needs. These identified needs are listed on each individual charter school page. For neighborhood schools, these needs are identified as district-wide needs and broken out and summed as seperate costs.

Bond funding is generally used for capital needs such as facility repairs, security upgrades, purchasing classroom equipment, buses and technology.


1551 Prairie Hawk Drive Castle Rock, CO 80109 Castle View High School Feeder Area, K-8 School built in 2001 Opened in 1996

Site Acreage:10 Facility Square Feet: 52,000

#### Academy Charter-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier



Estimated Total Construction Costs (in 2019 Dollars): \$433,090 Estimated Total Project Costs: \$498,610 - \$713,160



Tier	Project Type	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1	Capital Renewal	Fire Alarm Systems. Replacement within 5 years.	\$158,630	\$15880-\$68280	\$7940-\$34110
		Intercommunication and Paging System. Life cycle at 15-20 years.	\$21,150	\$2150-\$9150	\$1060-\$4550
		Interior Door Hardware. Replacement need in about 5 years.	\$158,630	\$15880-\$68280	\$7940-\$34110
	Maintenance	Water Treatment Systems. Check water treatment systems when HVAC systems replaced.	\$5,290	\$620-\$2320	\$270-\$1140
2	Capital Renewal	Curbs, Rails and Barriers. Repair as necessary	\$10,580	\$1130-\$4630	\$530-\$2280
		Exhaust Fans. Life cycle replacement at 15-20 years	\$31,730	\$3180-\$13680	\$1590-\$6830
		Exterior Wall Construction. Repair cracks at stucco	\$2,650	\$360-\$1160	\$140-\$570
		Exterior Windows. Recaulking of windows	\$10,580	\$1130-\$4630	\$530-\$2280
		Glazed Doors and EntrancesRecaulk front entry	\$1,060	\$150-\$550	\$60-\$230
		Paving and Surfacing. Sidewalks. Repair areas of damaged concrete	\$1,060	\$150-\$550	\$60-\$230
		Sink Countertops. Replace sink counter tops	\$31,730	\$3180-\$13680	\$1590-\$6830

Estimated Total Construction Costs (in 2019 Dollars): \$433,090 Estimated Project Management Costs Range: \$43,810 - \$186,910 Estimated Inflation Range: \$21,710 - \$93,160

Estimated Total Project Costs: \$498,610 - \$713,160

\* Note\* DCSD charter schools submit facility and infrastructure needs to the Construction Department for inclusion in the Master Capital Plan. DCSD staff also identified capital safety and security enhancements and Tier 1 capital needs at Academy Charter School. These projects will be addressed as part of the 2018 Bond as allowable by Colorado state law. For Academy Charter School the following Tier 1 projects will be addressed in the bond:

-Replace smoke dampers

**Castle Pines Campus** 6971 Mira Vista Lane Castle Pines, CO 80108 Rock Canyon High School Feeder Area, K-8

\$0

Castle Pines school built/opened in 2009

Site Acreage: 5.5 Facility Square Feet: 83,000

\$1,500,000




Estimated Total Construction Costs (in 2019 Dollars): \$265,450 Estimated Total Project Costs: \$305,320 - \$437,040

\$500,000

\*Note\* Estimated total costs include facility upgrade and facility modification items. These items were not assigned a Tier or Priority score by American Academy Charter School and therefore will not be displayed on the graph above.

\$1,000,000



Tier	Project Type	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1	Capital Renewal	BAS System (for HVAC) Replacement	\$95,180	\$9530-\$41030	\$4760-\$20470
2	Capital Renewal	Painting Hallways	\$31,730	\$3180-\$13680	\$1590-\$6830
Facility Modification	Facility Modification	Monument Sign	\$95,180	\$9530-\$41030	\$4760-\$20470
Facility Upgrade	Facility Upgrade	Additional Sidewalks	\$43,360	\$4350-\$18750	\$2170-\$9330

Estimated Total Construction Costs (in 2019 Dollars): \$265,450 Estimated Project Management Costs Range: \$26,590 - \$114,490 Estimated Inflation Range: \$13,280 - \$57,100

Estimated Total Project Costs: \$305,320 - \$437,040

<sup>\*</sup> Note\* DCSD charter schools submit facility and infrastructure needs to the Construction Department for inclusion in the Master Capital Plan. DCSD staff also identified capital safety and security enhancements. These projects will be addressed as part of the 2018 Bond as allowable by Colorado state law.

**Parker Campus** 11155 Motsenbocker Rd Parker, CO 80134 Chaparral High School Feeder Area, K-8

\$0

Motsenbocker campus built/opened in 2013

Site Acreage: 9.1 Facility Square Feet: 93,000


\$1,500,000



Estimated Total Construction Costs (in 2019 Dollars): \$66,110 Estimated Total Project Costs: \$76,150 -\$108,960

\$500,000

\$1,000,000



<sup>\*</sup>Note\* Estimated total costs include facility upgrade and facility modification items. These items were not assigned a Tier or Priority score by American Academy Charter School and therefore will not be displayed on the graph above.

Tier	Project Type	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
2	Capital Renewal	Painting Hallways	\$31,730	\$3180-\$13680	\$1590-\$6830
Facility Modification	Facility Modification	Barrier Netting Fence for soccer fields	\$7,940	\$870-\$3470	\$400-\$1710
Facility Upgrade	Facility Upgrade	Additional Shrubs, Trees and Plantings	\$26,440	\$2670-\$11470	\$1330-\$5690

Estimated Total Construction Costs (in 2019 Dollars): \$66,110 Estimated Project Management Costs Range: \$6,720 - \$28,620 Estimated Inflation Range: \$3,320 - \$14,230

Estimated Total Project Costs: \$76,150 - \$108,960

<sup>\*</sup> Note\* DCSD charter schools submit facility and infrastructure needs to the Construction Department for inclusion in the Master Capital Plan. DCSD staff also identified capital safety and security enhancements. These projects will be addressed as part of the 2018 Bond as allowable by Colorado state law.


**Lincoln Meadows Campus** 10260 Twenty Mile Rd. Parker, CO 80134 Chaparral High School Feeder Area, K-8

Lincoln Meadows campus school built/ opened in 2017

Site Acreage: 8.776 Facility Square Feet: 93,100

#### American Academy-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier






Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs		
	No capital projects identified at this time.					

<sup>\*</sup> Note\* DCSD charter schools submit facility and infrastructure needs to the Construction Department for inclusion in the Master Capital Plan. DCSD staff also identified capital safety and security enhancements. These projects will be addressed as part of the 2018 Bond as allowable by Colorado state law.


2131 Low Meadow Boulevard Castle Rock, CO 80109 Castle View High School Feeder Area, K-8 School built in 2013 School opened in 2013 Site Acreage: 10 Facility Square Feet: 78,376

#### Aspen View Academy-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier



Estimated Total Construction Costs (in 2019 Dollars): \$429,320 Estimated Total Project Costs: \$494,680 - \$707,210

\*Note\* Estimated total costs include facility upgrade and facility modification items. These items were not assigned a Tier or Priority score by Aspen View Charter School and therefore will not be displayed on the graph above.




Tier	Project Type	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Capital	Add parking lot signage	\$5,290	\$620-\$2320	\$270-\$1140
2	Renewal	Paint the interior of the building	\$26,440	\$2670-\$11470	\$1330-\$5690
	Security	Security-Replace security camera system	\$42,300	\$4300-\$18200	\$2120-\$9100
3	Capital Renewal	Resurface parking lot	\$52,880	\$5330-\$22830	\$2650-\$11370
	Security	Security-Add safety film to first floor windows	\$10,580	\$1130-\$4630	\$530-\$2280
	Capital	Add/replace trees along Low Meadow Blvd	\$7,410	\$800-\$3200	\$370-\$1600
4	Renewal	Seal concrete floor	\$15,870	\$1640-\$6840	\$800-\$3410
7	IT	IT-Replace/update staff laptops	\$31,730	\$3180-\$13680	\$1590-\$6830
	Security	Security-Upgrade card readers	\$6,880	\$730-\$3030	\$350-\$1480
	Facility Modification	Air duct cleaning	\$10,580	\$1130-\$4630	\$530-\$2280
Facility Modification		Divide 2 large rooms in half creating 4 medium rooms	\$52,880	\$5330-\$22830	\$2650-\$11370
		Replace classroom projectors for SMART boards	\$26,440	\$2670-\$11470	\$1330-\$5690
		Install a grease trap in the kitchen	\$103,010	\$10400-\$44300	\$5150-\$22150
Facility	Facility	Install concrete ramp from building to turf field	\$15,870	\$1640-\$6840	\$800-\$3410
Upgrade	Upgrade	Install fence between turf field and new community park	\$10,580	\$1130-\$4630	\$530-\$2280
		Upgrade the school library	\$10,580	\$1130-\$4630	\$530-\$2280

Estimated Total Construction Costs (in 2019 Dollars): \$429,320 Estimated Project Management Costs Range: \$43,830 - \$185,530 Estimated Inflation Range: \$21,530 - \$92,360

Estimated Total Project Costs: \$494,680 - \$707,210


<sup>\*</sup> Note\* DCSD charter schools submit facility and infrastructure needs to the Construction Department for inclusion in the Master Capital Plan. DCSD staff also identified capital safety and security enhancements. These projects will be addressed as part of the 2018 Bond as allowable by Colorado state law.

2270 Plaza Drive Highlands Ranch, CO 80129 Mountain Vista High School Feeder Area, K-8 School built in 2011 School opened in 2011 Site Acreage: 10.13 Facility Square Feet: 64,779



\*Note\* Estimated total costs include facility upgrade and facility modification items. These items were not assigned a Tier or Priority score by Benjamin Franklin Charter School and therefore will not be displayed on the graph above.

Estimated Total Project Costs: \$194,540 - \$278,000



Tier	Project Type	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1	Capital Renewal	Change out 3 backflow valves in the fire suppressing room	\$3,180	\$330-\$1430	\$160-\$690
		Exterior Building paint	\$21,150	\$2150-\$9150	\$1060-\$4550
2	Capital Renewal	Parking Lot Light replacements (6)	\$1,060	\$150-\$550	\$60-\$230
2		Replacing outside safety lighting	\$1,700	\$210-\$810	\$90-\$370
	Security	Security-Install an additional 3 surveillance cameras upstairs	\$4,020	\$490-\$1790	\$210-\$870
	Capital Renewal	Construct a fence at the west end of the playground	\$4,660	\$550-\$2050	\$240-\$1000
3		Construct concrete steps leading from sidewalk to playground	\$5,720	\$590-\$2490	\$290-\$1230
	Security	Security-Add 3M film and safety caulking to lower level windows	\$6,880	\$730-\$3030	\$350-\$1480
		Add Irrigation for trees along Plaza	\$2,650	\$360-\$1160	\$140-\$570
		Add privacy slatting to playground fence	\$5,610	\$600-\$2500	\$280-\$1210
4	Capital Renewal	Construct a housing for the trash dumpsters	\$5,290	\$620-\$2320	\$270-\$1140
4		Plant Oak trees to create privacy along playground	\$23,270	\$2340-\$10040	\$1170-\$5010
		Replace classroom projectors	\$25,380	\$2620-\$10920	\$1270-\$5460
	IT	IT-Replace computer lab desk top computers (26)	\$33,000	\$3310-\$14210	\$1650-\$7100
Facility Modification	Facility Modification	Construct a shed for turf groomer	\$5,820	\$590-\$2590	\$300-\$1250
Facility Upgrade	Facility Upgrade	Replace current faucets with touchless faucets	\$19,040	\$1970-\$8270	\$960-\$4100

Estimated Total Construction Costs (in 2019 Dollars): \$168,430 Estimated Project Management Costs Range: \$17,610 - \$73,310 Estimated Inflation Range: \$8,500 - \$36,260


Estimated Total Project Costs: \$194,540 - \$278,000

\* Note\* DCSD charter schools submit facility and infrastructure needs to the Construction Department for inclusion in the Master Capital Plan. DCSD staff also identified capital safety and security enhancements. These projects will be addressed as part of the 2018 Bond as allowable by Colorado state law.




16995 East Carlson Drive Parker, CO 80134 Chaparral High School Feeder Area, K-8 School built in 2004 Opened in 2002

Site Acreage: 7.5 Facility Square Feet: 40,000



Estimated Total Construction Costs (in 2019 Dollars): \$1,975,810 Estimated Total Project Costs: \$2,273,150 - \$3,251,540

\*Note\* Estimated total costs include facility upgrade, facility modification. and facility addition items. These items were not assigned a Tier or Priority score by Challenge to Excellence Charter School and therefore will not be displayed on the graph above.



Tier	Project Type Project Description		Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
		Carpeting 18 classrooms	\$74,030	\$7480-\$31880	\$3710-\$15920
		Caulk windows	\$6,880	\$730-\$3030	\$350-\$1480
		Hallways need patched and painted	\$39,660	\$4050-\$17150	\$1990-\$8530
		Mill, overlay, patch parking lot	\$21,150	\$2150-\$9150	\$1060-\$4550
		Replace areas of curb cracking	\$11,640	\$1170-\$5070	\$590-\$2510
	Capital Renewal	Replace sections of sidewalk	\$29,090	\$2920-\$12520	\$1460-\$6260
2		Replace toilet partitions	\$21,150	\$2150-\$9150	\$1060-\$4550
2		Resurface Playground	\$69,800	\$7010-\$30110	\$3490-\$15010
		Seal and caulk exterior wall	\$23,270	\$2340-\$10040	\$1170-\$5010
		Steel doors and frames need painted	\$17,450	\$1760-\$7560	\$880-\$3760
		Upgrade irrigation system	\$89,890	\$9020-\$38720	\$4500-\$19330
		Security-Install access controlled security and detection system	\$10,580	\$1130-\$4630	\$530-\$2280
	Security	Security-Install facility security camera system	\$37,020	\$3790-\$15990	\$1860-\$7960
		Security-Install intrusion alarm system	\$14,810	\$1500-\$6400	\$740-\$3190
	Capital	Parking lot signage & marking	\$9,310	\$1000-\$4100	\$470-\$2010
3	Renewal	Provide fencing for dumpsters and transformers	\$5,820	\$590-\$2590	\$300-\$1250
	Capital	Entire site landscape work	\$84,600	\$8500-\$36400	\$4230-\$18190
4	Renewal	Replace/add trees and shrubs	\$5,820	\$590-\$2590	\$300-\$1250
Building Addition	Building Addition	Building expansion	\$1,374,750	\$137550-\$591150	\$68740-\$295580
Facility Modification	Facility Modification	Install storage shed	\$21,150	\$2150-\$9150	\$1060-\$4550
Facility Upgrade	Facility Upgrade	Library upgrade	\$7,940	\$870-\$3470	\$400-\$1710

Estimated Total Construction Costs (in 2019 Dollars): \$1,975,810 Estimated Project Management Costs Range: \$198,450 - \$850,850 Estimated Inflation Range: \$98,890 - \$424,880

Estimated Total Project Costs: \$2,273,150 - \$3,251,540

-Upgrade fire alarm system -Add DDC controls -Replace roof top units -Upgrade intercom


<sup>\*</sup> Note\* DCSD charter schools submit facility and infrastructure needs to the Construction Department for inclusion in the Master Capital Plan. DCSD staff also identified capital safety and security enhancements and Tier 1 capital needs at Challenge to Excellence Charter School. These projects will be addressed as part of the 2018 Bond as allowable by Colorado state law. For Challenge to Excellence Charter School the following Tier 1 projects will be addressed in the bond:




311 East Castle Pines Parkway Castle Pines, CO 80108 Rock Canyon High School Feeder, K-8 School built in 2000 Opened in 1997

Site Acreage: 8.5 Facility Square Feet: 41,800

DCS Montessori Charter-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$683,130 Estimated Total Project Costs: \$733,310 -\$898,270



Tier	Project Type	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
Tier 1 Funded by the 2018 Bond	Capital Renewal	Replace 5 Rooftop units	\$350,000	\$0	\$0
1	Maintenance	Replace Roof	\$211,500	\$21200-\$91000	\$10580-\$45480
	Capital Renewal	Interior Finishes-Painting, flooring, ceiling maintenance, plumbing.	\$52,880	\$5330-\$22830	\$2650-\$11370
2		Exterior painting and sealing	\$15,870	\$1640-\$6840	\$800-\$3410
		Resurface parking lot	\$21,150	\$2150-\$9150	\$1060-\$4550
4	Capital Renewal	Renovate landscaping to be less water intensive	\$31,730	\$3180-\$13680	\$1590-\$6830

Estimated Total Construction Costs (in 2019 Dollars): \$683,130 Estimated Project Management Costs Range: \$33,500 - \$143,500 Estimated Inflation Range: \$16,680 - \$71,640


Estimated Total Project Costs: \$733,310 - \$898,270

\* Note\* DCSD charter schools submit facility and infrastructure needs to the Construction Department for inclusion in the Master Capital Plan. DCSD staff also identified capital safety and security enhancements and Tier 1 capital needs at DCS Montessori Charter School. These projects will be addressed as part of the 2018 Bond as allowable by Colorado state law. For DCS Montessori Charter School the following additional Tier 1 projects will be addressed in the bond:


-Replace boiler

18451 Ponderosa Drive Parker, CO 80134 Chaparral High School Feeder Area, K-6 Opened in 2015

Site Acreage: 7.39 Facility Square Feet: 27,481



\*Note\* Estimated total costs include security, facility upgrade. facility modification. a proposed addition, and mobiles. These items were not assigned a Tier or Priority score by Global Village Academy Charter School and therefore will not be displayed on the graph above.



Tier	Project Type	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
4	Capital Renewal	Landscaping of the property to maintain asthetics	\$10,690	\$1120-\$4620	\$540-\$2300
Building Addition	Building Addition	Construction of a school gym	\$847,800	\$84810-\$364610	\$42390-\$182280
		Install 20' x 30' storage building	\$25,380	\$2620-\$10920	\$1270-\$5460
Facility	Facility	Replacement of bark chips on the playground	\$46,850	\$4760-\$20160	\$2350-\$10080
Modification	Modification	Ride-on lawn mower / snow plow	\$9,730	\$1080-\$4280	\$490-\$2100
		Smart Boards for classrooms to assist with SPED and general instruction (x5)	\$4,230	\$470-\$1870	\$220-\$910
		Fencing around exterior of property to increase security and keep children away from creek / open space	\$71,490	\$7220-\$30820	\$3580-\$15370
Partition.	Facility	Installation of Closed-Circuit TV (CCTV) security system	\$42,730	\$4280-\$18380	\$2140-\$9190
Facility Upgrade	Facility Upgrade	Installation of turf on the sports field	\$89,890	\$9020-\$38720	\$4500-\$19330
		Retractable wall partions for installation in the library to allow multi-use room to be converted into additional classroom / testing space as and when needed	\$44,420	\$4490-\$19190	\$2230-\$9550
		ADA compliant ramp for modular classroom (including installation)	\$18,510	\$1900-\$8000	\$930-\$3980
Mobiles	Mobiles	Installation of a modular building to house additional classes (dry or wet)	\$158,630	\$15880-\$68280	\$7940-\$34110
		Paving for modular installation	\$4,340	\$470-\$1970	\$220-\$940
Security	Security	External door badge readers; prioritize western building entrance; link with student IDs to allow students to go between modular classrooms and main facility in a secure fashion	\$11,950	\$1250-\$5150	\$600-\$2570

Estimated Total Construction Costs (in 2019 Dollars): \$1,386,640 Estimated Project Management Costs Range: \$139,370 - \$596,970 Estimated Inflation Range: \$69,400 - \$298,170

Estimated Total Project Costs: \$1,595,410 - \$2,281,780


<sup>\*</sup> Note\* DCSD charter schools submit facility and infrastructure needs to the Construction Department for inclusion in the Master Capital Plan. DCSD staff also identified capital safety and security enhancements. These projects will be addressed as part of the 2018 Bond as allowable by Colorado state law.

19560 Stroh Rd. Parker, CO 80134 Chaparral High School Feeder Area, K-8

Built in 2017 Opened in 2018 Site Acreage: 8.02 Facility Square Feet: 44,596

## Leman Academy-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority







Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs			
	No capital projec	No capital projects identified at this time.					

<sup>\*</sup> Note\* DCSD charter schools submit facility and infrastructure needs to the Construction Department for inclusion in the Master Capital Plan. DCSD staff also identified capital safety and security enhancements. These projects will be addressed as part of the 2018 Bond as allowable by Colorado state law.


16700 Keystone Boulevard Parker, CO 80134 Chaparral High School Feeder, K-8 Opened in 2005

Site Acreage: 4.8 Facility Square Feet: 28,900





Estimated Total Construction Costs (in 2019 Dollars): \$839,110 Estimated Total Project Costs: \$928,660 - \$1,220,060



Tier	Project Type	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
Tier 1 Funded by the 2018 Bond	Capital Renewal	Rooftop Air Conditioner replacement.	\$250,000	\$0	0
		Carpet Replacement.	\$142,770	\$14340-\$61440	\$7140-\$30700
		Install new bathroom flooring.	\$28,560	\$2950-\$12350	\$1430-\$6140
		Air Duct Cleaning	\$15,870	\$1640-\$6840	\$800-\$3410
		Concrete Curb and Gutter Repair	\$14,810	\$1500-\$6400	\$740-\$3190
	Capital Renewal	Internal painting	\$10,580	\$1130-\$4630	\$530-\$2280
2		Mill and overlay parking lot/take middle islands out and add parking spots	\$105,750	\$10650-\$45550	\$5290-\$22740
2		Repair sunk in floor in middle school and library (foundation)	\$132,190	\$13320-\$56920	\$6610-\$28420
		Replace Handicap door opener at Kindergarten playground	\$10,580	\$1130-\$4630	\$530-\$2280
		Replace Handicap elevator	\$7,410	\$800-\$3200	\$370-\$1600
		Replace plumbing Fixtures	\$4,230	\$470-\$1870	\$220-\$910
	IT	Replace Telephone System	\$31,730	\$3180-\$13680	\$1590-\$6830
	Security	Upgrade Video Surveillance System	\$15,870	\$1640-\$6840	\$800-\$3410
		Concrete outside of music room	\$10,580	\$1130-\$4630	\$530-\$2280
3	Capital	Maintenance work on turf playing field (addition of in fill and removal of insects)	\$15,870	\$1640-\$6840	\$800-\$3410
3	Renewal	Repair and Replacement of chain link Fence	\$21,150	\$2150-\$9150	\$1060-\$4550
		Replace/Add Parking Lot Signage	\$5,290	\$620-\$2320	\$270-\$1140
4	Capital	Mulch Ground Cover	\$10,580	\$1130-\$4630	\$530-\$2280
4	Renewal	Replace/Add Parking Lot Signage	\$5,290	\$620-\$2320	\$270-\$1140

Estimated Total Construction Costs (in 2019 Dollars): \$839,110 Estimated Project Management Costs Range: \$60,040 - \$254,240

Estimated Inflation Range: \$29,510 - \$126,710 Estimated Total Project Costs: \$928,660 - \$1,220,060

-Replace lift at cafeteria -Repair water service piping

<sup>\*</sup> Note\* DCSD charter schools submit facility and infrastructure needs to the Construction Department for inclusion in the Master Capital Plan. DCSD staff also identified capital safety and security enhancements and Tier 1 capital needs at North Star Academy Charter School. These projects will be addressed as part of the 2018 Bond as allowable by Colorado state law. For North Star Academy Charter School the following additional Tier 1 projects will be addressed in the bond:


11661 Pine Drive Parker, CO 80138 Chaparral High School Feeder Area, K-8 School built in 2000 Opened in 2000

Site Acreage: 6.5 Facility Square Feet: 53,190

## Parker Core Knowledge-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$2,208,287 Estimated Total Project Costs: \$2,427,957 - \$3,149,737



Tier	Project Type	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
Tier 1 Funded by the	Capital	Install new DDC Controls	\$350,027	\$0	\$0
2018 Bond	Renewal	Replace roof top units on original building	\$400,000	\$0	\$0
1	Capital Renewal	Install new heat tape for north side downspout.	\$1,490	\$220-\$720	\$80-\$320
•	Maintenance	Replace roof 2005 & 2010 building.	\$203,470	\$20440-\$87540	\$10180-\$43750
		Replace carpet in original building.	\$377,530	\$37780-\$162380	\$18880-\$81170
	Capital Renewal	Replace VCT throughout building.	\$74,030	\$7480-\$31880	\$3710-\$15920
		Install barrier around kiln	\$1,490	\$220-\$720	\$80-\$320
		Install card readers on 10 exterior doors	\$6,980	\$720-\$3030	\$350-\$1510
2		Paint exterior downspouts	\$320	\$90-\$190	\$20-\$70
2		Recaulk control joints	\$2,440	\$270-\$1070	\$130-\$530
		Replace intercom and clock system with hard wired system	\$130,920	\$13190-\$56390	\$6550-\$28150
		Replace/repair damaged ceramic tile in restrooms	\$12,590	\$1320-\$5420	\$630-\$2710
		Re-seal asphalt parking lot	\$12,270	\$1240-\$5340	\$620-\$2640
		Re-seal CMU	\$2,540	\$270-\$1170	\$130-\$550
		Patch, prime and paint interior walls	\$226,100	\$22710-\$97310	\$11310-\$48610
3	Capital Renewal	Refurbish interior doors and jambs in original building	\$7,620	\$790-\$3290	\$390-\$1640
		Replace ceiling grid and tile	\$398,470	\$39940-\$171440	\$19930-\$85670

Estimated Total Construction Costs (in 2019 Dollars): \$2,208,287 Estimated Project Management Costs Range: \$146,680 - \$627,890

Estimated Inflation Range: \$72,990 - \$313,560 Estimated Total Project Costs: \$2,427,957 - \$3,149,737

Install smoke hatch over stage
-Install emergency generator and associated electrical
-Replace toilet partitions


<sup>\*</sup> Note\* DCSD charter schools submit facility and infrastructure needs to the Construction Department for inclusion in the Master Capital Plan. DCSD staff also identified capital safety and security enhancements and Tier 1 capital needs at Parker Core Knowledge Charter School. These projects will be addressed as part of the 2018 Bond as allowable by Colorado state law. For Parker Core Knowledge Charter School the following additional Tier 1 projects will be addressed in the bond:

15035 Compark Blvd Parker, CO 80134 Chaparral High School Feeder, K-8 School built in 2016 Opened in 2016

Site Acreage: 7.2

## Parker Performing Arts-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority





Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs		
	No capital projec	No capital projects identified at this time.				


<sup>\*</sup> Note\* DCSD charter schools submit facility and infrastructure needs to the Construction Department for inclusion in the Master Capital Plan. DCSD staff also identified capital safety and security enhancements. These projects will be addressed as part of the 2018 Bond as allowable by Colorado state law.

4085 Lark Sparrow Street Highlands Ranch, CO 80126 Highlands Ranch High School Feeder Area, K-8


School built in 1997 Opened in 2003

Site Acreage: 5.28 Facility Square Feet: 35,533

## Platte River Academy-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$1,171,220 Estimated Total Project Costs: \$1,295,240 - \$1,701,860



Tier	Project Type	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1	Maintenance	Ballasted EPDM Roofing	\$350,000	<b>\$</b> 0	\$0
		Carpet Replacement	\$142,770	\$14340-\$61440	\$7140-\$30700
		Air Duct Cleaning	\$15,870	\$1640-\$6840	\$800-\$3410
		Concrete Curb and Gutter Repair	\$7,410	\$800-\$3200	\$370-\$1600
	Capital Renewal	Internal painting	\$3,180	\$330-\$1430	\$160-\$690
2		Mill and overlay parking lot	\$105,750	\$10650-\$45550	\$5290-\$22740
		Replace plumbing Fixtures	\$10,580	\$1130-\$4630	\$530-\$2280
		Replace/Add Parking Lot Signage	\$5,290	\$620-\$2320	\$270-\$1140
		Resurface gym floor	\$26,440	\$2670-\$11470	\$1330-\$5690
	Security	Upgrade Video Surveillance System	\$33,320	\$3390-\$14390	\$1670-\$7170
		Expand sink area and drainage in Art Room	\$26,440	\$2670-\$11470	\$1330-\$5690
3	Capital .	Maintenance work on playing field (drainage, aerate, seeding, top dress)	\$19,040	\$1970-\$8270	\$960-\$4100
	Renewal	Playing Field Replacement (TBD if sod or artificial field)	\$408,200	\$40910-\$175610	\$20410-\$87770
		Repair and Replacement of Wood Fence	\$6,350	\$660-\$2760	\$320-\$1370
4	Capital Renewal	Bark Ground Cover	\$10,580	\$1130-\$4630	\$530-\$2280

Estimated Total Construction Costs (in 2019 Dollars): \$1,171,220 Estimated Project Management Costs Range: \$82,910 - \$354,010 Estimated Inflation Range: \$41,110 - \$176,630

Estimated Total Project Costs: \$1,295,240- \$1,701,860


<sup>\*</sup> Note\* DCSD charter schools submit facility and infrastructure needs to the Construction Department for inclusion in the Master Capital Plan. DCSD staff also identified capital safety and security enhancements and Tier 1 capital needs at Platte River Academy Charter School. These projects will be addressed as part of the 2018 Bond as allowable by Colorado state law. For Platte River Academy Charter School the following Tier 1 projects will be addressed in the bond:
-Replace roof top units
-Install handicap door opener at front door
-Install new phone system

3954 Trail Boss Ln. Castle Rock, CO 80104 Douglas County High School Feeder, K-8 School built/opened in 2017

Site Acreage: 15.969

## Parker Performing Arts-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority





Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs			
	No capital projects identified at this time.						

<sup>\*</sup> Note\* DCSD charter schools submit facility and infrastructure needs to the Construction Department for inclusion in the Master Capital Plan. DCSD staff also identified capital safety and security enhancements. These projects will be addressed as part of the 2018 Bond as allowable by Colorado state law.




6161 Business Center Drive Highlands Ranch, CO 80132 Highlands Ranch High School Feeder Area, K-12

Opened in 2010


Site Acreage: 14 Facility Square Feet: 110,000

## Sky View Academy-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$10,930,410 Estimated Total Project Costs: \$12,571,230 - \$17,982,160

\*Note\* Estimated total costs include facility upgrade items, mobiles, and an addition. These items were not assigned a Tier or Priority score and therefore will not be displayed on the graph above.



Tier	Project Type	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
		Repair VCT in cafeteria	\$31,730	\$3180-\$13680	\$1590-\$6830
		Replace carpet in elementary section	\$475,880	\$47630-\$204730	\$23800-\$102320
		Curb repair	\$52,880	\$5330-\$22830	\$2650-\$11370
	6	Install new lighting control system	\$126,900	\$12700-\$54600	\$6350-\$27290
	Capital Renewal	Recaulk, seal and paint exterior	\$105,750	\$10650-\$45550	\$5290-\$22740
		Replace cafetorium floor	\$42,300	\$4300-\$18200	\$2120-\$9100
		Replace playground equipment	\$158,630	\$15880-\$68280	\$7940-\$34110
2		Replace playground surface	\$31,730	\$3180-\$13680	\$1590-\$6830
		Resurface parking lot	\$475,880	\$47630-\$204730	\$23800-\$102320
	ΙΤ	Device replacement	\$31,730	\$3180-\$13680	\$1590-\$6830
	IT	Upgrade smartboard technology	\$211,500	\$21200-\$91000	\$10580-\$45480
	Security	Install additional Access Control/Door Alarms/Buzzers	\$31,730	\$3180-\$13680	\$1590-\$6830
		Install additional security cameras	\$31,730	\$3180-\$13680	\$1590-\$6830
		Install new security vestibule at front entrance	\$211,500	\$21200-\$91000	\$10580-\$45480
		Install window film at front entrance	\$6,350	\$660-\$2760	\$320-\$1370
3	Capital	Add additional parking	\$370,130	\$37080-\$159180	\$18510-\$79580
3	Renewal	Upgrade to LED lighting	\$158,630	\$15880-\$68280	\$7940-\$34110
4	Capital Renewal	Clean up landscape	\$10,580	\$1130-\$4630	\$530-\$2280
Building Addition	Building Addition	Elementary Addition	\$7,402,500	\$740300-\$3183100	\$370130-\$1591540
		Install 2 lane track around athletic field	\$185,070	\$18540-\$79640	\$9260-\$39790
		Install new scoreboard for athletic field	\$42,300	\$4300-\$18200	\$2120-\$9100
		Replace artificial turf	\$42,300	\$4300-\$18200	\$2120-\$9100
Facility	Facility	Add additional parking	\$370,130	\$37080-\$159180	\$18510-\$79580
Upgrade	Upgrade	Add lighting to athletic field	\$158,630	\$15880-\$68280	\$7940-\$34110
		Expand library	\$21,150	\$2150-\$9150	\$1060-\$4550
		Perform traffic flow study	\$10,580	\$1130-\$4630	\$530-\$2280
		Site Improvement for MS/HS exterior lunch area	\$26,440	\$2670-\$11470	\$1330-\$5690
Mobiles	Mobiles	Add modulars	\$105,750	\$10650-\$45550	\$5290-\$22740

Estimated Total Construction Costs (in 2019 Dollars): \$10,930,410
Estimated Project Management Costs Range: \$1,094,170 - \$4,701,570
Estimated Inflation Range: \$546,650 - \$2,350,180

Estimated Total Project Costs: \$12,571,230 - \$17,982,160

-Replace roof top units -Replace classroom door hardware locks -Replace anchor swinging light fixture -Repair damaged exterior lighting

<sup>\*</sup> Note\* DCSD charter schools submit facility and infrastructure needs to the Construction Department for inclusion in the Master Capital Plan. DCSD staff also identified capital safety and security enhancements and Tier 1 capital needs at SkyView Academy Charter School. These projects will be addressed as part of the 2018 Bond as allowable by Colorado state law. For SkyView Academy Charter School the following Tier 1 projects will be addressed in the bond:


8773 Ridgeline Boulevard Highlands Ranch, CO 80129 Mountain Vista High School Feeder Area, K-12

Opened in 2011

Site Acreage: 10


Facility Square Feet: 134,000

## STEM School and Academy-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2019 Dollars): \$2,712,180 Estimated Total Project Costs: \$3,120,460 - \$4,463,240

\*Note\* Estimated total costs include facility upgrade and facility modification items. These items were not assigned a Tier or Priority score and therefore will not be displayed on the graph above.



Tier	Project Type	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
ı IT		IT-Procure and replace IT network switches	\$22,210	\$2300-\$9600	\$1110-\$4780
'	11	IT-Replace 2 network servers	\$10,580	\$1130-\$4630	\$530-\$2280
		Replacement carpet	\$52,880	\$5330-\$22830	\$2650-\$11370
		Replacement flooring	\$26,440	\$2670-\$11470	\$1330-\$5690
		Exterior building repainting	\$69,800	\$7010-\$30110	\$3490-\$15010
2	Capital	Exterior joint weatherization	\$10,580	\$1130-\$4630	\$530-\$2280
2	Renewal	Lot asphalt mill and overlay	\$110,620	\$11090-\$47590	\$5540-\$23790
		Replace existing school store front doors	\$15,870	\$1640-\$6840	\$800-\$3410
		Replace MS kitchen door and frame	\$3,710	\$400-\$1600	\$190-\$800
		Replace water heater and piping retrofit	\$15,870	\$1640-\$6840	\$800-\$3410
		Gym sound attentuation	\$10,580	\$1130-\$4630	\$530-\$2280
	Capital	MS café window safety tinting / shades	\$10,580	\$1130-\$4630	\$530-\$2280
3	Renewal	Ridgeline roof replacement	\$521,350	\$52160-\$224260	\$26070-\$112090
		Roof clean up, walkway pavers, etc	\$6,880	\$730-\$3030	\$350-\$1480
	Security	Access security upgrades	\$10,580	\$1130-\$4630	\$530-\$2280
4	Capital Renewal	Site xeroscape	\$11,000	\$1110-\$4810	\$550-\$2370
Facility	Facility	Monument Sign refacing	\$8,890	\$920-\$3920	\$450-\$1910
Modification	Modification	MS Café electrical adds	\$2,650	\$360-\$1160	\$140-\$570
		2-8 Site playground	\$282,360	\$28250-\$121450	\$14120-\$60710
		Cafeteria sound attenuation	\$8,460	\$940-\$3640	\$430-\$1820
	Facility	Gym sound attentuation	\$10,580	\$1130-\$4630	\$530-\$2280
		MS Patio / Flagpole	\$42,830	\$4380-\$18480	\$2150-\$9210
Facility		Replace commons lights MS/HS to LED	\$75,720	\$7590-\$32590	\$3790-\$16280
Upgrade	Upgrade	Replace ES lights to LED	\$48,330	\$4880-\$20880	\$2420-\$10390
		Ridgeline entrance re-alignment	\$423,000	\$42300-\$181900	\$21150-\$90950
		Site Pratice / play field /lawn	\$846,000	\$84600-\$363800	\$42300-\$181890
		Site xeroscape	\$11,000	\$1110-\$4810	\$550-\$2370
		STEM HS patio	\$42,830	\$4380-\$18480	\$2150-\$9210

Estimated Total Construction Costs (in 2019 Dollars): \$2,712,180 Estimated Project Management Costs Range: \$272,570 - \$1,167,870

Estimated Inflation Range: \$135,710 - \$583,190 Estimated Total Project Costs: \$3,120,460 - \$4,463,240


-Upgrade fire alarm system
-Upgrade electrical switchgear
-Install new DDC controls
-Replace 5 rooftop units at Middle School


<sup>\*</sup> Note\* DCSD charter schools submit facility and infrastructure needs to the Construction Department for inclusion in the Master Capital Plan. DCSD staff also identified capital safety and security enhancements and Tier 1 capital needs at STEM School Highlands Ranch Charter School. These projects will be addressed as part of the 2018 Bond as allowable by Colorado state law. For STEM School Highlands Ranch Charter School the following Tier 1 projects will be addressed in the bond:

2490 South Perry Street Castle Rock, CO 80104 Douglas County High School Feeder Area, K-6 Opened in 2015

Site Acreage: 7 Facility Square Feet: 39,663

## World Compass Academy-Identified Facility Projects Estimated Construction Costs (in 2019 Dollars) by Site Component Tier and Priority






Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	No capital projec	ts identified at t	his time.	

<sup>\*</sup> Note\* DCSD charter schools submit facility and infrastructure needs to the Construction Department for inclusion in the Master Capital Plan. DCSD staff also identified capital safety and security enhancements. These projects will be addressed as part of the 2018 Bond as allowable by Colorado state law.



## 2019-2024 Capital Needs

Estimated Cost (in 2019 Dollars)



Capital Item	Estimated Capital Cost- 2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs	Total Project Cost
New Construction (1-5 Years, DCSD Standards)	\$455,699,301	\$0	\$0	\$455,699,301
Facility Reinvestment-Neighborhood Schools, Support Facilities	\$171,123,020	\$17,217,390-\$73,696,550	\$8,565,210-\$36,798,930	\$196,905,620-\$281,618,500
Charter Schools	\$23,269,187	\$2,166,250-\$9,285,760	\$1,079,280-\$4,638,070	\$26,514,717-\$37,193,017
Transportation	\$19,369,894	\$0	\$0	\$19,369,894
FF&E	\$11,815,000	\$1,181,500-\$3,899,000	\$590,750-\$2,540,225	\$13,587,250-\$18,254,225
Mobiles	\$6,600,000	\$0	\$330,000-\$1,419,000	\$6,930,000-\$8,019,000
Support Fleet	\$6,715,820	\$0	\$0	\$6,715,820
Safety & Security	\$4,980,215	\$0	\$0	\$4,980,215
Athletics	\$3,773,480	\$377,930-\$1,623,230	\$188,700-\$811,360	\$4,340,110-\$6,208,070
ADA Contingency	\$500,000	\$0	\$25,000-\$107,500	\$525,000-\$607,500
SPED Contingency	\$500,000	\$0	\$25,000-\$107,500	\$525,000-\$607,500
Playground Equipment	\$500,000	\$0	\$25,000-\$107,500	\$525,000-\$607,500

Estimated Cost (in 2019 Dollars): \$704,845,917

Estimated Project Management Costs Range: \$20,943,070 - \$88,504,540


Estimated Inflation Range: \$10,828,940- \$46,530,085

Estimated Total Cost: \$736,617,927 - \$839,880,542



# 2019-2024 Capital Needs by Tier

Estimated Cost (in 2019 Dollars)



\*Note\* Untiered needs include ADA compliance contingency costs, Special Education needs contingency costs, some charter school needs, new construction, and playground equipment.

Tier	Estimated Capital Cost- 2019	Potential Regulatory, Professional Services, and Contracting Costs-High	Potential Inflation Costs	Total Project Cost
Tier 1 Funded by the 2018 Bond	\$110,541,958	\$9,601,090-\$41,208,920	\$4,790,650-\$20,590,900	\$124,933,698-\$172,341,778
Tier 2 Funded by the 2018 Bond	\$3,698,410	\$370,120-\$1,590,720	\$184,950-\$795,180	\$4,253,480-\$6,084,310
Tier 1	\$6,146,800	\$581,120-\$2,494,120	\$289,980-\$1,246,420	\$7,017,900-\$9,887,340
Tier 2	\$60,582,661	\$5,482,460-\$23,393,730	\$2,718,060-\$11,670,970	\$68,783,181-\$95,647,361
Tier 3	\$51,230,248	\$3,356,970-\$13,167,630	\$1,997,410-\$8,582,685	\$56,584,628-\$72,980,563
Tier 4	\$2,071,530	\$211,240-\$895,250	\$103,920-\$445,640	\$2,386,690-\$3,412,420
Untiered	\$470,574,311	\$1,340,070-\$5,754,170	\$743,970-\$3,198,290	\$472,658,351-\$479,526,771


Estimated Cost (in 2019 Dollars): \$704,845,917


Estimated Project Management Costs Range: \$20,943,070 - \$88,504,540

Estimated Inflation Range: \$10,828,940- \$46,530,085

Estimated Total Cost: \$736,617,927 - \$839,880,542

## 2019-2024 New Construction







\*Note\* Total estimated costs for new construction include estimates for inflation and project management costs. Inflation is assumed at 5% per year. To open a building in year 4 of the 2019-2024 outlook, the majority of costs will be paid in year 2 or 3. Therefore, cost including the inflation factor is total building programmatic costs multiplied by 1.16. An additional \$20 M may be needed for road and utility infrastructure to the Ridgegate HS site pending the development's buildout

## 2024-2029 New Construction

#### **Current DCSD Construction Standards**



#### **Value Engineered Construction**



\*Note\* Total estimated costs for new construction include estimates for inflation and project management costs. Inflation is assumed at 5% per year. To open a building in year 9 of the 2019-2029 outlook, the majority of costs will be paid in year 7 or 8. Some facilities are anticipated to be needed earlier than year 9. Inflation was calculated appropriately in these instances.



# Appendix 1: History of Capital Improvements Neighborhood, Magnet, Alternative Schools, and Support Facilities

Acres Green Elementary		
1990 3,100 SF Addition	2004 Technology Improvements	2013 Daylighting Enhancement
1995 Drainage	2005 Roof Replacement	2014 Resurface Gymnasium Floor
1997 Drainage/Fire Hydrant	2005 Student Bathrooms	2016 Smoke Detectors & Horn Strobe Replacement
1998 Air Conditioning	2005 Security Access Control	2016 Replace Electrical Switchgear, Transformers, & Panels
2000 2,600 SF Addition	2008 Elevator	2017 Exterior Maintenance Painting
2000 Playground Improvements	2011 White Boards	2018 Makeup Air Unit
2004 Security Cameras/Radios	2012 Flooring Replacement	2018 Painting
Arrowwood Elementary		
2004 Mechanical Repair	2004 Security Access Control	2013 Resurface Paved Areas
2004 Movement Repair	2010 Carpet Replacement	2014 Clock System
2004 Technology Improvements	2011 Carpet Replacement	2014 Mechanical System Automated Controls
2004 Security Cameras/Radios	2012 Tile Replacement	2014 Carpet
Bear Canyon Elementary		
1996 Parking Lot Improvements	2003 Carpet Replacement	2012 Carpet Replacement - Mobiles
1997 Air Conditioning	2004 Technology Improvements	2013 Replace Restroom Floors
2003 Playground Improvements	2004 Security Cameras/Radios	2017 Replace Generator
2003 Bathroom Improvements	2004 Security Access Control	2017 Window Replacement-Multiple Areas
2003 Make-up Air	2009 3,100 SF Addition	2017 Window Replacement Multiple Aleas 2017 Replace Entry Walk-Off Carpet
•	_500 0,.00 0. /.aa.ao	
Buffalo Ridge Elementary	2012 Renair Rue Loon Paving	2014 Clock System
2006 Carpet Replacement	2012 Repair Bus Loop Paving	2014 Clock System
2006 Players and Improvements	2012 Carpet Replacement - Mobiles	2017 Rebuild Generator
2006 Playground Improvements	2013 Flooring Repair	2018 Generator Rebuild
2006 Security Access Control	2013 Fire Alarm Panel Replacement	
Bridge North		
2018 Additional Bridge Classrooms		
Cantril		
Cantril 1994 Roof repair	2001 Gym and Pre-school Roof	2015 Replace Cooling in Gym
	2001 Gym and Pre-school Roof 2006 Parking Lot	2015 Replace Cooling in Gym 2015 Restore Lunchroom
1994 Roof repair	•	
1994 Roof repair 1996 Asbestos Removal	2006 Parking Lot	2015 Restore Lunchroom
1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement	2006 Parking Lot 2006 Upgrade Local Area Network	2015 Restore Lunchroom
1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet	2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms	2015 Restore Lunchroom
1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler	2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint	2015 Restore Lunchroom
1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler  Castle Rock Elementary 1996 Playground Improvements	2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint	2015 Restore Lunchroom 2015 ADA Restroom Addition  2012 Playground Paving
1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler  Castle Rock Elementary 1996 Playground Improvements 1999 Air Conditioning	2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint  2004 Technology Improvements 2004 Security Cameras/Radios	2015 Restore Lunchroom 2015 ADA Restroom Addition  2012 Playground Paving 2012 Carpet Replacement - Mobiles
1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler  Castle Rock Elementary 1996 Playground Improvements 1999 Air Conditioning 2001 Playground Improvements	2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint  2004 Technology Improvements 2004 Security Cameras/Radios 2004 Security Access Control	2015 Restore Lunchroom 2015 ADA Restroom Addition  2012 Playground Paving
1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler  Castle Rock Elementary 1996 Playground Improvements 1999 Air Conditioning	2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint  2004 Technology Improvements 2004 Security Cameras/Radios 2004 Security Access Control 2011 White Boards	2015 Restore Lunchroom 2015 ADA Restroom Addition  2012 Playground Paving 2012 Carpet Replacement - Mobiles
1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler  Castle Rock Elementary 1996 Playground Improvements 1999 Air Conditioning 2001 Playground Improvements 2003 Re-ballast 2004 2,965 SF Addition	2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint  2004 Technology Improvements 2004 Security Cameras/Radios 2004 Security Access Control	2015 Restore Lunchroom 2015 ADA Restroom Addition  2012 Playground Paving 2012 Carpet Replacement - Mobiles
1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler  Castle Rock Elementary 1996 Playground Improvements 1999 Air Conditioning 2001 Playground Improvements 2003 Re-ballast 2004 2,965 SF Addition  Castle Rock Middle School	2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint  2004 Technology Improvements 2004 Security Cameras/Radios 2004 Security Access Control 2011 White Boards 2012 Parking Lot Paving	2015 Restore Lunchroom 2015 ADA Restroom Addition  2012 Playground Paving 2012 Carpet Replacement - Mobiles 2014 Clock System
1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler  Castle Rock Elementary 1996 Playground Improvements 1999 Air Conditioning 2001 Playground Improvements 2003 Re-ballast 2004 2,965 SF Addition  Castle Rock Middle School 2004 Technology Improvements	2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint  2004 Technology Improvements 2004 Security Cameras/Radios 2004 Security Access Control 2011 White Boards 2012 Parking Lot Paving	2015 Restore Lunchroom 2015 ADA Restroom Addition  2012 Playground Paving 2012 Carpet Replacement - Mobiles 2014 Clock System  2017 Addition of Secured Folding Partition Wall at Pods
1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler  Castle Rock Elementary 1996 Playground Improvements 1999 Air Conditioning 2001 Playground Improvements 2003 Re-ballast 2004 2,965 SF Addition  Castle Rock Middle School 2004 Technology Improvements 2004 Security Cameras	2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint  2004 Technology Improvements 2004 Security Cameras/Radios 2004 Security Access Control 2011 White Boards 2012 Parking Lot Paving  2013 Fire Alarm Replacement 2013 Refinish Gymnasium Floor	2015 Restore Lunchroom 2015 ADA Restroom Addition  2012 Playground Paving 2012 Carpet Replacement - Mobiles 2014 Clock System  2017 Addition of Secured Folding Partition Wall at Pods 2017 Replace Entry Walk-Off Carpet
1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler  Castle Rock Elementary 1996 Playground Improvements 1999 Air Conditioning 2001 Playground Improvements 2003 Re-ballast 2004 2,965 SF Addition  Castle Rock Middle School 2004 Technology Improvements 2004 Security Cameras 2004 Security Access Control	2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint  2004 Technology Improvements 2004 Security Cameras/Radios 2004 Security Access Control 2011 White Boards 2012 Parking Lot Paving  2013 Fire Alarm Replacement 2013 Refinish Gymnasium Floor 2014 Clock System	2015 Restore Lunchroom 2015 ADA Restroom Addition  2012 Playground Paving 2012 Carpet Replacement - Mobiles 2014 Clock System  2017 Addition of Secured Folding Partition Wall at Pods 2017 Replace Entry Walk-Off Carpet 2018 Blearchers
1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler  Castle Rock Elementary 1996 Playground Improvements 1999 Air Conditioning 2001 Playground Improvements 2003 Re-ballast 2004 2,965 SF Addition  Castle Rock Middle School 2004 Technology Improvements 2004 Security Cameras 2004 Security Access Control 2006 HVAC Upgrades	2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint  2004 Technology Improvements 2004 Security Cameras/Radios 2004 Security Access Control 2011 White Boards 2012 Parking Lot Paving  2013 Fire Alarm Replacement 2013 Refinish Gymnasium Floor 2014 Clock System 2014 Restroom Flooring	2015 Restore Lunchroom 2015 ADA Restroom Addition  2012 Playground Paving 2012 Carpet Replacement - Mobiles 2014 Clock System  2017 Addition of Secured Folding Partition Wall at Pods 2017 Replace Entry Walk-Off Carpet
1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler  Castle Rock Elementary 1996 Playground Improvements 1999 Air Conditioning 2001 Playground Improvements 2003 Re-ballast 2004 2,965 SF Addition  Castle Rock Middle School 2004 Technology Improvements 2004 Security Cameras 2004 Security Access Control 2006 HVAC Upgrades 2012 Kitchen Floor Repair	2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint  2004 Technology Improvements 2004 Security Cameras/Radios 2004 Security Access Control 2011 White Boards 2012 Parking Lot Paving  2013 Fire Alarm Replacement 2013 Refinish Gymnasium Floor 2014 Clock System 2014 Restroom Flooring 2014 Domestic Hot Water System Upgrade	2015 Restore Lunchroom 2015 ADA Restroom Addition  2012 Playground Paving 2012 Carpet Replacement - Mobiles 2014 Clock System  2017 Addition of Secured Folding Partition Wall at Pods 2017 Replace Entry Walk-Off Carpet 2018 Blearchers
1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler  Castle Rock Elementary 1996 Playground Improvements 1999 Air Conditioning 2001 Playground Improvements 2003 Re-ballast 2004 2,965 SF Addition  Castle Rock Middle School 2004 Technology Improvements 2004 Security Cameras 2004 Security Access Control 2006 HVAC Upgrades	2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint  2004 Technology Improvements 2004 Security Cameras/Radios 2004 Security Access Control 2011 White Boards 2012 Parking Lot Paving  2013 Fire Alarm Replacement 2013 Refinish Gymnasium Floor 2014 Clock System 2014 Restroom Flooring	2015 Restore Lunchroom 2015 ADA Restroom Addition  2012 Playground Paving 2012 Carpet Replacement - Mobiles 2014 Clock System  2017 Addition of Secured Folding Partition Wall at Pods 2017 Replace Entry Walk-Off Carpet 2018 Blearchers
1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler  Castle Rock Elementary 1996 Playground Improvements 1999 Air Conditioning 2001 Playground Improvements 2003 Re-ballast 2004 2,965 SF Addition  Castle Rock Middle School 2004 Technology Improvements 2004 Security Cameras 2004 Security Cameras 2004 Security Access Control 2006 HVAC Upgrades 2012 Kitchen Floor Repair 2012 Roof Replacement  Castle View High School	2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint  2004 Technology Improvements 2004 Security Cameras/Radios 2004 Security Access Control 2011 White Boards 2012 Parking Lot Paving  2013 Fire Alarm Replacement 2013 Refinish Gymnasium Floor 2014 Clock System 2014 Restroom Flooring 2014 Domestic Hot Water System Upgrade 2017 Chiller Replacement	2015 Restore Lunchroom 2015 ADA Restroom Addition  2012 Playground Paving 2012 Carpet Replacement - Mobiles 2014 Clock System  2017 Addition of Secured Folding Partition Wall at Pods 2017 Replace Entry Walk-Off Carpet 2018 Blearchers 2018 Hallway Carpet
1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler  Castle Rock Elementary 1996 Playground Improvements 1999 Air Conditioning 2001 Playground Improvements 2003 Re-ballast 2004 2,965 SF Addition  Castle Rock Middle School 2004 Technology Improvements 2004 Security Cameras 2004 Security Cameras 2004 Security Access Control 2006 HVAC Upgrades 2012 Kitchen Floor Repair 2012 Roof Replacement  Castle View High School 2006 New Construction	2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint  2004 Technology Improvements 2004 Security Cameras/Radios 2004 Security Access Control 2011 White Boards 2012 Parking Lot Paving  2013 Fire Alarm Replacement 2013 Refinish Gymnasium Floor 2014 Clock System 2014 Restroom Flooring 2014 Domestic Hot Water System Upgrade 2017 Chiller Replacement	2015 Restore Lunchroom 2015 ADA Restroom Addition  2012 Playground Paving 2012 Carpet Replacement - Mobiles 2014 Clock System  2017 Addition of Secured Folding Partition Wall at Pods 2017 Replace Entry Walk-Off Carpet 2018 Blearchers
1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler  Castle Rock Elementary 1996 Playground Improvements 1999 Air Conditioning 2001 Playground Improvements 2003 Re-ballast 2004 2,965 SF Addition  Castle Rock Middle School 2004 Technology Improvements 2004 Security Cameras 2004 Security Access Control 2006 HVAC Upgrades 2012 Kitchen Floor Repair 2012 Roof Replacement  Castle View High School	2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint  2004 Technology Improvements 2004 Security Cameras/Radios 2004 Security Access Control 2011 White Boards 2012 Parking Lot Paving  2013 Fire Alarm Replacement 2013 Refinish Gymnasium Floor 2014 Clock System 2014 Restroom Flooring 2014 Domestic Hot Water System Upgrade 2017 Chiller Replacement	2015 Restore Lunchroom 2015 ADA Restroom Addition  2012 Playground Paving 2012 Carpet Replacement - Mobiles 2014 Clock System  2017 Addition of Secured Folding Partition Wall at Pods 2017 Replace Entry Walk-Off Carpet 2018 Blearchers 2018 Hallway Carpet
1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler  Castle Rock Elementary 1996 Playground Improvements 1999 Air Conditioning 2001 Playground Improvements 2003 Re-ballast 2004 2,965 SF Addition  Castle Rock Middle School 2004 Technology Improvements 2004 Security Cameras 2004 Security Access Control 2006 HVAC Upgrades 2012 Kitchen Floor Repair 2012 Roof Replacement  Castle View High School 2006 New Construction 2007 Parking Lot Expansion	2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint  2004 Technology Improvements 2004 Security Cameras/Radios 2004 Security Access Control 2011 White Boards 2012 Parking Lot Paving  2013 Fire Alarm Replacement 2013 Refinish Gymnasium Floor 2014 Clock System 2014 Restroom Flooring 2014 Domestic Hot Water System Upgrade 2017 Chiller Replacement	2015 Restore Lunchroom 2015 ADA Restroom Addition  2012 Playground Paving 2012 Carpet Replacement - Mobiles 2014 Clock System  2017 Addition of Secured Folding Partition Wall at Pods 2017 Replace Entry Walk-Off Carpet 2018 Blearchers 2018 Hallway Carpet
1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler  Castle Rock Elementary 1996 Playground Improvements 1999 Air Conditioning 2001 Playground Improvements 2003 Re-ballast 2004 2,965 SF Addition  Castle Rock Middle School 2004 Technology Improvements 2004 Security Cameras 2004 Security Access Control 2006 HVAC Upgrades 2012 Kitchen Floor Repair 2012 Roof Replacement  Castle View High School 2006 New Construction 2007 Parking Lot Expansion	2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint  2004 Technology Improvements 2004 Security Cameras/Radios 2004 Security Access Control 2011 White Boards 2012 Parking Lot Paving  2013 Fire Alarm Replacement 2013 Refinish Gymnasium Floor 2014 Clock System 2014 Restroom Flooring 2014 Domestic Hot Water System Upgrade 2017 Chiller Replacement	2015 Restore Lunchroom 2015 ADA Restroom Addition  2012 Playground Paving 2012 Carpet Replacement - Mobiles 2014 Clock System  2017 Addition of Secured Folding Partition Wall at Pods 2017 Replace Entry Walk-Off Carpet 2018 Blearchers 2018 Hallway Carpet
1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler  Castle Rock Elementary 1996 Playground Improvements 1999 Air Conditioning 2001 Playground Improvements 2003 Re-ballast 2004 2,965 SF Addition  Castle Rock Middle School 2004 Technology Improvements 2004 Security Cameras 2004 Security Access Control 2006 HVAC Upgrades 2012 Kitchen Floor Repair 2012 Roof Replacement  Castle View High School 2006 New Construction 2007 Parking Lot Expansion  Chaparral High School	2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint  2004 Technology Improvements 2004 Security Cameras/Radios 2004 Security Access Control 2011 White Boards 2012 Parking Lot Paving  2013 Fire Alarm Replacement 2013 Refinish Gymnasium Floor 2014 Clock System 2014 Restroom Flooring 2014 Domestic Hot Water System Upgrade 2017 Chiller Replacement  2007 Technology Improvements 2007 Security Kiosk	2015 Restore Lunchroom 2015 ADA Restroom Addition  2012 Playground Paving 2012 Carpet Replacement - Mobiles 2014 Clock System  2017 Addition of Secured Folding Partition Wall at Pods 2017 Replace Entry Walk-Off Carpet 2018 Blearchers 2018 Hallway Carpet  2017 Replace Synthetic Turf Field
1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler  Castle Rock Elementary 1996 Playground Improvements 1999 Air Conditioning 2001 Playground Improvements 2003 Re-ballast 2004 2,965 SF Addition  Castle Rock Middle School 2004 Technology Improvements 2004 Security Cameras 2004 Security Access Control 2006 HVAC Upgrades 2012 Kitchen Floor Repair 2012 Roof Replacement  Castle View High School 2006 New Construction 2007 Parking Lot Expansion  Chaparral High School 2002 34,368 SF Addition	2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint  2004 Technology Improvements 2004 Security Cameras/Radios 2004 Security Access Control 2011 White Boards 2012 Parking Lot Paving  2013 Fire Alarm Replacement 2013 Refinish Gymnasium Floor 2014 Clock System 2014 Restroom Flooring 2014 Domestic Hot Water System Upgrade 2017 Chiller Replacement  2007 Technology Improvements 2007 Security Kiosk	2015 Restore Lunchroom 2015 ADA Restroom Addition  2012 Playground Paving 2012 Carpet Replacement - Mobiles 2014 Clock System  2017 Addition of Secured Folding Partition Wall at Pods 2017 Replace Entry Walk-Off Carpet 2018 Blearchers 2018 Hallway Carpet  2017 Replace Synthetic Turf Field  2017 Replace Synthetic Turf Field
1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler  Castle Rock Elementary 1996 Playground Improvements 1999 Air Conditioning 2001 Playground Improvements 2003 Re-ballast 2004 2,965 SF Addition  Castle Rock Middle School 2004 Technology Improvements 2004 Security Cameras 2004 Security Access Control 2006 HVAC Upgrades 2012 Kitchen Floor Repair 2012 Roof Replacement  Castle View High School 2006 New Construction 2007 Parking Lot Expansion  Chaparral High School 2002 34,368 SF Addition 2004 Flush Valves/Chiller	2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint  2004 Technology Improvements 2004 Security Cameras/Radios 2004 Security Access Control 2011 White Boards 2012 Parking Lot Paving  2013 Fire Alarm Replacement 2013 Refinish Gymnasium Floor 2014 Clock System 2014 Restroom Flooring 2014 Domestic Hot Water System Upgrade 2017 Chiller Replacement  2007 Technology Improvements 2007 Security Kiosk  2008 Special Education Wing Remodel 2010 Softball Field Fencing	2015 Restore Lunchroom 2015 ADA Restroom Addition  2012 Playground Paving 2012 Carpet Replacement - Mobiles 2014 Clock System  2017 Addition of Secured Folding Partition Wall at Pods 2017 Replace Entry Walk-Off Carpet 2018 Blearchers 2018 Hallway Carpet  2017 Replace Synthetic Turf Field  2017 Replace Synthetic Turf Field
1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler  Castle Rock Elementary 1996 Playground Improvements 1999 Air Conditioning 2001 Playground Improvements 2003 Re-ballast 2004 2,965 SF Addition  Castle Rock Middle School 2004 Technology Improvements 2004 Security Cameras 2004 Security Cameras 2004 Security Access Control 2006 HVAC Upgrades 2012 Kitchen Floor Repair 2012 Roof Replacement  Castle View High School 2006 New Construction 2007 Parking Lot Expansion  Chaparral High School 2002 34,368 SF Addition 2004 Flush Valves/Chiller 2004 Bleachers	2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint  2004 Technology Improvements 2004 Security Cameras/Radios 2004 Security Access Control 2011 White Boards 2012 Parking Lot Paving  2013 Fire Alarm Replacement 2013 Refinish Gymnasium Floor 2014 Clock System 2014 Restroom Flooring 2014 Domestic Hot Water System Upgrade 2017 Chiller Replacement  2007 Technology Improvements 2007 Security Kiosk  2008 Special Education Wing Remodel 2010 Softball Field Fencing 2010 Chiller	2015 Restore Lunchroom 2015 ADA Restroom Addition  2012 Playground Paving 2012 Carpet Replacement - Mobiles 2014 Clock System  2017 Addition of Secured Folding Partition Wall at Pods 2017 Replace Entry Walk-Off Carpet 2018 Blearchers 2018 Hallway Carpet  2017 Replace Synthetic Turf Field  2017 Replace Synthetic Turf Field

Chaparral High School Cont.		
2004 Dugouts	2012 Tile Replacement	2017 Replace Carpet in Main Hallways, Pod Hallways,
2004 Technology Improvements	2012 Carpet Replacement - Mobiles	and Vestibules
2006 Clearstory Windows	2013 Synthetic Turf Replacement	2018 Electrical Panels
2006 Parking Lot Improvements	2013 Interior Door Hardware Replacement	2018 Theater Stand Lighting
2006 Gymnasium Floor	2014 Clock System	2018 Auxillary Gym Joist Repairs
•	•	
2007 Tennis Courts	2014 Resurface Track	2018 Testing and Balancing
2007 Security Kiosk	2014 Intercom and Paging System Replacement	
Cherokee Trail Elementary		
2001 Air Conditioning	2005 3,000 SF Addition	2014 Resurface Gymnasium Floor
2001 Countertops/Partitions	2005 Playground Improvements	2016 Restroom Countertops Replacement
2003 Reballast	2005 Reballast	2017 Replace Generator
2003 Carpet Replacement	2005 Roof Replacement	2017 Replace Flooring in Restrooms
2004 Security Cameras/Radios	2012 Parking Lot Paving	2017 Replace Entry Walk-Off Closet
2004 Technology Improvements	2012 Playground Paving	2018 RTU Replacement
2004 Security Access Control	2014 Cafeteria Floor Replacement	
Cherry Valley Elementary		
1996 Roof Replacement	2004 Technology Improvements	2014 Update Water Well System
1998 Playground Improvements	2005 Security Access Control	2017 Window Replacement-Multiple Areas
1999 981 SF Addition	2006 Parking Lot Improvements	·
2004 Security Cameras/Radios	2008 Major Renovation	
0		
Cimarron Middle School	2012 Ad 8 Committee Brown B	2040 Flavotes Madaminstins
2010 New Construction	2012 Art & Computer Room Remodel	2018 Elevator Modernization
2011 Turn Lane and Stop Light	2018 Landscaping	
Clear Sky Elementary		
2008 New Construction	2012 Carpet Replacement - Mobiles	2018 Movement Issues
Copper Mesa Elementary		
2006 New Construction	2017 Replace Entry Walk-Off Carpet	
2000 NOW Contraction	2017 Replace Entry Walk Oil Galpet	
Cougar Run Elementary		
2003 Playground Improvements	2013 Fire Alarm Replacement	2017 Replace Entry Walk-Off Carpet
2003 Flooring Improvements	2013 Restroom Flooring	2018 Makeup Air Unit
2004 Security Cameras/Radios	2013 Roof Replacement	2018 Window Film
2005 Security Access Control	2014 Clock System	
2007 Carpet Replacement	2016 Concrete Slab Repairs	
Coyote Creek Elementary		
2004 Security Cameras/Radios	2007 Carpet Replacement	2010 Playing Field Improvements
2004 Technology Upgrades	2007 Playground Improvements	2017 Replace Entry Walk-Off Carpet
2005 Security Access Control	2010 3,200 SF Addition	
Cresthill Middle School		
Cresthill Middle School 1998 Tile Replacement	2003 Site Improvements	2005 Security Access Control
<b>'</b>	•	,
1999 SPED, Science Rooms	2004 Carpet Replacement	2010 14,500 SF Addition
2000 Carpet Replacement	2004 Technology Improvements	2010 Bleachers
2002 Make-up Air	2004 Security Cameras/Radios	2018 Landscaping
Daniel C. Oakes High School		
2000 Add Mobile/AC	2002 Major Renovation	2007 Roof Replacement
2001 Parking Lot	2007 Science Rooms	
District-Wide		
2018 Preschool Playground Equipment	2018 Wallpaper Seam Repairs	
, ,		
Douglas County High School - North B		
1992 30,890 SF Addition	2003 Science Room Conversion	2011 Life Safety Upgrade
1995 Team Room/Tennis Courts	2004 Cooling Units	2012 Replace Carpet
1995 Replace DDC	2004 Security Cameras/Radios	2012 Bathroom Improvements
1997 Air Conditioning	2004 Technology Improvements	2012 Partial Roof Replacement
2000 Running Track	2005 Security Access Control	2013 Projector Mounting
2001 Water System	2005 Security Kiosk	2013 Blackboard Removal
2002 Parking Lot Improvements	2008 Renovation - Phase I	2013 Energy Performance Contracting
2002 Artificial Turf	2010 Renovation - Phase II	2014 Electrical Switchgear and Panel board Replacement
		<u> </u>

2003 Bell System	2010 Communications Equipment	2017 Elevator Modernization
2003 Bathroom Improvements	2010 Addition - Athletic Complex	2018 Shop MAU Replacement
Pouglas County High School Sout	h Building	
Douglas County High School - Sout 1985 18,016 SF Addition		2017 Window Replacement-Multiple Areas
•	2006 Sidewalk Improvements	·
1993 Remodel - Phase I	2008 Roof Replacement	2017 Replace Entry Walk-Off Carpet
1997 Remodel - Phase II	2010 Communication Equipment	2018 Entry Carpet
2001 Water System		
Oouglas County Opportunity Center		
2017 Original Tenant Finish/Buildout		
Saale Ridae Elementary		
Eagle Ridge Elementary  1997 Air Conditioning	2004 Technology Improvements	2014 Resurface Gymnasium Floor
<u> </u>		·
1998 Tile Replacement	2005 Security Access Control	2016 Restroom Countertops Replacement
2001 Carpet Replacement	2007 Playground Improvements	2017 Replace Flooring in Restrooms
2003 Reballast	2013 Kitchen Floor Repair	2018 Bathrooms-Partitions, Countertops, & Flooring
2004 3,000 SF Addition	2014 Cafeteria Flooring	
Early Childhood Center		
2013 Gutter and Drain Repairs	2018 Window Tinting	
2018 Sinks	2018 SPED Calming Room	
Echo Park Stadium		
2012 Track Timing Stations	2013 Drainage Repairs	2018 Water Infiltration
2013 Tenant Finish to Building	2018 Track Repair	
The second secon		
Eldorado Elementary		
2001 New Construction	2005 Technology Improvements	2007 Technology Improvements
2004 Technology Improvements	2005 Security Access Control	2017 Convert Classroom to Special Education Calm Room
2004 Security Cameras/Radios	2006 Technology Improvements	2017 Replace Entry Walk-Off Carpet
lagstone Elementary		
2003 New Construction	2005 Technology Improvements	2018 Carpet Replacement - Mobile
		2016 Carpet Replacement - Mobile
2004 Security Cameras/Radios	2013 Carpet Replacement - Mobile	
2005 Security Access Control	2017 Replace Entry Walk-Off Carpet	
ox Creek Elementary		
2002 Lighting	2004 Technology Improvements	2012 Carpet Replacement - Mobile
2003 Playground Improvements	2005 Security Access Control	2017 Addition of Hand Rails on North Side of Building
2004 Security Cameras/Radios	2010 3,000 SF Addition	
Franktown Elementary		
1997 Bathroom Improvements	2004 Security Access Control	2012 Parking Lot Improvements
1998 Carpet Replacement	2004 Technology Improvements	2014 Update Water Well System
2000 Roof Replacement	2007 ADA Ramp	2014 Resurface Gymnasium Floor
2002 Remodel	2008 ADA Bathroom	2016 Domestic Hot Water System Upgrade
2004 Security Cameras/Radios	2012 Carpet Replacement	2018 Landscaping
Frontier Valley Elementary		
2002 New Construction	2005 Technology Improvements	2014 Update Water Well System
2004 Technology Improvements	2013 Cafeteria Floor Replacement	
2004 Security Cameras/Radios	2014 Clock System	
Gold Rush Elementary		
2010 New Construction	2017 Addition of Fence	2018 Landscaping
=,		
leritage Elementary	2005 Toobreless Incomes and	2017 Poplace From Wells Off Commit
2001 New Construction	2005 Technology Improvements	2017 Replace Entry Walk-Off Carpet
2004 Security Cameras/Radios	2012 Restroom Countertops	2018 Carpet Replacement
2005 Security Access Controls	2013 Carpet Replacement - Mobile	
Highlands Ranch High School		
1989 12,400 SF Addition	2002 Fencing	2014 Stage Lights and Catwalk
1994 Track Replacement	2002 35,175 SF Addition	2014 Resurface Track
1994 22,833 SF Addition	2004 Retaining Wall	2014 Intercom and Paging System Replacement
. JU I EE,UUU OI MUUIUUII	Loo i rotannig vvan	2011 Intersection and Laging Cystelli Replacement
1995 Hallway Infill	2004 Security Cameras/Radios	2014 Partial Roof Replacement

Highlands Ranch High School Cont.	2004 Security Assess Control	2015 Fire Alarm System Barlanament
1995 Parking Lot Improvements	2004 Security Access Control	2015 Fire Alarm System Replacement
1996 Vehicle Access	2004 Technology Improvements	2015 Generator Replacement
1997 Catwalk/Fire Doors	2005 Gas Shutoff Valves	2016 Parking Lot Resurface (Portions Only)
1997 Air Conditioning	2007 Security Kiosk	2017 Elevator Modernization
1999 Floor Tile Replacement	2010 Fire Alarm System Upgrade	2017 Convert Classroom to Special Education Calm Room
1999 Boilers	2012 Replace Artificial Turf Playfield	2018 Building Automation System
2000 Artificial Turf Playfield	2012 Partial Roof Replacement	2018 Domestic Hot Water System
2000 Batting Cages/Dugouts	2012 Replace Tile Flooring	2018 Bathroom-Toilet Partitions, Countertops, and Flooring
2000 Parking Lot Improvements	2012 Resurface Tennis Courts	2018 SPED Calming Room
Highlands Ranch Transportation Servi	ce Center	
2017 Addition of Mechanics Bay	2018 Oil/Lube System	
2018 Sidewalks		
ron Horse Elementary		
2004 Security Cameras/Radios	2012 Upgrade Controls System	2017 Concrete Stabilization of Pods (2)
2004 Technology Improvements	2013 Water Main Repair	2018 Soccer Field Fence
2005 Security Access Control	2013 Resurface Paved Areas	2018 Pod Settling
2010 Carpet Replacement	2014 Playpad Upgrade	2018 Mobile Ramp
2010 Cafeteria Flooring Repairs	2014 Fire Alarm System Replacement	
arkspur Elementary		
1992 Addition	2004 Clock System	2010 Gym Floor
1994 Rooftop Units	2004 Technology Improvements	2011 Roof Replacement
1997 Carpet Replacement	2005 Security Access Control	2010 Parking Lot Improvements
2000 Addition/Remodel	2009 Carpet Replacement	2013 Exterior Enhancement
2002 Playground Improvements	2006 Entry Tile Replacement	2016 Electrical Switchgear, Transformers, & Panel Replacement
2003 Intercom	2008 Elevator	2018 Bathrooms-Partitions, Countertops, & Flooring
Legacy Point Elementary		
2003 New Construction	2004 Technology Improvements	2017 Replace Entry Walk-Off Carpet
2004 Security Cameras/Radios	2012 Carpet Replacement - Mobile	, , , , , , , , , , , , , , , , , , , ,
2004 Security Access Control	2014 Clock System	
Legend High School 2008 New Construction	2013 Resand Gymnasium Floor	2014 Hillton Bood Traffic Signal
2008 22,097 SF Addition	2013 Repair Security Gate	2014 Hilltop Road Traffic Signal 2018 Reinforce Weight Room Floor
2000 22,097 SF Addition	2013 Repair Security Gate	2018 Relindice Weight Room Floor
Lone Tree Elementary		
2007 New Construction		
Mammoth Heights Elementary		
2007 New Construction	2012 Carpet Replacement - Mobile	
Meadow View Elementary		
2000 New Construction	2012 Concrete Repairs - service entry	2014 Clock System
2004 Technology Improvements	2013 Carpet Replacement - Mobile	2014 Interior Doors
2004 Security Cameras/Radios	2013 Window Replacement	2014 Carpet
2005 Security Access Control	2013 Interior Door Replacement	2018 Fire Alarm Dampers
Mesa Middle School		
2008 New Construction	2018 SPED Calming Room	
Mountain Ridge Middle School		2018 Bathrooms-Partitions, Countertops, & Flooring
Mountain Ridge Middle School 2003 New Construction	2004 Security Access Control	2010 Datiliodilis-Faitiliolis, Couliteitops, & Fiddiliu
2003 New Construction	2004 Security Access Control 2014 Clock System	2010 Battiloonis-Fattiloris, Countertops, & Flooring
2003 New Construction 2004 Technology Improvements	2014 Clock System	2010 Baumounis-Familions, Countertops, & Flooring
2003 New Construction	•	2010 Baumounis-Familions, Countertops, & Flooring
2003 New Construction 2004 Technology Improvements 2004 Security Cameras/Radios  Mountain View Elementary	2014 Clock System 2017 Addition of Secured Folding Partition Wall	
2003 New Construction 2004 Technology Improvements 2004 Security Cameras/Radios  Mountain View Elementary 1994 Roof Improvements	2014 Clock System 2017 Addition of Secured Folding Partition Wall 2001 5,278 SF Addition	2008 Roof Replacement
2003 New Construction 2004 Technology Improvements 2004 Security Cameras/Radios  Mountain View Elementary 1994 Roof Improvements 1997 Carpet Replacement	2014 Clock System 2017 Addition of Secured Folding Partition Wall  2001 5,278 SF Addition 2004 Security Cameras/Radios	2008 Roof Replacement 2014 Kitchen and Gymnasium Flooring
2003 New Construction 2004 Technology Improvements 2004 Security Cameras/Radios  Mountain View Elementary 1994 Roof Improvements 1997 Carpet Replacement 1999 Bathroom Improvements	2014 Clock System 2017 Addition of Secured Folding Partition Wall  2001 5,278 SF Addition 2004 Security Cameras/Radios 2004 Security Access Control	2008 Roof Replacement
2003 New Construction 2004 Technology Improvements 2004 Security Cameras/Radios  Mountain View Elementary 1994 Roof Improvements 1997 Carpet Replacement 1999 Bathroom Improvements 2000 Parking Lot Improvements	2014 Clock System 2017 Addition of Secured Folding Partition Wall  2001 5,278 SF Addition 2004 Security Cameras/Radios 2004 Security Access Control 2004 Technology Improvements	2008 Roof Replacement 2014 Kitchen and Gymnasium Flooring
2003 New Construction 2004 Technology Improvements 2004 Security Cameras/Radios  Mountain View Elementary 1994 Roof Improvements 1997 Carpet Replacement 1999 Bathroom Improvements	2014 Clock System 2017 Addition of Secured Folding Partition Wall  2001 5,278 SF Addition 2004 Security Cameras/Radios 2004 Security Access Control	2008 Roof Replacement 2014 Kitchen and Gymnasium Flooring
2004 Technology Improvements 2004 Security Cameras/Radios  Mountain View Elementary  1994 Roof Improvements 1997 Carpet Replacement 1999 Bathroom Improvements 2000 Parking Lot Improvements	2014 Clock System 2017 Addition of Secured Folding Partition Wall  2001 5,278 SF Addition 2004 Security Cameras/Radios 2004 Security Access Control 2004 Technology Improvements	2008 Roof Replacement 2014 Kitchen and Gymnasium Flooring

Mountain Vista High School Cont.		
2004 Chiller	2010 Site Improvements - Curb	2017 Convert Tennis Courts to Post Tension
2004 Security Cameras/Radios	2012 Tile Replacement - Halls/Classrooms	2018 Bleachers
2004 Security Access Control	2013 Resand Gymnasium Floor	2018 Synthetic Turf
2004 Technology Improvements	2013 Tennis Courts	2018 Track Repairs
2005 Artificial Turf Playfield	2014 Clock System	2018 Bathrooms-Partitions, Countertops, & Flooring
2005 "F" Pod Addition	2014 Resurface Track	2010 Datimoonio i antiiono, obamonopo, a i looling
2006 Clearstory windows	2014 Intercom and Paging System Replacement	
Northeast Elementary		
1992 8,642 SF Addition	2004 Security Cameras/Radios	2013 Playfield Replacement
1999 Roof Replacement	2004 Security Access Control	2014 Clock System
1999 Sidewalk	2006 Kitchen Make-up Air	2015 Fire Alarm System Replacement
2001 Playground Improvements	2011 White Boards	2015 Boiler, Chiller, and Controls Upgrade
2001 Access Road	2012 Site Lighting Poles	2017 Window Replacement-Multiple Areas
2002 1,540 SF Addition	2012 Tile Replacement - Halls/Classrooms	2018 Bathrooms-Partitions, Countertops, & Flooring
2004 Technology Improvements	2013 Daylighting Enhancement	
Northridge Elementary		
1996 Playground Improvements	2004 Security Cameras/Radios	2014 Cafeteria Flooring
1997 Air Conditioning	2005 Security Access Control	2014 Resurface Gymnasium Floor
2000 Carpet Replacement	2005 Playground Improvements	2018 Fire Alarm Devices
2004 3,590 SF Addition	2011 Sidewalk/Bridge	
2004 Technology Improvements	2013 Stage Partition	
Parker Joint Use Facility		
1993 Addition/Remodel	2003 Addition/Remodel	2014 Partial Roof Replacement
Pine Grove Elementary		
2004 Technology Improvements	2005 Security Access Controls	2010 3,996 SF Addition
2004 Security Cameras/Radios	2006 Carpet Replacement	2018 Mobile Ramp
Pine Lane Intermediate		
1992 1,980 SF Addition	2004 Security Cameras/Radios	2013 Daylighting Enhancement
1998 1,874 SF Addition	2005 Security Access Control	2014 Carpet
2003 HVAC Improvements	2005 Playground Imrovements	2016 Electrical Switchgear, Transformers, & Panel Replacement
2004 Intercom	2005 Elevator	2016 Roof Replacement (1 Section)
2004 Technology Improvements	2010 Roof Replacement	
Pine Lane Primary		
1994 Roof Replacement	2001 Bus Loop Improvements	2010 Roof Replacement
1996 Connect to Public Water	2003 6,951 SF Addition	2012 Carpet Replacement
1996 Playground Improvements	2004 Technology Improvements	2012 Carpet Replacement - Mobile
1996 Carpet Replacement	2004 Security Improvements	2013 Restroom Remodel
1998 Playground Improvements	2006 Parking Lot Improvements	2016 Electrical Switchgear, Transformers, & Panel Replacement
Pioneer Primary		
2005 Security Access Control	2011 Restroom Flooring Replacement	2014 Restroom Flooring
2006 Parking Lot Improvements	2014 Clock System	2014 Fire Alarm System Replacement
2008 Carpet Replacement	2014 Roof Repair	
Ponderosa High School		
1995 Parking Lot Improvements	2004 Security Cameras/Radios	2014 Intercom
1996 HVAC Improvements	2004 Technology Improvements	2014 Hallway/Classroom Flooring
1998 Roof Repair	2006 Special Education Restrooms	2014 Roof Replacement
1998 Water Main	2007 Security Kiosk	2015 Electrical Switchgear and Panel Board Replacement
1999 Gym Floor Replacement	2010 Security Detection System	2015 Track Replacement
2000 Boilers	2011 Carpet Replacement	2016 Boiler and Condensing Units Replacement
2001 Running Track	2012 Door Replacement/Repair	2017 ADA Modifications in Auditorium
2002 Addition/Remodel	2012 Tile Replacement - Halls-Classrooms	2017 Replace Theater Lighting System Processor
2003 Artificial Turf Playfield	2013 ADA Compliance	2017 Addition of Dust Collector
2004 Air Handling Units	2014 Resurface Turf Field	2018 Post Tension Tennis Courts
2004 Security Access Control	2014 Autoshop Expansion	2018 Theater Strand Lighting
Plum Creek Academy		
1997 Boiler	2001 Water Tap	2008 Roof Repairs
1998 Air Conditioning	2003 Addition	2009 Carpet
1999 Roof		

2001 New Construction	2004 Security Improvements	2018 Carnet Replacement
2001 New Construction 2004 Technology Improvements	2004 Security Improvements 2012 Carpet Replacement - Mobile	2018 Carpet Replacement 2018 Bathrooms-Partitions, Countertops, & Flooring
2004 Technology Improvements	2012 Carpet Replacement - Mobile	2018 Batillooms-Faithfors, Countertops, & Flooring
Ranch View Middle School		
1997 New Construction	2007 Security Kiosk	2017 Addition of Secured Folding Partition Wall at Pods
2004 Technology Improvements	2013 Resand Gymnasium Floor	2017 Convert Classroom to Special Education Calm Room
2004 Security Access Control	2014 Domestic Hot Water System Upgrade	2018 Cooling Tower
2004 Security Cameras/Radios	2017 Replace Fire Alarm System	2018 SPED Calming Room
Daniela da Elamanda da		
Redstone Elementary 2005 New Construction	2013 Carpet Replacement - Mobile	2017 Replace Entry Walk-Off Carpet
2003 New Construction	2013 Carpet Replacement - Mobile	2017 Replace Entry Walk-Off Carpet
Renaissance Elementary		
2006 New Construction	2012 Restroom Countertops	
Total Comment With Colored		
Rock Canyon High School	0007.0	0044 D. ( T. (5) H.
2003 New Construction	2007 Security Kiosk	2014 Resurface Turf Field
2004 Security Access Control	2010 28,249 SF Addition	2014 Intercom and Paging System Replacement
2004 Security Cameras/Radios	2010 Clearstory Windows	2018 Landscaping
2004 Technology Improvements	2013 Track Replacement	
Rock Ridge Elementary		
1995 Parking Lot Improvements	2003 Carpet Replacement	2012 Parking Lot/Playground Paving
1996 Parking Lot Improvements	2004 Security Cameras/Radios	2013 Carpet Replacement - Mobile
1997 Air Conditioning	2004 Technology Improvements	2014 Fence
2000 Playground Improvements	2005 Security Access Control	2014 Cafeteria Flooring
2001 Playground Improvements	2005 3,000 SF Addition	2017 Replace Entry Walk-Off Carpet
_ , ,, , , ,		
Rocky Heights Middle School	2004 Consuits Assess Cont.	2042 Decimana
2003 New Construction	2004 Security Access Control	2012 Drainage
2004 Security Cameras/Radios	2007 Security Kiosk	2014 Clock System
2004 Technology Improvements	2010 Drainage	2017 Addition of Secured Folding Partition Wall
Roxborough Intermediate		
2008 New Construction	2018 Movement Issues	
Roxborough Primary		2010 1 200 27 1 1 111
2000 Playground Improvements	2004 Intercom	2010 1,000 SF Addition
2001 Parking Lot Improvements	2004 Security Cameras/Radios	2013 Kitchen Floor Repair
2002 Generator	2004 Technology Improvements	2017 Replace Entry Walk-Off Carpet
2004 Carpet Replacement	2005 Security Access Control	
Saddle Ranch Elementary		
1999 New Construction	2005 Security Access Control	2016 Boiler Replacement (2)
2004 Technology Improvements	2013 Flooring Replacement	
2004 Security Cameras/Radios	2014 Clock System	
Sage Canyon Elementary		
2010 New Construction	2014 Repair to Handicap Ramp	2018 Window Tinting
Sagewood Middle School		
2004 Security Access Control	2006 HVAC Upgrade	2016 Domestic Hot Water System Upgrade
2004 Security Access Control 2004 Security Cameras/Radios	2010 Track Resurface	2017 Addition of Secured Folding Partition Wall
2004 Technology Improvement	2010 Track Resultace 2015 Fire Alarm System Replacement	2017 Addition of Secured Folding Partition Wall 2017 Window Glazing in Commons Area
2004 Technology Improvement	2010 The Alaim System Replacement	2017 Window Glazing in Commons Area 2018 Window Tinting
Sand Creek Elementary		
1990 8,237 SF Addition	2004 Security Cameras/Radios	2017 Replace Flooring in Restrooms
1999 Air Conditioning	2005 Security Access Control	2017 Window Replacement in Multiple Areas
2000 Playground Improvements	2005 3,000 SF Addition	2017 Replace Entry Walk-Off Carpet
2002 Carpet Replacement	2013 Carpet Replacement - Mobile	
2003 Reballast	2014 Cafeteria Flooring	
2004 Technology Improvements	2016 Restroom Countertop Replacement	
Sedalia Elementary	2004 Tophnologic Incorporation	2011 Dioutiold Doubles
1966 Gutters/Downspouts	2004 Technology Improvements	2011 Playfield Replacement
1992 Addition	2004 Security Cameras/Radios	2012 Sanitary Improvements

1999 Addition	2005 Security Access Control	2013 Daylighting Enhancement
2001 Countertops/Fountains	2005 Carpet Replacement	2014 Fire Alarm System Replacement
2003 HVAC Controls	2006 HVAC Upgrades	2014 Resurface Gymnasium Floor
2004 Roof Replacement	2006 Playground Improvements	2016 Rooftop Unit Replacement (2)
2004 Clock Replacement	2006 Roof Replacement	2017 Window Replacement-Multiple Areas
ierra Middle School		
1995 Partial Roof Replacement	2006 Gym Floor	2014 Resurface Gym Floor
1996 Heat Piping	2006 Road Connection	2014 Domestic Hot Water System Upgrade
1997 Partial Roof Replacement	2006 Bus Loop Improvements	2016 Electrical Panel Replacement
2003 Bathroom Improvements	2006 Lockers	2016 Emergency Generator Replacement
2003 Site Improvements	2007 Bleachers	2017 Replace Fire Alarm System
2004 Electrical Improvements	2011 Tile Replacement - Hallways	2017 Window Replacement-Multiple Areas
2004 9,000 SF Addition	2012 Clock System Upgrade	2017 Additional Lighting in Cafeteria
2004 Clock Replacement	2012 Kitchen Floor Repair	2018 Cafeteria Lighting
2004 Technology Improvements	2012 Partial Roof Replacement	2018 Entrance Improvements
2004 Security Cameras/Radios	2013 Cooling - Gymnasiums	
2005 Security Access Control	2014 Fence	
2005 Partial Roof Replacement	2014 Update Water Well System	
2006 Bleachers	2014 Remodel Special Needs Suite	
Soaring Hawk Elementary		
2004 New Construction	2004 Security Cameras/Radios	2012 Carpet Replacement - Mobile
2004 Technology Improvements	2005 Security Access Control	2014 Clock System
South Ridge Elementary		
1992 5,380 SF Addition	2004 Security Cameras/Radios	2013 Daylighting Enhancement
1994 Rooftop Units	2004 Security Access Control	2014 Clock System
1995 Mechanical Improvements	2004 Technology Improvements	2014 Resurface Gymnasium Floor
1997 Playground Improvements	2006 Roof Replacement	2016 Roof Replacement (1 Section)
1998 Drainage	2006 Elevator	2017 ADA Restrooms
2003 Rooftop Units	2012 Interior Door Hardware Replacement	2017 Replace Handwash Basins
2003 Water Service	2012 Carpet Replacement	2018 Bathrooms-Partitions, Countertops, & Flooring
Stone Mountain Elementary		
2007 New Construction		
Student Support Center		
Student Support Center 2007 New Mobile		
2007 New Mobile Summit View Elementary		
2007 New Mobile  Summit View Elementary  2000 Playground Improvements	2005 Security Access Control	2014 Cafeteria Flooring
2007 New Mobile  Summit View Elementary  2000 Playground Improvements  2004 Security Cameras/Radios	2005 Carpet Replacement	2014 Resurface Gymnasium Floor
2007 New Mobile  Summit View Elementary  2000 Playground Improvements	-	-
2007 New Mobile  Summit View Elementary  2000 Playground Improvements  2004 Security Cameras/Radios  2004 Technology Improvements  ThunderRidge High School	2005 Carpet Replacement 2008 2,684 SF Addition	2014 Resurface Gymnasium Floor 2018 Bathrooms-Partitions, Countertops, & Flooring
2007 New Mobile  Summit View Elementary  2000 Playground Improvements  2004 Security Cameras/Radios  2004 Technology Improvements  FhunderRidge High School  1998 34,368 SF Addition	2005 Carpet Replacement 2008 2,684 SF Addition  2007 Resurface Tennis Courts	2014 Resurface Gymnasium Floor 2018 Bathrooms-Partitions, Countertops, & Flooring 2014 Intercom and Paging System Replacement
2007 New Mobile  Summit View Elementary  2000 Playground Improvements 2004 Security Cameras/Radios 2004 Technology Improvements  ThunderRidge High School	2005 Carpet Replacement 2008 2,684 SF Addition	2014 Resurface Gymnasium Floor 2018 Bathrooms-Partitions, Countertops, & Flooring
2007 New Mobile  Summit View Elementary  2000 Playground Improvements  2004 Security Cameras/Radios  2004 Technology Improvements  ThunderRidge High School  1998 34,368 SF Addition  2004 Artificial Turf Playfield  2004 Batting Cages	2005 Carpet Replacement 2008 2,684 SF Addition  2007 Resurface Tennis Courts	2014 Resurface Gymnasium Floor 2018 Bathrooms-Partitions, Countertops, & Flooring 2014 Intercom and Paging System Replacement
2007 New Mobile  Summit View Elementary  2000 Playground Improvements  2004 Security Cameras/Radios  2004 Technology Improvements  ThunderRidge High School  1998 34,368 SF Addition  2004 Artificial Turf Playfield	2005 Carpet Replacement 2008 2,684 SF Addition  2007 Resurface Tennis Courts 2007 Security Kiosk	2014 Resurface Gymnasium Floor 2018 Bathrooms-Partitions, Countertops, & Flooring  2014 Intercom and Paging System Replacement 2015 Tennis Court Resurfacing
2007 New Mobile  Summit View Elementary  2000 Playground Improvements  2004 Security Cameras/Radios  2004 Technology Improvements  ThunderRidge High School  1998 34,368 SF Addition  2004 Artificial Turf Playfield  2004 Batting Cages	2005 Carpet Replacement 2008 2,684 SF Addition  2007 Resurface Tennis Courts 2007 Security Kiosk 2008 Concrete Slab Repair	2014 Resurface Gymnasium Floor 2018 Bathrooms-Partitions, Countertops, & Flooring  2014 Intercom and Paging System Replacement 2015 Tennis Court Resurfacing 2016 Turf Field Replacement
2007 New Mobile  Summit View Elementary  2000 Playground Improvements  2004 Security Cameras/Radios  2004 Technology Improvements  ThunderRidge High School  1998 34,368 SF Addition  2004 Artificial Turf Playfield  2004 Batting Cages  2004 Chiller	2005 Carpet Replacement 2008 2,684 SF Addition  2007 Resurface Tennis Courts 2007 Security Kiosk 2008 Concrete Slab Repair 2012 Tile Replacement - Halls/Classrooms	2014 Resurface Gymnasium Floor 2018 Bathrooms-Partitions, Countertops, & Flooring  2014 Intercom and Paging System Replacement 2015 Tennis Court Resurfacing 2016 Turf Field Replacement 2016 Interior Door Hardware
2007 New Mobile  Summit View Elementary  2000 Playground Improvements 2004 Security Cameras/Radios 2004 Technology Improvements  FhunderRidge High School  1998 34,368 SF Addition 2004 Artificial Turf Playfield 2004 Batting Cages 2004 Chiller 2004 Security Cameras/Radios	2005 Carpet Replacement 2008 2,684 SF Addition  2007 Resurface Tennis Courts 2007 Security Kiosk 2008 Concrete Slab Repair 2012 Tile Replacement - Halls/Classrooms 2012 Resurface Track	2014 Resurface Gymnasium Floor 2018 Bathrooms-Partitions, Countertops, & Flooring  2014 Intercom and Paging System Replacement 2015 Tennis Court Resurfacing 2016 Turf Field Replacement 2016 Interior Door Hardware 2017 Replace Carpet in Main and Pod Hallways and Vestibules
2007 New Mobile  Summit View Elementary  2000 Playground Improvements 2004 Security Cameras/Radios 2004 Technology Improvements  FhunderRidge High School  1998 34,368 SF Addition 2004 Artificial Turf Playfield 2004 Batting Cages 2004 Chiller 2004 Security Cameras/Radios 2004 Security Access Control	2005 Carpet Replacement 2008 2,684 SF Addition  2007 Resurface Tennis Courts 2007 Security Kiosk 2008 Concrete Slab Repair 2012 Tile Replacement - Halls/Classrooms 2012 Resurface Track 2012 Resurface Tennis Courts	2014 Resurface Gymnasium Floor 2018 Bathrooms-Partitions, Countertops, & Flooring  2014 Intercom and Paging System Replacement 2015 Tennis Court Resurfacing 2016 Turf Field Replacement 2016 Interior Door Hardware 2017 Replace Carpet in Main and Pod Hallways and Vestibules 2018 Tennis Court Repairs
2007 New Mobile  Summit View Elementary  2000 Playground Improvements 2004 Security Cameras/Radios 2004 Technology Improvements  ThunderRidge High School  1998 34,368 SF Addition 2004 Artificial Turf Playfield 2004 Batting Cages 2004 Chiller 2004 Security Cameras/Radios 2004 Security Access Control 2004 Technology Improvements 2006 Clearstory Windows	2005 Carpet Replacement 2008 2,684 SF Addition  2007 Resurface Tennis Courts 2007 Security Kiosk 2008 Concrete Slab Repair 2012 Tile Replacement - Halls/Classrooms 2012 Resurface Track 2012 Resurface Tennis Courts 2014 Fire Alarm System Replacement	2014 Resurface Gymnasium Floor 2018 Bathrooms-Partitions, Countertops, & Flooring  2014 Intercom and Paging System Replacement 2015 Tennis Court Resurfacing 2016 Turf Field Replacement 2016 Interior Door Hardware 2017 Replace Carpet in Main and Pod Hallways and Vestibules 2018 Tennis Court Repairs 2018 Bathrooms-Partitions, Countertops, & Flooring
2007 New Mobile  Summit View Elementary  2000 Playground Improvements 2004 Security Cameras/Radios 2004 Technology Improvements  FhunderRidge High School  1998 34,368 SF Addition 2004 Artificial Turf Playfield 2004 Batting Cages 2004 Chiller 2004 Security Cameras/Radios 2004 Security Access Control 2004 Technology Improvements 2006 Clearstory Windows	2005 Carpet Replacement 2008 2,684 SF Addition  2007 Resurface Tennis Courts 2007 Security Kiosk 2008 Concrete Slab Repair 2012 Tile Replacement - Halls/Classrooms 2012 Resurface Track 2012 Resurface Tennis Courts 2014 Fire Alarm System Replacement	2014 Resurface Gymnasium Floor 2018 Bathrooms-Partitions, Countertops, & Flooring  2014 Intercom and Paging System Replacement 2015 Tennis Court Resurfacing 2016 Turf Field Replacement 2016 Interior Door Hardware 2017 Replace Carpet in Main and Pod Hallways and Vestibules 2018 Tennis Court Repairs 2018 Bathrooms-Partitions, Countertops, & Flooring
2007 New Mobile  Summit View Elementary  2000 Playground Improvements 2004 Security Cameras/Radios 2004 Technology Improvements  ThunderRidge High School  1998 34,368 SF Addition 2004 Artificial Turf Playfield 2004 Batting Cages 2004 Chiller 2004 Security Cameras/Radios 2004 Security Access Control 2004 Technology Improvements 2006 Clearstory Windows	2005 Carpet Replacement 2008 2,684 SF Addition  2007 Resurface Tennis Courts 2007 Security Kiosk 2008 Concrete Slab Repair 2012 Tile Replacement - Halls/Classrooms 2012 Resurface Track 2012 Resurface Tennis Courts 2014 Fire Alarm System Replacement 2014 Partial Roof Replacement	2014 Resurface Gymnasium Floor 2018 Bathrooms-Partitions, Countertops, & Flooring  2014 Intercom and Paging System Replacement 2015 Tennis Court Resurfacing 2016 Turf Field Replacement 2016 Interior Door Hardware 2017 Replace Carpet in Main and Pod Hallways and Vestibules 2018 Tennis Court Repairs 2018 Bathrooms-Partitions, Countertops, & Flooring 2018 SPED Calming Room
2007 New Mobile  Summit View Elementary  2000 Playground Improvements 2004 Security Cameras/Radios 2004 Technology Improvements  FhunderRidge High School  1998 34,368 SF Addition 2004 Artificial Turf Playfield 2004 Batting Cages 2004 Chiller 2004 Security Cameras/Radios 2004 Security Access Control 2004 Technology Improvements 2006 Clearstory Windows  Fimber Trail Elementary 2003 New Construction 2004 Technology Improvements	2005 Carpet Replacement 2008 2,684 SF Addition  2007 Resurface Tennis Courts 2007 Security Kiosk 2008 Concrete Slab Repair 2012 Tile Replacement - Halls/Classrooms 2012 Resurface Track 2012 Resurface Tennis Courts 2014 Fire Alarm System Replacement 2014 Partial Roof Replacement	2014 Resurface Gymnasium Floor 2018 Bathrooms-Partitions, Countertops, & Flooring  2014 Intercom and Paging System Replacement 2015 Tennis Court Resurfacing 2016 Turf Field Replacement 2016 Interior Door Hardware 2017 Replace Carpet in Main and Pod Hallways and Vestibules 2018 Tennis Court Repairs 2018 Bathrooms-Partitions, Countertops, & Flooring 2018 SPED Calming Room
2007 New Mobile  Summit View Elementary  2000 Playground Improvements 2004 Security Cameras/Radios 2004 Technology Improvements  ThunderRidge High School  1998 34,368 SF Addition 2004 Artificial Turf Playfield 2004 Batting Cages 2004 Chiller 2004 Security Cameras/Radios 2004 Security Access Control 2004 Technology Improvements 2006 Clearstory Windows  Timber Trail Elementary 2003 New Construction 2004 Technology Improvements	2005 Carpet Replacement 2008 2,684 SF Addition  2007 Resurface Tennis Courts 2007 Security Kiosk 2008 Concrete Slab Repair 2012 Tile Replacement - Halls/Classrooms 2012 Resurface Track 2012 Resurface Tennis Courts 2014 Fire Alarm System Replacement 2014 Partial Roof Replacement	2014 Resurface Gymnasium Floor 2018 Bathrooms-Partitions, Countertops, & Flooring  2014 Intercom and Paging System Replacement 2015 Tennis Court Resurfacing 2016 Turf Field Replacement 2016 Interior Door Hardware 2017 Replace Carpet in Main and Pod Hallways and Vestibules 2018 Tennis Court Repairs 2018 Bathrooms-Partitions, Countertops, & Flooring 2018 SPED Calming Room
2007 New Mobile  Summit View Elementary  2000 Playground Improvements 2004 Security Cameras/Radios 2004 Technology Improvements  FhunderRidge High School  1998 34,368 SF Addition 2004 Artificial Turf Playfield 2004 Batting Cages 2004 Chiller 2004 Security Cameras/Radios 2004 Security Access Control 2004 Technology Improvements 2006 Clearstory Windows  Fimber Trail Elementary 2003 New Construction 2004 Technology Improvements	2005 Carpet Replacement 2008 2,684 SF Addition  2007 Resurface Tennis Courts 2007 Security Kiosk 2008 Concrete Slab Repair 2012 Tile Replacement - Halls/Classrooms 2012 Resurface Track 2012 Resurface Tennis Courts 2014 Fire Alarm System Replacement 2014 Partial Roof Replacement  2012 Chiller Replacement 2014 Clock System	2014 Resurface Gymnasium Floor 2018 Bathrooms-Partitions, Countertops, & Flooring  2014 Intercom and Paging System Replacement 2015 Tennis Court Resurfacing 2016 Turf Field Replacement 2016 Interior Door Hardware 2017 Replace Carpet in Main and Pod Hallways and Vestibules 2018 Tennis Court Repairs 2018 Bathrooms-Partitions, Countertops, & Flooring 2018 SPED Calming Room  2018 Bathrooms-Partitions, Countertops, & Flooring
2007 New Mobile  Summit View Elementary  2000 Playground Improvements 2004 Security Cameras/Radios 2004 Technology Improvements  ThunderRidge High School  1998 34,368 SF Addition 2004 Artificial Turf Playfield 2004 Batting Cages 2004 Chiller 2004 Security Cameras/Radios 2004 Security Access Control 2004 Technology Improvements 2006 Clearstory Windows  Timber Trail Elementary 2003 New Construction 2004 Technology Improvements  Trailblazer Elementary 2004 Security Access Control	2005 Carpet Replacement 2008 2,684 SF Addition  2007 Resurface Tennis Courts 2007 Security Kiosk 2008 Concrete Slab Repair 2012 Tile Replacement - Halls/Classrooms 2012 Resurface Track 2012 Resurface Tennis Courts 2014 Fire Alarm System Replacement 2014 Partial Roof Replacement  2012 Chiller Replacement 2014 Clock System	2014 Resurface Gymnasium Floor 2018 Bathrooms-Partitions, Countertops, & Flooring  2014 Intercom and Paging System Replacement 2015 Tennis Court Resurfacing 2016 Turf Field Replacement 2016 Interior Door Hardware 2017 Replace Carpet in Main and Pod Hallways and Vestibules 2018 Tennis Court Repairs 2018 Bathrooms-Partitions, Countertops, & Flooring 2018 SPED Calming Room  2018 Bathrooms-Partitions, Countertops, & Flooring
2007 New Mobile  Summit View Elementary  2000 Playground Improvements 2004 Security Cameras/Radios 2004 Technology Improvements  ThunderRidge High School  1998 34,368 SF Addition 2004 Artificial Turf Playfield 2004 Batting Cages 2004 Chiller 2004 Security Cameras/Radios 2004 Security Access Control 2004 Technology Improvements 2006 Clearstory Windows  Timber Trail Elementary 2003 New Construction 2004 Technology Improvements  Trailblazer Elementary  2004 Security Access Control 2004 Security Access Control 2004 Security Access Control 2004 Security Cameras/Radios	2005 Carpet Replacement 2008 2,684 SF Addition  2007 Resurface Tennis Courts 2007 Security Kiosk 2008 Concrete Slab Repair 2012 Tile Replacement - Halls/Classrooms 2012 Resurface Track 2012 Resurface Tennis Courts 2014 Fire Alarm System Replacement 2014 Partial Roof Replacement  2012 Chiller Replacement 2014 Clock System  2007 Carpet Replacement 2011 Security Door	2014 Resurface Gymnasium Floor 2018 Bathrooms-Partitions, Countertops, & Flooring  2014 Intercom and Paging System Replacement 2015 Tennis Court Resurfacing 2016 Turf Field Replacement 2016 Interior Door Hardware 2017 Replace Carpet in Main and Pod Hallways and Vestibules 2018 Tennis Court Repairs 2018 Bathrooms-Partitions, Countertops, & Flooring 2018 SPED Calming Room  2018 Bathrooms-Partitions, Countertops, & Flooring 2018 Bathrooms-Partitions, Countertops, & Flooring
2007 New Mobile  Summit View Elementary  2000 Playground Improvements 2004 Security Cameras/Radios 2004 Technology Improvements  ThunderRidge High School  1998 34,368 SF Addition 2004 Artificial Turf Playfield 2004 Batting Cages 2004 Chiller 2004 Security Cameras/Radios 2004 Security Access Control 2004 Technology Improvements 2006 Clearstory Windows  Timber Trail Elementary 2003 New Construction 2004 Technology Improvements  Trailblazer Elementary  2004 Security Access Control 2004 Security Access Control 2004 Security Access Control 2004 Security Cameras/Radios 2004 Technology Improvements	2005 Carpet Replacement 2008 2,684 SF Addition  2007 Resurface Tennis Courts 2007 Security Kiosk 2008 Concrete Slab Repair 2012 Tile Replacement - Halls/Classrooms 2012 Resurface Track 2014 Resurface Tennis Courts 2014 Fire Alarm System Replacement 2014 Partial Roof Replacement 2014 Clock System  2007 Carpet Replacement 2011 Security Door 2013 Restroom Flooring	2014 Resurface Gymnasium Floor 2018 Bathrooms-Partitions, Countertops, & Flooring  2014 Intercom and Paging System Replacement 2015 Tennis Court Resurfacing 2016 Turf Field Replacement 2016 Interior Door Hardware 2017 Replace Carpet in Main and Pod Hallways and Vestibules 2018 Tennis Court Repairs 2018 Bathrooms-Partitions, Countertops, & Flooring 2018 SPED Calming Room  2018 Bathrooms-Partitions, Countertops, & Flooring 2018 Bathrooms-Partitions, Countertops, & Flooring 2018 Bathrooms-Partitions, Countertops, & Flooring 2018 Roof Repair

1996 Tran Fuel Tank Removal	2003 Tran Thermal Performance	2012 Freezer Roof Replacement
2000 A/C Print Shop	2006 Warehouse Freezer Addition	2017 Addition of Transportation Building F
2003 CSAP Processing Center	2007 Parking Lot	2018 Electrical Maintenance
2003 Tran Carpet	2007 Security Gate	2018 Fuel Tank Upgrade
2003 Asphalt Parking Lot	2009 O&M HVAC	
est Support Center		
2012 Install Generator	2012 Student Records/ITS Office Reconfiguration	
2012 Insulat Outer Walls and Windos	2018 RTU Replacement	
filcox		
1989 Renovation	2000 Renovation	2002 Data Center
1994 Mechanical	2000 Renovation	2013 North Roof Replacement
1996 Renovation	2001 Renovation	2016 Additional Card Access and Cameras

2006 Carpet Replacement

2010 Flooring Replacement

2012 Controls System Upgrade

2013 Fire Alarm Panel Replacement

2013 Resurface Playground

2014 Clock System

2004 Security Cameras/Radios


2004 Security Access/Control

2006 Bus Loop Improvements

2004 Technology Improvements



### Capital Funding by Source, 2012-2019



Funding Source	2012	2013	2014	2015	2016	2017	2018	Total (By Funding Source)
2006 Bond Building Fund	\$5,736,968	\$2,572,041	\$0	\$0	\$0	\$0	\$0	\$8,309,009
2009 COP Building Fund	\$0	\$7,137,584	\$6,195,979	\$0	\$0	\$0	\$0	\$13,333,563
2012 COP Building Fund	\$0	\$0	\$0	\$0	\$931,000	\$0	\$0	\$931,000
2014 COP Building Fund	\$0	\$0	\$0	\$5,751,380	\$792,000	\$3,740,000	\$0	\$10,283,380
Capital Projects Fund	\$0	\$0	\$979,738	\$304,875	\$2,263,000	\$5,750,000	\$4,952,070	\$14,249,683
Capital Projects Fund (Performance Contracts)	\$0	\$3,000,000	\$1,055,000	\$0	\$0	\$0	\$0	\$4,055,000
Facilities Rental Revenue	\$0	\$0	\$0	\$80,000	\$250,000	\$0	\$265,679	\$265,679
Transportation	\$0	\$0	\$0	\$0	\$408,000	\$312,000	\$0	\$720,000
Cash in Lieu	\$0	\$0	\$0	\$0	\$0	\$2,100,000	\$266,500	\$2,366,500
Grand Total	\$5,736,968	\$12,709,625	\$8,230,717	\$6,136,255	\$4,644,000	\$11,902,000	\$5,484,249	\$54,843,814

Capital Funding 2012-2019: \$54,843,814



## <u>Cantril</u>

Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Flooring Carpet. Replace carpet in main hallway PS.	\$1,910	\$200-\$900	\$100-\$410
	Exterior Wall Construction. Repair, painting of stucco at restroom addition	\$3,810	\$400-\$1700	\$190-\$820
	Exterior Wall Construction. Re-point all stone masonry. Repair chimneys.	\$23,480	\$2430-\$10130	\$1180-\$5050
	Paint Exterior. Paint all exterior wood after restoration	\$9,420	\$990-\$4090	\$480-\$2030
	Exterior Windows. Renovate all exterior windows, includes abatement	\$210,450	\$21060-\$90560	\$10530-\$45250
	Other Doors and Entrances. Replace north entry storefront. Repair work done to stop rust. PS	\$4,660	\$550-\$2050	\$240-\$1000
	Interior Windows and Storefronts. Refinish window frames PS	\$1,060	\$150-\$550	\$60-\$230
	Interior Doors. Replace approx 50% of doors. Sand and refinish rest of doors (historic)	\$9,420	\$990-\$4090	\$480-\$2030
	Interior Doors. Refinish doors PS	\$4,660	\$550-\$2050	\$240-\$1000
	Interior Door Frames. Refinish door frames PS Fabricated Toilet Partitions. Refurbish or replace toilet	\$4,660	\$550-\$2050	\$240-\$1000
	partitions in boys preschool restroom PS	\$2,120	\$290-\$990	\$110-\$460
	Storage Shelving and Lockers. Refurbish storage cabinets in main hallway PS	\$1,060	\$150-\$550	\$60-\$230
	Sink Countertops. Replace all sink countertops, 3 total PS	\$2,750	\$360-\$1260	\$140-\$600
2-Medium	Lathe and Plaster. Repair multiple cracks in plaster walls	\$4,660	\$550-\$2050	\$240-\$1000
	Ceiling Finishes. Repair cracked plaster ceiling in foyer area, stage, and stage hallways, repaint. Clean and restain wood ceiling in gym	\$14,070	\$1440-\$6140	\$710-\$3030
	Ceiling Finishes. Repair cracked plaster ceiling in foyer area, stage, and stage hallways, repaint. Clean and restain wood ceiling in gym	\$9,420	\$990-\$4090	\$480-\$2030
	Tile Ceilings. Replace/remove glue down tiles in hallway, abatement may be needed PS	\$2,540	\$270-\$1170	\$130-\$550
	Lavatories. Upgrade lavatories PS	\$2,540	\$270-\$1170	\$130-\$550
	Sinks. Replace sinks at preschool hall and boys restroom (2) PS	\$1,590	\$220-\$720	\$80-\$350
	Theater and Stage Equipment. Replace folding stage curtain	\$7,620	\$790-\$3290	\$390-\$1640
	Fixed Casework. Refinish existing storage cupboards and cabinets	\$1,910	\$200-\$900	\$100-\$410
	Paving and Surfacing. Sidewalks. Replace sidewalk at SE entry, fix drainage issues	\$9,420	\$990-\$4090	\$480-\$2030
	Paving and Surfacing. Sidewalks. Replace section of sidewalk at south preschool room. Fix trip hazard at north entry landing PS	\$2,970	\$340-\$1340	\$150-\$640
	Site Lighting Controls. Add site lighting controls	\$11,850	\$1260-\$5160	\$600-\$2550
3-High	Standard Slab on Grade. Recoat garage flooring	\$4,660	\$550-\$2050	\$240-\$1000
	Wall Foundations. Recaulk areas of potential water infiltration	\$3,920	\$490-\$1690	\$200-\$850
	Standard Slab on Grade. Repair buckling at men's restroom floor	\$10,370	\$1040-\$4540	\$520-\$2230
	Interior Door Frames. Sand down and refinish door frames. Some might need to be replaced.(historic)	\$9,420	\$990-\$4090	\$480-\$2030
	Regular Stairs. Restoration of 2 sets of outside metal stairs	\$2,970	\$340-\$1340	\$150-\$640
	Paint Interior	\$17,240	\$1770-\$7470	\$870-\$3710
3-Medium	Paint Interior. Paint Interior PS Wainscoating. Sand and refinish wood wainscoating	\$7,090 \$23,480	\$720-\$3120 \$2430-\$10130	\$360-\$1530 \$1180-\$5050
	(historic). Repaint if only option Fire Sprinkler Water Supply. Install sprinkler system	•		· ·
	Fire Sprinkler Standpipe. Install sprinkler service and	\$93,700 \$37,440	\$9410-\$40310 \$3770-\$16170	\$4690-\$20150 \$1880-\$8050
	standpipe Fixed Casework. Replace casework in classrooms, sink in preschool PS	\$2,540	\$270-\$1170	\$130-\$550
	Blinds and Other Window Treatment. Replace blinds as necessary	\$4,660	\$550-\$2050	\$240-\$1000

## Cantril cont.

Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
3-Medium	Fences and Gates. Repair chain link fencing around front perimeter. Remove vegetation damaging fence	\$1,910	\$200-\$900	\$100-\$410
3-Low	Interior Windows & Storefronts. Re-install glass windows on hallway walls for daylighting on second level.	\$5,720	\$590-\$2490	\$290-\$1230
	Chilled Water Systems. Add air cooled chiller	\$67,050	\$6760-\$28860	\$3360-\$14420
4-Medium	Other Landscape Features. Re-landscape area in front of building	\$46,750	\$4760-\$20160	\$2340-\$10050

## **Chaparral High School**

Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
2 Madium	Flooring Cafeteria. Replace VCT in commons and hallways.	\$91,060	\$9150-\$39250	\$4560-\$19580
2-Medium	Wall Foundations. Recaulk foundation where concrete meets	\$32,790	\$3320-\$14120	\$1640-\$7050
3-High	Structural Slab on Grade. The closet between rooms 322 and 207 the floor has dropped and cracked, it needs mud jacking done or repair and the tiles need replaced.	\$3,490	\$410-\$1510	\$180-\$750
	Vinyl Coverings. Most wings needs vinyl repair or replacement	\$102,160	\$10250-\$43950	\$5110-\$21970
	Suspended Ceilings. Replace kitchen tile with food grade	\$6,140	\$670-\$2670	\$310-\$1320
3-Medium	Fire Sprinkler Water Supply. Would need to sprinkle all areas if renovation. Building partially sprinkled. Pods not sprinkled.	\$309,320	\$30990-\$133090	\$15470-\$66510
	Playing Fields. Softball Field. Fence needs replaced	\$34,480	\$3530-\$14830	\$1730-\$7420

## Cougar Run

	Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	3-Medium	Vinyl. Coverings. Wall Finishes. Repair wall vinyl. Some vinyl replaced 2005. Seams in corridor areas need repair	\$4,230	\$470-\$1870	\$220-\$910
		Interceptors. Grease interceptor OK would like to bypass	\$8,570	\$940-\$3740	\$430-\$1850
		Fire Sprinkler. Original Installation in cafeteria only, would need to be brought up to code if remodel.	\$417,080	\$41730-\$179430	\$20860-\$89680

## **Douglas County High School**

Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Revise domestic water service and distribution throughout north building to provide adequate residual pressures to fixtures and equipment. (Includes insulation).	\$350,570	\$35140-\$150840	\$17530-\$75380
	Terminal Self-Contained Units. North Building: Replace cabinet unit heaters	\$44,530	\$4480-\$19180	\$2230-\$9580
	Exhaust Ventilation Systems. Kitchen hood and vent systems do not meet current code.	\$39,660	\$4050-\$17150	\$1990-\$8530
	Exhaust Ventilation Systems. Smoke vents are required over the Stage. Install four (4)	\$24,640	\$2560-\$10660	\$1240-\$5300
	Exhaust Ventilation Systems. South- lower level student restrooms have inadequate ventilation.	\$8,990	\$920-\$3920	\$450-\$1940
	Glazed Roof Openings- Remove and replace broken 2x2 and 2x4 acrylic double dome skylights (12 each). Check remainder.	\$13,440	\$1370-\$5870	\$680-\$2890
	Interior Door Hardware. Upgrade door hardware for ADA compliance.	\$82,490	\$8320-\$35520	\$4130-\$17740
Tier 1	Replace exterior downspouts on South Bldg with more durable construction.	\$23,480	\$2430-\$10130	\$1180-\$5050
Funded by the 2018 Bond	Rusted roof deck areas above admin under BUR - remove and replace 1 small bad area. Add steel sump pans at 2 roof drains. Patch BUR	\$12,380	\$1330-\$5330	\$620-\$2660
	South Building: Revise art room ventilation systems. The current systems are not operating properly	\$19,890	\$2020-\$8620	\$1000-\$4280
	South- Refinish all Gyp Board soffits.	\$2,540	\$270-\$1170	\$130-\$550
	Terminal Self-Contained Units. Replace cabinet unit heaters	\$29,720	\$2990-\$12790	\$1490-\$6390
	Potable Water Distribution & Storage. Domestic Water Service. Meter old and in bad location. Replace under Phase 2. Abandon in Phase 3.	\$6,140	\$670-\$2670	\$310-\$1320
	Provide lighting in the south parking lot	\$69,270	\$6940-\$29840	\$3470-\$14900
	Sanitary Sewer Systems. Poor drainage at 7 downspouts at east end of south side South Bldg. Replace storm inlets and reconnect to storm drain	\$48,970	\$4940-\$21140	\$2450-\$10530
	Interior Door Hardware. DOOR HARDWARE / No sound seals on music area doors - 4 locations.	\$4,870	\$540-\$2140	\$250-\$1050
	Passenger Elevators. Renovate elevator.	\$158,630	\$15880-\$68280	\$7940-\$34110
	Provide one MDF and five IDF's rooms. The building does not have dedicated IDF and MDF rooms equipped with proper power and air conditioning	\$237,100	\$23810-\$102010	\$11860-\$50980
	North- Science CR 62, VCT floor has loosened and been repaired. Other tiles are beginning to loosen. Replace all tile.	\$7,300	\$810-\$3210	\$370-\$1570
	Flooring Carpet. Replace carpet throughout school.	\$136,950	\$13760-\$58960	\$6850-\$29450
	Flooring Hallways/Classrooms. Repair VCT throughout building.	\$5,290	\$620-\$2320	\$270-\$1140
	Flooring Hallways/Classrooms. Replace carpet with VCT 105 lobby.	\$3,600	\$410-\$1610	\$180-\$780
	Flooring Hallways/Classrooms. Replace carpet with VCT south costume storage, drama office, STAR lab. Abatement cost not included.	\$11,320	\$1190-\$4890	\$570-\$2440
2-High	Flooring Hallways/Classrooms. Replace VCT in all corridors.	\$58,060	\$5850-\$25050	\$2910-\$12490
	South 101 Dance, ramp wood flooring boards cupped. Replace and threshold.	\$2,540	\$270-\$1170	\$130-\$550
	South 102A Office, remove exist'g carpet Provide new carpet and rubber base	\$1,380	\$230-\$630	\$70-\$300
	South 104B Office, 50, 50B, 53B, 66A remove and replace VCT beyond life.	\$7,940	\$870-\$3470	\$400-\$1710
	South 50A, 50C Office, remove VCT beyond life; provide carpet.	\$2,750	\$360-\$1260	\$140-\$600
	Aluminum. windows in 66 & 67 single glazed. Adjacent HM frames rusting.	\$430	\$80-\$280	\$30-\$100

Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Broken concrete curbing in numerous areas. Remove and replace.	\$5,080	\$530-\$2230	\$260-\$1100
	DOORS NORTH / Exterior HM frames rusting. Refinish at Y,	\$2,540	\$270-\$1170	\$130-\$550
	Drinking Fountains and Coolers. Replace water coolers and drinking fountains throughout the north building. Refrigerant failing	\$51,820	\$5190-\$22290	\$2600-\$11150
	Existing grease interceptor is single compartment - replace w/ double compartment to meet code.	\$31,520	\$3190-\$13590	\$1580-\$6780
	Exposed steel beams / columns at Life Mgmt Wing rusting. Repaint. Paint Wood transoms above Metal Shop door and at Boiler Room and wood soffit at door F.	\$14,920	\$1590-\$6490	\$750-\$3210
	Exterior Wall Construction. Recaulk control joints at North Bldg	\$6,770	\$740-\$2940	\$340-\$1460
	Fixed Casework. Add more casework in SPED Kitchen	\$12,380	\$1330-\$5330	\$620-\$2660
	Fixed Casework. At admin - numerous base cabinet countertops too high and sink not ADA accessible	\$22,320	\$2290-\$9690	\$1120-\$4800
	Fixed Casework. At all science cr's - base cab countertops too high - not ADA accessible, no ADA sinks	\$16,820	\$1690-\$7290	\$850-\$3620
	Fixed Casework. At Art 42 - base cab countertops too high - not ADA accessible, no ADA sinks	\$6,140	\$670-\$2670	\$310-\$1320
	Fixed Casework. At career center - transaction surface countertops too high - not ADA accessible	\$1,700	\$210-\$810	\$90-\$370
	Fixed Casework. At main entry concession - transaction surface countertops too high - not ADA accessible	\$8,780	\$930-\$3830	\$440-\$1890
	Fixed Casework. At photography cr's - base cab countertops too high - not ADA accessible, no ADA sinks	\$7,300	\$810-\$3210	\$370-\$1570
	Fixed Casework. At teacher lounge - base cab countertops too high - not ADA accessible, no ADA sinks	\$4,130	\$480-\$1780	\$210-\$890
2-High	Fixed Casework. Display cases north bldg not DCSD standard. All doors and sliding hardware bad- replace	\$8,990	\$920-\$3920	\$450-\$1940
	Fixed Casework. Replace plan center top edge peel & wood veneer peel in Sci 36, 37, 60, 61.	\$5,080	\$530-\$2230	\$260-\$1100
	Fixed Casework. Science casework too high to comply w/ ADA, no accessible sinks	\$9,520	\$990-\$4190	\$480-\$2050
	Interceptors. Sand and oil interceptor at north building auto shop not operating properly - replace	\$39,770	\$4040-\$17140	\$1990-\$8550
	Interior Construction. Auditorium control room: no ADA access. Room too small and counter too high	\$15,870	\$1640-\$6840	\$800-\$3410
	Interior Construction. Upgrade auditorium with wheel chair spaces for ADA	\$750	\$160-\$360	\$40-\$160
	Interior Doors. Install new astragal and coordinator to fire doors. (6) locations	\$430	\$80-\$280	\$30-\$100
	Interior Doors. Replace flex locker room door	\$1,170	\$140-\$540	\$60-\$250
	North - some area separation wall penetrations need to be fire sealed	\$11,000	\$1110-\$4810	\$550-\$2370
	North Bldg brick veneer joints at Life Mgmt Wing and vertical joints at west face Auditorium deteriorating. Repoint	\$6,350	\$660-\$2760	\$320-\$1370
	North- E Wing entries do not have recessed mats	\$1,380	\$230-\$630	\$70-\$300
	North- Gymnasium exit doors in fire walls have damaged trim at exit devices. No label on doors and frames- Provide new doors, frames, hardware	\$30,140	\$3070-\$12970	\$1510-\$6480
	Overhead Doors. North Bldg -rolling counter doors too high for ADA at student store and attendance office	\$9,520	\$990-\$4190	\$480-\$2050
	Painted CMU exterior walls at Industrial Arts need touch up paint at downspouts after leaks repaired. Also repaint cu east side East Hall Kalwall monitor	\$9,950	\$1060-\$4360	\$500-\$2140
	Paving & Surfacing. South Building, no complying accessible route to grade outside Commons 100 and gym 103 west exits	\$24,010	\$2500-\$10400	\$1200-\$5170

Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Cost
	Paving and Surfacing. Access from northwest parking lot to North Bldg Main Entry is narrow, ill-defined. Clarify pedestrian route thru parking lot, remove dead end aisle, enlarge adjacent concrete island/add crosswalk; widen sidewalk to Main E	\$22,950	\$2360-\$9960	\$1150-\$4940
	Paving and Surfacing. Parking Lot. Resurface parking lot	\$528,750	\$52950-\$227450	\$26440-\$113690
	Paving and Surfacing. Sidewalks. Designated Entrance: Ramp at North Bldg Main Entry is to steep (1:12) Construct Ramp. Revise accessible route from Parking lot.	\$11,530	\$1180-\$4980	\$580-\$2480
	Paving and Surfacing. Sidewalks. Large concrete expansion/contraction joints at many concrete walks and curbs need repair and sealing.	\$9,950	\$1060-\$4360	\$500-\$2140
	Paving and Surfacing. Sidewalks. No accessible route from Front Street along North Driveway to North Bldg Main Entrance. Add concrete walks along north side west parking lot, regrade drive in front of Main Entrance and reconstruct w/in ADA; add	\$501,260	\$50150-\$215550	\$25070-\$107770
	Paving and Surfacing. Sidewalks. Pedestrian access from East park lot to North & South Bldgs exceeds ADA slope Regrade / replace concrete walk from NE corner South Bldg. to new track location	\$15,870	\$1640-\$6840	\$800-\$3410
	Paving and Surfacing. Sidewalks. Replace sidewalks displaced more than 1/2".	\$12,060	\$1250-\$5250	\$610-\$2600
	Provide plaster sink with large capacity plaster trap at north building art 41	\$10,160	\$1050-\$4450	\$510-\$2190
	Ramps . Ramp into Metal & Auto Shops too steep. Doorway access into Auto non ADA conforming	\$5,080	\$530-\$2230	\$260-\$1100
	Ramps. North- Auditorium- No ramp access to lower thrust stage or main stage from seating area. Provide lift or ramp	\$45,480	\$4630-\$19630	\$2280-\$9780
2-High	Regular Stairs. Handrails on stairs in E-Wing are too large, don't extend past bottom riser - not ADA compliant - replace	\$13,220	\$1390-\$5790	\$670-\$2850
	Repair 2 holes in exterior masonry at north wall of library	\$1,060	\$150-\$550	\$60-\$230
	Repair loose brick mortar on south exterior parapet wall of Room 82 (Weight Room)	\$6,140	\$670-\$2670	\$310-\$1320
	Repair masonry where water infiltrates mortar joint, 6+ locations (North Bldg)	\$22,320	\$2290-\$9690	\$1120-\$4800
	Replace deck mounted gas turrets at north building	\$16,920	\$1780-\$7280	\$850-\$3640
	Replace faucets at art sinks located in north building room 42	\$2,540	\$270-\$1170	\$130-\$550
	Replace floor drains and revise drainage connections within kitchen at south building	\$12,910	\$1300-\$5600	\$650-\$2780
	Replace floor sinks and drains and all connected waste piping below the floor within the kitchen of the north building	\$169,100	\$17010-\$72810	\$8460-\$36360
	Replace leaking north building teacher's lounge sink and faucet	\$2,540	\$270-\$1170	\$130-\$550
	Replace the wash fountain & DF located in the north building wood shop	\$9,730	\$1080-\$4280	\$490-\$2100
	Revise piping at sinks in classroom 53 of north building to allow for proper fixture operation	\$5,080	\$530-\$2230	\$260-\$1100
	Sinks. Replace stainless steel science sinks where classroom	\$37,120	\$3790-\$15990	\$1860-\$7980
	program dictates with epoxy sinks Sinks. Replace stainless steel sink in darkroom 45	\$2,540	\$270-\$1170	\$130-\$550
	Special Foundations. Repair foundation on bleacher walls where handrail post inserts have caused severe damage to block and concrete from moisture penetration thaw and freeze.	\$44,530	\$4480-\$19180	\$2230-\$9580
	Suspended Ceilings. Replace suspended grid ceiling in admin offices, not fire rated	\$20,410	\$2090-\$8790	\$1020-\$4390
	Theater & Stage Equipment. Auditorium theatrical equipment old and not comparable with other high schools	\$276,440	\$27670-\$118870	\$13830-\$59440

Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Theater & Stage Equipment. South 100A Stage/Dance, stage curtain drags on floor. Curtain and track damaged. Replace curtain and track system.	\$15,870	\$1640-\$6840	\$800-\$3410
	Waste Piping. Revise drainage piping at sink in auto shop room 51 to comply with code	\$8,990	\$920-\$3920	\$450-\$1940
	WINDOWS NORTH / Caulk perimeters at Life Mgmt Wing	\$2,540	\$270-\$1170	\$130-\$550
	DOORS SOUTH / Exterior HM windows, doors/frames rusting; refinish all locations	\$7,510	\$800-\$3300	\$380-\$1620
	Exterior Wall Construction. CMU and Brick. Repair CMU exterior wall of greenhouse, cracked and paint blistering	\$1,380	\$230-\$630	\$70-\$300
	Fixed Casework. At admin - Reception countertop too high- Not ADA accessible	\$4,450	\$460-\$1960	\$230-\$960
	Fixed Casework. Main Office wood transaction desk wood split. P-lam edges loose and peeling.	\$2,540	\$270-\$1170	\$130-\$550
	Fixed Casework. Repair/replace casework	\$3,070	\$340-\$1340	\$160-\$660
	Fixed Casework. White cabinets of 1971 vintage need new doors and latches. Many damaged in Art area. Countertop edges peeling. (casework and countertop in Ceramic CR ok condition)	\$15,870	\$1640-\$6840	\$800-\$3410
	Fixed Walls. Fire seal some area separation wall penetrations and top of walls	\$6,670	\$740-\$2940	\$340-\$1440
	Fixed Walls. Repair broken cement block and wall crack in gym. Fire Department pull station is installed on broken block. Crack follows joints to ceiling.	\$2,120	\$290-\$990	\$110-\$460
	Interior Construction. Install complying HC stall, accessories or grab bars in restrooms 100N, 100O, 103E, 103I, 43D, 43F	\$26,230	\$2680-\$11380	\$1320-\$5640
	Interior Construction. Most all single staff toilet rooms don't meet ADA accessibility, too small, sinks too high, revise to provide at least one men & women per floor	\$126,380	\$12730-\$54430	\$6320-\$27170
2-High	Interior Construction. Upgrade restrooms throughout building as needed	\$46,750	\$4760-\$20160	\$2340-\$10050
	Interior Construction. Upgrade stage, stage office, dressing rooms and costume storage room for ADA	\$23,690	\$2420-\$10220	\$1190-\$5100
	Paving and Surfacing. Parking Lot. Resurface parking lot	\$264,380	\$26530-\$113730	\$13220-\$56850
	Paving and Surfacing. Sidewalks. Steep walk at southeast corner of East parking lot of South Bldg. Remove existing walk and replace with new concrete walk adjacent to driveway curb	\$24,540	\$2470-\$10570	\$1230-\$5280
	Regular Stairs. Re-configure, add handrails, rebuild stairs at stage 100	\$24,640	\$2560-\$10660	\$1240-\$5300
	Regular Stairs. Replace corridor stair handrails, rectangular and not ADA compliant	\$14,490	\$1520-\$6320	\$730-\$3120
	Repair cracks in exterior stone façade at 7+ locations (South Bldg)	\$13,960	\$1450-\$6050	\$700-\$3010
	Repair cracks in Stucco fascia east & south elevations South Bldg. Caulk and repaint	\$8,570	\$940-\$3740	\$430-\$1850
	Replace sink faucet at math office in south building	\$1,380	\$230-\$630	\$70-\$300
	South Building- southeast entrance exterior wall projecting rowlock brick trim courses have been broken off. Remove and replace all broken rowlock trim and replace with new flush rowlock brick	\$29,190	\$3020-\$12620	\$1460-\$6280
	South- Caulk all control joints at South Bldg	\$1,380	\$230-\$630	\$70-\$300
	South Commons & Lobby exterior single glazed HM window frames. Provide new aluminum storefront framing with insulated glass	\$164,870	\$16540-\$70940	\$8250-\$35450
	South- Compression seal at ext wall located east of main north entry missing above 4' and loose below 4' - replace with ej cover	\$2,650	\$360-\$1160	\$140-\$570
	South- Provide ej cover at exterior brick wall west of main north entry where previous addition meets existing building	\$2,650	\$360-\$1160	\$140-\$570
	South- Storage 102B, infill south wall masonry openings	\$2,540	\$270-\$1170	\$130-\$550

Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	South- water damage to gyp board sills at Newspaper S65 - seal window frames and repair sills	\$1,490	\$220-\$720	\$80-\$320
	South/ Locker Room doors damaged. Provide new HM door and hardware.	\$4,020	\$490-\$1790	\$210-\$870
2-High	TOILET PARTITIONS North / Many beyond life; Replace (Replaced in I.A. toilets)	\$50,660	\$5150-\$21850	\$2540-\$10900
	TOILET PARTITIONS South / Locker Room damaged; Replace	\$2,650	\$360-\$1160	\$140-\$570
	WINDOWS SOUTH / Caulk perimeters at all windows	\$24,640	\$2560-\$10660	\$1240-\$5300
	Carpeting. Replace carpeting in 2 story addition. media center. and teachers lounge.	\$89,150	\$8960-\$38360	\$4460-\$19170
	Flooring Restroom. Replace ceramic tile flooring with seamless acrylic in two sets of restrooms at 2 story addition.	\$13,440	\$1370-\$5870	\$680-\$2890
	Edge of wood Stage floor broken, tacky.	\$3,070	\$340-\$1340	\$160-\$660
	Fabricated Toilet Partitions. Replace toilet partitions in 2 sets of restrooms at 2 story addition	\$8,460	\$940-\$3640	\$430-\$1820
	Interior Construction. Upgrade restrooms in two storey addition, restroom in north hall, and old locker rooms.	\$44,630	\$4480-\$19280	\$2240-\$9600
	Lavatories. Replace lavs and sinks in 2 sets of restrooms at 2 story addition, restroom in north hall, and old locker rooms	\$23,480	\$2430-\$10130	\$1180-\$5050
	North- additional vent in Jewelry classroom requested to allow 6 work stations + two mini kilns	\$17,030	\$1780-\$7380	\$860-\$3670
	Paving & Surfacing. Poor access for trash trucks north side North Bldg. Reposition dumpster area for direct truck access.	\$2,010	\$300-\$900	\$100-\$440
2-Medium	Paving and Surfacing. Parking Lot. Regrade and repave concrete paving area at North Bldg Industrial Arts area, ponds water, icing.	\$32,680	\$3330-\$14130	\$1640-\$7030
z-meutum	Paving and Surfacing. Parking Lot. Regrade and repave flat parking area north of North Bldg, poor drainage. Add area drains	\$159,260	\$15950-\$68550	\$7970-\$34250
	Remove abandoned water and waste piping rendered inactive by the removal of evaporative cooling equipment	\$2,540	\$270-\$1170	\$130-\$550
	Special HVAC Systems and Equipment. Provide key switch and push button style to meet code for gas control stations at all science classrooms	\$49,390	\$5020-\$21320	\$2470-\$10620
	Special HVAC Systems and Equipment. Revise natural gas piping feeding to the north classroom wing to be overhead	\$21,150	\$2150-\$9150	\$1060-\$4550
	Vehicle circulation problems at South Driveway for bus entry/exit. Driveway widened in Phase 1restripe. Add right turn lane under Stadium Expansion. Requires relocating traffic light pole and electrical box.	\$2,010	\$300-\$900	\$100-\$440
	Eliminate neutralization at specific locations in the south building	\$5,080	\$530-\$2230	\$260-\$1100
	Stair, Tread & Landing Finishes. Replace stairtread west entry north stairs and small stairs from offices to lower level	\$8,150	\$860-\$3560	\$410-\$1760
	Auto Shop sectional doors operational, need minor repairs to replace seals and missing rollers.	\$850	\$160-\$460	\$50-\$190
	Fixed Walls. KALWALL NORTH / Some leaks in middle hall	\$850	\$160-\$460	\$50-\$190
3-High	Insulation. Replace pipe insulation on all domestic hot water and hot water circulation piping throughout if piping not replaced	\$117,280	\$11830-\$50530	\$5870-\$25220
	North Bldg groundface CMU stained, grimy. Paint w/ oil- based enamel	\$19,890	\$2020-\$8620	\$1000-\$4280
	North- exit doors at south vestibule from main gym racked, not closing properly - replace	\$11,740	\$1270-\$5070	\$590-\$2530
	Repair cracked masonry at SW interior corner of Commons	\$12,380	\$1330-\$5330	\$620-\$2660

Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Repair cracked masonry over window at interior corridor. (NW corner of courtyard)	\$3,920	\$490-\$1690	\$200-\$850
	Repair masonry mortar at drinking fountains southwest corner of gym	\$2,540	\$270-\$1170	\$130-\$550
	Suspended Ceilings. Replace 33% of ceiling tiles, stained or damaged. Replace grid in classrooms	\$38,710	\$3900-\$16700	\$1940-\$8330
	Temp CR area at South Bldg bare from foot traffic. Dress up grade and reseed	\$4,450	\$460-\$1960	\$230-\$960
	Blinds and Other Window Treatment. Add window coverings at faculty lounge	\$8,990	\$920-\$3920	\$450-\$1940
	Classroom #54 concrete slab is raised 1"-2" for entire center portion of room. +/- 4' wide apron slopes down at entire room perimeter.	\$24,640	\$2560-\$10660	\$1240-\$5300
	Column Foundations. South west corner court yd inner wall is separating from pillar.	\$34,480	\$3530-\$14830	\$1730-\$7420
	Patch cracks in GB bulkheads at north wall of entry Lobby	\$7,510	\$800-\$3300	\$380-\$1620
	Repair cracked masonry at each truss location above windows; add control joints (south wall)	\$14,920	\$1590-\$6490	\$750-\$3210
	Repair cracked masonry at north wall of Dance Studio	\$5,080	\$530-\$2230	\$260-\$1100
	Repair cracked masonry at north wall of north stair corridor	\$5,080	\$530-\$2230	\$260-\$1100
3-High	Repair floor slab cracks or joints approx. 7 locations (damaged flooring)	\$14,920	\$1590-\$6490	\$750-\$3210
	Repair masonry near base of drain alcove at Wood Shop	\$2,540	\$270-\$1170	\$130-\$550
	Replace loose brick cap at truss location (south wall Science #11	\$1,380	\$230-\$630	\$70-\$300
	South Communication Room 60G, replace missing east wall above ceiling CMU face shell	\$1,380	\$230-\$630	\$70-\$300
	South- Corridor 100G, replace broken face shell and infill gap around north wall fire alarm horn.	\$1,380	\$230-\$630	\$70-\$300
	South-Gym 103 gyp board at east wall above lockers is damaged by balls- replace with more durable material	\$6,240	\$670-\$2770	\$320-\$1350
	Superstructure. Need-Repair cracks in one concrete column south of Science #11 and one south of Commons	\$17,980	\$1830-\$7830	\$900-\$3870
	Suspended Ceilings. 101A, remove and replace water damaged portion of gyp. board. ceiling (at NW). Repair 140 sf, Fire tape new and existing GB joints.	\$1,910	\$200-\$900	\$100-\$410
	Suspended Ceilings. 9x9 ACT in Vocal Office loose and missing tiles. Install 2x4 SAG	\$850	\$160-\$460	\$50-\$190
	Suspended Ceilings. Corridor 51D ceiling tiles missing and damaged - replace	\$320	\$90-\$190	\$20-\$70
	Suspended Ceilings. Replace ceiling tiles entire building as needed.	\$24,220	\$2490-\$10490	\$1220-\$5210
	Upper Floor. South Restroom 7P, install new floor expansion joint cover along east wall	\$1,910	\$200-\$900	\$100-\$410
	Backfill needed at low areas at edge of sidewalks and curbs east side of bus loop	\$5,080	\$530-\$2230	\$260-\$1100
	Backfill needed at low areas at edge of sidewalks and curbs north side of drive to east parking lot.	\$2,540	\$270-\$1170	\$130-\$550
	Channel at south side of Southwest Playfield (from parking lot to Front Street) is eroding. Install underground storm drain between upper and lower inlets.	\$63,770	\$6440-\$27440	\$3190-\$13710
3-Medium	Either side of the path north of East Parking Lot has bare spots. Reseed, sod, irrigate and add fence to control traffic.	\$20,840	\$2170-\$8970	\$1050-\$4480
	Erosion and poor drainage at southwest corner of South Bldg parking lot. Regrade, repair asphalt, curb & gutter / enlarge inlet.	\$29,720	\$2990-\$12790	\$1490-\$6390
	Erosion of hill east of South Bldg. Regrade, add fence, native seed and irrigation	\$30,250	\$3060-\$13060	\$1520-\$6510

Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Fences and Gates. Balls from Southwest Playfield roll onto South Drive. Add estate fence with mesh along south side of Drive.	\$17,770	\$1840-\$7740	\$890-\$3820
	Fences and Gates. Chain Link fence at Metal Shop non- conforming to DCSD Standard	\$2,540	\$270-\$1170	\$130-\$550
	Fences and Gates. Fences and Gates. Multiple social paths exist through native seed areas. Add site fencing to limit cut through by students.	\$15,870	\$1640-\$6840	\$800-\$3410
	Fences and Gates. Repair/replace fence at walks at parking lot west of North bldg.	\$9,950	\$1060-\$4360	\$500-\$2140
	Fences and Gates. Sections of 6' ht. chain link fence at the south perimeter of the school are barbed, not knuckled.	\$30,670	\$3140-\$13240	\$1540-\$6600
	Install headwalls at each end of CMP northeast corner South Bldg.	\$9,950	\$1060-\$4360	\$500-\$2140
	No acoustical wall panels in Vocal Room; low ceilings substandard acoustics	\$37,120	\$3790-\$15990	\$1860-\$7980
	Northeast side of North Bldg has only sparse native seed. Add cobble, shrub beds, irrigation, and sod w/ mow band.	\$59,330	\$5980-\$25580	\$2970-\$12760
	Old wooden site furnishings present splinter hazard. Replace w/ non-wooden	\$9,520	\$990-\$4190	\$480-\$2050
3-Medium	Paint Interior. Paint cmu & gyp board in main, center and east halls	\$49,390	\$5020-\$21320	\$2470-\$10620
	Pedestrians are walking up a steep dirt path from south parking lot to South Bldg North Entry. Re-landscape to stop	\$12,060	\$1250-\$5250	\$610-\$2600
	Ponding water at riprap clogged inlet south of south Stadium building. Regrade area and clean out riprap	\$22,320	\$2290-\$9690	\$1120-\$4800
	Poor drainage at north side of South Bldg and at greenhouse. Regrade and modify storm pipes at existing downspouts.	\$34,690	\$3520-\$15020	\$1740-\$7460
	Poor drainage east side of North Bldg at lower floor exits. Pipe existing downspouts to existing storm system.	\$4,230	\$470-\$1870	\$220-\$910
	Poor drainage in Courtyard of North bldg. Rework grading, flatwork, storm system.	\$159,160	\$15950-\$68450	\$7960-\$34220
	Rusty, exposed steel edger northwest of South Bldg. Replace w/ bend-a-board.	\$2,540	\$270-\$1170	\$130-\$550
	Vinyl Coverings. Need-Replace vinyl covered sheetrock below skylights in south hallway. Appears to have water damage.	\$4,550	\$560-\$2060	\$230-\$980
	Paint Interior. South 100I Kitchen, 100J Dishwash. CMU wall surface not smooth per Health Dept. standards. Apply filler or veneer plaster and epoxy paint.	\$47,060	\$4750-\$20250	\$2360-\$10120
	Repair walls & door frames, repaint South in lower level, faculty lounge, special ed, admin, support spaces	\$103,750	\$10460-\$44660	\$5190-\$22310
	Add shade trees west of South Bldg west parking area plus 12 trees in 4 islands in Northwest Parking Lot	\$28,660	\$2950-\$12350	\$1440-\$6170
	Front Street landscaping and irrigation	\$173,750	\$17460-\$74760	\$8690-\$37360
	Other Landscape Features. Improve native growth on south side of building	\$8,990	\$920-\$3920	\$450-\$1940
	Landscape erosion on hill at east stadium entrance. Spilling on to side wall. Improve landscape to fix	\$2,230	\$280-\$980	\$120-\$480
	Playing Fields. Discus Area; old style backstop - replace w/ DSCD standard	\$6,140	\$670-\$2670	\$310-\$1320
4-Medium	Playing Fields. Shot Put Area; old style backstop - replace w/ DCSD standard	\$4,660	\$550-\$2050	\$240-\$1000
	Provide dishwasher at teacher's lounge in south building	\$2,540	\$270-\$1170	\$130-\$550
	Remove existing dirt road to Central Playfield from NE corner South Bldg.	\$14,920	\$1590-\$6490	\$750-\$3210
	Repair & replace landscape and mulch in parking lots at north building.	\$32,680	\$3330-\$14130	\$1640-\$7030
	Replace mulch at northwest, west and southwest perimeter of North Bldg.	\$29,720	\$2990-\$12790	\$1490-\$6390
	Provide disposer at teacher's lounge sink in south building	\$1,380	\$230-\$630	\$70-\$300

## Furniture, Fixtures, and Equipment

Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
-I ∩W/	DC Oakes High School / District Media Center . Replace furniture with 21st century learning fuurniture	\$25,000	\$2500-\$10800	\$1250-\$5380
3-Low	Rock Canyon High School . Replace furniture with 21st century learning fuurniture	\$400,000	\$40000-\$172000	\$20000-\$86000
3-Low	Soaring Hawk Elementary . Replace furniture with 21st century learning fuurniture	\$200,000	\$20000-\$86000	\$10000-\$43000

## North Transportation Terminal

Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
2-Medium	Paving and Surfacing. Sidewalks. Repair/replace sections of sidewalk in front of building	\$18,720	\$1890-\$8090	\$940-\$4030
Z-Medium	Paving and Surfacing. Sidewalks. Install paved sidewalk to bus area and south employee parking from building	\$37,440	\$3770-\$16170	\$1880-\$8050
	Interior Windows and Storefronts. Sand and refinish/paint interior windows	\$4,660	\$550-\$2050	\$240-\$1000
	Interior Door Frames. Replace door jambs as necessary	\$7,620	\$790-\$3290	\$390-\$1640
	Paint Interior. Paint interior	\$14,070	\$1440-\$6140	\$710-\$3030
	Suspended Ceilings. Replace ceiling tile. Replace some grid sections	\$10,900	\$1110-\$4710	\$550-\$2350
	Tile Ceilings. Remove old tile from ceilings (abatement). Refinish exposed areas	\$42,200	\$4310-\$18210	\$2110-\$9080
3-Medium	Blinds and Other Window Treatment. Replace window blinds	\$9,420	\$990-\$4090	\$480-\$2030
	Curbs, Rails and Barriers. Add curb and gutter for proper drainage	\$46,750	\$4760-\$20160	\$2340-\$10050
	Retaining Walls. Repair/replace retaining walls at NW area of building at parking lot, entrance to site on east side	\$4,660	\$550-\$2050	\$240-\$1000
	Site Lighting Poles. Add site lighting to all bus and employee parking	\$37,440	\$3770-\$16170	\$1880-\$8050
3-Low	Miscellaneous Structures. Markee sign. Install markee sign at front entry.	\$4,660	\$550-\$2050	\$240-\$1000
	Other Landscape Features. Trim cottonwood trees on canal to keep from damaging fencing	\$4,660	\$550-\$2050	\$240-\$1000
4-Medium	Other Landscape Features. Remove dirt pile at north end of east parking lot for future expansion	\$6,670	\$740-\$2940	\$340-\$1440
	Flagpoles. Relocate flagpole to front entry	\$1,060	\$150-\$550	\$60-\$230
4-Low	Planting. Install ornamental landscaping at front entry, replace dead trees around site	\$9,420	\$990-\$4090	\$480-\$2030

Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Paving & Surfacing. Bus Loop. Resurface asphalt bus loop	\$39,450	\$3960-\$17060	\$1980-\$8490
	Paving & Surfacing. Sidewalks. Repair/replace sections of sidewalk as necessary	\$9,950	\$1060-\$4360	\$500-\$2140
	Paving and Surfacing. Parking Lot. Resurface asphalt parking lot	\$78,680	\$7930-\$33930	\$3940-\$16920
2-High	Playing Fields. Playground. Replace asphalt playground	\$19,780	\$2030-\$8530	\$990-\$4260
2 mgn	Retractable Partitions. Refurbish or replace all classroom partitions	\$49,180	\$4930-\$21230	\$2460-\$10580
	Solid Exterior Doors. Repair or refinish exterior doors	\$5,080	\$530-\$2230	\$260-\$1100
	Wash Fountains. Replace trough washing stations with sinks (6)	\$16,920	\$1780-\$7280	\$850-\$3640
	Window Storefronts. Repair/replace classroom storefronts	\$60,810	\$6100-\$26200	\$3040-\$13080
	Flooring Kitchen. Replace VCT in kitchen.	\$63,450	\$6350-\$27350	\$3180-\$13650
	Flooring Kitchen. Replace VCT in kitchen.	\$63,450	\$6350-\$27350	\$3180-\$13650
	Flooring Restroom. Replace ceramic tile with poured acylic.	\$63,450	\$6350-\$27350	\$3180-\$13650
2-Medium	Exterior Wall Construction. Repair stucco from woodpecker damage	\$2,120	\$290-\$990	\$110-\$460
2 Medium	Solid Exterior Doors. Replace exterior doors	\$79,320	\$7990-\$34190	\$3970-\$17060
	Exterior Wall Construction. Recaulk remaining control joints	\$3,180	\$330-\$1430	\$160-\$690
	Paint Exterior. Exterior entrances need painted again if not replaced	\$3,710	\$400-\$1600	\$190-\$800
	Site Improvements. Improve parking areas and access	\$60,070	\$6040-\$25840	\$3010-\$12920
	Interior Door Frames. Sand/repaint interior door frames	\$22,210	\$2300-\$9600	\$1110-\$4780
	Interior Doors. Refinish doors	\$44,310	\$4500-\$19100	\$2220-\$9530
	Playing Fields. Multi-use Field. Renovate multi-use field	\$78,680	\$7930-\$33930	\$3940-\$16920
3-High	Suspended Ceilings. Replace grid ceiling and tile in original building	\$164,970	\$16530-\$71030	\$8250-\$35470
	Wall Foundations. Recaulk foundation where concrete meets	\$5,500	\$610-\$2410	\$280-\$1190
	Playing Fields. Multi-use Field. Renovate multi-use field	\$78,680	\$7930-\$33930	\$3940-\$16920
	Wall Foundations. Recaulk foundation where concrete meets, quite a bit has been done	\$7,940	\$870-\$3470	\$400-\$1710
	Column Foundations. Repair steel beams and concrete foundation on south gym wall	\$5,290	\$620-\$2320	\$270-\$1140
	Fire Sprinkler Water Supply. Install sprinkler system	\$412,320	\$41290-\$177390	\$20620-\$88650
	Vinyl Coverings. Repair or replace vinyl coverings	\$5,930	\$680-\$2580	\$300-\$1280
	Fire Sprinkler Water Supply. Fire sprinkle building	\$392,650	\$39350-\$168850	\$19640-\$84420
3-Medium	Flooring Tile. Replace entry way tile	\$11,530	\$1180-\$4980	\$580-\$2480
	Interior Doors. Refinish interior doors Site Improvements. Repair drainage issues at front of site	\$5,290 \$9,950	\$620-\$2320 \$1060-\$4360	\$270-\$1140 \$500-\$2140
	· · · · · · · · · · · · · · · · · · ·	•		
	Suspended Ceilings. Replace ceiling grid and tile	\$132,190	\$13320-\$56920	\$6610-\$28420
	Vinyl Coverings. Minor repair of vinyl coverings	\$5,080	\$530-\$2230	\$260-\$1100
4-High	Seeding and Sodding. Renovate grass area around school.	\$9,950	\$1060-\$4360	\$500-\$2140
4-High	Seeding and Sodding. Renovate grass area around school.	\$9,950	\$1060-\$4360	\$500-\$2140

#### Ponderosa High School

Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Water Closets. Some in good condition, some poor (50%). Upgrade to autoflush valves	\$24,540	\$2470-\$10570	\$1230-\$5280
	Lavatories. Some in good condition, some poor (50%). Upgrade to autosensor	\$32,680	\$3330-\$14130	\$1640-\$7030
	Wash Fountains. Poor condition, need replaced	\$22,210	\$2300-\$9600	\$1110-\$4780
	Showers. Poor condition, need upgraded	\$24,540	\$2470-\$10570	\$1230-\$5280
	Acid Waste Systems. Poor condition, needs upgraded.	\$16,290	\$1720-\$7020	\$820-\$3510
	Energy Supply. Install new gas supply lines for new gas kitchen equipment	\$59,010	\$6000-\$25400	\$2950-\$12690
2-High	Air Purifiers. Poor condition, needs upgraded	\$40,820	\$4180-\$17590	\$2050-\$8780
	Paint Spray Booth Ventilation. Poor condition, needs upgraded	\$73,610	\$7400-\$31700	\$3680-\$15830
	Moveable Furnishings. Remove chalkboards or repurpose with different writing medium	\$12,270	\$1240-\$5340	\$620-\$2640
	Fixed Casework. Refurbish lockers.	\$24,330	\$2480-\$10480	\$1220-\$5230
	Paving and Surfacing. Parking Lot. Resurface asphalt parking lot	\$441,830	\$44280-\$190080	\$22100-\$95000
	Ceiling Finishes. Remove all existing exposed sound proofing. Replace with other sound absorption product.	\$60,810	\$6100-\$26200	\$3040-\$13080
	Flooring Kitchen. Replace Terrazzo tile with MMA.	\$5,080	\$530-\$2230	\$260-\$1100
	Flooring Gym. Sand and resurface small gym floor.	\$19,780	\$2030-\$8530	\$990-\$4260
2-Medium	Exterior Wall Construction. Recaulk control joints.	\$9,420	\$990-\$4090	\$480-\$2030
2 Medium	Interceptors, Grease. Poor condition, needs upgraded.	\$24,540	\$2470-\$10570	\$1230-\$5280
	Wall Foundations. Recaulk foundation where concrete meets	\$9,420	\$990-\$4090	\$480-\$2030
	Interior Construction. Renovate kitchen area	\$29,510	\$3000-\$12700	\$1480-\$6350
	Insulation. Poor condition. Replace insulation	\$12,380	\$1330-\$5330	\$620-\$2660
3-High	Blinds & Other Window Treatment. If the Pella windows get replaced new blinds will need to be installed	\$28,130	\$2880-\$12180	\$1410-\$6050
	Fire Sprinkler Water Supply. Building sprinkled at stage only. Install new sprinkler system for code compliance. Replace existing heads.	\$448,700	\$44910-\$193010	\$22440-\$96470
	Paving and Surfacing. Parking Lot. install asphalt parking lots at west side athletic fields, east side between tennis courts and softball field.	\$606,380	\$60730-\$260830	\$30320-\$130370
3-Medium	Fences & Gates. Repair/replace cable fence and split rail fence west side and split rail at bus loop	\$17,240	\$1770-\$7470	\$870-\$3710
	Other Landscape Features. Improve drainage on east and west sides	\$30,460	\$3150-\$13150	\$1530-\$6550

#### Ranch View Middle School

Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
3-High	Miscellaneous Structures. Repair plant structure in front of school, metal rusting	\$7,620	\$790-\$3290	\$390-\$1640
	Vinyl Coverings. Repair/replace vinyl wall covering as necessary	\$5,500	\$610-\$2410	\$280-\$1190
3-Medium	Fences and Gates. Replace and add fencing at front entrance.	\$6,670	\$740-\$2940	\$340-\$1440
	Retaining Walls. Repair/replace and add retaining walls on N and NE side of building	\$48,860	\$4950-\$21050	\$2450-\$10510
4-High	Seeding and Sodding. Replace areas of turf around school	\$8,780	\$930-\$3830	\$440-\$1890
4-Medium	Planting. Replace/add trees and bushes	\$6,670	\$740-\$2940	\$340-\$1440

#### Sierra Middle School

Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
3-High	Playing Fields. Football Field. Renovate football field	\$78,680	\$7930-\$33930	\$3940-\$16920
	Paint Interior. Paint classrooms	\$147,310	\$14790-\$63390	\$7370-\$31680
	Fire Sprinkler Water Supply. Fire sprinkle building	\$589,030	\$58980-\$253380	\$29460-\$126650
3-Medium	Special Facilities. Rebuild greenhouse on south side of building	\$10,580	\$1130-\$4630	\$530-\$2280
5-Mediuiii	Retaining walls. Repair retaining walls at double entry	\$5,080	\$530-\$2230	\$260-\$1100
	Playing Fields. Resurface track.	\$34,480	\$3530-\$14830	\$1730-\$7420
	Playing Fields. Football Field. Replace goal posts with multi- function goals	\$2,010	\$300-\$900	\$100-\$440
3-Low	Miscellaneous Structures. Markee sign, shade structures. Replace outside basketball hoops if warranted	\$2,650	\$360-\$1160	\$140-\$570
4-High	Seeding and Sodding. Renovate areas of landscaping	\$9,950	\$1060-\$4360	\$500-\$2140

## South Ridge Elementary School

Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Fences and Gates. Repair/replace all fencing around school perimeter, parking areas	\$5,080	\$530-\$2230	\$260-\$1100
3-High	Playing Fields. Multi-use Field. Renovate play field and other site improvements	\$257,720	\$25790-\$110890	\$12890-\$55410
	Playing Fields. Multi-use Field. Install new synthetic turf for multi-use field	\$294,620	\$29480-\$126790	\$14740-\$63350
	Vinyl Coverings. Repair or replace vinyl coverings	\$5,930	\$680-\$2580	\$300-\$1280
	Flooring Tile. Replace entry way tile	\$17,240	\$1770-\$7470	\$870-\$3710
	Fire Sprinkler Water Supply. Fire sprinkle building	\$392,650	\$39350-\$168850	\$19640-\$84420
3-Medium	Site Improvements. Repair drainage issues, add retaining walls	\$98,350	\$9860-\$42360	\$4920-\$21150
	Fences and Gates. Repair/replace field backstop fencing	\$14,920	\$1590-\$6490	\$750-\$3210
	Fences and Gates. Repair fencing between parking lot and playground	\$2,650	\$360-\$1160	\$140-\$570
3-Low	Gutters and Downspouts. Rework downspouts back of school by stairs	\$2,650	\$360-\$1160	\$140-\$570
4-High	Wall Foundations. Recaulk foundation where concrete meets	\$5,500	\$610-\$2410	\$280-\$1190
4-nigii	Other Landscape Features. Improve site landscape features	\$147,310	\$14790-\$63390	\$7370-\$31680


## ThunderRidge High School

Tier & Priority Class	Project Description	Estimated Construction Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Theater & Stage Equipment, Auditorium Sound Equipment. Small stage curtains are torn and need replaced on one side. Replace approximately 100 seats in auditorium due to backs cracking.	\$48,970	\$4940-\$21140	\$2450-\$10530
2-High	Paving and Surfacing. Repair/replace asphalt walks to athletic fields	\$10,370	\$1040-\$4540	\$520-\$2230
	Paving & Surfacing, Sidewalks. Repair/Replace areas of sidewalk as necessary	\$9,310	\$1000-\$4100	\$470-\$2010
	Flooring Cafeteria. Replace VCT.	\$8,990	\$920-\$3920	\$450-\$1940
2-Medium	Site Improvements. Improve traffic flow at both schools	\$645,610	\$64600-\$277700	\$32280-\$138810
Z-Medium	Paving and Surfacing. Parking Lot. Resurface asphalt parking lot, upper level	\$528,750	\$52950-\$227450	\$26440-\$113690
3-High	Wall Foundations. Recaulk foundation where concrete meets	\$9,420	\$990-\$4090	\$480-\$2030
	Suspended Ceilings. Replace kitchen tile with food grade	\$8,570	\$940-\$3740	\$430-\$1850
3-Medium	Fire Sprinkler Water Supply. Building partially sprinkled. Pods not spinkled. Would need to sprinkle all areas if renovation by code	\$267,240	\$26770-\$114970	\$13370-\$57460
4-High	Site Lighting Poles. Paint parking lot poles	\$6,670	\$740-\$2940	\$340-\$1440
4-Medium	Other Landscape Features. Repair hillside in front of snack shack	\$40,820	\$4180-\$17590	\$2050-\$8780

# Appendix 3 **Development Summary**

#### **Development Growth Cycle**

The following diagram illustrates the correlation between residential housing development (certificates of occupancy) and the generation of school-age children. As neighborhoods develop and build out, there is a lag time of nearly seven to 12 years before the number of students generated at elementary, middle, and high school reaches its maximum impact in a school. As neighborhoods mature and students grow older, some families move away and neighborhoods continue their cycle of generating students again, only this time at a more consistent pace.



The district may utilize the four-track year-round calendar at the elementary level, and mobile classrooms at all levels to help mitigate the peak impact of development as depicted by the dotted lines on the diagram.

#### **Development Impact**

When determining the impact of residential development, Douglas County School District evaluates how many students are expected from any given development based on density. Once the student generation is calculated, it is then determined how much land would be required to build a school as well as capital mitigation. Often times, a development will generate acreage, but not enough for an entire school site. In these cases, the district may choose to accept a portion of the acreage in a commercial area if there is a commercial area as part of the project. These areas would help mitigate the growing needs for support service space as the district grows. The district may also collect cash-inlieu of land, or a combination of both. Collecting cash-in-lieu for smaller dedications allows the district to use this money to mitigate capacity needs with mobile classrooms, construction modifications, or the purchase of land in the future with consolidated funding.

The district has a voluntary capital mitigation process that evaluates the amount of taxes a development will produce, including both residential and commercial if applicable, and determines the gap between what is paid to the district in taxes and what it costs to construct a school through bonds and debt retirement. The district evaluates the impact over a 20, 30, and 40-year school building life cycle. Knowing that buildings have a longer life than 20-years, but acknowledging building components have limited operational life spans, the District asks the developer to voluntarily contribute mid-range between the 30 and 40-year numbers.

Although not inclusive of all development in the planning areas, a development summary in each Planning Area is provided on the following pages. These developments are in the building phase or in various stages of the review processes within the County. A map and summary table of the sites dedicated to the district for future schools have also been included.


\*Highlands Ranch, Lone Tree, Castle Pines, Roxborough, and portions of Littleton

Development	Jurisdiction	Zoned	Built to Date (As of 01/01/2019)	Built from 01/01/2018 to 01/01/2019
470 Frontage CO	Douglas County	240	112	0
Acres Green	Douglas County	1,053	1,053	0
Bluffmont Estate Condos (aka Bluffmont Park Mansion Homes)	Lone Tree	93	93	0
Carriage Club	Lone Tree	249	279	0
Castle Pines Town Center	Castle Pines	675	0	0
Castle Pines Village	Douglas County	2,792	1,667	32
Centennial Ridge	Lone Tree	357	123	0
Chatfield East	Douglas County	103	100	2
Chatfield Farms	Douglas County	428	361	4
Club Terrace Condos	Lone Tree	65	65	0
Erickson	Douglas County	1,971	1,007	126
Erickson	Littleton	180	180	0
Fairways at Lone Tree	Lone Tree	108	108	0
Happy Canyon (Includes Ranch and South Subdivisions)	Douglas County	207	198	1
Heritage Hills (Amendment 6)	Lone Tree	3,073	1,223	12
Heritage Hills 002	Douglas County	1,100	800	0
Highlands Ranch	Douglas County	36,020	35,034	317
Hunting Hill	Douglas County	528	108	0
Intravest 320	Douglas County	980	831	0
Inverness	Douglas County	457	381	20
Inverness Views	Douglas County	283	0	0
Lagae Ranch	Castle Pines	631	77	57
Littleton Commons West	Littleton	385	385	0
Lone Tree	Lone Tree	938	938	0
Masters Park Condominiums	Lone Tree	96	96	0
OmniPark	Douglas County	230	230	0
Plum Creek Planned Development	Douglas County	1,100	0	0
Province Center	Douglas County	536	536	1
Ridgegate (Includes Ridgegate, Ridgegate Section 15, and Ridgegate East)	Lone Tree	12,000	1,681	257
River Canyon	Douglas County	250	89	19
Roxborough Park	Douglas County	2,868	949	0
Roxborough Village	Douglas County	2.748	1,995	0
Sterling Ranch	Douglas County	12,050	320	273
Surrey Ridge (Includes Estates and Peak Subdivisions)	Douglas County	196	171	1
Taos of Lone Tree	Lone Tree	76	76	0
The Canyons (North Canyons)	Castle Pines	2,500	0	0
The Estates at Park Meadows	Douglas County	518	518	0
The Fairways	Lone Tree	301	301	0
Wolhurst	Littleton	57	57	0

The table above summarizes the number of units zoned and built (to date) in the North Planning Area. The North Planning Area consists of Highlands Ranch, Lone Tree, Castle Pines, Roxborough, and portions of Littleton. Data on the number of units zoned and built was collected from Douglas County Department of Community Development, City of Littleton, City of Castle Pines, and the City of Lone Tree.

#### Land Inventory-North Planning Area

• The table and map below show the dedicated school sites in the North Planning Area.




Feeder	Site Name	Site Type	Site Size (Acres)	Site Status
Highlands Ranch High School	Acres Green	Elementary	31.83	Platted
Highlands Ranch High School	Eastridge	Elementary	10.041	Platted
Highlands Ranch High School	Colorado Boulevard	Alternative Site	0.756	Platted
Highlands Ranch High School	Ridgegate A	Elementary	8	Unplatted
Highlands Ranch High School	Ridgegate B	Elementary	8	Unplatted
Highlands Ranch High School	Ridgegate C	Elementary	8	Unplatted
Highlands Ranch High School	Ridgegate D	Middle & High	90	Unplatted
Mountain View High School	Toepfer Park A	Elementary	6.984	Platted
Mountain View High School	Toepfer Park B	Elementary	3.016	Platted
Rock Canyon High School	Hidden Pointe	Elementary	10.44	Platted
Rock Canyon High School	Canyons North B	Elementary	12	Unplatted
Rock Canyon High School	Canyons North A	Elementary	12	Unplatted
Rock Canyon High School	Canyons North C	Middle	25	Unplatted
Rock Canyon High School	Castle Pines Village	Elementary	10.1	Platted
ThunderRidge High School	Westridge Glen	Elementary	10.677	Platted
ThunderRidge High School	Sterling Ranch A	Elementary or K-8	12	Platted
ThunderRidge High School	Sterling Ranch B	Elementary or K-8	11	Unplatted
ThunderRidge High School	Sterling Ranch C	Elementary or K-8	12	Unplatted
ThunderRidge High School	Sterling Ranch D	Elementary or K-8	12	Unplatted
ThunderRidge High School	Sterling Ranch E	Middle	30	Unplatted
ThunderRidge High School	Sterling Ranch F	High	60	Unplatted
ThunderRidge High School	Solstice	Elementary or K-8	15.98	Unplatted

			Built to Date	Built from 01/01/2018
Development	Jurisdiction	Zoned	(As of 01/01/2019)	to 01/01/2019
Arbors	Castle Rock	118	0	0
Auburn Ridge	Castle Rock	289	90	0
Bell Mountain Ranch	Douglas County	309	305	0
Brookwood	Castle Rock	72	57	7
Cambridge Heights	Castle Rock	100	0	0
Canyons South (Macanta)	Douglas County	968	0	0
Castle Highlands	Castle Rock	490	325	1
Castle Meadows	Castle Rock	288	0	0
Castle Oaks (aka Terrain)	Castle Rock	2,767	1,366	249
Castle Pines Commercial (Includes Promenade)	Castle Rock	1,550	1,009	204
Castle Ridge East	Castle Rock	30	28	0
Castle Rock Estates (Diamond Ridge)	Castle Rock	126	126	0
Castleview Estates (Includes The Oaks of Castle Rock)	Castle Rock	574	122	4
Castlewood Ranch	Castle Rock	1,300	1,272	8
Central Castle Rock (Downtown)	Castle Rock	2,649	2,319	2
Christy Ridge	Douglas County	120	115	0
Covenant at Castle Rock	Castle Rock	58	62	34
Crystal Valley Ranch	Castle Rock	3,475	1,206	313
Dawson Ridge	Castle Rock	7,900	0	0
Founders Village (Includes Founders and Bella Mesa)	Castle Rock	5,421	2,305	27
Hazen Moore	Castle Rock	243	160	24
Heckendorf Ranch	Castle Rock	630	293	0
Hillside	Castle Rock	120	0	0
Indian Creek Ranch	Douglas County	184	174	1
Keene Ranch	Douglas County	247	228	7
Lanterns	Castle Rock	1,200	0	0
Louviers (Town of)	Douglas County	114	108	2
Maher Ranch (Sapphire Pointe)	Castle Rock	2,409	858	1
Meadows	Castle Rock	10,644	6,566	482
Memmen Young Infill	Castle Rock	1,035	0	0
Meribel Village	Douglas County	544	4	0
Metzler Ranch	Castle Rock	1,716	1,315	2
Perry Park	Douglas County	1,327	703	9
Perry Park East	Douglas County	163	152	1
Perry Pines	Douglas County	135	131	1
Plum Creek	Castle Rock	3,025	1,547	2
Plum Creek Ridge	Castle Rock	162	76	23
Plum Creek South	Castle Rock	505	137	0
Red Hawk	Castle Rock	926	793	0
Sage Port	Douglas County	595	499	9
Sandstone Ranch	Douglas County	106		0
Scott II	Castle Rock	305	298	0
Silver Heights Stanbro PD	Douglas County	110	104 0	0
Wolfensberger Apartments (formerly Graham	Castle Rock	124	-	-
PD)	Castle Rock	56	56	56
Woodlands (Includes Scott Ranch)	Castle Rock	1,160	535	1
Woodmoor Mountain	Douglas County	143	61	0
Young American	Castle Rock	1,206	561	0

The table above summarizes the number of units zoned and built (to date) in the West Planning Area. The West Planning Area consists of Castle Rock, Larkspur, Sedalia and portions of Unincorporated Douglas County. Data on the number of units zoned and built was collected from Douglas County Department of Community Development, and the Town of Castle Rock.

• The table and map below show the dedicated school sites in the West Planning Area.



Feeder	Site Type	Site Size (Acres)	Site Name	Site Status
Douglas County High School	Elementary	11.6	Castle Oaks Estates	Platted
Douglas County High School	High	62.869	Castlewood Ranch	Platted
Douglas County High School	Elementary	10	Crystal Valley A	Platted
Douglas County High School	Elementary	10.1	Crystal Valley B	Platted
Douglas County High School	Middle	20.17	Crystal Valley C	Platted
Douglas County High School	Middle	27.02	Macanta A	Platted
Douglas County High School	Elementary	10.09	Macanta B	Platted
Douglas County High School	Elementary	17.8	Plum Creek	Platted
Douglas County High School	Elementary	9	Sapphire Pointe	Platted
Douglas County High School	Alternative Site	3.8	Hazen Moore	Unplatted
Douglas County High School	PK-8	25.49	Lanterns	Unplatted
Douglas County High School	Elementary	10	Rock Canyon Ranch	Unplatted
Douglas County High School	Elementary	12.3	Bella Mesa	Unplatted
Douglas County High School	Elementary	10	Pine Canyon	Unplatted
Douglas County High School	PK-8	17.78	Pioneer Ranch	Unplatted
Castle View High School	Middle	4.72	Hockaday A	Platted
Castle View High School	Middle	13.59	Hockaday B	Platted
Castle View High School	Middle	6.69	Hockaday C	Platted
Castle View High School	Elementary	10	Larkspur	Platted
Castle View High School	Alternative Site	1	Pine Cliff	Platted
Castle View High School	Elementary	10.01	Red Hawk	Platted
Castle View High School	Elementary	10.014	The Meadows Filing 20	Platted
Castle View High School	Elementary	10	Dawson Ridge A	Unplatted
Castle View High School	Elementary	10	Dawson Ridge B	Unplatted
Castle View High School	Elementary	50	Dawson Ridge D	Unplatted
Castle View High School	Elementary	10	Dawson Ridge C	Unplatted


<sup>\*</sup>Note\* Plum Creek site and Crystal Valley A & C sites are joint sites with Castle Rock Parks & Recreation.

Development	Jurisdiction	Zoned	Built to Date (As of 01/01/2019)	Built from 01/01/2018 to 01/01/2019
Antelope Heights	Parker	241	203	0
Anthology (Anthology North)	Parker	3,082	0	0
Bannockburn	Douglas County	187	181	1
Bradbury (Bradbury Ranch)	Parker	1,607	1,450	0
Carousel Farms	Parker	140	16	16
Challenger Park	Parker	571	512	0
Cielo	Douglas County	343	0	0
Clarke Farms	Parker	2,515	2,282	0
Compark	Douglas County	917	452	0
Compark	Parker	391	72	1
Cottonwood Highlands	Parker	773	155	100
Cottonwood South	Douglas County	855	610	0
Deerfield	Douglas County	197	188	2
Douglas 234 (aka Horse Creek)	Parker	548	403	0
Enclave at Cherry Creek	Parker	285	57	0
Foxhill	Douglas County	100	2	0
Gondolier Farms	Douglas County	145	1	0
Grandview Estates	Douglas County	264	242	0
Hein Center	Parker	260	0	0
Hidden River	Parker	1,023	925	0
Homestead Hills	Douglas County	136	129	2
Homestead Property	Parker	370	0	0
Horseshoe Ridge	Parker	405	294	0
Kings Point South	Aurora	650	0	0
Liberty Village (aka Cobblestone Ranch, aka Villages at Castle Rock)	Castle Rock	1,245	834	104
Lincoln Creek Village	Douglas County	724	109	57
Lundieck (Vantage Point)	Parker	306	400	400
Mead's Crossing	Parker	352	156	0
Meridian International Business Center	Douglas County	5,125	4,407	141
Newlin Meadows	Parker	330	257	0
Olde Towne (Neu Towne)	Parker	595	193	11
Overlook at Cherry Creek	Parker	193	122	82
Parker East	Douglas County	105	102	2
Parker Hilltop	Parker	486	456	0
Parker Homestead (Heirloom)	Parker	280	251	13
Parker Ridge	Douglas County	114	102	2
Parker Sr Village	Parker	118	0	0
Pine Bluffs	Parker	483	271	21
Pine Drive Property	Parker	64	0	0
Pine Lane	Parker	270	0	0
PWSD Mahoney Property	Parker	463	0	0
Rampart Station (Preston Hills)	Parker	193	139	0
Reata North (Idyllwilde)	Parker	925	629	76
Reata South	Douglas County	175	70	10
Robinson Ranch	Parker	124	57	0
Rocking Horse	Aurora	2,000	721	254
Salisbury Heights	Parker	134	92	43
Sierra Ridge	Douglas County	1,600	1,019	157
Stone Creek (aka Stone Creek Ranch)	Douglas County	329	0	0
Stonegate	Douglas County	3,739	3,477	40
Stroh Crossing	Parker	135	11	11
Stroh Ranch (Includes Ironstone Condominiums at Stroh Ranch)	Parker	2,817	2,014	80
Sun Marke	Parker	223	0	0
Tallman Gulch	Douglas County	121	36	3
The Pinery (includes Pradera and Timbers)	Douglas County	4,855	4,200	14
Village on the Green	Parker	80	65	0
Villages of Parker (Canterberry)	Parker	2,726	2,574	0
Watermark on Twenty Mile	Parker	294	140	140
Westcreek Lakes	Douglas County	218	68	0
Willow Park (Willow Pointe)	Parker	350	265	0
Willow Ridge (Willow Pointe)	Parker	392	260	0
	1	332		·

The table to the right summarizes the number of units zoned and built (to date) in the East Planning Area. The East Planning Area consists of Parker, Franktown, Cherry Valley, and portions of Aurora, Elbert County, North-East Castle Rock, and Unincorporated Douglas County. Data on the number of units zoned and built was collected from Douglas **County Department** of Community Development, Town of Castle Rock,Town of Parker, and City of Aurora.

## Land Inventory-East Planning Area

• The table and map above show all the dedicated school sites in the East Planning Area.



Feeder	Site Type	Site Size (Acres)	Site Name	Site Status
Chaparral High School	Elementary	10	Elkhorn Ranch	Unplatted
Chaparral High School	Elementary	11.7	Kings Point South	Unplatted
Chaparral High School	Elementary	10.1	Meridian Village	Platted
Chaparral High School	Alternative Site	5.832	Newlin Crossing	Unplatted
Chaparral High School	Elementary	17.995	Pine Drive	Platted
Chaparral High School	Elementary	12.817	Rocking Horse	Platted
Chaparral High School	Elementary	10.033	Sierra Ridge	Platted
Chaparral High School	Elementary or PK-8	26.8	Spring Valley Ranch	Unplatted
Legend High School	Undetermined	3.492	Kime Ranch	Unplatted
Legend High School	PK-8	18	Pine Drive	Platted
Ponderosa High School	Elementary	12	Anthology A	Unplatted
Ponderosa High School	Elementary	12	Anthology B	Unplatted
Ponderosa High School	Elementary	12	Anthology C	Unplatted
Ponderosa High School	Elementary	12	Anthology D	Unplatted
Ponderosa High School	Middle	25	Anthology E	Unplatted
Ponderosa High School	High	50	Anthology F	Unplatted
Ponderosa High School	K-8	22.482	Cielo	Platted
Ponderosa High School	Elementary	11.21	Cobblestone Ranch	Platted
Ponderosa High School	Other	2	Hilltop	Platted
Ponderosa High School	Alternative Site	6.678	Meadowlark	Unplatted
Ponderosa High School	Elementary	12.352	Pinery	Platted
Ponderosa High School	Alternative Site	2	Pinery West	Unplatted
Ponderosa High School	Elementary	10.011	Pradera	Platted
Ponderosa High School	Elementary	10.321	Timbers	Platted

# Appendix 4 Capital Needs by Year

	Estimated Construction Cost	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs	Estimated Total Project Cost
A C 51		und contracting costs		
Acres Green Elementary 2019-20	¢1 600 FF0	\$170370-\$727870	\$0	¢1850020 ¢2417420
2019-20	\$1,689,550 \$105,750	\$10650-\$45550	\$10,840	\$1859920-\$2417420 \$127240-\$162140
Arrowwood Elementary	\$103,730	\$10030-\$43330	\$10,840	\$127240-\$102140
2019-20	\$1,551,440	\$156130-\$668130	\$0	\$1707570-\$2219570
2020-21	\$216,800	\$21820-\$93420	\$22,240	\$260860-\$332460
2022-23	\$110,430	\$11210-\$47710	\$17,460	\$139100-\$175600
2023-24	\$63,450	\$6350-\$27350	\$13,650	\$83450-\$104450
Bear Canyon Elementary	\$03,430	\$0330 \$27330	\$13,030	\$65456 \$164456
2019-20	\$285,560	\$28930-\$123430	\$0	\$314490-\$408990
2020-21	\$669,110	\$67360-\$287960	\$68,630	\$805100-\$1025700
2023-24	\$158,630	\$15980-\$68380	\$34,120	\$208730-\$261130
Buffalo Ridge Elementary	\$130,030	\$13300 \$00300	\$31,120	\$200,30 \$201130
2019-20	\$1,823,560	\$183750-\$785370	\$0	\$2007310-\$2608930
2021-22	\$23,270	\$2340-\$10040	\$2,390	\$28000-\$35700
Cantril Building	<del>+</del>	7=2.10 4.3010	,550	1=1300 403,00
2019-20	\$212,680	\$21780-\$91890	\$0	\$234460-\$304570
2020-21	\$1,554,350	\$158560-\$671660	\$159,640	\$1872550-\$2385650
2023-24	\$63,450	\$6450-\$27350	\$13,650	\$83550-\$104450
Castle Rock Elementary			ĺ	
2019-20	\$1,407,350	\$141210-\$605810	\$0	\$1548560-\$2013160
2020-21	\$1,245,810	\$125350-\$536850	\$127,800	\$1498960-\$1910460
Castle Rock Middle School			,	
2019-20	\$1,283,400	\$129940-\$553340	\$0	\$1413340-\$1836740
2020-21	\$12,270	\$1240-\$5340	\$1,260	\$14770-\$18870
2022-23	\$158,630	\$15880-\$68280	\$25,070	\$199580-\$251980
Castle View High School				
2020-21	\$54,990	\$5510-\$23710	\$5,640	\$66140-\$84340
2021-22	\$2,009,250	\$200950-\$864050	\$205,950	\$2416150-\$3079250
2022-23	\$1,514,460	\$151690-\$651490	\$239,310	\$1905460-\$2405260
Chaparral High School				
2019-20	\$3,576,370	\$358970-\$1539370	\$0	\$3935340-\$5115740
2020-21	\$727,560	\$72840-\$312940	\$74,580	\$874980-\$1115080
2021-22	\$103,330	\$10390-\$44590	\$10,600	\$124320-\$158520
2022-23	\$158,630	\$15880-\$68280	\$25,070	\$199580-\$251980
Cherokee Trail Elementary				
2019-20	\$315,400	\$32020-\$136420	\$0	\$347420-\$451820
2020-21	\$287,230	\$28900-\$123700	\$29,460	\$345590-\$440390
2021-22	\$402,090	\$40450-\$173150	\$41,230	\$483770-\$616470
2023-24	\$784,990	\$78630-\$337630	\$168,780	\$1032400-\$1291400
Cherry Valley Elementary	AC14 = 10	#C2250 #255 : 52	* ^	4677060 4000170
2019-20	\$614,710	\$62350-\$265460	\$0	\$677060-\$880170
2020-21	\$4,560	\$560-\$2060	\$480	\$5600-\$7100
2023-24	\$40,730	\$4200-\$17700	\$8,770	\$53700-\$67200
Clear Sky Elementary	£54.000	¢5510 ¢33710	40	¢60500 ¢70700
2019-20	\$54,990	\$5510-\$23710	\$0	\$60500-\$78700
2023-24	\$883,590	\$89000-\$380400	\$190,030	\$1162620-\$1454020
Copper Mesa Elementary	¢157160	¢15000 ¢67000	¢ 0	\$1720F0 \$22F0F0
2019-20	\$157,160	\$15890-\$67890 \$138400 \$550000	\$0 \$121.210	\$173050-\$225050 \$1530130 \$1061630
2021-22	\$1,279,520	\$128400-\$550900	\$131,210	\$1539130-\$1961630
Cougar Run Elementary 2019-20	\$2,067,760	\$208300-\$890800	\$0	\$2276060 \$2059560
2019-20	\$2,067,760	\$1240-\$5340	\$0 \$1,260	\$2276060-\$2958560 \$14770-\$18870
	\$12,270	\$1240-\$3340	\$1,∠0U	\$14770-\$18870
Coyote Creek Elementary 2019-20	\$377,160	\$28470 \$162070	\$0	\$415620 \$540020
2019-20	\$54,990	\$38470-\$162870 \$5510-\$23710	\$0 \$5,640	\$415630-\$540030
		\$5510-\$23710 \$22460-\$05760		\$66140-\$84340 \$270540-\$352840
2022-23 Cresthill Middle School	\$221,990	\$22460-\$95760	\$35,090	\$279540-\$352840
2019-20	\$139,190	\$14150-\$60050	\$0	\$153340-\$199240
2019-20	\$178,190	\$17920-\$76720	\$18,270	\$214380-\$273180
ZUZU-Z I	\$170,19U	\$11360-\$10160	\$10,Z/U	\$414300-\$41310U

	Estimated Construction Cost	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs	Estimated Total Project Cost
2021-22	\$201,690	\$20340-\$86840	\$20,680	\$242710-\$309210
2023-24	\$63,450	\$6450-\$27350	\$13,650	\$83550-\$104450
	ledia Center			
2019-20	\$201,470	\$20360-\$86860	\$0	\$221830-\$288330
2020-21	\$52,880	\$5330-\$22830	\$5,430	\$63640-\$81140
2023-24	\$42,300	\$4300-\$18200	\$9,100	\$55700-\$69600
DCHS Stadium	¢1 214 170	¢121010 ¢522510	<b>*</b> • •	#1336000 #1736600
2019-20	\$1,214,170	\$121910-\$522510	\$0	\$1336080-\$1736680
2020-21	\$84,600	\$8500-\$36500	\$8,680	\$101780-\$129780
Douglas County High School 2019-20	\$9,882,770	\$995370-\$4257470	\$0	\$10878140-\$14140240
2019-20	\$179,160	\$18180-\$77280	\$18,380	\$215720-\$274820
2020-21	\$84,600	\$8500-\$36400	\$8,680	\$101780-\$129680
Douglas County HS South Bldg	\$64,000	\$8300-\$30400	\$6,060	\$101780-\$129080
2019-20	\$1,967,390	\$201410-\$850110	\$0	\$2168800-\$2817500
2013-20	\$8,150	\$860-\$3560	\$840	\$9850-\$12550
2022-23	\$158,630	\$15880-\$68280	\$25,070	\$199580-\$251980
Eagle Ridge Elementary	¥130,030	\$13000 \$00200	423,070	\$133333 \$231333
2019-20	\$726,110	\$73070-\$312770	\$0	\$799180-\$1038880
2020-21	\$959,930	\$96430-\$413130	\$98,430	\$1154790-\$1471490
2021-22	\$455,290	\$45740-\$196040	\$46,680	\$547710-\$698010
Early Childhood Center-CR	,		,	
2022-23	\$84,600	\$8500-\$36400	\$13,370	\$106470-\$134370
Echo Park Stadium	,		,	
2019-20	\$21,150	\$2150-\$9150	\$0	\$23300-\$30300
Eldorado Elementary				
2019-20	\$1,664,370	\$167280-\$716580	\$0	\$1831650-\$2380950
2021-22	\$63,450	\$6350-\$27350	\$6,510	\$76310-\$97310
2023-24	\$560,210	\$56570-\$241370	\$120,500	\$737280-\$922080
Flagstone Elementary				
2019-20	\$814,810	\$81610-\$350510	\$0	\$896420-\$1165320
2020-21	\$880,240	\$88820-\$379420	\$90,300	\$1059360-\$1349960
2023-24	\$481,010	\$48200-\$207000	\$103,430	\$632640-\$791440
Fox Creek Elementary	#270.0C0	420550 4121150	**	#200520 #401120
2019-20	\$279,960	\$28660-\$121160	\$0	\$308620-\$401120
2022-23 Franktown Elementary	\$50,880	\$5250-\$21950	\$8,050	\$64180-\$80880
2019-20	\$1,973,820	\$198760-\$849880	\$0	\$2172580-\$2823700
2019-20	\$167,090	\$16820-\$72020	\$17,130	\$201040-\$256240
2022-23	\$370,130	\$37080-\$159180	\$58,490	\$465700-\$587800
2023-24	\$26,450	\$2880-\$11580	\$5,700	\$35030-\$43730
Frontier Valley Elementary	Ψ <b>2</b> 0, <del>1</del> 30	Ψ2000 Ψ11000	¥3,700	\$55550 \$75750
2019-20	\$317,250	\$31750-\$136450	\$0	\$349000-\$453700
2020-21	\$1,275,540	\$128530-\$549430	\$130,820	\$1534890-\$1955790
2022-23	\$427,400	\$42820-\$184020	\$67,550	\$537770-\$678970
2023-24	\$397,630	\$39890-\$171190	\$85,510	\$523030-\$654330
Gold Rush Elementary				
2023-24	\$703,830	\$71080-\$303280	\$151,380	\$926290-\$1158490
Heritage Elementary				
2019-20	\$1,404,110	\$141330-\$604630	\$0	\$1545440-\$2008740
2021-22	\$63,450	\$6350-\$27350	\$6,510	\$76310-\$97310
2023-24	\$145,420	\$14810-\$62810	\$31,290	\$191520-\$239520
Highlands Ranch High School				
2019-20	\$6,079,290	\$609470-\$2615470	\$0	\$6688760-\$8694760
2020-21	\$1,142,100	\$114300-\$491200	\$117,070	\$1373470-\$1750370
2021-22	\$105,750	\$10650-\$45550	\$10,840	\$127240-\$162140
2023-24	\$237,940	\$23870-\$102370	\$51,160	\$312970-\$391470
Iron Horse Elementary				
2019-20	\$1,267,960	\$127980-\$546680	\$0	\$1395940-\$1814640
2020-21	\$62,400	\$6310-\$26910	\$6,400	\$75110-\$95710

	Estimated Construction Cost	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs	Estimated Total Project Cost
2022-23	\$439,310	\$44230-\$189130	\$69,440	\$552980-\$697880
Joint Service Center				
2019-20	\$61,660	\$6260-\$26660	\$0	\$67920-\$88320
2020-21	\$300,850	\$30900-\$130000	\$30,930	\$362680-\$461780
Larkspur Elementary	** ** ***			
2019-20	\$1,345,550	\$135760-\$579960	\$0	\$1481310-\$1925510
2020-21	\$33,320	\$3400-\$14400 \$17220-\$72120	\$3,430	\$40150-\$51150
2023-24	\$169,230	\$17220-\$73120	\$36,400	\$222850-\$278750
Legacy Point Elementary 2019-20	\$9,950	\$1060-\$4360	\$0	\$11010-\$14310
2019-20	\$810,250	\$82140-\$349640	\$83,130	\$975520-\$1243020
2023-24	\$1,254,200	\$125620-\$539520	\$269,680	\$1649500-\$2063400
Legend High School	\$1,234,200	\$123020-\$339320	\$209,000	\$1049300-\$2003400
2023-24	\$2,848,410	\$285580-\$1225380	\$612,460	\$3746450-\$4686250
Lone Tree Elementary A Magnet Sch		\$203300 \$1223300	\$012,100	\$37 TO 130 \$ 1000230
2023-24	\$1,399,870	\$140730-\$602630	\$301,030	\$1841630-\$2303530
Mammoth Heights Elementary	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		,	
2023-24	\$768,340	\$77690-\$331190	\$165,250	\$1011280-\$1264780
Meadow View Elementary			,	
2019-20	\$2,338,330	\$234860-\$1006760	\$0	\$2573190-\$3345090
2020-21	\$114,850	\$11560-\$49460	\$11,780	\$138190-\$176090
2022-23	\$23,380	\$2440-\$10140	\$3,700	\$29520-\$37220
2023-24	\$63,450	\$6350-\$27350	\$13,650	\$83450-\$104450
Mesa Middle School				
2023-24	\$504,250	\$51040-\$217340	\$108,450	\$663740-\$830040
Mountain Ridge Middle School				
2019-20	\$93,600	\$9520-\$40420	\$0	\$103120-\$134020
2020-21	\$868,700	\$87880-\$374680	\$89,140	\$1045720-\$1332520
2023-24	\$1,882,360	\$188460-\$809660	\$404,730	\$2475550-\$3096750
Mountain View Elementary	¢2.196.470	\$220110-\$941420	\$0	\$2406580 \$2127800
2019-20 2023-24	\$2,186,470 \$2,650	\$360-\$1160	\$570	\$2406580-\$3127890 \$3580-\$4380
Mountain Vista High School	\$2,030	\$300-\$1100	\$370	\$3380-\$4380
2019-20	\$4,553,250	\$456310-\$1959110	\$0	\$5009560-\$6512360
2021-22	\$84,600	\$8500-\$36400	\$8,680	\$101780-\$129680
2023-24	\$1,634,930	\$163930-\$703430	\$351,540	\$2150400-\$2689900
Northeast Elementary	<del>+ 1,00 1,000</del>	Ţ. 03330 Ţ. 03.30	+33.,3.0	<del>+</del> 2.30.00 <del>+</del> 2003300
2019-20	\$1,815,210	\$183060-\$781960	\$0	\$1998270-\$2597170
2021-22	\$466,360	\$46650-\$200550	\$47,810	\$560820-\$714720
2023-24	\$18,520	\$2000-\$8000	\$3,990	\$24510-\$30510
Northridge Elementary				
2019-20	\$486,290	\$49320-\$209920	\$0	\$535610-\$696210
2020-21	\$806,490	\$81330-\$347630	\$82,750	\$970570-\$1236870
2022-23	\$84,600	\$8500-\$36500	\$13,380	\$106480-\$134480
O&M East	4406	A 41 0 F 0 A 1 = = 1 = 2	442.272	4402170 12222
2020-21	\$409,150	\$41950-\$177150	\$42,070	\$493170-\$628370
O&M West- Bldg A	£1C 0F0	#1010 #7710	¢1.770	#20520 #26420
2020-21	\$16,950	\$1810-\$7710 \$2020-\$8320	\$1,770	\$20530-\$26430
2021-22	\$19,190 \$21,150		\$1,970 \$4,550	\$23180-\$29480 \$27850 \$34850
2023-24 Pine Grove Elementary	\$21,150	\$2150-\$9150	\$4,55U	\$27850-\$34850
2019-20	\$569,420	\$57720-\$245820	\$0	\$627140-\$815240
2019-20	\$54,990	\$5510-\$23710	\$5,640	\$66140-\$84340
2022-23	\$8,250	\$860-\$3560	\$1,310	\$10420-\$13120
Pine Lane Intermediate (N)	¥0,230	4000 4000	ψ1,510	\$10120 \$13120
2019-20	\$2,572,670	\$258650-\$1107750	\$0	\$2831320-\$3680420
2023-24	\$1,937,360	\$194080-\$833580	\$416,570	\$2548010-\$3187510
Pine Lane Primary (S)	, , , , , , , , , , , , , , , , , , , ,	, , , , , , , , , , , , , , , , , , , ,	,	
2019-20	\$1,630,030	\$164280-\$702390	\$0	\$1794310-\$2332420
2020-21	\$105,750	\$10650-\$45550	\$10,840	\$127240-\$162140

	Estimated Construction Cost	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs	Estimated Total Project Cost
2022-23	\$63,450	\$6350-\$27350	\$10,030	\$79830-\$100830
2023-24	\$212,580	\$21570-\$91770	\$45,740	\$279890-\$350090
Pioneer Elementary				
2019-20	\$1,636,480	\$164830-\$705130	\$0	\$1801310-\$2341610
2022-23	\$7,940	\$870-\$3470	\$1,260	\$10070-\$12670
Ponderosa High School	¢7.721.200	¢776240 ¢2226070	<b>#</b> O	¢0507620 ¢11050260
2019-20 2021-22	\$7,731,390 \$60,810	\$776240-\$3326970 \$6100-\$26200	\$0 \$6,240	\$8507630-\$11058360 \$73150-\$93250
2021-22	\$1,755,450	\$175650-\$754950	\$0,240	\$2208480-\$2787780
Prairie Crossing Elementary	\$1,733,430	\$173030 \$73 <del>4</del> 330	\$277,500	\$2200400 \$2707700
2019-20	\$1,774,140	\$178420-\$763920	\$0	\$1952560-\$2538060
2021-22	\$63,450	\$6350-\$27350	\$6,510	\$76310-\$97310
2023-24	\$235,310	\$23710-\$101510	\$50,620	\$309640-\$387440
Ranch View Middle School			,	
2019-20	\$1,786,590	\$179990-\$769790	\$0	\$1966580-\$2556380
2020-21	\$1,632,910	\$163530-\$702530	\$167,410	\$1963850-\$2502850
2022-23	\$76,470	\$7870-\$32970	\$12,100	\$96440-\$121540
Redstone Elementary				
2019-20	\$8,150	\$870-\$3670	\$0	\$9020-\$11820
2021-22	\$1,283,570	\$129010-\$553110	\$131,670	\$1544250-\$1968350
Renaissance Magnet School				
2019-20	\$640	\$70-\$370	\$0	\$710-\$1010
2020-21	\$22,000	\$2210-\$9510	\$2,260	\$26470-\$33770
2022-23	\$124,820	\$12960-\$54160	\$19,760	\$157540-\$198740
Rock Canyon High School	¢40.200	¢4120 ¢17220	<b>*</b> • •	\$44220 ¢57520
2019-20	\$40,200	\$4120-\$17320	\$0	\$44320-\$57520
2021-22 Rock Ridge Elementary	\$4,468,190	\$447290-\$1921790	\$458,040	\$5373520-\$6848020
2019-20	\$358,320	\$36020-\$154420	\$0	\$394340-\$512740
2019-20	\$388,760	\$39180-\$167480	\$39,880	\$467820-\$596120
2021-22	\$1,158,190	\$115930-\$498230	\$118,730	\$1392850-\$1775150
2023-24	\$333,910	\$33500-\$143700	\$71,800	\$439210-\$549410
Rocky Heights Middle School	\$333,310	\$33300 \$1.137.00	\$71,000	\$ 133210 \$313110
2019-20	\$14,600	\$1510-\$6310	\$0	\$16110-\$20910
2020-21	\$1,979,940	\$199070-\$852670	\$203,050	\$2382060-\$3035660
2023-24	\$2,405,830	\$240900-\$1034800	\$517,280	\$3164010-\$3957910
Roxborough Intermediate			,	
2019-20	\$413,920	\$41500-\$178100	\$0	\$455420-\$592020
2023-24	\$564,750	\$56930-\$243230	\$121,470	\$743150-\$929450
Roxborough Primary				
2019-20	\$467,150	\$47690-\$201800	\$0	\$514840-\$668950
2020-21	\$72,870	\$7340-\$31340	\$7,470	\$87680-\$111680
2021-22	\$39,450	\$4060-\$17060	\$4,050	\$47560-\$60560
2023-24	\$63,450	\$6450-\$27350	\$13,650	\$83550-\$104450
Saddle Ranch Elementary	¢1 570 700	#1F0100 #600000	* ^	#1720000 #220000
2019-20	\$1,579,700	\$159100-\$680800	\$0	\$1738800-\$2260500
2022-23	\$317,160	\$31970-\$136570	\$50,120	\$399250-\$503850
2023-24	\$84,600	\$8500-\$36400	\$18,190	\$111290-\$139190
Sagewood Middle School 2019-20	\$2,454,070	\$246890-\$1056690	\$0	\$2700960-\$3510760
2019-20	\$2,454,070	\$151020-\$649320	\$0 \$154,760	\$1815470-\$2313770
2020-21	\$85,770	\$8640-\$36940	\$134,760	\$107970-\$136270
Sand Creek Elementary	<b>ΦΟ 3</b> , 7 7 <b>0</b>	<b>ルローサンロサイリ</b>	ψ13,300	ψ101310-Φ130210
2019-20	\$1,492,070	\$149810-\$642210	\$0	\$1641880-\$2134280
2019-20	\$843,530	\$85010-\$363810	\$86,540	\$1015080-\$1293880
2022-21	\$317,250	\$31750-\$136450	\$50,130	\$399130-\$503830
Sedalia Elementary	¥317,230	ψ <u>σσσ</u>	450,150	\$333130 \$303030
2019-20	\$1,518,140	\$153050-\$654060	\$0	\$1671190-\$2172200
2020-21	\$158,630	\$15880-\$68280	\$16,260	\$190770-\$243170
2022-23	\$197,970	\$19960-\$85360	\$31,290	\$249220-\$314620

	Estimated Construction Cost	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs	Estimated Total Project Cost
Shea Stadium				
2019-20	\$1,044,480	\$105080-\$450080	\$0	\$1149560-\$1494560
2020-21	\$76,140	\$7660-\$32860	\$7,820	\$91620-\$116820
2023-24	\$8,250	\$860-\$3560	\$1,780	\$10890-\$13590
Sierra Middle School				
2019-20	\$4,369,520	\$438770-\$1880770	\$0	\$4808290-\$6250290
2020-21	\$74,030	\$7480-\$31880	\$7,590	\$89100-\$113500
2022-23	\$512,380	\$51560-\$220660	\$80,980	\$644920-\$814020
Soaring Hawk Elementary				
2019-20	\$800,440	\$80290-\$344290	\$0	\$880730-\$1144730
2021-22	\$464,360	\$46580-\$199980	\$47,620	\$558560-\$711960
2022-23	\$84,600	\$8500-\$36400	\$13,370	\$106470-\$134370
South Ridge Elementary	¢2.550.210	\$257020 \$1522220	<b>*</b> •	\$2016120 ¢5000540
2019-20	\$3,558,210	\$357920-\$1532330	\$0	\$3916130-\$5090540
2020-21	\$63,450 \$142,700	\$6350-\$27350 \$14750.\$61650	\$6,510	\$76310-\$97310
2022-23	\$142,790	\$14750-\$61650	\$22,580	\$180120-\$227020
Stone Mountain Elementary	¢170 100	\$17920-\$76720	\$18,270	\$214290 \$272190
2020-21 2023-24	\$178,190 \$554,390	\$17920-\$76720 \$56000-\$238900	\$18,270 \$119,240	\$214380-\$273180 \$729630-\$912530
Student Assistance Office	\$554,390	\$56000-\$238900	\$119,240	\$729630-\$912530
2020-21	\$67,320	\$7410-\$29710	\$6,960	\$81690-\$103990
Summit View Elementary	\$07,320	37410-329710	\$0,900	\$81090-\$103990
2019-20	\$310,130	\$31630-\$134130	\$0	\$341760-\$444260
2020-21	\$258,270	\$26090-\$111290	\$26,510	\$310870-\$396070
2023-24	\$169,210	\$17010-\$72910	\$36,400	\$222620-\$278520
ThunderRidge High School	\$109,210	\$17010 \$72910	¥30, <del>1</del> 00	\$222020 \$270320
2019-20	\$5,351,080	\$536890-\$2303000	\$0	\$5887970-\$7654080
2020-21	\$267,240	\$26770-\$114970	\$27,400	\$321410-\$409610
2022-23	\$158,630	\$15880-\$68280	\$25,070	\$199580-\$251980
Timber Trail Elementary	<b>\$130,030</b>	\$13000 \$00 <u>2</u> 00	\$23,070	\$133300 \$231300
2019-20	\$793,130	\$79380-\$341080	\$0	\$872510-\$1134210
2020-21	\$794,470	\$80290-\$342690	\$81,510	\$956270-\$1218670
2023-24	\$396,650	\$39760-\$170660	\$85,290	\$521700-\$652600
Trailblazer Elementary	,			
2019-20	\$1,674,930	\$168770-\$721380	\$0	\$1843700-\$2396310
Transportation - Castle Rock Bldg B				
2019-20	\$420,780	\$42230-\$181030	\$0	\$463010-\$601810
2020-21	\$355,820	\$36320-\$153820	\$36,540	\$428680-\$546180
2021-22	\$1,910	\$200-\$900	\$200	\$2310-\$3010
2023-24	\$26,440	\$2670-\$11470	\$5,690	\$34800-\$43600
TransportationNorth				
2019-20	\$146,940	\$14780-\$63380	\$0	\$161720-\$210320
2020-21	\$2,002,000	\$202740-\$863240	\$205,390	\$2410130-\$3070630
Warehouse-Bldg E				
2019-20	\$101,520	\$10180-\$43680	\$0	\$111700-\$145200
2020-21	\$260,620	\$26490-\$112690	\$26,770	\$313880-\$400080
2023-24	\$10,580	\$1130-\$4630	\$2,280	\$13990-\$17490
West Support Center	40.00 40.0		• •	***************************************
2019-20	\$262,480	\$26430-\$112930	\$0	\$288910-\$375410
2020-21	\$163,630	\$16620-\$70620	\$16,800	\$197050-\$251050
Wilcox Building	¢221.200	#224F0 #120F50	<b>#</b> 0	#252040 #450040
2019-20	\$321,390	\$32450-\$138550	\$0	\$353840-\$459940
2020-21	\$1,102,870	\$111250-\$475950	\$113,160	\$1327280-\$1691980
Wildcat Mountain Elementary	¢E40.000	¢55000 ¢333400	<b>#</b> O	¢505050 ¢774350
2019-20	\$540,890	\$55060-\$233460	\$0	\$595950-\$774350
2022-23	\$289,980	\$29150-\$124950	\$45,830	\$364960-\$460760 \$383440 \$478440
2023-24	\$290,820	\$29090-\$125090	\$62,530	\$382440-\$478440
Athletics 2019-20	\$528,750	\$52950-\$227450	\$0	\$581700-\$756200
2019-20	\$1,658,480	\$166130-\$713430	\$0 \$170,010	\$1994620-\$2541920

	Estimated Construction Cost	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs	Estimated Total Project Cost
2021-22	\$1,057,500	\$105900-\$454900	\$108,400	\$1271800-\$1620800
2022-23	\$528,750	\$52950-\$227450	\$83,550	\$665250-\$839750
Furniture, Fixtures, and Equipment				
2019-20	\$990,000	\$99000-\$425700	\$0	\$1089000-\$1415700
2020-21	\$6,630,000	\$663000-\$2850900	\$679,580	\$7972580-\$10160480
2021-22	\$2,300,000	\$230000-\$989000	\$235,750	\$2765750-\$3524750
2022-23	\$1,270,000	\$127000-\$546100	\$200,660	\$1597660-\$2016760
2023-24	\$625,000	\$62500-\$268800	\$134,380	\$821880-\$1028180
Mobile Replacement				
2019-20	\$4,400,000	\$440000-\$1892000	\$0	\$4840000-\$6292000
2020-21	\$400,000	\$40000-\$172000	\$41,000	\$481000-\$613000
2021-22	\$600,000	\$60000-\$258000	\$61,500	\$721500-\$919500
2022-23	\$800,000	\$80000-\$344000	\$126,400	\$1006400-\$1270400
2023-24	\$400,000	\$40000-\$172000	\$86,000	\$526000-\$658000

<sup>\*</sup>Note\* The Needs by Year list shown above is inclusive of only those needs that have been estimated by year. This includes those needs identified on each individual facility profile page, mobiles, athletic fields, and FF&E (furniture, features and equipment) needs. Identified capital needs for charter schools, information technology, transportation, safety and security, support fleet, and new construction are not currently projected by year and therefor not included in this list.

## Appendix 5 Capital Needs Deltas Since 2018-19

## Deltas by Capital Need Item

Capital Item	2018-19 Total Project Cost Estimate	2019-20 Total Project Cost Estimate	2018-19 vs. 2019-20 Total Project Cost Delta
ADA Contingency	\$525,000-\$607,500	\$525,000-\$607,500	\$0
Athletics	\$4,103,515-\$5,405,984	\$4,340,110-\$6,208,070	\$236,595-\$802,086
Charter Schools	\$25,464,795-\$36,425,728	\$26,514,717-\$37,193,017	\$1,049,922-\$767,289
Facility Reinvestment-Neighborhood Schools, Support Facilities	\$186,125,490-\$266,219,547	\$196,905,620-\$281,618,500	\$10,780,130-\$15,398,953
FF&E	\$13,587,250-\$18,254,225	\$13,587,250-\$18,254,225	\$0
Information Technology	\$27,400,000	\$0	(\$27,400,000)
Mobiles	\$6,930,000-\$8,019,000	\$6,930,000-\$8,019,000	\$0
New Construction (1-5 Years, DCSD Standards)	\$256,200,304	\$455,699,301	\$199,498,997
Playground Equipment	\$525,000-\$607,500	\$525,000-\$607,500	\$0
Safety & Security	\$9,552,714	\$4,980,215	(\$4,572,499)
SPED Contingency	\$525,000-\$607,500	\$525,000-\$607,500	\$0
Support Fleet	\$6,715,820	\$6,715,820	\$0
Transportation	\$22,279,935	\$19,369,895	(\$2,910,040)

Capital Need by Tier	Estimated Capital Cost-2019	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation	Total Project Cost
ADA Contingency	\$500,000	\$0	\$25,000-\$107,500	\$525,000-\$607,500
Athletics	\$3,773,480	\$377,930-\$1,623,230	\$188,700-\$811,360	\$4,340,110-\$6,208,070
1	\$0	\$0	\$0	\$0
2	\$3,701,250	\$370,650-\$1,592,150	\$185,080-\$795,830	\$4,256,980-\$6,089,230
3	\$72,230	\$7,280-\$31,080	\$3,620-\$15,530	\$83,130-\$118,840
4	\$0	\$0	\$0	\$0
Charter Schools	\$23,269,187	\$2,166,250-\$9,285,760	\$1,079,280-\$4,638,070	\$26,514,717-\$37,193,017
1	\$2,591,337	\$89,680-\$383,980	\$44,610-\$191,680	\$2,725,627-\$3,166,997
2	\$4,635,190	\$467,440-\$1,997,950	\$232,140-\$996,920	\$5,334,770-\$7,630,060
3	\$2,171,060	\$218,470-\$935,170	\$108,600-\$466,840	\$2,498,190-\$3,573,070
4	\$337,960	\$34,710-\$146,210	\$16,960-\$72,730	\$389,630-\$556,900
Untiered	\$13,375,010	\$1,340,070-\$5,754,170	\$668,970-\$2,875,790	\$15,384,050-\$22,004,970
Facility Reinvestment- Neighborhood Schools, Support Facilities	\$171,123,020	\$17,217,390-\$73,696,550	\$8,565,210-\$36,798,930	\$196,905,620-\$281,618,500
1	\$100,509,510	\$10,076,650-\$43,250,780	\$5,028,020-\$21,611,530	\$115,614,180-\$165,371,820
2	\$49,625,950	\$5,014,490-\$21,394,350	\$2,485,790-\$10,673,400	\$57,126,230-\$81,693,700
3	\$19,253,990	\$1,949,720-\$8,302,380	\$964,440-\$4,141,090	\$22,168,150-\$31,697,460
4	\$1,733,570	\$176,530-\$749,040	\$86,960-\$372,910	\$1,997,060-\$2,855,520
FF&E	\$11,815,000	\$1,181,500-\$3,899,000	\$590,750-\$2,540,225	\$13,587,250-\$18,254,225
1	\$0	\$0	\$0	\$0
2	\$0	\$0	\$0	\$0
3	\$11,815,000	\$1,181,500-\$3,899,000	\$590,750-\$2,540,225	\$13,587,250-\$18,254,225
4	\$0	\$0	\$0	\$0
Mobiles	\$6,600,000	\$0	\$330,000-\$1,419,000	\$6,930,000-\$8,019,000
1	\$0	\$0	\$0	\$0
2	\$0	\$0	\$0	\$0
3	\$6,600,000	\$0	\$330,000-\$1,419,000 \$0	\$6,930,000-\$8,019,000
New Construction (1- 5 Years, DCSD Standards)	\$0 \$455,699,301	\$0 <b>\$0</b>	\$0	\$0 \$455,699,301
Playground Equipment	\$500,000	\$0	\$25,000-\$107,500	\$525,000-\$607,500
Safety & Security	\$4,980,215	\$0	\$0	\$4,980,215
1	\$0	\$0	\$0	\$0
2	\$0	\$0	\$0	\$0
3	\$4,980,215	\$0	\$0	\$4,980,215
4	\$0	\$0	\$0	\$0
SPED Contingency	\$500,000	\$0	\$25,000-\$107,500	\$525,000-\$607,500
Transportation	\$19,369,895	<b>\$0</b>	\$0	\$19,369,895
1	\$6,713,461	\$0	\$0	\$6,713,461
2	\$6,318,681	\$0	\$0	\$6,318,681
3	\$6,337,753	\$0	\$0	\$6,337,753
4	\$0	\$0	\$0	\$0
Support Fleet	\$6,715,820	\$0	\$0	\$6,715,820
1	\$6,715,820	\$0	\$0	\$6,715,820
2	\$0	\$0	\$0	\$0
3	\$0	\$0	\$0	\$0
4	\$0	\$0	\$0	\$0
Grand Total	\$704,845,917	\$20,943,070-\$88,504,540	\$10,828,940-\$46,530,085	\$736,617,927-\$839,880,542

